

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBB1047A190415

**Estimate**

Customer

Name: Auto &amp; General Insurance (Singapore) Pte Ltd

Date: 18-04-19

Address Motor Claims Department

Vehicle No: GBB1047A

190 Clemenceau Avenue #03-01

Model/Make: Toyota Hiace

Singapore Shopping Centre

Singapore 239924

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front <del>bumper</del> Bumper <i>de</i>	\$ 796.80	<i>+</i>
2	Bumper Bracket <i>de</i>	\$ 380.40	<i>X</i>
3	Head Lamp <i>ALS</i>	\$ 930.70	<i>+</i>
4	Head Lamp Clip 1 set <i>ALS</i>	\$ 45.00	<i>SN X</i>
5	Radiator <i>ALS</i>	\$ 2,133.90	<i>+</i>
6	Radiator Coolant <i>25%</i>	\$ 45.00	<i>SN X</i>
7	Door "ROC" Sticker <i>ALS</i>	\$ 48.00	<i>SN 305. ✓</i>
	To check all wiring & electrical component for proper function	\$ 80.00	<i>- 20</i>
	To remove & replace radiator & conduct pressure test and bleed system	\$ 140.00	<i>- 11X</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	<i>- 300</i>
	To putty & spray painting & including touch up paint on accident affected	\$ 300.00	<i>- 200</i>
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	<i>- 11X</i>

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 5,479.80

Total amount in Lump Sum Basis for repaired vehicle



SDLS: \_\_\_\_\_

M/s Liu's Brother Auto Engrg Wks

*not added*  
*black*  
*2/3 @ 2200/-*  
*22/4/19*  
*the photo attached*  
*3 dy.*

*P-3861.4*  
*257*  
*2896.05*  
*3446.05*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: