

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0512/2019/DY/TF
Date : 18-Apr-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **SMH 2517 S**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm. Sim Ee Lin
Address : Blk 5 Tampines Ave 8
#13-08
Singapore 529596
Telephone : HP +65 81002788
Type of Claim : Third Party Claims
Policy No. : DMPPHQ19-001001
Vehicle No : **SLW 4621 T** ✓
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Feb-18
Engine No : CHZ 624515
Chassis No : WAUZZZ8V0J1037950
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Apr-19

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 4621 T

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according to damage.	s/n \$ 280.00 ✓
2	To dismantle and renew rear bumper. Re-organise rear crash managements components. Reinstall all parts removed.	\$ 900.00 500
3	To respray rear bumper.	\$ 800.00 550
4	To carry out diagnostic check.	s/n \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 2,172.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 4621 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Rehnd</i>	\$1,793.00	✓
2	REAR BUMPER STICKY PAD <i>{ new</i>	\$21.00	+
3	REAR BUMPER FIXING PARTS	\$175.00	✓
4	REAR BUMPER TOP GUIDE SECTION - LH / RH <i>{ new</i>	\$30.00	+
5	REAR BUMPER TOP GUIDE SECTION PIN <i>{ new</i> 2	\$53.00	+
6	REAR BUMPER SPOILER <i>new</i>	\$216.00	✓
7	REAR BUMPER REFLECTOR - LH / RH <i>new</i>	\$76.00	+
8	REAR BUMPER REINFORCEMENT BAR <i>new</i>	\$522.00	+
9	REAR BUMPER BRACKET - LH / RH <i>new</i>	\$51.00	+
10	REAR BUMPER SENSOR <i>{ new</i> 2	\$462.00	+
11	REAR BUMPER SENSOR SEAL 4	\$12.00	+
12	SUNDRIES ?	\$400.00	?
TOTAL SPARE PARTS CHARGES :		\$3,811.00	
TOTAL LABOUR CHARGES		\$ 2,172.00	
GRAND TOTAL		\$ 5,983.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 23/04/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant