

ASS. REC. BY:

REF: CS/MSG19007064/A92d3

Special Instruction:

Survivor: GAASSIGNMENT (Office)From (Person): Chia Ngue Pui of MSGDate/Time: 22.4.19 17.33 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJ2 2232DInsured: SLT 5075Dat Workshop m/s Chew MotorTel: 67479241of 1 Kati Buki Ave 6, #01-43Policy No: MSD/VP9/18-000001Claim No: 591480

Sum Insured:

Excess:

Make of Veh:

D.O.A. 19.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 22.4.2019 5.39 p.mPerson Contacted: SukiVehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJ2 2232D - ✓</u>
	<u>SLT 5075D - x</u>
<u>24/4/19 @ 2pm</u>	<u>Informed Chia Ngue Pui, we are pending estimate from repairer.</u>
<u>06/5/19 @ 12.46pm</u>	<u>Varised to Chia Ngue Pui via Messenger.</u>
	<u>US \$8000, 12 days (Ref to 29513.50, 7972)</u>

minimum

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SJ22232D Yr Regn: 2007 JanType: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish c.c. 1784Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 150114 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZNE100324530Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 22/04/19

Survey held at: _____

Des. of Damages: Frd / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TPMS/G.COE Expiry: 23/01/22

RECEIVED 8 MAY 2019

MV: 23KPV: 14.5KNett: 851K

Date/Time, File Pass to?

Date/Time, File Return to?

1) 06/5 turnst

2) _____

3) _____

4) _____

5) _____

6) _____

Pres. Report

Final Report

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

___ \$ + RS. ___ \$

Photos

Others

TOTAL

250



New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



SEARCH

Wish

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Search

View All

Advanced Search

Used Car Comparison

--- Comparing 4 Vehicles ---

Toyota Wish 1.8A (COE till 10/2021)



Add to Shortlist

Toyota Wish 1.8A X Limited (COE till 10/2021)



Add to Shortlist

Toyota Wish 1.8A (COE till 08/2021)



Add to Shortlist

Toyota Wish 1.8A X Limited (COE till 11/2021)



Add to Shortlist

Clear All

Add all to Shortlist

Back to search result

CAR DETAILS

Price	\$19,800	\$20,800	\$21,800	\$20,800
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	02-Oct-2006	26-Oct-2006	27-Oct-2006	24-Nov-2006
Manufactured	2006	2006	2006	2006
Mileage	-	140,000 km	-	-
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,794 cc	1,794 cc	1,794 cc	1,794 cc
Road Tax	\$1,264 /yr	\$1,264 /yr	\$1,264 /yr	\$1,264 /yr
Power	97.0 kW (130 bhp)	97.0 kW (130 bhp)	97.0 kW (130 bhp)	97.0 kW (130 bhp)
Curb Weight	1,300 kg	1,300 kg	1,300 kg	1,300 kg
Features	-	Powerful & Reliable 1.8L DOHC 16V VVT-i Engine, Smooth 5-Speed Steptronic Gearbox, ABS, EPS, Digital Climate Control A/C, SRS Airbags, Walnut Trimming	Powerful And Reliable 16 Valves VVT-i DOHC Engine, Smooth 4 Speed Steptronic Gearbox, Digital Climate Control Aircon, Airbags, ABS, 7 Seaters.	Powerful And Reliable 16 Valves VVT-i DOHC Engine, Smooth 4 Speed Steptronic Gearbox, Digital Climate Control Aircon, Airbags, ABS, 7 Seaters.
Accessories	-	Premium Leather Seats, Touchscreen DVD Audio Systems, Sport Rims, Reverse Sensors, Auto Retractable Side Mirrors With Indicators, Knockdown Rear Seats	Stock Rims, Factory Fitted Audio System, Reverse Sensors, Electrical Retractable Side Mirrors, Upholstery Leather Seats, Etc.	Sports Rims, Leather Seats With Reverse Camera, Solar Film, Knockdown Rear Seats
Description	Well Kept. Good Condition. High Paper Value. High Trade In. Bank Loan And In House Loan Available.	Don't Miss It! Rare 1 Ownership Wish! Low Mileage Done! Guaranteed Accident Free & No Repair Needed! Very Well Maintained By Previous Owner. Buy With Assurance! Various Bank Or In House Loan Available. All Trade-In Welcome! View To Believe It's Condition! So Hurry Call To An Make Appointment Today Before It's Gone!	Superb Condition. Very Well Taken Care. Don't Miss It! Up To 100% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled Warranty Complete With Certificate And Test Report. Check Out Our New Offer Now. Meet Our Friendly Consultant For An Non-Obligation Advice.	Superb Condition. Very Well Taken Care. Don't Miss It! Up To 100% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled Warranty Complete With Certificate And Test Report. Check Out Our New Offer Now. Meet Our Friendly Consultant For An Non-Obligation Advice.
COE	\$28,376	\$28,376	\$27,232	\$28,027
OMV	\$18,279	\$18,333	\$19,158	\$18,460
ARF	\$20,107	\$20,167	\$21,074	\$20,306
Depreciation	\$8,090 /yr	\$8,280 /yr	\$9,230 /yr	\$8,030 /yr
No. of Owners	3	1	2	2
Type of Vehicle	MPV	MPV	MPV	MPV
Category	COE Car	COE Car	COE Car	COE Car
Availability	Available	Available	Available	Available
Remarks				

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 06 May 2019

Preliminary Advice

Insured Vehicle No	: SLT5075D	Accident Date	: 19/04/2019
TP Vehicle No	: SJZ2232D	Assignment Date	: 22/04/2019
Make	: TOYOTA WISH	Est. Duration of Repair	: 12.00
Date of Inspection	: 22/04/2019		
Inspection At	: CHEW MOTOR PTE LTD (KAKI BUKIT) (HQ) 1 KAKI BUKIT AVE 6, #01-43 BLK C @ AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,513.50
Revised Amount	:S\$	10,318.83
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,318.83
Lump Sum Repair	:S\$	8,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 24 April 2019 2:00 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SJZ 2232D (POLICY NO.: MSD/VPCP/18-000001)

This mail is associated with :
***SJZ2232D**
[SLT5075D]
TP
POH CHER SOI
Apr 19 2019 8:00AM
[BlueCar East Asia Pte Ltd]
Chew Motor Pte Ltd (kaki Bukit)

Dear Nyuk Pui,

Please be informed that we have inspected the vehicle SJZ 2232D.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/04/2019 15:36
Date Of Accident	19/04/2019 08:30
Exact Location Of Accident	MULTI STOREY CARPARK OF BLK 354 JURONG EAST ST 31
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ2232D
Insured/Policyholder	
Name Of Registered Owner	POH CHER SOI
NRIC No	S1500727C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91910727
Alternative Phone No	OFFICE-91910727

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5046319274-08
Cover Note Number	

Driver

Name of Driver	POH CHER SOI
NRIC No	S1500727C
Date Of Birth	12/12/1961
Occupation	INDOOR
Date Of Driving Pass	10/09/1979
Driving Experience	39 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91910727
Fax Number	
Contact Number	OFFICE-91910727
Email Address	NOEMAIL

Address	BLK 541 BUKIT PANJANG RING ROAD #08-865
Postcode	670541
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE WAS PARKED STATIONARY AT THE MULTI STOREY CARPARK OF BLK 354 JURONG EAST STREET 31. WHEN I RETURNED TO MY VEHICLE, I REALISED THAT MY VEHICLE WAS HIT ON THE FRONT PORTION. DUE TO THE IMPACT, MY VEHICLE MOVED BACKWARDS AND HIT ONTO THE PILLAR WALL AT THE BACK. THERE'S ALSO NOTE LEFT BY VEHICLE B AND HIS CONTACT NUMBER. HE WATNED TO COMPENSATE ON THE DAMAGES. HOWEVER, DUE TO THE DAMAGES, I TOLD DRIVER B THAT I WILL CLAIM AGAINST HIS INSURANCE INSTEAD.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT5075D
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

my vehicle was parked stationary at the multi story carpark of blk 354, along east st31

when i returned to my vehicle, i realised that my vehicle was hit on the front portion. due to the impact, my vehicle moved backwards and hit onto the pillar wall at the next.


there's also notes left by vehicle B on my wheel number and he wished to compensate on the damages.

however, due to the damages, i told driver B that i will claim against his insurance instead.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

23/04/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

T?MSIG.
Xiao Chen

Accident date: 19/04/2019

Estimated repair cost for vehicle no: SJZ2232D TOYOTA WISH 1.8 A '07

CHASSIS: ZNE100324530

S/n	Qty	Items	U/price	Amount	
1	1	Front Bonnet Buckled		\$581.40	✓
2	2	Front Bonnet Hinge New	\$115.30	\$230.60	+
3	1	Front Bonnet Emblem Logo New		\$61.40	✓
4	1	Front Bonnet Chrome Cracked		\$218.90	✓
5	1	Front Bonnet Lock New		\$112.20	+
6	1	Front Bonnet Inner Rubber ?		\$108.10	+
7	1	Front Bonnet Insulator ? New		\$188.00	+
8	8	Front Bonnet Insulator Clip	\$6.50	\$52.00	+
9	2	Front Head Lamp Cracked	\$586.00	\$1,172.00	✓
10	1	Front Grille Cracked		\$185.20	✓
11	1	Front Bumper Bent		\$451.80	✓
12	8	Front Bumper Clip New	\$6.50	\$52.00	30
13	2	Front Bumper Side Retainer New	\$78.00	\$156.00	✓
14	1	Front Bumper Number Plate Cracked		\$50.00	✓
15	1	Front Bumper Center Lower Garnish New		\$116.00	+
16	1	Front Bumper Inner Sponge Cracked		\$135.40	✓
17	1	Front Bumper Reinforcement Bent		\$286.20	✓
18	2	Front Bumper Fog Lamp ? New	\$374.50	\$749.00	✓
19	2	Front Bumper Fog Lamp Cover ? New	\$131.10	\$262.20	+
20	1	Front Support Panel Repair		\$781.10	+
21	1	Front Brace Panel Bent		\$141.40	✓
22	1	Front Air-Con Condenser Bent		\$788.30	✓
23	1	Front Air-Con Section Pipe ? New		\$365.10	+
24	1	Front Air-Con Discharge Pipe ? New		\$426.20	+
25	1	Front Radiator New		\$1,118.10	+
26	1	Front Radiator Fan Motor Assy New		\$546.30	+
27	1	Rear Boot Lid Dented		\$1,315.20	✓
28	2	Rear Boot Lid Hinge New	\$141.40	\$282.80	+

29	2	Rear Boot Lid Shock Absorber	new	\$371.80	\$743.60	+
30	1	Rear Boot Lid Emblem Logo	new		\$51.10	✓
31	1	Rear Boot Lid Wish Chrome Moulding	new		\$274.40	+
32	1	Rear Boot Lid Number Plate	new		\$50.00	+
33	2	Rear Boot Lid Number Plate Lamp	new	\$105.10	\$210.20	+
34	1	Rear Boot Lid Wiper Link	new		\$122.25	+
35	1	Rear Boot Lid Wiper Arm	new		\$181.90	+
36	1	Rear Boot Lid Wiper Arm Cover	new		\$122.35	+
37	1	Rear Boot Lid Wiper Motor	new		\$389.20	+
38	1	Rear Boot Lid Inner Lock	new		\$374.40	+
39	1	Rear Boot Lid Inner Rubber	new		\$381.90	+
40	1	Rear Boot Lid Inner Trim Board	new		\$781.40	+
41	1	Rear Boot Lid Inner Top Center Garnish	new		\$282.60	+
42	2	Rear Boot Lid Inner Top Side Garnish	new	\$122.80	\$245.60	+
43	1	Rear Boot Lid Top Spoiler	cracked		\$950.00	704
44	1	Rear Boot Lid Top Spoiler Brake Lamp	cracked		\$328.60	✓
45	1	Rear Boot Lid Windscreen	shattered		\$971.80	✓
46	1	Rear Boot Lid Windscreen Seal	new		\$125.00	✓
47	2	Rear Boot Lid Windscreen Moulding	new	\$68.00	\$136.00	✓
48	2	Rear Tail Lamp	new	\$387.40	\$774.80	+
49	4	Rear Tail Lamp Clip	new	\$8.00	\$32.00	+
50	2	Rear Tail Lamp Panel	new	\$378.20	\$756.40	+
51	1	Rear Bumper	detached		\$625.20	✓
52	8	Rear Bumper Clip	new	\$6.50	\$52.00	30
53	2	Rear Bumper Side Retainer	new	\$132.10	\$264.20	✓
54	2	Rear Bumper Side Reflector	new	\$141.40	\$282.80	+
55	1	Rear Bumper Reverse Sensor (Special Nett)	Damaged		\$380.00	200%
56	1	Rear End Panel Outer	Repair		\$519.80	+
57	1	Rear End Panel Top Garnish	new		\$375.40	+
58	2	Rear Fender Inner Trim Board	new	\$471.40	\$942.80	+
59	16	Rear Fender Inner Trim Board Clip	new	\$6.50	\$104.00	+
60	2	Rear Fender Cowling	new	\$172.20	\$344.40	+
61	12	Rear Fender Cowling Clip	new	\$6.50	\$78.00	+
62	1	Rear Spare Tyre Panel	new		\$980.30	+
63	1	Rear Spare Tyre Panel Top Cover	new		\$292.20	+
64	1	Rear Spare Tyre Panel Sealant	new		\$450.00	+
65	1	Rear Exhaust	new		\$961.20	+
66	2	Rear Exhaust Mounting	new	\$67.60	\$135.20	+
67	1	Rear Center Exhaust	new		\$1,714.20	+
68	1	Roof Top Panel	Repair		\$2,883.40	+

810510

Subtotal :- \$30,603.50

607882

SW: 900.

Labour charges

To remove & refit cushion	\$280.00 80
To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00 120
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & center exhaust	\$380.00 x
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To check wiring	\$100.00 60
Tuff kote	\$150.00 60
Towing fee	3340- \$150.00 x
Panel beating	\$2,800.00 1400
Spray painting	\$2,400.00 1200

Subtotal :- \$6,910.00

Total:- \$37,513.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 10318.82
L/S: 8K (Nett Value)
12 Days

8K

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Apr 2019 11:08		22 Apr 2019 17:33 Edit Adj Rpt	S\$8,000.00 Edit Estimates	S\$8,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	BlueCar East Asia Pte Ltd, Co. Reg. No.: 201617259H								
Main Claimant:	POH CHER SOI, ID: S1500727C								
Vehicle Reg. No.:	SJZ2232D	Date of Loss:	19/04/2019 08:00 - :59 [146 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 591480	Policy/Cover Note No.:	MSD/VPCP/18-000001 (Comprehensive) Coverage: 01/01/2019 - 31/12/2019						
Vehicle Reg. No. (Insured):	SLT5075D	Policy No. (Claimant):							
		Excess:							
Repairer:	Chew Motor Pte Ltd (Kaki Bukit) (HQ) 1 KAKI BUKIT AVE 6, #01-43 BLK C @ AUTOBAY, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 22/05/2019]								
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY:DISPUTE (01 NON-REPORTING) CONTACT: SUKYL CHONG 6747 9241								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJZ2232D (591480)**
[SLT5075D]
TP
POH CHER SOI
Apr 19 2019 8:00AM
[BlueCar East Asia Pte Ltd]
Chew Motor Pte Ltd (kaki Bukit)



















































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)











































View View in Browser

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	24/04/19 16:53	Letter to OI Informing TPD	1 Load HTML		

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	06/05/19 12:16	Adjuster Immediate Advice	1 Load HTML		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
2	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
3	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
4	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
5	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
6	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
7	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
8	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
9	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
10	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
11	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
12	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
13	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
14	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
15	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
16	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
17	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
18	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
19	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
20	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
21	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
22	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
23	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
24	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
25	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
26	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
27	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
28	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
29	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	
30	06/05/19 11:27	General View	1 Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
38	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
41	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
44	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/05/19 11:27	General View	 Load JPG	<input checked="" type="checkbox"/>
49	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
81	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	06/05/19 11:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/04/19 11:09	TP PRI NOTICE	 Load PDF	
2	22/04/19 11:18	SJZ2232D SKETCH PLAN	 Load PDF	
3	22/04/19 11:18	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK	 Load PDF	
4	23/04/19 11:49	TP - SJZ2232D GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19007064/AGQD3Q2

Date: 08/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VPCP/18-000001

Claimant Vehicle No: SJZ2232D

Insured Vehicle No: SLT5075D

Date of Loss: 19/04/2019

Nature of Claim: TP

Claim No: 591480

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ2232D	Engine No:	1ZZ2688160
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100324530
Reg. Date:	24/01/2007 (Man. Year: 2006)	Odometer:	150114 km
Colour:	Blue		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,603.50	6,978.82	23,624.68	77.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,910.00	3,340.00	3,570.00	51.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,513.50	10,318.82	27,194.68	72.49
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	37,513.50	8,000.00	29,513.50	78.67
+ GST 7.00/7.00% (S\$)	2,625.95	560.00	2,065.95	78.67
Nett Amount (S\$)	40,139.45	8,560.00	31,579.45	78.67

INSPECTION

Date of Assignment: 22/04/2019

Date Inspected: 22/04/2019 Inspected At:

Chew Motor Pte Ltd (kaki Bukit) (HQ)
1 KAKI BUKIT AVE 6, #01-43 BLK C @
AUTOBAY
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ2232D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	581.40 F	*581.40 FL
2	2		*FRONT BONNET HINGE	Not Necessary	230.60 F	*- FL
3	1		*FRONT BONNET EMBLEM LOGO	Necessary	61.40 F	*61.40 FL
4	1		*FRONT BONNET CHROME	Cracked	218.90 F	*218.90 FL
5	1		*FRONT BONNET LOCK	Not Necessary	112.20 F	*- FL
6	1		*FRONT BONNET INNER RUBBER	Not Necessary	108.10 F	*- FL
7	1		*FRONT BONNET INSULATOR	Not Necessary	188.00 F	*- FL
8	8		*FRONT BONNET INSULATOR CLIP	Not Necessary	52.00 F	*- FL
9	2		*FRONT HEAD LAMP	Cracked	1,172.00 F	*1,172.00 FL
10	1		*FRONT GRILLE	Cracked	185.20 F	*185.20 FL
11	1		*FRONT BUMPER	Deformed	451.80 F	*451.80 FL
12	8		*FRONT BUMPER CLIP	Necessary	52.00 F	*30.00 FL
13	2		*FRONT BUMPER SIDE RETAINER	Necessary	156.00 F	*156.00 FL
14	1		*FRONT BUMPER NUMBER PLATE	Cracked	50.00 F	*50.00 FL
15	1		*FRONT BUMPER CENTER LOWER GARNISH	Not Necessary	116.00 F	*- FL
16	1		*FRONT BUMPER INNER SPONGE	Cracked	135.40 F	*135.40 FL
17	1		*FRONT BUMPER REINFORCEMENT	Bent	286.20 F	*286.20 FL
18	2		*FRONT BUMPER FOG LAMP	Not Necessary	749.00 F	*- FL
19	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	262.20 F	*- FL
20	1		*FRONT SUPPORT PANEL	Repair	781.10 F	*- FL
21	1		*FRONT BRACE PANEL	Bent	141.40 F	*141.40 FL
22	1		*FRONT AIR-CON CONDENSER	Bent	788.30 F	*788.30 FL
23	1		*FRONT AIR -CON SECTION PIPE	Not Necessary	365.10 F	*- FL
24	1		*FRONT AIR -CON DISCHARGE PIPE	Not Necessary	426.20 F	*- FL
25	1		*FRONT RADIATOR	Not Necessary	1,118.10 F	*- FL
26	1		*FRONT RADIATOR FAN MOTOR ASSY	Not Necessary	546.30 F	*- FL
27	1		*REAR BOOT LID	Dented	1,315.20 F	*1,315.20 FL
28	2		*REAR BOOT LID HINGE	Not Necessary	282.80 F	*- FL
29	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	743.60 F	*- FL
30	1		*REAR BOOT LID EMBLEM LOGO	Necessary	51.10 F	*51.10 FL
31	1		*REAR BOOT LID WISH CHROME MOULDING	Not Necessary	274.40 F	*- FL
32	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
33	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	210.20 F	*- FL
34	1		*REAR BOOT LID WIPER LINK	Not Necessary	122.25 F	*- FL
35	1		*REAR BOOT LID WIPER ARM	Not Necessary	181.90 F	*- FL
36	1		*REAR BOOT LID WIPER ARM COVER	Not Necessary	122.35 F	*- FL
37	1		*REAR BOOT LID WIPER MOTOR	Not Necessary	389.20 F	*- FL
38	1		*REAR BOOT LID INNER LOCK	Not Necessary	374.40 F	*- FL
39	1		*REAR BOOT LID INNER RUBBER	Not Necessary	381.90 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	781.40 F	*- FL
41	1		*REAR BOOT LID INNER TOP CENTER GARNISH	Not Necessary	282.60 F	*- FL
42	2		*REAR BOOT LID INNER TOP SIDE GARNISH	Not Necessary	245.60 F	*- FL
43	1		*REAR BOOT LID TOP SPOILER	Cracked	950.00 FS	*700.00 FS
44	1		*REAR BOOT LID TOP SPOILER BRAKE LAMP	Cracked	328.60 F	*328.60 FL
45	1		*REAR BOOT LID WINDSCREEN	Shattered	971.80 F	*971.80 FL
46	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	125.00 F	*125.00 FL
47	2		*REAR BOOT LID WINDSCREEN MOULDING	Necessary	136.00 F	*136.00 FL
48	2		*REAR TAIL LAMP	Not Necessary	774.80 F	*- FL
49	4		*REAR TAIL LAMP CLIP	Not Necessary	32.00 F	*- FL
50	2		*REAR TAIL LAMP PANEL	Not Necessary	756.40 F	*- FL
51	1		*REAR BUMPER	Deformed	625.20 F	*625.20 FL
52	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
53	2		*REAR BUMPER SIDE RETAINER	Necessary	264.20 F	*264.20 FL
54	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	282.80 F	*- FL
55	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
56	1		*REAR END PANEL OUTER	Repair	519.80 F	*- FL
57	1		*REAR END PANEL TOP GARNISH	Not Necessary	375.40 F	*- FL
58	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	942.80 F	*- FL
59	16		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
60	2		*REAR FENDER COWLING	Not Necessary	344.40 F	*- FL
61	12		*REAR FENDER COWLING CLIP	Not Necessary	78.00 F	*- FL
62	1		*REAR SPARE TYRE PANEL	Not Necessary	980.30 F	*- FL
63	1		*REAR SPARE TYRE PANEL TOP COVER	Not Necessary	292.20 F	*- FL
64	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	450.00 F	*- FL
65	1		*REAR EXHAUST	Not Necessary	961.20 F	*- FL
66	2		*REAR EXHAUST MOUNTING	Not Necessary	135.20 F	*- FL
67	1		*REAR CENTER EXHAUST	Not Necessary	1,714.20 F	*- FL
68	1		*ROOF TOP PANEL	Repair	2,883.40 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,603.50	9,005.10
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,026.28
Total Parts (\$\$)	30,603.50	6,978.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION	New	280.00	80.00
2	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR ,FAN MOTOR & TOP UP GAS	New	380.00	120.00
3	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
4	TO REMOVE & REFIT REAR & CENTER EXHAUST	New	380.00	0.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
6	GUM	New	50.00	50.00
7	TO CHECK WIRING	New	100.00	60.00
8	TUFF KOTE	New	150.00	60.00
9	TOWING FEE	New	150.00	0.00
10	PANEL BEATING	New	2,800.00	1,400.00
11	SPRAY PAINTING	New	2,400.00	1,400.00
Gross Labour Cost (\$\$)			6,910.00	3,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >