

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: YM8180X190413

Estimate**Customer**

Name: ERGO Insurance Pte Ltd

Address: Motor Claims Department

5 Temasek Boulevard #04-01

Suntec Tower Five Singapore 038985

Date: 18-04-19

Vehicle No: YM8180K

Model/Make Hino FD8JPKA

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Cargo Deck Panel	\$ 900.00	SN 800 5.2
2	Cargo Deck Panel Inner Plywood 02 pcs (\$200.00 SN)	\$ 400.00	SN 200 1pc
3	Cargo Deck Sliding Door	\$ 2,600.00	SN 2200
4	Cargo Deck Sliding Door Lock	\$ 250.00	SN X
5	Cargo Deck Sliding Door Plywood 03 pcs (@ \$200.00)	\$ 600.00	SN one 400 2pc
6	Cargo Deck Sliding Door Lower Panel	\$ 450.00	SN X
7	Cargo Deck Sliding Door Pillar	\$ 800.00	SN 600
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc.	\$ 1,400.00	- 800
	Remove, replace and transfer sliding door panel, fitting and mechanisms		
	To putty & spray painting & including touch up paint on accident affected area	\$ 1,000.00	700
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 100.00	11X

Total Parts & Labour of estimate for damaged vehicle

\$ 8,500.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

\$700
4500

M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not allowed
LKK
22/4/19
4500

4500
the photo after repair.