

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Your ref :

TP :

25/4/2019

M/S EQ INSURANCE

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR GU3113U

TO SUPPLY :

List Items

1	1 PC	HEADLAMP RH	one	\$ 1,145.80	✓
2	1 PC	RH CORNER PANEL	2	\$ 329.80	X
3	1 PC	RH DOOR	3.03m	\$ 1,742.60	?
4	1 PC	LH STEP GARNISH		\$ 318.30	?
5	2 PC	DOOR HINGES	set	\$ 197.28	✓
				\$ 3,733.78	
			252	less 20%	\$ (746.76)
				\$ 2,987.02	
6	1 PC	FRONT DOOR STICKER	new	\$ 15.00	20
7		CHECK WIRING		\$ 35.00	
8		SPRAY PAINTING(PILLAR, DOOR, PANEL BUMPER ,ARH)		\$ 1,150.00	800
9		LABOUR CHARGE		\$ 980.00	600
				<u>\$ 5,167.02</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged
 LKK
 P/P
 4 days
 25/4/19