

Please arrange to survey vehicle at
 8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT
 SINGAPORE 415875



*not actual
 value
 taken from survey
 4 days.
 23/4/19*

LINDA LIAO
 ABWIN SERVICE PTE LTD
 DID: 67139417
 Fax: 67139415
 HP: 97519596

Date : 20/04/2019
 TP Vehicle No. : GBG-1063-B
 To : AXA INSURANCE SINGAPORE PTE LTD
 Attn : Motor Claim Department

Owner : TEO WEE KIONG (ZHANG WEIQIANG)
 AIG ASIA PACIFIC INSURANCE PTE LTD
 Certificate No. : 1700065901-01
 Vehicle No. : SLS-3926-S
 Make & Model : MAZDA 3 1.6 HATCHBACK (A)

Accident Date: 17/04/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Item			
1	FRONT BUMPER	<i>Dis</i> \$1,025.00	—
10	FRONT BUMPER CLIPS	<i>per</i> \$60.00	—
1	FRONT BUMPER RETAINER RHS	<i>17</i> \$35.00	X
1	FRONT BUMPER RETAINERS LHS	<i>17</i> \$35.00	X
1	FRONT BUMPER INNER GARNISH RH	<i>17</i> \$55.00	X
1	FRONT BUMPER TOW COVER RH	<i>17</i> \$55.00	X
1	FRONT BUMPER SPONGE CENTER	<i>17</i> \$105.00	X
1	FRONT BUMPER BRACKET RH	<i>17</i> \$45.00	X
1	FRONT BUMPER FOG LAMP RH	<i>one</i> \$45.00	X
1	FRONT BUMPER FOG LAMP CHROME MOULDING RH	<i>17</i> \$35.00	X
1	FRONT BUMPER FOG LAMP GARNISH	<i>one</i> \$35.00	—
1	FRONT BUMPER CHROME RH	<i>17</i> \$215.00	X
1	HEADLAMP RH	<i>one</i> \$3,985.60	X
4	HEADLAMP CLIPS RH	<i>17</i> \$32.00	X
1	FRONT FENDER (RH)	<i>17</i> \$395.60	X
1	FRONT FENDER INNER SHIELD RH	<i>17</i> \$165.00	X
10	FRONT FENDER INNER SHIELD CLIP	<i>17</i> \$60.00	X
1	FRONT GRILLE CENTER CHROME	<i>17</i> \$350.00	X
1	FRONT GRILLE LOGO	<i>17</i> \$85.00	X
1	FRONT BONNET GRILLE	<i>17</i> \$350.00	X
	Sub Total	\$7,168.20	
	Discount 20% on Parts	(\$1,433.64)	
		\$5,734.56	
Special Nett			
1	FRONT NO PLATE WITH CASING	<i>17</i> \$65.00	X
	Sub Total	\$65.00	

LINDA LIAO
 ABWIN SERVICE PTE LTD
 DID: 67139417
 Fax: 67139415
 HP: 97519596

Date : 20/04/2019
 TP Vehicle No. : GBG-1063-B
 To : AXA INSURANCE SINGAPORE PTE LTD
 Attn : Motor Claim Department

Owner : TEO WEE KIONG (ZHANG WEIQIANG)
 AIG ASIA PACIFIC INSURANCE PTE LTD
 Certificate No. : 1700065901-01
 Vehicle No. : SLS-3926-S
 Make & Model : MAZDA 3 1.6 HATCHBACK (A)

Accident Date: 17/04/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
Labour & Misc			
	TO CHECK & REFOCUS FRONT HEADLAMP & WIRING CHECK	\$150.00	20
17	TO CONDUCT 4 WHEEL ALIGNMENT	\$250.00	X
17	TO APPLY TUFF KOTE ON AFFECTED AREA.	\$150.00	X
	TO PANEL BEAT, REPAIR, REPLACE FRONT PORTION.	\$1,800.00	580
	TO SPRAY PAINT ON AFFECTED AREAS.	\$1,800.00	800
	Sub Total	\$4,150.00	

Sub Total \$9,949.56
GST 7% \$696.47
Total \$10,646.03

LKA Auto Consultants hence notify the Repairer of the following:

- To remove rust after spray painting
- To replace damaged part(s) during resurvey
- Work orders are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: