

POLY CASE OWNER: LOH CHH HANG

CC 4, Mh 1900 7080, Bhasy

LDAC

Sub type:

Mr. Lim

DOI:

ASSIGNMENT

22/11/19

Date / Time:

21/11/19

Registered in Merimen:

21/11/19

Pre-assign / CCU / FTE

SJU 6878R



Insured Vehicle No.:

Name of Insured:

TAN BOON TUCK

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

18/11/19

Is driver the owner?

(☒ YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: ☒ YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability: % Final ? Yes / No

SLD 6532D



INSRS:

WSP:

Tel:

Liability:

RMKS:

1 car Auto Pro.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SLD 6532D - X; SJU 6878R - X

3VC, 013RD & LAST.

23/03/19

- PLUS RECOVERED. OI INVOLVED IN A 3 VEH. C.C. 4 WAS THE LAST CAR. SEND OTHER 4 EMAIL TO OI TO NOTIFY TP CLAIM 4 NCD ISSUES.
- BUREAU LIABILITY CLARTE
- PINKISHED
- TP LOD IN BY EMAIL

31/07/19

- TYPE REPORT FOR MANDATE APPROVAL
- REPORT DONE

24/08/19

- SEND MANDATE TO AIG

26/09/19

- AIG APPROVED MANDATE.
- SEND 1ST OFFER TO TP
- TP ACCEPTED OFFER.
- ALL BOCS IN ORDER. TO CLOSE.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 23/07/19-VIC

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost: HS

S\$ 18,500.00 (14 days) Reduction: 43 %

Confirm by:

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

ADON

Email ☒ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 28

IF NO or B 28, Ass. Lia: 100%

Repair Cost:

S\$ 18,500.00

(3 VEH. C.C.; 01 VEH.)

Loss of Rental (LOR):

S\$ 1,400.00 (14 days) x \$100.00

Loss of Use (LOU):

S\$ - (3 x days)

Loss of Income (LOI):

S\$ 180.00 x 3 days

LOR only ☒ LOU only ☐

LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/TA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

TOWING S\$ 120.00

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 20,207.45 Global Sum S\$ 20,200.00

1) Claim status: ☒ Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$350.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 20,200.00

Name 1:

TEAM AUTOPRO PTE LTD

Payee 2: (Strike if N/A)

S\$ -

Name 2:

Payee 3: (Strike if N/A)

S\$ -

Name 3:

REF: AIG

ASSIGNMENT

From: Date: 22/4/19

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SLD G532D
at Workshop n/s Team Autopro

of 160 Sin Ming Drive #01-14

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLD G532D Yr Regn: 24/6/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda 1.8L 15X A C.C. 1436

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 95455 T/Radio: Insured / Std / NI / NA

Eng/No: L15B4037286

C/No: R111117285

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60/16

R: 215/60/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 18/4/19 D.O.I. 22/4/19

Survey held at Team Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18,500.00

L/S 21,500.00
CRAB: 14,000.50/13%

MIV 62,000/2

PV 46,300/2

NV 21,200/2

Team Autopro
24/4/19

Date/Time, File Pass to?

☐ : Proli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation:

) 3 + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

SJE :

Date of Survey :

Date of ReSurvey :

Contacts :

After-Paint:

Vehicle Nos : SLD 6532D

Model : HONDA VEZEL

Year :

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit \$	TOTAL \$
1	TAILGATE	1	\$ 1,620.00	\$ 1,620.00
2	TAILGATE OUTER GARNISH	1	\$ 385.00	\$ 385.00
3	TAILGATE OUTER GARNISH CLIPS	1	\$ 50.00	\$ 50.00
4	TAILGATE LOGO	1	\$ 58.00	\$ 58.00
5	TAILGATE REFLECTOR	2	\$ 395.00	\$ 790.00
6	TAILGATE REFLECTOR CLIPS	2	\$ 50.00	\$ 100.00
7	TAILGATE INNER LOCK	1	\$ 245.00	\$ 245.00
8	TAILGATE LOCK SENSOR	1	\$ 230.00	\$ 230.00
9	TAILGATE TRIM BOARD	1	\$ 325.00	\$ 325.00
10	TAILGATE TRIM BOARD CLIPS	1	\$ 50.00	\$ 50.00
11	TAILGATE WEATHERSTRIP	1	\$ 185.00	\$ 185.00
12	TAILGATE SOLENOID SWITCH	1	\$ 195.00	\$ 195.00
13	REAR WINDSCREEN MOULDING BOTTOM	1	\$ 118.00	\$ 118.00
14	REAR WINDSCREEN MOULDING TOP	1	\$ 118.00	\$ 118.00
15	REAR WINDSCREEN SIDE moulding	2	\$ 86.00	\$ 172.00
16	SMART BUZZER	1	\$ 285.00	\$ 285.00
17	REAR BUMPER	1	\$ 1,185.00	\$ 1,185.00
18	REAR BUMPER CLIPS	1	\$ 50.00	\$ 50.00
19	REAR BUMPER SIDE RETAINER	2	\$ 88.00	\$ 176.00
20	REAR BUMPER BRACKET	2	\$ 116.00	\$ 232.00
21	REAR BUMPER REFLECTOR	2	\$ 187.00	\$ 374.00
22	REAR END PANEL	1	\$ 725.00	\$ 725.00
23	REAR END PANEL TOP GARNISH	1	\$ 204.00	\$ 204.00
24	REAR END PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$ 50.00
25	SPARE TYRE PANEL	1	\$ 1,230.00	\$ 1,230.00
26	SPARE TYRE PANEL TOW HOOK MEMBER	1	\$ 672.00	\$ 672.00
27	SPARE TYRE PANEL INSULATOR	1	\$ 240.00	\$ 240.00
28	SPARE TYRE PANEL TOP BOARD	1	\$ 420.00	\$ 420.00
29	SPARE TYRE PANEL TOOLS TRAY	1	\$ 264.00	\$ 264.00
30	SPARE TYRE PANEL LOWER SPLASH COVER	1	\$ 296.00	\$ 296.00
31	SPARE TYRE PANEL LOWER SPLASH COVER CLIPS	1	\$ 50.00	\$ 50.00
32	EXHAUST MUFFLER	1	\$ 885.00	\$ 885.00
33	EXHAUST MOUNTING	2	\$ 88.00	\$ 176.00
34	REAR ARC GARNISH	2	\$ 225.00	\$ 450.00
35	REAR ARC GARNISH CLIPS	2	\$ 50.00	\$ 100.00
36	TAILLAMP	2	\$ 635.00	\$ 1,270.00
37	TAILLAMP CLIPS	2	\$ 50.00	\$ 100.00
38	FRONT BUMPER	1	\$ 1,027.50	\$ 1,027.50
39	FRONT BUMPER LOWER	1	\$ 480.00	\$ 480.00
40	FRONT BUMPER CLIPS	1	\$ 50.00	\$ 50.00

41	FRONT BUMPER SIDE RETAINER	2	\$ 65.00	78.00	\$ 130.00	156.00	NK
42	FRONT BUMPER REINFORCEMENT	1	\$ 361.00		\$ 361.00	361.00	DDV
43	FRONT BUMPER GRILLE	1	\$ 223.00		\$ 223.00	223.00	BRV
44	FRONT BUMPER GRILLE CLIPS	1	\$ 50.00		\$ 50.00	50.00	NK
45	FRONT BUMPER CENTRE GRILLE	1	\$ 118.00		\$ 118.00	118.00	BRV
46	FRONT BUMPER CENTRE GRILLE CLIPS	1	\$ 50.00		\$ 50.00	50.00	NK
47	FRONT BUMPER FOG LAMP	2	\$ 387.90		\$ 775.80	775.80	BRV
48	FRONT BUMPER FOG LAMP GARNISH	2	\$ 82.00		\$ 164.00	164.00	DDV
49	FRONT GRILLE LOGO	1	\$ 82.00		\$ 82.00	82.00	NK
50	FRONT GRILLE BASE	1	\$ 1,150.00		\$ 1,150.00	1,150.00	BRV
51	FRONT GRILLE TOP SIDE BRACKETS	2	\$ 55.00		\$ 110.00	110.00	NK
52	FRONT GRILLE TOP CENTRE BRACKET	1	\$ 120.50		\$ 120.50	120.50	BRV
53	FRONT GRILLE CHROME MOULDING	1	\$ 95.00	224.00	\$ 190.00	224.00	SCB
54	FRONT GRILLE CLIPS	1	\$ 50.00		\$ 50.00	50.00	NK
55	HEADLAMP	2	\$ 1,759.00	2,540.00	\$ 3,518.00	5,080.00	BRV
56	HEADLAMP LOWER BRACKETS	2	\$ 165.00		\$ 330.00	330.00	NNX
57	BONNET	1	\$ 1,130.00		\$ 1,130.00	1,130.00	DDV
58	BONNET LOCK	1	\$ 183.00		\$ 183.00	183.00	BT
59	BONNET INSULATOR	1	\$ 180.50		\$ 180.50	180.50	NK
60	BONNET INSULATOR CLIPS	1	\$ 50.00		\$ 50.00	50.00	NK
61	FRONT SUPPORT PANEL	1	\$ 688.20		\$ 688.20	688.20	BT
62	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 285.00		\$ 285.00	285.00	NK
63	FRONT SUPPORT PANEL TOP GARNISH CLIPS	1	\$ 50.00		\$ 50.00	50.00	NK
64	AIR GUIDE	2	\$ 48.00		\$ 96.00	96.00	THV
65	AIR INTAKE DUCT	1	\$ 115.00		\$ 115.00	115.00	THV
66	A/C CONDENSER	1	\$ 688.50		\$ 688.50	688.50	BT
67	A/C CONDENSER FAN ASSY	1	\$ 398.00		\$ 398.00	398.00	NK
68	A/C CONDENSER HIGH PRESSURE PIPE	1	\$ 163.50		\$ 163.50	163.50	BT
69	A/C CONDENSER LOW PRESSURE PIPE	1	\$ 135.70		\$ 135.70	135.70	BT
70	RADIATOR	1	\$ 875.00		\$ 875.00	875.00	DDV
71	RADIATOR TOP BRACKET	1	\$ 49.00	88.00	\$ 97.00	88.00	NK

22,216.5

Parts Sub Total :	\$ 22,850.50	22,850.50
Discount	\$ 4570.1	5,968.64
PARTS TOTAL :	\$ 18,280.40	23,874.56

Nos.	SPECIAL NETT	Qty	Unit \$	TOTAL \$	
1	SUNDRIES	1	\$ 100.00	\$ 100.00	NNX
2	WINDSCREEN PRIMER AND CLEANER	1	\$ 80.00	\$ 80.00	✓
3	TAILGATE WINDSCREEN INNER SEAL	1	\$ 100.00	\$ 100.00	✓
4	TAILGATE WINDSCREEN SEALANT	1	\$ 100.00	\$ 100.00	✓
5	TAILGATE REFLECTOR SEAL	1	\$ 100.00	\$ 100.00	NNX
6	TAILGATE SEALANT	1	\$ 100.00	\$ 100.00	✓
7	TAILLAMP SEAL	1	\$ 120.00	\$ 120.00	NNX
8	TAILLAMP BASE PANEL SEALANT	2	\$ 100.00	\$ 200.00	✓
9	REAR END PANEL SEALANT	1	\$ 100.00	\$ 100.00	✓
10	SPARE TYRE PANEL SEALANT	1	\$ 280.00	\$ 280.00	✓
12	REVERSE SENSOR	2	\$ 150.00	\$ 300.00	✓
13	RADIATOR COOLANT	1	\$ 120.00	\$ 120.00	✓
14	A/C FLUID	1	\$ 80.00	\$ 80.00	✓
15	BONNET SEALANT	1	\$ 100.00	\$ 100.00	✓
16	FRONT SUPPORT PANEL SEALANT	1	\$ 100.00	\$ 100.00	✓
17	NO PLATE WITH GARNISH	2	\$ 80.00	\$ 160.00	✓

1,000

SPECIAL NETT TOTAL : \$ 10,800.00 2,140.00

Nos.	LABOUR	S\$
1	R&R TAILGATE COMPONENT	\$ 60.00 100.00
2	R&R REVERSE SENSOR	\$ 60.00 80.00
3	R&R EXHAUST PIPE	\$ 150.00
4	R&R A/C CONDENSER	\$ 80.00 100.00
5	R&R RADIATOR	\$ 80.00 100.00
6	R&R REAR WINDSCREEN	\$ 120.00 200.00
7	RUST PROOFING	\$ 60.00 80.00
8	SPRAY PAINTING FRONT	\$ 700.00 1,000.00
9	PANEL BEAT FRONT	\$ 700.00 1,500.00
10	SPRAY PAINTING REAR	\$ 900.00 1,400.00
11	PANEL BEAT REAR	\$ 900.00 1,800.00
12	CONDUCT WATER LEAKAGE TEST	\$ N/A -60.00
LABOUR TOTAL:		\$ 3,810.00 6,570.00

3,810

PARTS TOTAL: \$ 18,286.42 23,874.56

SPECIAL NETT TOTAL: \$ 1,080.00 2,140.00

LABOUR TOTAL: \$ 3,810.00 6,570.00

GRAND TOTAL: \$ 27,106.50 32,584.56

27106.50

@20% 4634.08

18536.32

4/5 18500/2

1/P : 22,216.5

S/N : 1,000

L = 3,810

27,026.5

Less 20% discount

21,621.2 / 14 days

Resurvey 24/4/19

Lump sum repair

Repair days 14

Lim Teow Guan

Min

LKIC Auto Consultants

TG Lim

Min

26/7/19

I hereby acknowledge that I have been notified of the following: 1. The cost of the repair work. 2. The cost of the labour. 3. The cost of the materials. 4. The cost of the paint. 5. The cost of the rust proofing. 6. The cost of the water leakage test. 7. The cost of the panel beat. 8. The cost of the spray painting. 9. The cost of the exhaust pipe. 10. The cost of the reverse sensor. 11. The cost of the radiator. 12. The cost of the A/C condenser. 13. The cost of the windscreen. 14. The cost of the tailgate component. I hereby acknowledge that I have been notified of the following: 1. The cost of the repair work. 2. The cost of the labour. 3. The cost of the materials. 4. The cost of the paint. 5. The cost of the rust proofing. 6. The cost of the water leakage test. 7. The cost of the panel beat. 8. The cost of the spray painting. 9. The cost of the exhaust pipe. 10. The cost of the reverse sensor. 11. The cost of the radiator. 12. The cost of the A/C condenser. 13. The cost of the windscreen. 14. The cost of the tailgate component. Acknowledged by Repairer Signature: Date:
--

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2109B
Vehicle Details	
Vehicle No.:	SLD6532D
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15B4037286
Chassis No.:	RU11117285
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,704.00
Original Registration Date:	24 Jun 2016
First Registration Date:	24 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$9,704.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jun 2026
PARF Rebate Amount:	\$7,278.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,200.00
COE Rebate Amount:	\$39,556.00
Total Rebate Amount:	\$46,834.00

The information contained herein is correct as at 24 Apr 2019

OK

dep 8910/yr

MV 68,000/2
PV 46,800/2
NY 21,200/2

TOTEN line
24/4/19



ANNOUNCING Speedo Motoring as sgCarMart Premium Dealer for the 8th Consecutive Year



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2019 Mer White Color Attrage 1.2 CVT Cruise Control!



Very Well Maintained Double
Color Paint And Wheel Protection
Non-Vapor Run-Vapor
Direct Owner (SMALL)

- Free VICOM evaluation
- Free grooming and 3 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category ▾

◀ Back (1 2 3 4 5 6 7 8 9 10) Next ▶

Sort by Date Posted ▾

20 results/page ▾

198 vehicles

Honda Vezel

Advanced Search



Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection		Honda Vezel	Any	Any	2016	Any	Any	All
	Honda Vezel 1.5A X Honda Sensing	\$69,800	\$8,910 /yr	28-Jun-2016	1,496 cc	28,000 km	SUV	Available
1 Owner! AA Trust Certified Quality Vehicle! Upgraded 18" Sports Rims, And Door Step Kit. Very Well Maintained By One Single Owner Only! Low Maintenance And Fuel Efficient. Beautiful White Exterior An...								
AA Trust Automotive								
Posted: 21-Apr-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X	-	N.A	28-Jun-2016	1,496 cc	-	SUV	SOLD
Super Low Mileage 28,000Km, One Owner, Like New, View To Appreciate.								
Posted: 22-Feb-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X	-	N.A	28-Jun-2016	1,496 cc	-	SUV	SOLD
Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivaled Warranty Complete With Certificate And Test Report. Check Out Our New Offer Now. M...								
Classic Credit Pte Ltd								
Posted: 30-Jan-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X	-	N.A	04-Jul-2016	1,496 cc	-	SUV	SOLD
Just Arrived! Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.								
Posted: 02-Mar-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Toyota Camry takes on Volkswagen's Passat							
The Toyota Camry offers more legroom for rear passengers, is sportier around corners and has more safety systems but the Volkswagen Passat is more affordable and feels more premium overall.								
Find out more!								
	Honda Vezel Hybrid 1.5A X	-	N.A	04-Jul-2016	1,496 cc	-	SUV	SOLD
Fuel Type: Petrol-Electric								
Lowest Price Tag Need No Compare With Others, Accident Free, Optional Warranty From Reputable Workshop, 1 Owner Non Rentals Unit, Auto Tailgate, Flexible Loan Subject To Approval, Best Buy In Terms Of...								
Car Empire Automobiles Pte Ltd								
Posted: 17-Feb-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X	-	N.A	11-Jul-2016	1,496 cc	-	SUV	SOLD
Well Maintained 1 Owner Unit! Low Mileage Non Private Hire Unit! Selling Cheap! Practical And Fuel Efficient SUV! Spacious And Easy To Maintain! Trade In Available! Call For A Viewing Appointment Toda...								
Mayfair Motoring								
Posted: 01-Mar-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda								
	Honda Vezel 1.5A X	-	N.A	13-Jul-2016	1,496 cc	-	SUV	SOLD
Limited Period Only Loan Interest At 2.28%, Extremely Well Maintained And Fully Agent Maintained, This Beast Does Not Just Look Beautiful, It's 100% Accident Free. View To Believe! Up To 80% Financing...								

PREMIUM AD

PREMIUM AD

Compare

MOTOR CAR (Frt)

Front Portion

Vehicle No: 317 6532 D

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992112	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

MOTORCAR (Rear)

Vehicle No: SLD 6532D

Rear Portion

NAC	INC	Item	CON	AC	QTY
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DL	V	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NAC		
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NAC	V	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DL	V	
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	V	
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector	DL	V	
1187	994549	Tailgate Lamp	DL	V	
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber	DL	V	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	DD	V	
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

PRE-REPAIR INSPECTION REQUEST – SLD6532D vs SJU6878R (OI) on D.O.A.: 18/04/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Sent: 22/4/2019 1:23:18 PM
Attachments: 2 days.pdf; CIA Draft.pdf

Hi,

Please refer to the enclosed request from **Team AutoPro Pte Ltd**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNDL, Claims Operations – Auto

Yinnul.Hor@aig.com | www.aig.sg

1.59pm @ 22/4/19
vehicle in
Aashwee
sur @ nar. Lim

From: teamautopl@gmail.com [mailto:teamautopl@gmail.com]

Sent: Monday, April 22, 2019 12:12 PM

To: Hor, Yinnul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJU6878R AND SLD6532D ON 18/04/2019

Dear Sirs,

With reference to your list of surveyors, we are agreeable with the appointment of Mr Lim of LKK as the SJE for subject claim.

Kindly note our personnel in charge for the survey as follows:-

Contact Person Alan Koh 9092 7279
Frederick Lim 9674 6635
Email teamautopl@gmail.com
Address
Survey Address 160 Sin Ming Dr, #01-14 Singapore 575722

Thank you for your kind attention to our request.

From: Hor, Yinnul

Sent: Mon, 22 Apr 2019 03:09:42 +0000

To: teamautopl@gmail.com

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJU6878R AND SLD6532D ON 18/04/2019

Without Prejudice

Your Reference : SLD6532D
Our Reference : SJU6878R

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd

Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore PHOL Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

From: TeamAutoPro North [mailto:teamautopl@gmail.com]

Sent: Saturday, April 20, 2019 1:17 PM

To: Chan, Yoke Shi; Chin, Lee-Ying; Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Abu Kassim, Noor Mariesa; Supramaniam, Darshene; Tan, Lily (AIG)

Subject: [EXTERNAL] 2 Days Notice: SLD 6532 D (Our Ref) and SJU 6878 R (Your Ref) Dated 18th April 2019

This message is from an external sender; be cautious with links and attachments.

Road Traffic Accident Involving SLD 6532 D (Our Ref) and SJU 6878 R (Your Ref)

Dated 18th April 2019, Time around 21:54

@ BEFORE SLE TOWARDS BKE EXIT

We represent our client, Chean Chin Yung Nelson, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SLD 6532 D and your insured's vehicle registration number: SJU 6878 R.

Enclosed herewith a copy of our 2 Days Notice Letter and the relevant Singapore Accident Statement filed for your reference.

Please let us know within 2 working days from today, your list of at least ten (10) motor surveyors, via email to the following personnel:-

Contact Person	Alan Koh	9092 7279
	Frederick Lim	9674 6635
Email Address	teamautopl@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722	

Thank you for your attention to this email and we look forward to your earliest reply.

--

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,

Michelle Lim

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

385 Sin Ming Drive

#01-02 Vicom Inspection Centre

Singapore 575718

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original

and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Print Received Message

This mail is associated with :

***SLD6532D (0613499311SG)
[SJU6878R]**

TP

CHEAN CHIH YUNG, NELSON

Apr 18 2019 9:00PM

[TAN BOON TECK]

Team Autopro Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 26/09/2019 08:23 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$20207.45) - SLD6532D - Claim Handler: Loh, Chee-Heng

Approved:20207.45.

Vic (LKKAUTO)

From: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Sent: Thursday, 26 September, 2019 8:23 AM
To: Vic (LKKAUTO)
Cc: Admin A
Subject: RE: <SEEK MANDATE> Your Ref: 0613499311SG - ACCIDENT INVOLVING VEHICLES SJU 6878R (OI) / SLD 6532D (TP) / OTHERS ON 18/04/2019 - LKK REF CC4/AIG19007080/Bha3

Dear Vic,

Mandate given in Merimen. Kindly try to lower towing fee to \$120.

COR	\$18,500
Rental	\$1400
LOU	\$180
Towing	\$120
LTA fee	\$7.45
Total	\$20,207.45

Thank you.

Best regards,
Loh Chee Heng
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1881
Chee-Heng.Loh@aig.com | www.aig.sg



Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Tuesday, 24 September 2019 3:59 PM
To: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: [EXTERNAL] <SEEK MANDATE> Your Ref: 0613499311SG - ACCIDENT INVOLVING VEHICLES SJU 6878R (OI) / SLD 6532D (TP) / OTHERS ON 18/04/2019 - LKK REF CC4/AIG19007080/Bha3

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: S10166554

Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle

S1D6532D

Chassis Number

RU11117285

2. Name of Policyholder

CHEAH CHIH YUNG NELSON

3. Effective Date of Insurance

24 Jun 2018

4. Expiry Date of Insurance

23 Jun 2019

5. Persons or Classes of Persons entitled to drive#

(a) The Policyholder

(b) Any other person who is driving on the Policyholder's order or with his/her permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

(a) Use for hire or reward.

(b) Use for racing, pace-making, reliability trial or speed-testing.

(c) Use for the carriage of goods (other than samples) in connection with any trade or business.

(d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)

S\$600

EXCESS (SECTION 2)

N/A

WINDSCREEN EXCESS

S\$100

ADDITIONAL EXCESS

N/A

UNNAMED DRIVER EXCESS

PLEASE REFER OVERLEAF

REPAIR AT OWNER'S PREFERRED WORKSHOP

NO

INSURE WITH COE

YES

NCD PROTECTION

YES (FREE)

TRANSPORT ALLOWANCE

NO

EXCESS WAIVER

NO

PRIMARY DRIVER

CHEAH CHIH YUNG NELSON

NAMED DRIVER (1)

N/A

NAMED DRIVER (2)

N/A

HIRE PURCHASE COMPANY

OCBC BANK LTD

SUM INSURED

MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Agency **KRUISE AUTO PTE. LTD. (00000573427)**

Date of Issue **22 Jun 2018 14:37 hrs**

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

PROFORMA INVOICE

**ATTENTION:**

Cheah Chin Yung Nelson

PI Number P1907-0413

PI Date 31-Jul-2019

Vehicle No. SLD 6532D

Accident Date 18-Apr-2019

S/No	Description	Unit Price	Quantity	Amount
1	Spare Parts and Labour for Accident Repair of Vehicle Nos. SLD 6532D	COR Lump Sum		\$ 18,500.00

Notes:

1) All payments must be made only in the form of cash or crossed cheque payable to "Team AutoPro Pte Ltd".

Total Amount \$ 18,500.00

Authorized Signature



INFORMATION RESOURCES

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT. THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

Business Profile (Company) of TEAM AUTOPRO PTE. LTD. (201811621K)

Date: 30/08/2019

The Following Are The Brief Particulars of :

Registration No.	:	201811621K
Company Name.	:	TEAM AUTOPRO PTE. LTD.
Former Name if any	:	
Incorporation Date.	:	05/04/2018
Company Type	:	EXEMPT PRIVATE COMPANY LIMITED BY SHARES
Status	:	Live Company
Status Date	:	05/04/2018

Principal Activities

Activities (I)	:	REPAIR AND MAINTENANCE OF MOTOR VEHICLES (INCLUDING INSTALLATION OF PARTS & ACCESSORIES) (95301)
Description	:	
Activities (II)	:	RENTING AND LEASING OF PRIVATE CARS WITHOUT OPERATOR (77101)
Description	:	

Capital

Issued Share Capital (AMOUNT)	Number of Shares *	Currency	Share Type
500000	500000	SINGAPORE, DOLLARS	ORDINARY

* Number of Shares includes number of Treasury Shares

Paid-Up Capital (AMOUNT)	Number of Shares	Currency	Share Type
500000		SINGAPORE, DOLLARS	ORDINARY

COMPANY HAS THE FOLLOWING ORDINARY SHARES HELD AS TREASURY SHARES

Number Of Shares	Currency
------------------	----------

INFORMATION RESOURCES

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT, THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

Business Profile (Company) of TEAM AUTOPRO PTE. LTD. (201811621K)

Date: 30/08/2019

Registered Office Address	160 SIN MING DRIVE #02-12 SIN MING AUTOCITY SINGAPORE (575722)
Date of Address	22/08/2019
Date of Last AGM	
Date of Last AR	
FYE As At Date of Last AR	

Audit Firms
NAME

Charges				
Charge No.	Date Registered	Currency	Amount Secured	Chargee(s)

Officers/Authorised Representative(s)

Name	ID	Nationality	Source of Address	Date of Appointment
Address		Position Held		
LEE WEI KOK	S7305773F	SINGAPORE CITIZEN	ACRA	05/04/2018
127C KIM TIAN ROAD #15-549 KIM TIAN GREEN SINGAPORE (163127)		Director		
TAN ZHI RONG	S8934111F	SINGAPORE CITIZEN	OSCARS	13/07/2018
70A TELOK BLANGAH HEIGHTS #06-513 TELOK BLANGAH RIDGEVIEW SINGAPORE (101070)		Secretary		

Shareholder(s)

Name	ID	Nationality/Place of Incorporation/Origin	Source of Address	Address Changed
Address				
1 KO KOK CHUAN	S1701263J	SINGAPORE CITIZEN	OSCARS	04/01/2015

Authentication No. : J19643168D



WITHOUT PREJUDICE

Our Ref: SLD 6532D

Your Ref: SJU 6878R

31st July 2019

ATTN: LKK Auto Consultants Pte Ltd
INSURER: AIG Asia Pacific Insurance Pte Ltd

Dear Vic,

Accident Involving: SLD 6532D and SJU 6878R

Date of Accident: 18 April 2019

Location of Accident: Before SLE Towards BKE Exit

We refer to the aforementioned accident and hereby submit our claim as below:

Cost of Repair as agreed	\$	18,500.00
Total Days for LOR/U	17 Days	2 Days PRS + 14 Repair Days Agreed + 2 Sunday + 1 PH- Labour Day
Add Loss of Rental	\$	1,820.00 14 Days Inv#WPLIN0003112
Add Loss of Use	\$	240.00 3 Days
Total	\$	20,560.00
Add Towing Fee	\$	180.00
Add LTA Search Fee	\$	7.45
GRAND TOTAL	\$	20,747.45

Kindly pay the Grand Total Amount of **\$20,747.45** to:

Team AutoPro Pte Ltd
160 Sin Ming Drive #01-14
Sin Ming AutoCity
Singapore 575722

For further query, please feel free to contact us at 6258 1955 or email: teamautooffice@gmail.com

Thank you



Regards
Adel (Ms)

Team AutoPro Pte Ltd Co Reg No: 201811621K

160 Sin Ming Drive #01-14 Sin Ming AutoCity Singapore 575722

Tel: 6258-1955 Fax: 6258-1956 Email: teamautooffice@gmail.com / teamautopl@gmail.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG19007080/Bha3

23 JULY 2019

**TAN BOON TECK
BLK 252 JURONG EAST STREET 24
#04-103
SINGAPORE 600252**

By Post & By Email

Dear Sir/Madam,

ACCIDENT INVOLVING SJU 6878R / SLD 6532D / OTHERS ON 18/04/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.


Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,


Vic Alpeh

Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

Tan.btshawn@gmail.com
(Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Tuesday, 23 July, 2019 5:41 PM
To: Tan.btshaw@gmail.com
Cc: Admin A; Vic (LKKAUTO)
Subject: Your Ref: SJU 6878R_ACCIDENT INVOLVING SJU 6878R / SLD 6532D / OTHERS ON 18/04/2019



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG19007080/Bha3

23 JULY 2019

**TAN BOON TECK
BLK 252 JURONG EAST STREET 24
#04-103
SINGAPORE 600252**

By Post & By Email

Dear Sir/Madam,

ACCIDENT INVOLVING SJU 6878R / SLD 6532D / OTHERS ON 18/04/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

To : Team AutoPro Pte Ltd
CRN : 201811621K
located at : 385 Sin Ming Drive #01-02 Vicom Inspection Centre Singapore 575718

Letter of Authorization & Undertaking

In Respect of Accident Involving my/our Vehicle No.: SLD 6532D
and 534 6878R and SLQ 4664B
and _____ and _____
@ Before SLE towards BKE Exit.
dated 18/04/2019

1. I/We hereby irrevocably authorize you to demand claim- settle/receive whatever amount settled/payable by the third party and/or its insurer in my/our name, for the costs of repair, loss of use/rental and all other necessary costs related to my/our vehicle that was damaged pursuant to the aforesaid accident.
2. I/We acknowledge that any settlement you may reach on my/our behalf is on a "Without Prejudice" and "Without Admission Of Liability" basis.
3. I/We agree to assign the whole proceeds of my/our third party claim to you. The third party and /or its insurer shall accept this letter as my irrevocable authorization to pay the compensated amount directly to you - in the form of payment cheque made in favor to **Team AutoPro Pte Ltd.**

In the event that the payment cheque is being made in my/our favor, I/we hereby undertake to return the full amount to you, within 7 days from receiving and clearance of the said payment cheque. Failing which, you will have the legal rights to take legal proceedings against me/us to recover the said sum, with further costs and disbursements to be incurred by me/us.

4. I/We further authorize you to settle the aforesaid claim in a manner that you deem fit and to utilize the monies to pay your charges without further reference to me/us. The payment to you shall amount to a good discharge of your obligation to me/us in respect of the settlement monies.
5. Should the third party claim be unsuccessful due to untruthful statements from me/us, I/we undertake to pay for all your expenses, costs and fees incurred, immediately upon your demand.
6. This authorisation shall remain in force until revoked by me/us in writing to you, subject to terms and conditions being agreed by both parties. I/We further understand that revocation is not allowed once your workshop has commenced on the repair of my/our vehicle.

Yours faithfully,



Claimant Signature & Co's Stamp (if applicable)

22/4/2019
Date: _____

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **TEAM AUTOPRO PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$20,200.00** (Global Sum – all in) for vehicle no. **SLD 6532D** that was damaged pursuant to the accident which occurred on **18/04/2019** (date) along **SLE NEAR EXIT TO BKE** (location) involving vehicle no/s **SJU 6878R**. This is pursuant to the inspection conducted on **22/04/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **CHEAH CHIH YUNG, NELSON (XIE ZHIYONG)** ("the third party claimant") of vehicle no. **SLD 6532D** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLD 6532D** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 2nd (day) of October (month) **2019** (year)



Signed by appointed surveyor

*My execution of this Discharge Voucher is in full and final settlement for my claim for Property Damage & non-property damage to any other claims arising from the same accident.



Signed by "the workshop" (with chop)



Kindly remit payment to our office address stated. If you have any query pertaining to this invoice, please feel free to contact us.

Date Of Accident:	18/4/2019
-------------------	-----------



WIN WIN RENT-A-CAR PTE LTD

Invoice

SLD6532D
CHEAH CHIH YUNG NELSON
BLK 218 TAMPINES ST 24
#04-10
S(520218)

Invoice No : WPLIN0003112
Invoice Date : 4/5/2019
Due Date : 4/5/2019
VHA No : 3598
Referral ID : T066

Description :	Amount
Rental for 14 Day/s @ \$130 per Day \$	1,820.00

Vehicle No : SLJ4754L

Vehicle Description : Honda Shuttle 1.5G

Rental Period : 19/04/2019 to 03/05/2019

Total Amount Payable : \$ 1,820.00

WIN WIN RENT-A-CAR PTE LTD

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875
Tel: 6315 8479 H/P: 9833 0807


VHA No: 3598

Invoice No:

Hirer's Vehicle No:

UEN: 201505115E

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULARS		Vehicle No: 3598		Replace Veh No: 3510 6230	
Name: (as in I/C)		Mileage Out: 23432		Mileage Out:	
NRIC / FIN No:		Make & Model:		Auto / Manual	
Address (Res): -10		Out : Date 17/4/19		Time: 1100	
Name & Address of Employer:		HIRE / PERIOD EXPIRY		Time:	
Occupation:		Driving Exp:		NON-WAIVER EXCESS-\$	
Singapore Driving Licence No:		CHARGES			
Issue Date:		Date of Birth:		Daily 14 @ \$ 130 per day 11870	
Tel: (O) (R) HP:		Weekly @ \$ per week			
ADDITIONAL DRIVER'S PARTICULARS		Monthly @ \$ per month			
Name: (as in I/C)		Hours @ \$ per hour			
NRIC / FIN No:		Extension @ \$			
Address (Res):		Delivery/Collection Service			
Occupation:		Driving Exp:		SUB-TOTAL \$	
Singapore Driving Licence No:		PETROL LEVEL			
Issue Date:		Date of Birth:		Out E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F	
Tel: (O) (R) H/P:		In E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F			
VEHICLE CHECK LIST		Fuel			
INDICATE: D - DENTS A - ACCIDENTS S - SCRATCHES		Traffic / Parking Fines			
		TOTAL CHARGES \$			
MISSING / FAULTY ACCESSORIES / PARTS		Hirer's Signature			
REMARKS:		Additional Driver's Signature			

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN RENT-A-CAR PTE LTD in connection with this agreement is true.

*IMPORTANT

1. VEHICLE IS STRICTLY PROHIBITED FOR "HIRE FOR REWARDS" USAGE SUCH AS UBER / GRABCAR / GRABSHARE ETC.
2. ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE AUTHORIZED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
3. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
4. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
5. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
6. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN RENT-A-CAR PTE LTD.

RETURN OF VEHICLE: THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
17/4/19	1100	23432			



24 HOUR RECOVERY SERVICES
24 HRS HOTLINE: 8455 5669

Co Reg No: 53333929D

No. 16349



Date: 18-04-19

M/S : Team Auto (Alex)

Vehicle No : SLD 6532D Model : Vaze

From : SLB → BKE Time Start : 1000

To : 01-14 AutoCity Time End : 1030

Remarks : 1100

- | | | | |
|---|---|---|---------------------------------|
| ☐ Change Tyres / Jump Start | ☒ Accident | ☐ Use Car Carrier | ☐ Loaded |
| ☐ Basement / Multi Carpark | ☐ Low Body Kit / Low Spoiler | ☐ Open Door | |
| ☒ Using King Dolley | ☐ Dismantle Brake / Shaft | ☐ Crane Up / Winch Out | |

AMOUNT S\$

1801-

Received By

for 24 hour Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdeemeanour to your vehicle whilst being transported.

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

SLD 65320 (GUOCONG)

Print Date/Time : 20 Apr 2019 / 12:02:31

Receipt Date/Time : 20 Apr 2019 / 12:02:31

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190420-000579

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SJU6878R				
As at 18 Apr 2019/21:54:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SJU6878R			
	Enquiry Fee	7.00	0.49	7.49
	20190420120124905564			
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	xxxxxxxxxxxx9330	Credit Card:		
		Visa/MasterCard		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2019 Edit Reg		22 Apr 2019 00:00 Edit Adj Rpt	S\$18,500.00 Edit Estimates	S\$18,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN BOON TECK , ID: S80038553								
Main Claimant:	CHEAN CHIH YUNG, NELSON , ID: S78121098								
Vehicle Reg. No.:	SLD6532D	Date of Loss:	18/04/2019 21:00 - :59 [33 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0613499311SG	Policy/Cover Note No.:	1800141151 (Comprehensive) Coverage: 30/11/2018 - 29/11/2020						
Vehicle Reg. No. (Insured):	SJU6878R	Policy No. (Claimant):	-						
		Excess:							
Repairer:	Team Autopro Pte Ltd - Sin Ming (HQ) 160 SIN MING DRIVE #02-12 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 9674 6635 / 9092 7279								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 26/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (26/09/2019): Alert - Adj Mandate Approved (S\$20207.45) - SLD6532D - Claim Handler: Loh, Chee-...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD6532D (0613499311SG)
[SJU6878R]

TP

CHEAN CHIH YUNG, NELSON

Apr 18 2019 9:00PM

[TAN BOON TECK]

Team Autopro Pte Ltd - Sin Ming

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Letters/Correspondences						1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit			
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print			
1	31/07/19 16:57	Chassis Number		Load JPG	☒		
2	31/07/19 16:57	Odometer Reading		Load JPG	☒		
3	31/07/19 16:57	General View		Load JPG	☒		
4	31/07/19 16:57	General View		Load JPG	☒		
5	31/07/19 16:57	General View		Load JPG	☒		
6	31/07/19 16:57	General View		Load JPG	☒		
7	31/07/19 16:57	General View		Load JPG	☒		
8	31/07/19 16:57	General View		Load JPG	☒		
9	31/07/19 16:57	General View		Load JPG	☒		
10	31/07/19 16:57	General View		Load JPG	☒		
11	31/07/19 16:57	General View		Load JPG	☒		
12	31/07/19 16:57	General View		Load JPG	☒		
13	31/07/19 16:57	General View		Load JPG	☒		
14	31/07/19 16:57	General View		Load JPG	☒		
15	31/07/19 16:57	General View		Load JPG	☒		
16	31/07/19 16:57	General View		Load JPG	☒		
17	31/07/19 16:57	General View		Load JPG	☒		
18	31/07/19 16:57	General View		Load JPG	☒		
19	31/07/19 16:57	General View		Load JPG	☒		
20	31/07/19 16:57	General View		Load JPG	☒		
21	31/07/19 16:57	General View		Load JPG	☒		
22	31/07/19 16:57	General View		Load JPG	☒		
23	31/07/19 16:57	General View		Load JPG	☒		
24	31/07/19 16:57	General View		Load JPG	☒		
25	31/07/19 16:57	General View		Load JPG	☒		
26	31/07/19 16:57	General View		Load JPG	☒		
27	31/07/19 16:57	General View		Load JPG	☒		
28	31/07/19 16:57	General View		Load JPG	☒		
29	31/07/19 16:57	General View		Load JPG	☒		
30	31/07/19 16:57	General View		Load JPG	☒		
31	31/07/19 16:57	General View		Load JPG	☒		
32	31/07/19 16:57	General View		Load JPG	☒		
33	31/07/19 16:57	General View		Load JPG	☒		
34	31/07/19 16:57	General View		Load JPG	☒		
35	31/07/19 16:57	General View		Load JPG	☒		
36	31/07/19 16:57	General View		Load JPG	☒		
37	31/07/19 16:57	General View		Load JPG	☒		
38	31/07/19 16:57	General View		Load JPG	☒		
39	31/07/19 16:57	General View		Load JPG	☒		
40	31/07/19 16:58	General View		Load JPG	☒		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	31/07/19 16:58	General View	 Load JPG	☒
42	31/07/19 16:58	General View	 Load JPG	☒
43	31/07/19 16:58	General View	 Load JPG	☒
44	31/07/19 16:58	General View	 Load JPG	☒
45	31/07/19 16:58	General View	 Load JPG	☒
46	31/07/19 16:58	General View	 Load JPG	☒
47	31/07/19 16:58	General View	 Load JPG	☒
48	31/07/19 16:58	General View	 Load JPG	☒
49	31/07/19 16:58	General View	 Load JPG	☒
50	31/07/19 16:58	General View	 Load JPG	☒
51	31/07/19 16:58	General View	 Load JPG	☒
52	31/07/19 16:58	General View	 Load JPG	☒
53	31/07/19 16:58	General View	 Load JPG	☒
54	31/07/19 16:58	General View	 Load JPG	☒
55	31/07/19 16:58	General View	 Load JPG	☒
56	31/07/19 16:58	General View	 Load JPG	☒
57	31/07/19 16:58	General View	 Load JPG	☒
58	31/07/19 16:58	General View	 Load JPG	☒
59	31/07/19 16:58	General View	 Load JPG	☒
60	31/07/19 16:58	General View	 Load JPG	☒
61	31/07/19 16:58	General View	 Load JPG	☒
62	31/07/19 16:58	General View	 Load JPG	☒
63	31/07/19 16:58	General View	 Load JPG	☒
64	31/07/19 16:58	General View	 Load JPG	☒
65	31/07/19 16:58	General View	 Load JPG	☒
66	31/07/19 16:58	General View	 Load JPG	☒
67	31/07/19 16:58	General View	 Load JPG	☒
68	31/07/19 16:58	General View	 Load JPG	☒
69	31/07/19 16:58	General View	 Load JPG	☒
70	31/07/19 16:58	General View	 Load JPG	☒
71	31/07/19 16:58	General View	 Load JPG	☒
72	31/07/19 16:58	General View	 Load JPG	☒
73	31/07/19 16:58	General View	 Load JPG	☒
74	31/07/19 16:58	General View	 Load JPG	☒
75	31/07/19 16:58	General View	 Load JPG	☒
76	31/07/19 16:58	General View	 Load JPG	☒
77	31/07/19 16:58	General View	 Load JPG	☒
78	31/07/19 16:58	General View	 Load JPG	☒
79	31/07/19 16:58	General View	 Load JPG	☒
80	31/07/19 16:58	General View	 Load JPG	☒
81	31/07/19 16:58	General View	 Load JPG	☒
82	31/07/19 16:58	General View	 Load JPG	☒
83	31/07/19 16:58	General View	 Load JPG	☒
84	31/07/19 16:58	General View	 Load JPG	☒
85	31/07/19 16:58	General View	 Load JPG	☒
86	31/07/19 16:58	General View	 Load JPG	☒
87	31/07/19 16:58	Reinspection Photo	 Load JPG	☒
88	31/07/19 16:58	Reinspection Photo	 Load JPG	☒
89	31/07/19 16:58	Reinspection Photo	 Load JPG	☒
90	31/07/19 16:58	Reinspection Photo	 Load JPG	☒
91	31/07/19 16:58	Reinspection Photo	 Load JPG	☒
92	31/07/19 16:58	Reinspection Photo	 Load JPG	☒
93	31/07/19 16:58	Reinspection Photo	 Load JPG	☒
94	31/07/19 16:58	Reinspection Photo	 Load JPG	☒
95	31/07/19 16:58	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	31/07/19 16:58	Reinspection Photo		☒
97	31/07/19 16:58	Reinspection Photo		☒
98	31/07/19 16:58	Reinspection Photo		☒
99	31/07/19 16:58	Reinspection Photo		☒
100	31/07/19 16:58	Reinspection Photo		☒
101	31/07/19 16:58	Reinspection Photo		☒
102	31/07/19 16:58	Reinspection Photo		☒
103	31/07/19 16:58	Reinspection Photo		☒
104	31/07/19 16:58	Reinspection Photo		☒
105	31/07/19 16:58	Reinspection Photo		☒
106	31/07/19 16:58	Reinspection Photo		☒
107	31/07/19 16:58	Reinspection Photo		☒
108	31/07/19 16:58	Reinspection Photo		☒
109	31/07/19 16:58	Reinspection Photo		☒
110	31/07/19 16:58	Reinspection Photo		☒
111	31/07/19 16:58	Reinspection Photo		☒
112	31/07/19 16:58	Reinspection Photo		☒
113	31/07/19 16:58	Reinspection Photo		☒
114	31/07/19 16:58	Reinspection Photo		☒
115	31/07/19 16:58	Reinspection Photo		☒
116	31/07/19 16:58	Reinspection Photo		☒
117	31/07/19 16:58	Reinspection Photo		☒
118	31/07/19 16:58	Reinspection Photo		☒
119	31/07/19 16:58	Reinspection Photo		☒
120	31/07/19 16:58	Reinspection Photo		☒
121	31/07/19 16:58	Reinspection Photo		☒
122	31/07/19 16:58	Reinspection Photo		☒
123	31/07/19 16:58	Reinspection Photo		☒
124	31/07/19 16:58	Reinspection Photo		☒
125	31/07/19 16:58	Reinspection Photo		☒
126	31/07/19 16:58	Reinspection Photo		☒
127	31/07/19 16:58	Reinspection Photo		☒
128	31/07/19 16:58	Reinspection Photo		☒
129	31/07/19 16:58	Reinspection Photo		☒
130	31/07/19 16:58	Reinspection Photo		☒
131	31/07/19 16:58	Reinspection Photo		☒
132	31/07/19 16:58	Reinspection Photo		☒
133	31/07/19 16:58	Reinspection Photo		☒
134	31/07/19 16:58	Reinspection Photo		☒
135	31/07/19 16:58	Reinspection Photo		☒
136	31/07/19 16:58	Reinspection Photo		☒
137	31/07/19 16:58	Reinspection Photo		☒
138	31/07/19 16:58	Reinspection Photo		☒
139	31/07/19 16:58	Reinspection Photo		☒
140	31/07/19 16:58	Reinspection Photo		☒
141	31/07/19 16:58	Reinspection Photo		☒
142	31/07/19 16:58	Reinspection Photo		☒
143	31/07/19 16:58	Reinspection Photo		☒
144	31/07/19 16:58	Reinspection Photo		☒
145	31/07/19 16:58	Reinspection Photo		☒
146	31/07/19 16:58	Reinspection Photo		☒
147	31/07/19 16:58	Reinspection Photo		☒
148	31/07/19 16:58	Reinspection Photo		☒
149	31/07/19 16:58	Reinspection Photo		☒
150	31/07/19 16:58	Reinspection Photo		☒
151	31/07/19 16:58	Reinspection Photo		☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
152	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
153	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
154	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
155	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
156	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
157	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
158	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
159	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
160	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
161	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
162	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
163	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
164	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
165	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
166	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
167	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
168	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
169	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
170	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
171	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
172	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
173	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
174	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
175	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
176	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
177	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
178	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
179	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
180	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
181	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
182	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
183	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
184	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
185	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
186	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
187	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
188	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
189	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
190	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
191	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
192	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
193	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
194	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
195	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
196	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
197	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
198	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
199	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
200	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
201	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
202	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
203	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
204	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
205	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
206	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒
207	31/07/19 16:58	Reinspection Photo	1	Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
208	31/07/19 16:59	Reinspection Photo		Load JPG	☒
209	31/07/19 16:59	Reinspection Photo		Load JPG	☒
210	31/07/19 16:59	Reinspection Photo		Load JPG	☒
211	31/07/19 16:59	Reinspection Photo		Load JPG	☒
212	31/07/19 16:59	Reinspection Photo		Load JPG	☒
213	31/07/19 16:59	Reinspection Photo		Load JPG	☒
214	31/07/19 16:59	Reinspection Photo		Load JPG	☒
215	31/07/19 16:59	Reinspection Photo		Load JPG	☒
216	31/07/19 16:59	Reinspection Photo		Load JPG	☒
217	31/07/19 16:59	Reinspection Photo		Load JPG	☒
218	31/07/19 16:59	Reinspection Photo		Load JPG	☒
219	31/07/19 16:59	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/04/19 20:05	ACKNOWLEDGEMENT EMAIL TO AIG DD 22.4.19		Load PDF	
2	22/04/19 20:05	EMAIL FROM AIG DD 22.4.19		Load PDF	
3	22/04/19 20:05	NOTIFICATION FROM WORKSHOP		Load PDF	
4	22/04/19 20:05	TP GIA REPORT		Load PDF	
5	23/07/19 17:42	EMAIL TO OI		Load PDF	
6	23/07/19 17:42	LETTER TO OI		Load PDF	
7	26/07/19 13:31	TP ESTIMATE - FINALIZED		Load PDF	
8	13/09/19 12:49	TOWING FEE		Load PDF	
9	13/09/19 12:49	RENTAL RECEIPT		Load PDF	
10	13/09/19 12:49	LTA SEARCH		Load PDF	
11	13/09/19 12:49	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	23/04/19 10:43	OI GIA REPORT		Load PDF	
2	03/05/19 10:21	TP GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJU6878R (Insd veh)	Model:	HONDA VEZEL 1.5 X (A)
	SLD6532D (TP veh)		
Date of Accident:	18/04/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	32,584.56
Final Repair Cost	:	\$	20,200.00
Loss of Use	:	\$	3.00 days at \$60.00 per day
Rental (if any)	:	\$	14 days
LTA / GIA Search Fee	:	\$	
Others:Towing Fee	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	20,200.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____100_____(%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): _____100_____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Team Autopro Pte Ltd	:	\$ 20,200.00
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

JOANNE LEE KHANG MIN

17 Oct
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19007080/BHA3Q2

Date: 17/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800141151
Claimant SLD6532D **Insured Vehicle No :** SJU6878R
Vehicle No : SLD6532D **Nature of Claim:** TP **Claim No:** 0613499311SG
Date of Loss: 18/04/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD6532D**
 Make & Model: HONDA VEZEL, 1.5 X (A) Engine No: L15B4037286
 Reg. Date: 24/06/2016 (Man. Year: 2016) Chassis No: RU11117285
 Colour: Silver Odometer: 95455 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,014.56	19,360.40	6,654.16	25.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,570.00	3,810.00	2,760.00	42.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,584.56	23,170.40	9,414.16	28.89
Approved Total (Overridden) (S\$)		18,500.00		
Nett Amount (S\$)	32,584.56	18,500.00	14,084.56	43.22
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Car Rental (14.0 x S\$100.00/day) (S\$)		1,400.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		20,207.45		
Global Sum Settlement (S\$)		20,200.00		

INSPECTION

Date of Assignment: 22/04/2019
 Date Inspected: 22/04/2019 Inspected At: TEAM AUTOPRO PTE LTD
 160 SIN MING DRIVE #02-12 SIN
 MING AUTOCITY
 SINGAPORE 575722

Estimated Period of Repair: 14.0 days

Adjuster: Lim Teow Guan**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,620.00 FL	*1,100.90 FL
2	1		*TAILGATE OUTER GARNISH	Not Necessary	385.00 FL	*- FL
3	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	50.00 FL	*- FL
4	1		*TAILGATE LOGO	Necessary	58.00 FL	*39.90 FL
5	2		*TAILGATE REFLECTOR	Broken	790.00 FL	*580.00 FL
6	2		*TAILGATE REFLECTOR CLIPS	Necessary	100.00 FL	*60.00 FL
7	1		*TAILGATE INNER LOCK	Jammed	245.00 FL	*218.00 FL
8	1		*TAILGATE LOCK SENSOR	Shorted	230.00 FL	*195.00 FL
9	1		*TAILGATE TRIM BOARD	Broken	325.00 FL	*153.40 FL
10	1		*TAILGATE TRIM BOARD CLIPS	Necessary	50.00 FL	*30.00 FL
11	1		*TAILGATE WEATHERSTRIP	Cut	185.00 FL	*185.00 FL
12	1		*TAILGATE SOLENOID SWITCH	Shorted	195.00 FL	*150.00 FL
13	1		*REAR WINDSCREEN MOULDING BOTTOM	Necessary	118.00 FL	*118.00 FL
14	1		*REAR WINDSCREEN MOULDING TOP	Necessary	118.00 FL	*118.00 FL
15	2		*REAR WINDSCREEN SIDE MOULDING	Necessary	172.00 FL	*118.00 FL
16	1		*SMART BUZZER	Shorted	285.00 FL	*285.00 FL
17	1		*REAR BUMPER	Crushed	1,185.00 FL	*980.00 FL
18	1		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	176.00 FL	*144.00 FL
20	2		*REAR BUMPER BRACKET	Bent	272.00 FL	*232.00 FL
21	2		*REAR BUMPER REFLECTOR	Broken	374.00 FL	*270.00 FL
22	1		*REAR END PANEL	Dented	725.00 FL	*595.60 FL
23	1		*REAR END PANEL TOP GARNISH	Dislodged	204.00 FL	*132.30 FL
24	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FL	*30.00 FL
25	1		*SPARE TYRE PANEL	Crushed	1,230.00 FL	*1,230.00 FL
26	1		*SPARE TYRE PANEL TOW HOOK MEMBER	Bent	672.00 FL	*95.00 FL
27	1		*SPARE TYRE PANEL INSULATOR	Necessary	240.00 FL	*240.00 FL
28	1		*SPARE TYRE PANEL TOP BOARD	Torn	420.00 FL	*420.00 FL
29	1		*SPARE TYRE PANEL TOOLS TRAY	Not Necessary	264.00 FL	*- FL
30	1		*SPARE TYRE PANEL LOWER SPLASH COVER	Distorted	296.00 FL	*296.00 FL
31	1		*SPARE TYRE PANEL LOWER SPLASH COVER CLIPS	Necessary	50.00 FL	*30.00 FL
32	1		*EXHAUST MUFFLER	Bent	885.00 FL	*885.00 FL
33	2		*EXHAUST MOUNTING	Necessary	176.00 FL	*112.00 FL
34	2		*REAR ARC GARNISH	Broken	450.00 FL	*380.00 FL
35	2		*REAR ARC GARNISH CLIPS	Necessary	100.00 FL	*60.00 FL
36	2		*TAILLAMP	Broken	1,270.00 FL	*1,155.00 FL
37	2		*TAILLAMP CLIPS	Necessary	100.00 FL	*60.00 FL
38	1		*FRONT BUMPER	Dented	1,027.50 FL	*927.50 FL
39	1		*FRONT BUMPER LOWER	Dented	480.00 FL	*391.10 FL
40	1		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
41	2		*FRONT BUMPER SIDE RETAINER	Necessary	158.00 FL	*130.00 FL
42	1		*FRONT BUMPER REINFORCEMENT	Dented	361.00 FL	*321.00 FL
43	1		*FRONT BUMPER GRILLE	Broken	223.00 FL	*223.00 FL
44	1		*FRONT BUMPER GRILLE CLIPS	Necessary	50.00 FL	*30.00 FL
45	1		*REAR BUMPER CENTRE GRILLE	Broken	118.00 FL	*118.00 FL
46	1		*REAR BUMPER CENTRE GRILLE CLIPS	Necessary	50.00 FL	*30.00 FL
47	2		*REAR BUMPER FOG LAMP	Broken	775.80 FL	*665.40 FL
48	2		*REAR BUMPER FOG LAMP GARNISH	Dislodged	164.00 FL	*164.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*FRONT GRILLE LOGO	Necessary	82.00 FL	*52.00 FL
50	1		*FRONT GRILLE BASE	Broken	1,150.00 FL	*1,150.00 FL
51	2		*FRONT GRILLE SIDE BRACKETS	Necessary	110.00 FL	*110.00 FL
52	1		*FRONT GRILLE TOP CENTRE BRACKET	Broken	120.50 FL	*120.50 FL
53	2		*FRONT GRILLE CHROME MOULDING	Scratched	224.00 FL	*190.00 FL
54	1		*FRONT GRILLE CLIPS	Necessary	50.00 FL	*30.00 FL
55	2		*HEADLAMP	Broken	5,080.00 FL	*3,518.00 FL
56	2		*HEADLAMP LOWER BRACKETS	Not Necessary	330.00 FL	*- FL
57	1		*BONNET	Dented	1,130.00 FL	*1,020.00 FL
58	1		*BONNET LOCK	Bent	183.00 FL	*183.00 FL
59	1		*BONNET INSULATOR	Not Necessary	180.50 FL	*- FL
60	1		*BONNET INSULATOR CLIPS	Necessary	50.00 FL	*30.00 FL
61	1		*FRONT SUPPORT PNAEL	Bent	688.20 FL	*576.20 FL
62	1		*FRONT SUPPORT PNAEL TOP GARNISH	Not Necessary	285.00 FL	*- FL
63	1		*FRONT SUPPORT PNAEL TOP GARNISH CLIPS	Necessary	50.00 FL	*30.00 FL
64	2		*AIR GUIDE	Torn	96.00 FL	*96.00 FL
65	1		*AIR INTAKE DUCT	Torn	115.00 FL	*95.00 FL
66	1		*A/C CONDENSER	Bent	688.50 FL	*688.50 FL
67	1		*A/C CONDENSER FAN ASSY	Not Necessary	398.00 FL	*- FL
68	1		*A/C CONDENSER HIGH PRESSURE PIPE	Bent	163.50 FL	*163.50 FL
69	1		*A/C CONDENSER LOW PRESSURE PIPE	Bent	135.70 FL	*135.70 FL
70	1		*RADIATOR	Dented	875.00 FL	*875.00 FL
71	1		*RADIATOR TOP BRACKET	Bent	88.00 FL	*49.00 FL
72	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS
73	1		*WINDSCREEN PRIMER AND CLEANER	Necessary	80.00 FS	*40.00 FS
74	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	100.00 FS	*60.00 FS
75	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
76	1		*TAILGATE REFLECTOR SEAL	Not Necessary	100.00 FS	*- FS
77	1		*TAILGATE SEALANT	Necessary	100.00 FS	*60.00 FS
78	1		*TAILLAMP SEAL	Not Necessary	120.00 FS	*- FS
79	2		*TAILLAMP BASE PANEL SEALANT	Necessary	200.00 FS	*100.00 FS
80	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
81	1		*SPARE TYRE PANEL SEALANT	Necessary	280.00 FS	*140.00 FS
82	2		*REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
83	1		*RADIATOR COOLANT	Necessary	120.00 FS	*60.00 FS
84	1		*A/C FLUID	Necessary	80.00 FS	*80.00 FS
85	1		*BONNET SEALANT	Necessary	100.00 FS	*60.00 FS
86	1		*FRONT SUPPORT PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
87	2		*NO PLATE WITH GARNISH	Necessary	160.00 FS	*100.00 FS

F=Franchise part. S=SpocNett. L=ListitemDisc.

Sub Total (S\$) 31,983.20 23,930.50

- List Item Discount on L Items 20.00/20.00% (S\$) 5,968.64 4,570.10

Total Parts (S\$) 26,014.56 19,360.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R TAILGATE COMPONENT	New	100.00	60.00
2	R&R REVERSE SENSOR	New	80.00	60.00
3	R&R EXHAUST PIPE	New	150.00	150.00
4	R&R A/C CONDENSER	New	100.00	80.00
5	R&R RADIATOR	New	100.00	80.00
6	R&R REAR WINDSCREEN	New	200.00	120.00
7	RUST PROOFING	New	80.00	60.00
8	SPRAY PAINTING FRONT	New	1,000.00	700.00
9	PANEL BEAT FRONT	New	1,500.00	700.00
10	SPRAY PAINTING REAR	New	1,400.00	900.00
11	PANEL BEA REAR	New	1,800.00	900.00
12	CONDUCT WATER LEAKAGE TEST	New	60.00	0.00
Gross Labour Cost (S\$)			6,570.00	3,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >