



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110	Cust No/Name KCV08748/Mr Tan Min Hur, Terence (chen M Reg No/Reg Date SMA7772A / 13/07/2018 Date In/Mileage 13/06/2019/ 20428 Chassis No JMAXTGK1WJZ002632 Engine No 4B40DP0147 Make/Model MIT/ECLIPSE CROSS 1.5 T/C 2WD (T12 Colour/Trim X04 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000061	Credit	01/07/2019/ 14:10	DS	323 / ChrisBulaciac	22879

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 DIAGNOSTIC / SCANNING				250.00
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS				80.00
S MIPNT88088 TO REPLACE FRT BUMPER, REINFORCEMENT, ETC - REPLACE TOP & LH SUPPORT PANEL STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS				1200.00
S MIPNT98088 SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS				840.00
X JJ6400J509 FACE, FR BUMPER	1.00	664.00	0.00	664.00
X JJ6405A231HA EXTENSION, FR BUMPER	1.00	314.00	0.00	314.00
X JJ6512A681 INNER CLIP, FR BUMPER	7.00	3.00	0.00	21.00
X JJ6407A247 GARNISH, FR BUMPER SI	1.00	72.00	0.00	72.00
X JJ6407A245 GARNISH, FR BUMPER SI	1.00	212.00	0.00	212.00
X JJ6400H655 LH BRKT, F/BMPR T/SIG	1.00	17.00	0.00	17.00
X JJ8301D073 LH HEADLAMP ASSY	1.00	1957.00	0.00	1957.00
X JJ8264A323XA COVER, HEADLAMP WASHE	1.00	52.00	0.00	52.00
X JJ8264A325 LH ACTUATOR, HEADLAMP	1.00	112.00	0.00	112.00
X JJMR200300 CLIP, BUMPER	20.00	2.00	0.00	40.00
Z NOTES ACCIDENT ON 16/04/2019 AT 48 ENTERPRISE HUB OUTSIDE #01-113 LOT 49 OWNER CLAIMING THIRD PARTY LOSS OF USE 4DAYS TP # SLF7824U TP INS : EQ				
Z NOTES FINALIZATION ATTENTION : GUO QIANG LKK				

4 Days
Guo Qiang. 14/8/19.
confirm \$5831

Confirm & accepted by

Finalization

24/7/19

ATTN: GUO QIANG

Authorized signatory and company stamp

Parts	3,461.00
Labour	0.00
Standard Menu	0.00
Specialist Job	2,370.00
Others (Lub, etc)	0.00
Sundry	0.00
Total (w/o GST)	5,831.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal the rubber seal or other repair requiring the removal of the windscreen.