

29/11/13 wef
ASS. REC. BY:

PRS
XAL

REF:

MSG/MSG18012788/Gt63-1
MSIG

C8180R

ASSIGNMENT

(-2019)

From: _____ Date: 17/07/18
Estimated Cost: _____
OD (TP) WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: GX 9304 E
at Workshop m/s Reliable Carz
of 8 Kaki Bk + Ave 4 # 05-50 premier
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: Jason @ 8166 9797

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$10k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 6X9304E Yr Regn: 03 Nov 2004

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan URVAN c.c 2953

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 397115 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN/MG4E 2580712037

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: 6 S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or OHTSU

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. _____

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$2000 - \$3000

24/7/18 Submit PRS Report.

Confirm final lump sum \$3,100/- 4 days
(Red. 2790.64, 47%)

Date/Time, File Pass to?

1) 23/11/13 Typist

Date/Time, File Return to?

2) _____

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: 150-120

Transportation: _____

\$ + RS. \$ SI

Photos

Others

TOTAL

30

Report Format : TP

Lump Sum / I.B.I.: (\$ 3100/-)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1801R
Vehicle Details	
Vehicle No.:	GX9304E
Vehicle to be Exported:	No
Intended De-registration Date:	23 Jul 2018
Vehicle Make:	NISSAN
Vehicle Model:	URVAN
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	ZD30044415
Chassis No.:	JN1MG4E25Z0712037
Maximum Power Output:	-
Open Market Value:	\$21,779.00
Original Registration Date:	03 Nov 2004
First Registration Date:	03 Nov 2004
Transfer Count:	6
Actual ARF Paid:	\$1,089.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$25,133.00
COE Rebate Amount:	\$7,053.00
Total Rebate Amount:	\$7,053.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 23 Jul 2018

OK

Vehicle No.: **GX 9304E**

Model: **NISSAN URBAN**

FAX NO. 465-8385 (during)
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

QTY DESCRIPTION

AMOUNT (\$\$)

List Items:

- 1 Trunklid assy **/ BT**
- 1 Trunklid lock **X NN**
- 2 Trunklid hinge @ S\$71.80 **X NN**
- 1 Trunklid emblem "LOGO" **/ AC**
- 1 Trunklid outer handle **X NN**
- 1 Rear bumper **/ AC**
- 2 Rear bumper retainer @ S\$12.10 **X NN**
- 1 Rear end panel **X Repair**
- 1 Rear step board panel **X Repair**

*2613.20
10%
2378.88*

1916.20
325.70
143.60
66.40
466.30
660.60
24.20
246.20
464.10

10
 Less **10%**
 Subtotal **3450.64**

Special Nett Items:

- 1 Rear windscreen sealant
- 1 Rear windscreen sealant foam
- 1 Rear bumper clip (set)
- 1 Trunklid sticker "70 KM/H"
- 1 Trunklid sticker "8 PAX"
- 1 Reverse sensor **/ DM**

AC 310

80.00 **40**
 60.00 **20**
 50.00 **30**
 20.00 **10**
 20.00 **10**
 250.00 **200**

Subtotal **480.00**

Labour Charges:

- To transfer trunklid mechanism
- To remove and refix rear windscreen
- To remove and refix reverse sensor
- To cut, welding and repair above parts
- To spray painting on affected areas

1200

120.00 **60**
 120.00 **100**
 120.00 **40**
 800.00 **400**
 800.00 **600**

Subtotal **1,960.00**

18 Days

*Total: 3835.68
4%: 31K*

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

5890.64

04 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Jul 2018		13 Jul 2018 17:06 Edit Adj Rpt	S\$3,100.00 Edit Estimates	S\$3,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: MUHAMMAD IRSADI BIN MUNARIS , ID: S8319358A									
Main Claimant: BENJI PET SERVICES PTE LTD , Co. Reg. No.: 20143180R									
Vehicle Reg. No.: GX9304E		Date of Loss:	10/07/2018 22:00 - :59 [164 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type: TP / MSC/V/18-000945		Policy/Cover Note No.:	MSD/VMW/18-384892-CA (Comprehensive) Coverage: 13/06/2018 - 12/06/2019						
Vehicle Reg. No. (Insured): FBM9920T		Policy No. (Claimant):							
		Excess:							
Repairer: Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/04/2019]									
Adj Asg. Remarks: SURVEY AGREE ON SJE - REQUEST TO ASSIGN LKK (ADRIAN LING) OI NOT REPORTED CONTACT: JASON LEE 8166 9797									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (18/04/2019): Report Send Back Alerts - GX9304E (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GX9304E (MSC/V/18-000945)**
[FBM9920T]
TP
BENJI PET SERVICES PTE LTD
Jul 10 2018 10:00PM
[MUHAMMAD IRSADI BIN MUNARIS]
Reliable Carz Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
2	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
3	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
4	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
5	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
6	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
7	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
8	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
9	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
10	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
11	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
12	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
13	24/07/18 10:46	General View							Load JPG	<input checked="" type="checkbox"/>
14	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
15	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
16	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
17	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
18	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
19	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
20	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
21	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
22	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
23	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
24	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
25	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
26	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
27	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
28	24/07/18 10:47	Dismantled Parts							Load JPG	<input checked="" type="checkbox"/>
Documentation								1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print
1	13/07/18 14:40	PRI - CROSSBORDERS LLC							Load PDF	
2	13/07/18 15:11	SURVEY AGREE ON SJE - LKK (ADRIAN LING).							Load PDF	
3	13/07/18 15:13	GX9304E TP E-FILE REPORT							Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	23/04/19 17:36	PRS Invoice							Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG18012788/GTD3E2-1**Date:** 23/04/2019REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: MSD/VMW/18-384892-CA

Claimant Vehicle No: GX9304E

Insured Vehicle No: FBM9920T

Date of Loss: 10/07/2018

Nature of Claim: TP

Claim No: MSCV/18-000945

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GX9304E**

Make & Model: NISSAN URVAN, 3.0 D (M)

Reg. Date: 03/11/2004 (Man. Year: 2004)

Colour: Silver

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: ZD30044415

Chassis No: JN1MG4E25Z0712037

Odometer: 397115 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: OHTSU 5 mm

Rear Left Side: OHTSU 5 mm

Front Right Side: OHTSU 5 mm

Rear Right Side: OHTSU 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,361.97	2,688.88	1,673.09	38.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,200.00	760.00	38.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,321.97	3,888.88	2,433.09	38.49
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	6,321.97	3,100.00	3,221.97	50.96

INSPECTION

Date of Assignment: 13/07/2018

Date Inspected: 17/07/2018

Inspected At:

Reliable Carz Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #05-50
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 23 Apr 2019)
Parts:	N/A	NISSAN URVAN 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GX9304E)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRUNKLID ASSY	Bent	1,916.20 FL	*1,916.20 FL
2	1		*TRUNKLID LOCK	Not Necessary	325.70 FL	*- FL
3	2		*TRUNKLID HINGE	Not Necessary	143.60 FL	*- FL
4	1		*TRUNKLID EMBLEM LOGO	Necessary	66.40 FL	*66.40 FL
5	1		*TRUNKLID OUTER HANDLE	Not Necessary	466.30 FL	*- FL
6	1		*REAR BUMPER	Deformed	660.60 FL	*660.60 FL
7	2		*REAR BUMPER RETAINER	Not Necessary	24.20 FL	*- FL
8	1		*REAR END PANEL	Repair	246.20 FL	*- FL
9	1		*REAR STEP BOARD PANEL	Repair	464.10 FL	*- FL
10	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
11	1		*REAR WINDSCREEN SEALANT FOAM	Necessary	60.00 FS	*20.00 FS
12	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
13	1		*TRUNKLID STICKER 70KM/H	Necessary	20.00 FS	*10.00 FS
14	1		*TRUNKLID STICKER 8 PAX	Necessary	20.00 FS	*10.00 FS
15	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
					Sub Total (S\$)	4,793.30
					- List Item Discount on L Items 10.00/10.00% (S\$)	431.33
					Total Parts (S\$)	4,361.97
						2,688.88

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER TRUNKLID MECHANISM	New	120.00	60.00
2	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	100.00
3	TO REMOVE AND REFIX REVERSE SENSOR	New	120.00	40.00
4	TO CUT, WELDING AND REPAIR ABOVE PARTS	New	800.00	400.00
5	TO SPRAY PAINTING ON AFFECTED AREAS	New	800.00	600.00
Gross Labour Cost (\$\$)			1,960.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >