



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

JIE XIN ALUMINIUM AND GLAZING WORKS PTE LTD

23/04/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TECH

Joy.

Accident date: 20/04/2019

Estimated repair cost for vehicle no: GBB801X KIA 2900L 2.9 M '08

CHASSIS: KNCSE014287327854

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Panel <i>new</i>		\$397.00 <i>+</i>
2	1	Front Panel Emblem Logo <i>new</i>		\$96.00 <i>+</i>
3	1	Front Bumper <i>new</i>		\$465.00 <i>-</i>
4	1	Front Bumper Number Plate <i>Best</i>		\$50.00 <i>-</i>
5	1	Front Bumper Reinforcement <i>Best</i>		\$236.00 <i>-</i>
6	2	Front Head Lamp <i>Cracked</i>	\$326.00	\$652.00 <i>+</i>
7	1	Rear Tailgate <i>Dented</i>		\$695.00 <i>-</i>
8	1	Rear Tailgate KIA MOTORS Sticker <i>new</i>		\$96.00 <i>-</i>
9	1	Rear Tailgate CC Logo <i>new</i>		\$60.00 <i>-</i>
10	2	Rear Tailgate Top Side Handle <i>new</i>	\$158.00	\$316.00 <i>+</i>
11	2	Rear Tailgate Lower Side Lock <i>Best</i>	\$141.00	\$282.00 <i>-</i>
12	2	Rear Tailgate Lower Side Hinge <i>Best</i>	\$152.00	\$304.00 <i>150</i>
13	2	Rear Tailgate Lower Side Bracket <i>new</i>	\$136.00	\$272.00 <i>+</i>
14	2	Rear Tailgate Lower Side Rubber Stopper <i>1 piece missing</i>	\$28.00	\$56.00 <i>28</i>
15	1	Rear Tailgate Lower Member <i>Dented</i>		\$750.00 <i>450</i>
16	1	Rear Crossmember <i>Best</i>		\$679.00 <i>-</i>
17	2	Rear Tail Lamp <i>Cracked</i>	\$294.00	\$588.00 <i>-</i>
18	2	Rear Tail Lamp Panel <i>Best</i>	\$248.00	\$496.00 <i>-</i>
19	1	Rear Number Plate Lamp <i>Cracked</i>		\$59.00 <i>-</i>
20	1	Rear Number Plate Panel <i>Best</i>		\$126.00 <i>-</i>
21	1	Rear Spare Tyre Lock <i>new</i>		\$208.00 <i>+</i>
22	1	Rear Exhaust <i>Best</i>		\$486.00 <i>-</i>
23	2	Rear Exhaust Mounting <i>new</i>	\$28.00	\$56.00 <i>+</i>
24	1	Rear Centre Exhaust <i>new</i>		\$822.00 <i>+</i>
25	1	Rear Floor Panel <i>new</i>		\$10,000.00 <i>+</i>

5388

4858.20

Subtotal :- \$18,247.00

S/n	Qty	Items / Special Nett	U/price	Amount
26	1	Rear Tailgate 70km/H Sticker <i>3 new</i>		\$30.00 <i>10 (SW)</i>
27	1	Rear Tailgate 13Pax Sticker		\$30.00 <i>10 (SW)</i>
28	1	Rear Tailgate Aluminium Cover <i>3 new</i>		\$450.00 <i>X</i>
29	100	Rear Tailgate & Floor Panel Aluminium Rivet <i>3 new</i>	\$3.50	\$350.00 <i>800</i>
30	1	Rear Number Plate <i>could</i>		\$50.00 <i>30 (SW)</i>
31	1	Rear Reverse Sensor <i>Damaged</i>		\$350.00 <i>200 (SW)</i>
32	1	Rear Floor Panel Aluminium Cover <i>4 new</i>		\$950.00 <i>X</i>

330

Subtotal :- \$2,210.00

Labour charges

To remove & refit rear & centre exhaust

~~\$380.00~~ *80*

To remove & refit floor box & repair chassis frame

\$2,800.00 *X*

To check wiring

~~\$100.00~~ *60*

Towing fee

2340

\$150.00 *X*

Tuff kote

\$150.00 *X*

Panel beating

~~\$2,000.00~~ *1200*

Spray painting

~~\$2,000.00~~ *800*

To remove rear canopy to facilitate repairs

*200
500*

Subtotal :- \$7,580.00

Total :- \$28,037.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 7,528.20

4/5: 6K

07 days

6K