

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL ST #04-05 IOB BUILDING
049711

Attention : Motor Claim Department
Contact : 6223 8122

Estimate : ES190064

Date : 22/04/2019
Vehicle Num. : SLG 1061M (LCR)
Make/Model : HONDA VEZEL
Chassis/Eng# :
Accident Date : 05/04/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE		1,100.00
2.	1	REAR TAILGATE VEZEL EMBLEM		56 84.00
3.	1	REAR BUMPER		865.00
4.	1	REAR WINDSCREEN GLASS MOULDING		150 195.00
List Total S\$:				2,244.60
20.00% Discount S\$:				448.92
				1,795.68
SPECIAL NETT ITEMS :				
1.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS		30.00
2.	1SET	REAR BUMPER CLIP		30.00
3.	1SET	REAR WINDSCREEN SEALANT		60 80.00
Special Nett Total S\$:				140.00
LABOUR :				
REMOVE & REFIT REAR WINDSCREEN GLASS				120 180.00
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				50 180.00
WIRINGS CHECK AND RECTIFY WHERE NECESSARY				30 180.00
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN REAR PANELS WHERE NECESSARY AND REPLACE ABOVE PARTS				400 800.00
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS				400 800.00
Labour Total S\$:				2,140.00

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total S\$: 4,075.68

Three Jia - LKK
23/4/19
P/P 4days
