

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111  
 Tel No. : 6287 6666 Fax No. : 6257 1330  
 CO./GST Reg. No. 201019626G  
**SHC 5217Z**

**AAD1904-185**

*Not Authorized  
 L/Rep & Food*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration :

**SHC 5217Z**  
 VF1ABL15AUC276139  
 RENAULT  
 LATITUDE  
 17.4.2019  
**AIG**  
 19/2/2014

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1	BUMPER RETAINER FRT LH	\$	<i>Dir</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.21
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
1	TOW COVER FRT	\$	<i>Sn</i> 28.61
1	HEADLAMP LH	\$	<i>M3/RT</i> 1,184.43 ✓
1	HEADLAMP HARNESS	\$	<i>Sn</i> 928.29 X
1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>Sn</i> 278.84 X
1	FENDER BRACKET LOWER LH	\$	<i>Sn</i> 15.79 X
1	FENDER INSULATOR LH	\$	<i>Sn</i> 130.84 X
1	DOOR PANEL FRT LH	\$	<i>M/Wan</i> 2,844.66 ✓
1	DOOR HINGE UPPER LH	\$	<i>R</i> 261.28
1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55
1	DOOR CHECK FRT LH	\$	<i>Sn</i> 194.77
1	DOOR LOCK FRT LH	\$	<i>R</i> 908.75
1	DOOR CATCH FRT LH	\$	<i>Sn</i> 131.23
1	DOOR HANDLE OUTER FRT LH	\$	<i>Sn</i> 477.76
1	DOOR HANDLE COVER FRT LH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR FRT LH	\$	<i>R</i> 505.19
1	DOOR REGUALTOR MOTOR FRT LH	\$	<i>Sn</i> 796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Sn</i> 120.97

**Trans-cab Auto Services Pte Ltd**

**AAD1904-185**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5217Z**

1	DOOR PANEL REAR LH	\$	<i>RM</i>	2,844.66	X
1	DOOR MIRROR ASSY LH	\$	<i>CMA</i>	1,483.40	X
1	WIPER RESERVOIR	\$	<i>RM</i>	348.25	X
1	WIPER RESERVOIR NECK	\$	<i>RM</i>	136.11	X
1	WIPER RESERVOIR MOTOR	\$	<i>RM</i>	270.06	X
		<b>\$</b>		<b>19,575.50</b>	
		10% <b>\$</b>		<b>1,957.55</b>	
		<b>\$</b>		<b>17,617.95</b>	

**Special Nett**

1SET	BUMPER CLIP FRT	\$	<i>RM</i>	66.00	X
1	BUMPER BRACKET CLIP FRT LH	\$	<i>RM</i>	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>RM</i>	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>RM</i>	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>RM</i>	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>RM</i>	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>RM</i>	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	<i>RM</i>	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>RM</i>	80.00	<i>60 RM</i>
1	FRONT DOOR STICKER 'Chassis'	\$	<i>RM</i>	50.00	<i>15 RM</i>
1	REAR DOOR STICKER '6555 3333'	\$	<i>RM</i>	80.00	<i>60 RM</i>
1	DOOR CHECK BOLT	\$	<i>RM</i>	22.69	} X
1	DOOR GUIDE SCREW	\$	<i>RM</i>	10.85	
1	DOOR HINGE BOLT	\$	<i>RM</i>	10.85	
1	DOOR HINGE NUT RH	\$	<i>RM</i>	14.60	
1	DOOR CHECK BOLT	\$	<i>RM</i>	22.69	
1	DOOR CHECK NUT	\$	<i>RM</i>	3.75	
1	DOOR LOCK SCREW L70Y	\$	<i>RM</i>	6.12	
1	DOOR CATCH SCREW L70Y	\$	<i>RM</i>	10.06	
1	FRONT RIGHT TYRE RIM	\$	<i>RM</i>	330.00	
1	FRONT RIGHT TYRE	\$	<i>RM</i>	300.00	
1	FRONT LEFT TYRE RIM	\$	<i>RM</i>	330.00	
1	FRONT LEFT TYRE	\$	<i>RM</i>	300.00	

**TOTAL \$ 1,879.63**

**TOTAL PARTS \$ 19,497.58**

**Trans-cab Auto Services Pte Ltd**

AAD1904-185

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5217Z

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	500
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	nn X
Putty and spray painting of the affected portion.	\$	4,200.00	940
To rust-proofing of the affected areas.	\$	170.00	60
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	nn X
To check steering geometry and computer wheel alignment	\$	220.00	60
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	20
To vacuum, replace, refix and recharge air condenser	\$	380.00	nn X
To replace, refix and top up coolant for radiator	\$	170.00	nn X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	nn X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	nn X
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	nn X
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	60

**Trans-cab Auto Services Pte Ltd**

**AAD1904-185**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5217Z**

**TOTAL \$ 10,950.00**

**Over All Total \$ 30,447.58**

**LUMP SUM(REPAIR DAY)**

~~14~~ days

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: