

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5013U**AAD1904-187***Not Authored
11 Sep @ 4400h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5013U

VF1ABL15AUC275173

RENAULT

LATITUDE

18.4.2019

AIG

30/10/2013

PART**LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMEP R BRACKET SIDE RH REAR
- 5 1 BUMEP R RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMEP R BRACKET SIDE LH REAR
- 8 1 BUMPER RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 OUTER PANEL REAR (End Panel)
- 14 1 OUTER PANEL REAR (End Panel)TRIM
- 15 1 BOOT REAR
- 16 1 TAILLAMP RH
- 17 1 TAILLAMP PANEL RH
- 18 1 TAILLAMP LH
- 19 1 TAILLAMP PANEL LH

\$	<i>Bu</i>	1,108.46	✓
\$	<i>Da 10/1</i>	768.84	✓
\$	<i>SL</i>	113.47	}
\$	<i>SL</i>	135.97	
\$	<i>SL</i>	44.99	
\$	<i>SL</i>	43.61	
\$	<i>SL</i>	135.97	
\$	<i>SL</i>	44.99	
\$	<i>SL</i>	43.61	
\$	<i>KL</i>	777.52	}
\$	<i>KL</i>	225.95	
\$	<i>KL</i>	225.95	
\$	<i>KL</i>	1,471.77	}
\$	<i>SL</i>	404.56	
\$	<i>Bu</i>	2,872.68	✓
\$	<i>SL</i>	552.55	X
\$	<i>KL</i>	986.70	X
\$	<i>SL</i>	552.55	X
\$	<i>KL</i>	986.70	X

\$ **11,496.85**10% \$ **1,149.69**\$ **10,347.17****Special Nett**

- 1 1SET PARKING AID
- 2 1SET REAR BUMPER CLIP
- 3 1SET BUMPER BRACKET CTR CLIP

\$	<i>SL</i>	700.00	X
\$	<i>KL</i>	66.00	✓
\$	<i>KL</i>	33.00	✓

Trans-cab Auto Services Pte Ltd**AAD1904-187**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5013U

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	52	17.82	X
11	2 REAR WINDSCREEN SELANT	\$	na	80.00	X
12	1 WINDSCREEN MOULDING	\$	na	100.00	X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
14	1 REAR BOOT STICKER 'Trans-cab'	\$	na	80.00	305m
15	1 REAR BOOT STICKER '6555-3333'	\$	na	80.00	305m
TOTAL		\$		605.82	
TOTAL PARTS		\$		10,952.99	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	4001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1904-187**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5013U

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 *X*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 *X***TOTAL \$ 7,410.00****Over All Total \$ 28,710.15****(LUMP SUM)****Repair Days****~~10 DAYS~~***2 1/2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: