

ASS. REC. BY:

REF: CS/SM019007112/DSd312

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Ruth chua

of SMO

Date/Time: 23.4.19 11.09 a.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SHA 785R

Insured: SLD 855L

at Workshop m/s Chunni motor

Tel: 64836016

of BIK 10 #01-05106

Policy No: DIGMTPV01008413

Claim No: CMTD1901970

Sum Insured:

Excess:

Make of Veh:

D.O.A. 18.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 23.4.19 11.59 a.m

Person Contacted:

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 785R - (13) EQ117015961 / L12639.2

DOA - 15/08/2017

SLD 855L - X

25/4 - Revised via preli advise via menimen

Surveyor

ASSIGNMENT

COB 2023 May

May 2015

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 123 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHA7825R

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Trailer / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

C.C.

1685

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

533838

T/Radio: Insured / Std / NI / NA

Eng/No:

D4FDEU463227

C/No:

KMHLB41UMFu069229

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

18/04/2019

D.O.I.

23/04/2019

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/3 Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Sompoo SLD855L

27/05/19 Jinyun 2/5 13700/- with 12 days of rev
(\$ 15,788-40 Red - 54%)

RECEIVED 27 MAY 2019

Date/Time, File Pass to?

27/05/19
Type

1)

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

12

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation

S + RS, SI

Photos

Others

TOTAL

450
10

460

Report Format :

Lump Sum / I.B.I: (\$ 13,700/- 45)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 25 Apr 2019

Preliminary Advice

Insured Vehicle No	: SLD855L	Accident Date	: 18/04/2019
TP Vehicle No	: SHA7825R	Assignment Date	: 23/04/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 7.00
Date of Inspection	: 23/04/2019		
Inspection At	: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,488.40
Revised Amount	:S\$	14,390.16
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,390.16
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : SURVEY ON WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Apr 2019		23 Apr 2019 11:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	TEO KENG HWA, ID: S7273790C, Tel: +6598343013, Email: KENGHWA.TEO@GMAIL.COM		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 1900303821R		
Vehicle Reg. No.:	SHA7825R	Date of Loss:	18/04/2019 19:00 - :59
Claim Type:	TP / CMTD1901970	Policy/Cover Note No.:	D18MTPV01008413 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD855L	Policy No. (Claimant):	
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/05/2019]		
Driver/Custodian (Insured):	TEO KENG HWA (46 / Male) , NRIC: S7273790C, Tel: +6598343013 Email: KENGHWA.TEO@GMAIL.COM		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

MCD619051225 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 20/04/2019 14:16
 SUBMITTED BY: Janet Lim Siong Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 20/04/2019 14:16
 Date Of Accident 18/04/2019 19:40
 Exact Location Of Accident WOODLANDS RD X TURF CLUB AVE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA7825R
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number MCOM0015
 Cover Note Number
 Driver
 Name of Driver ZAINAL BIN OSMAN
 NRIC No S1697366A
 Date Of Birth 31/07/1965
 Occupation OUTDOOR
 Date Of Driving Pass 31/07/1997
 Driving Experience 21 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-93832364
 Fax Number
 Contact Number
 EMail Address ZAINALOSMAN1965@GMAIL.COM

Address BLK 878 WOODLANDS AVENUE 9
 #01-298
 Postcode 730878
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER ATTACHED - TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLD855L
 Vehicle Make/Model/Colour TOYOTA
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TEO KENG HWA
 NRIC/Passport Number S7273790C
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

FRONT LH

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

ZAINAL BIN OSMAN

Approximate Age

Injuries Sustain

NECK AND LOWER BACK

Injured person in which vehicle?

SHA7825R

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have Insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have Insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time: 20.4.2019

Driver's Signature
(If driver is not the policyholder)
Date & Time: 20.4.2019 @12:30hrs

Reporting Centre Personnel's Signature
Name: Lisa Diong
NRIC/FIN No.:

SKETCH PLAN

-As attached

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/4/2019 @ 19:40hrs, my taxi (A) was travelling along Woodlands Rd cross junction of Turf Club Ave.

With 1 female passenger on board.

On the traffic junction with Turf Club Ave.I was travelling straight and traffic light was green.I proceeded straight, upon crossing the junction,Suddenly veh (B) (SLD 855L) ,on my opposite side made a right turn without giving way to me,and collided onto my taxi (A) front RH portion.

Veh (B) SLD 855L-was driven by Mr Teo Keng Hwa,Nric no:S 7273790C.

After the accident, I felt pain on my neck and lower back, will seek doctor later on.

I have a CCTV footage to support my claims.

DECLARATION


I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time: 20.4.2019

Driver's Signature
(If driver is not the policyholder)
Date & Time: 20.4.2019 @12:30hrs

Reporting Centre Personnel's Signature
Name: **Lisa Diong**
NRIC/FIN No.:



Faisal B Osman

20/04/2019

— 17 —

(over)

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7825R

DATE :22.04.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Sompo

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover broken		\$	544.50 ✓
	Front Bumper Sponge NH		\$	99.20 X
	Front Bumper Reinforcement NH		\$	402.10 X
	Front Bumper Grille (RH) NH		\$	41.60 X
	Front Bumper Bracket Top (RH) NH		\$	22.40 X
	Front Bumper Bracket (RH) broken		\$	24.60 ✓
	Headlamp Support Top Cover NH		\$	222.60 X
	Headlamp Support Panel Assy broken		\$	907.40 ✓
	Headlamp (RH) broken		\$	1,388.00 ✓
	Headlamp Halogen Bulb /RH) NH		\$	14.40 X
	Radiator Expansion Tank NH		\$	28.30 X
	Front Fender (RH) Buc		\$	663.00 ✓
	Front Fender Apron Panel (RH) Buc		\$	637.00 ✓
	Front Fender Shield (RH) destroyed		\$	174.90 ✓
	Wiper Container broken		\$	61.90 ✓
	Wiper Container Motor Done		\$	75.00 ✓
	Front Wheel Rim (RH) & destroyed		\$	325.30 ✓
	Front Wheel Hub Cap (RH) end		\$	107.10 ✓
	Front Wheel Bearing (RH) & Done		\$	540.50 ✓
	Front Shock Absorber (Assy) (RH) & bt		\$	342.20 ✓
	Front Shock Absorber Mounting (RH) NH		\$	108.80 X
	Front Drive Shaft (RH) & Done		\$	1,030.80 ✓
	Rack & Pinion Assy & Done		\$	1,191.30 ✓
	STG Tie End & destroyed		\$	62.60 ✓
	Stabilizer Bar & destroyed		\$	252.30 ✓
	Stabilizer Bar Bush (RH) NH		\$	16.40 X
	Stabilizer Bar Link (RH) & destroy		\$	61.10 ✓
	Stabilizer Bracket(RH) NH		\$	24.00 X
	Front Suspension Lower Arm (RH) & bt		\$	529.30 ✓
	Knuckle Arm (RH) & destroyed		\$	552.00 ✓
	Engine Under Cover NH		\$	334.60 X
	Engine Crossmember & destroyed		\$	2,094.40 ✓
	ABS Sensor (RH) NH		\$	234.00 X
	Electric Power Steering NH		\$	3,641.00 X
	Gearbox & Jam Done		\$	14,808.00 ✓
	Gearbox Mounting NH		\$	215.40 X
	SUB TOTAL		\$	31,778.00
	LESS 20%		\$	6,355.60
	DISCOUNTED TOTAL		\$	25,422.40
	Front Tyre (RH) Puncture 50% depreciation.		\$	108.00
	TOTAL		\$	216.00
				Nett L

SHA 7825R

[illegible]

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19007112/DSD3N2

Date: 30/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01008413
Claimant Vehicle No :	SHA7825R	Insured Vehicle No :	SLD855L
Date of Loss:	18/04/2019	Nature of Claim:	TP
		Claim No:	CMTD1901970

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7825R	Engine No:	D4FDEU463227
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMFU069229
Reg. Date:	28/05/2015 (Man. Year: 2015)	Odometer:	533838 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	25,638.40	15,360.16	10,278.24	40.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	1,880.00	1,970.00	51.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,488.40	17,240.16	12,248.24	41.54
Approved Total (Overridden) (S\$)		13,700.00		
(S\$)	29,488.40	13,700.00	15,788.40	53.54
+ GST 7.00/7.00% (S\$)	2,064.19	959.00	1,105.19	53.54
Nett Amount (S\$)	31,552.59	14,659.00	16,893.59	53.54

INSPECTION

Date of Assignment:	23/04/2019	
Date Inspected:	23/04/2019 Inspected At:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047
Estimated Period of Repair:	12.0 days	

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2019)
Parts: 143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHA7825R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Broken	544.50 FL	*544.50 FL
2	1		*FRONT BUMPER SPONGE	Not Necessary	99.20 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	402.10 FL	*- FL
4	1		*FRONT BUMPER GRILLE (RH)	Not Necessary	41.60 FL	*- FL
5	1		*FRONT BUMPER BRACKET TOP (RH)	Not Necessary	22.40 FL	*- FL
6	1		*FRONT BUMPER BRACKET (RH)	Broken	24.60 FL	*24.60 FL
7	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
8	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
9	1		*HEADLAMP (RH)	Broken	1,388.00 FL	*1,388.00 FL
10	1		*HEADLAMP HALOGEN BULB (RH)	Not Necessary	14.40 FL	*- FL
11	1		*RADIATOR EXPANSION TANK	Not Necessary	28.30 FL	*- FL
12	1		*FRONT FENDER (RH)	Buckled	663.00 FL	*663.00 FL
13	1		*FRONT FENDER APRON PANEL (RH)	Buckled	637.00 FL	*637.00 FL
14	1		*FRONT FENDER SHIELD (RH)	Dislodged	174.90 FL	*174.90 FL
15	1		*WIPER CONTAINER	Broken	61.90 FL	*61.90 FL
16	1		*WIPER CONTAINER MOTOR	Damaged	75.00 FL	*75.00 FL
17	1		*FRONT WHEEL RIM (RH)	Distorted	325.30 FL	*325.30 FL
18	1		*FRONT WHEEL HUB CAP (RH)	Cut	107.10 FL	*107.10 FL
19	1		*FRONT WHEEL BEARING (RH)	Damaged	540.50 FL	*540.50 FL
20	1		*FRONT SHOCK ABSORBER (ASSY)(RH)	Bent	342.20 FL	*342.20 FL
21	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	108.80 FL	*- FL
22	1		*FRONT DRIVE SHAFT (RH)	Damaged	1,030.80 FL	*1,030.80 FL
23	1		*RACK & PINION ASSY	Damaged	1,191.30 FL	*1,191.30 FL
24	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
25	1		*STABILIZER BAR	Distorted	252.30 FL	*252.30 FL
26	1		*STABILIZER BAR BUSH (RH)	Not Necessary	16.40 FL	*- FL
27	1		*STABILIZER BAR LINK (RH)	Distorted	61.10 FL	*61.10 FL
28	1		*STABILIZER BRACKET (RH)	Not Necessary	24.00 FL	*- FL
29	1		*FRONT SUSPENSION LOWER ARM (RH)	Bent	529.30 FL	*529.30 FL
30	1		*KNUCKLE ARM (RH)	Distorted	552.00 FL	*552.00 FL
31	1		*ENGINE UNDER COVER	Not Necessary	334.60 FL	*- FL
32	1		*ENGINE CROSSMEMBER	Distorted	2,094.40 FL	*2,094.40 FL
33	1		*ABS SENSOR (RH)	Not Necessary	234.00 FL	*- FL
34	1		*ELECTRIC POWER STEERING	Not Necessary	3,641.00 FL	*- FL
35	1		*GEARBOX MOUNTING	Not Necessary	215.40 FL	*- FL
36	1		*GEARBOX	Jammed/Damaged	11,846.40 FS	*6,000.00 FS
37	1		*FRONT TYRE (RH)(50%)(DEPRECIATION)	Punctured	216.00 FS	*108.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	29,032.40	17,673.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,394.00	2,313.04
Total Parts (\$\$)	25,638.40	15,360.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,500.00	800.00
2	SPRAY PAINTING CHARGE	New	750.00	500.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFFKOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
8	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	150.00
10	REMOVE/REFIX GEARBOX	New	450.00	150.00
Gross Labour Cost (S\$)			3,850.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >