

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 24 Apr 2019

**Preliminary Advice**

|                    |                                                                                                              |                         |               |
|--------------------|--------------------------------------------------------------------------------------------------------------|-------------------------|---------------|
| Vehicle No         | : YN3199X                                                                                                    | Accident Date           | : 16/04/2019  |
| Make               | : MITSUBISHI FE83PE6SRDEB                                                                                    | Policy No.              | : 29084255MKC |
| Assignment Date    | : 22/04/2019                                                                                                 | Excess                  | : S\$700.00   |
| Date of Inspection | : 23/04/2019                                                                                                 | Est. Duration of Repair | : 9.00        |
| Inspection At      | : SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)<br>BLK 3 PIONEER ROAD NORTH, #01-18<br>SINGAPORE 628457 |                         |               |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 15,356.80 |
| Revised Amount              | :S\$ | 10,231.90 |
| Check Items (Estimated)     | :S\$ | 3,628.90  |
| Total                       | :S\$ | 13,860.80 |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 31,000.00 |
| COE / PARF Rebate  | :S\$ | 18,374.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 12,626.00 |

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) Pending repair cost from repairer