

INS. CASE OWNER:

CC 0, 087 1900 711, V26352

LKK:
IDAC:

Surveyor:

m/agents

DOI:

ASSIGNMENT

m/4/19

Date / Time:

m/4/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Jm 68R

Name of Insured:

TRANSMARE - CHEMIE (S) P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

23/4

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: SIMON LEE LEE MENG

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

VLO10520

Policy No.:

8-M1172-MVA-2014

Make / Model:

MITSUBISHI

Place of Accident:

PIONEER KP

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJH 14052



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fastech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time:

SJH 14052 - 2

Jm 68R - 2

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 31/7/2019

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45 SS 9,500

(10 days) Reduction: 61 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

9/9/19

Confirm with Jason

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.: 27

Fast to

If NO or B 28, Ass. Lia:

Repair Cost:

CULGST SS 10,165

Loss of Rental (LOR):

SS

(- days)

Loss of Use (LOU):

SS

720 (\$ 60 x 12 days)

Loss of Income (LOI):

SS

(\$ - x - days)

LOR only ☐ LOU only ☒

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow / Independent)

Legal Cost

SS

Total:

SS

10,887

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

10,887

Name 1:

FASTECH AUTO PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP

\$400

COPY SENT
m/10/19

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Q3E

Pahlin

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

10 days + 1 Sunday + 1 Holiday = 12 days.

C Red \$14,905.40/6/1.)

16/5/19 4/5 \$9500 confirmed with Aler.

27-7-2023 LTA 1583e net 8665

has to G.A

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

not Arthur
Hale
2/5 # 9500/
23/4/19
10dy.

VEHICLE NO: SJH 1405Z

QTY	PARTICULAR			
1 PCS	REAR WINDSCREEN		shortened	\$1,105.30
1 PCS	REAR WINDSCREEN MOULDING		neu	\$68.50
1 PCS	REAR WINDSCREEN INNER SEAL		neu	\$35.00
1 PCS	REAR WINDSCREEN WIPER ARM		neu	\$121.00 X
1 PCS	REAR WIPER BLADE		neu	\$68.50 X
1 PCS	REAR WIPER MOTOR		Self/Jan	\$335.10
1 PCS	TAILGATE	7 81	Body/Jan	\$803.20
1 PCS	TAILGATE 'H' LOGO		neu	\$45.00
1 PCS	TAILGATE OUTER GARNISH		neu	\$245.50
1 PCS	TAILGATE 'FIT' EMBLEM		neu	\$42.50
1 PCS	TAILGATE INNER LOCK	245-50	Body/Jan	\$266.20
1 PCS	TAILGATE WEATHERSTRIP		neu	\$148.20
1 PCS	TAILGATE INNER TRIM BOARD		Body/Jan	\$341.80
1 SET	TAILGATE INNER TRIM BOARD CLIPS		neu	\$50.00
2 PCS	TAILGATE INNER TOP SIDE GARNISHS @\$195.20		neu	\$390.40 X
2 PCS	TAILGATE REAR LICENCE LAMPS @\$50.50		neu	\$101.00 X
1 PCS	REAR BUMPER		neu	\$545.30
2 PCS	REAR BUMPER SIDE RETAINERS @\$36.50		N/S Bump	\$73.00 1/2 C
1 SET	REAR BUMPER CLIPS		neu	\$30.00
1 PCS	REAR END PANEL		Body/Jan	\$306.30
1 PCS	REAR END PANEL TOP GARNISH		neu	\$166.50
2 PCS	REAR FENDERS @\$971.00	o/s r	N/S Body/Jan	\$1,942.00 1/2 C
2 PCS	REAR FENDER INNER TRIM BOARDS @\$385.00		Body/Jan	\$770.00
1 SET	REAR FENDER INNER TRIM BOARD CLIPS		neu	\$39.00
1 PCS	REAR FENDER INNER TOP SIDE GARNISH N/S	165-50	neu	\$248.00
1 PCS	REAR WHEEL HOUSING PANELS N/S		neu	\$795.20 X
1 PCS	REAR TAILLAMP PANEL N/S		Body/Jan	\$288.50
2 PCS	TAILLAMPS @\$305.00		N/S Bump	\$610.00
1 PCS	REAR AIR VENT		neu	\$86.20 X
2 PCS	REAR BUMPER SPLASH SHIELDS @\$45.00		neu	\$90.00 X
1 PCS	REAR DOOR N/S		neu	\$971.10 X
1 PCS	REAR FENDER GLASS N/S		neu	\$350.00 X
1 PCS	ROOF MOULDING N/S		neu	\$122.30
1 PCS	REAR SHOCK ABSORBER N/S		neu	\$322.20 X
1 PCS	REAR WHEEL HUB BEARING N/S		neu	\$380.00 X
1 PCS	REAR FLOOR PANEL		neu	\$911.40 X
1 PCS	REAR FLOOR PANEL TOP BOARD		Body/Jan	\$315.00
1 PCS	REAR FLOOR PANEL TOOLS SPONGE		neu	\$485.00
1 PCS	ROOF LINING		neu	\$866.20 X
		8294.30	(202	\$14,880.40
1 PCS	S.NETT		neu	\$50.00 40 51
1 PCS	REAR WINDSCREEN SEALANT		neu	\$200.00 X
1 PCS	REAR WINDSCREEN SOLAR FILM		Body/Jan	\$50.00 40
1 PCS	REAR LICENCE PLATE W/HOLDER		Body/Jan	\$380.00 350
1 SET	REAR REVERSE CAMERA		Body/Jan	\$280.00 200
1 SET	REAR REVERSE SENSOR		Body/Jan	

1 PCS TAILGATE TOP SPOILER
 1 PCS TAILGATE THIRD LAMP
 1 PCS REAR FENDER GLASS SEALANT N/S
 1 PCS REAR BUMPER LOWER SKIRTING
 1 SET REAR FLOOR PANEL INSULATOR

one \$880.00 600 S.N
 SNO \$185.00 ✓ S.N
 RU \$50.00 40 S.N
 CNA \$820.00 500 S.N
 11 \$200.00 X

LABOUR CHARGES:

TO CHECK WIRING
 TO DISMANTLE & REPLACING REVERSE SENSOR
 TO DISMANTLE & REPLACING REAR WINDSCREEN
 TO DISMANTLE & REPLACING REAR FENDER GLASS N/S
 TO DISMANTLE & REFIX ROOF LINING
 TO CONDUCT WHEEL ALIGNMENT
 TO DISMANTLE & REFIX REAR UNDERCARRIAGE
 TO DISMANTLE & REFIX FUEL TANK
 TO SPRAY RUST PROOFING
 TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTREY
 TO MOUNT VEHICLE ON CAR O-LINER
 LABOUR FOR PANEL BEATING & REPLACING PARTS
 TO PUTTY & SPRAY PAINTING

\$80.00 30
 \$80.00 50
 \$150.00 120
 \$100.00 80
 \$280.00 150
 11 \$120.00 X
 11 \$280.00 X
 \$100.00 60
 \$180.00 100
 \$180.00 80
 11 \$380.00 X
 \$2,500.00 1500
 \$2,000.00 1400

TOTAL \$24,405.40

12/60-44
 9/28

When a repairer is notified of a claim, they must notify the insurer of the following:

- The nature of the damage
- The location of the damage
- The extent of the damage
- The estimated cost of the damage
- The estimated time to complete the repair
- The estimated time to complete the repair
- The estimated time to complete the repair
- The estimated time to complete the repair

Acknowledged by Repairer
 Signature:
 Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	8732G

Vehicle Details

Vehicle No.:	SJH1405Z
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	L13A4100323
Chassis No.:	GE61090916
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$12,084.00
Original Registration Date:	28 Jul 2008
First Registration Date:	28 Jul 2008
Transfer Count:	2
Actual ARF Paid:	\$11,230.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	27 Jul 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$18,583.00
COE Rebate Amount:	\$15,835.00
Total Rebate Amount:	\$15,835.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Apr 2019

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 8732G

Vehicle Details

Vehicle No.: SJH1405Z
Vehicle to be Exported: No
Intended Deregistration Date: 24 Apr 2019
Vehicle Make: HONDA
Vehicle Model: FIT 1.3G A
Primary Colour: Silver
Manufacturing Year: 2008
Engine No.: L13A4100323
Chassis No.: GE61090916
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$12,084.00
Original Registration Date: 28 Jul 2008
First Registration Date: 28 Jul 2008
Transfer Count: 2
Actual ARF Paid: \$11,230.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 27 Jul 2023
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$18,583.00
COE Rebate Amount: \$15,825.00
Total Rebate Amount: \$15,825.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Apr 2019

OK



Fit

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Mandai Motor Trading » Honda Fit 1.3A G (COE till 04/2023)

Honda Fit 1.3A G (COE till 04/2023)

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map

Price	\$23,800		
Depreciation	\$5,940 /yr	Reg Date	25-Apr-2008 (4yrs 1day COE left)
Mileage	N.A.	Manufactured	2008
Road Tax	\$649 /yr	Transmission	Auto
Dereg Value	\$15,484 as of today (change)	OMV	\$11,104
COE	\$19,328	ARF	\$11,104
Engine Cap	1,339 cc	Power	73.0 kW (97 bhp)
Curb Weight	1,010 kg	No. of Owners	2
Type of Vehicle	Hatchback		

Features
View specs of the Honda Fit (2008-2013)

Category
COE Car

Status
Available

Resources

Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Car Valuation - Free
Find out the market value of your existing car for free. Get started



- Shortlist
- Compare
- Add note
- Report Error
- More Actions

Seller Information	
Company	Mandai Motor Trading » dealer's pricelist » 36 vehs sold 21 vehs available
Address	31 West Coast Highway #01-08/09 Search cars nearby this location
Location	West Coast Car Mart
Office No	67775585
Contact Person(s)	Darren 82233251 Heng Heng 90058812 Hui Ling 90368887

Posted on: 22-Apr-2019 | Last Updated on: 22-Apr-2019

Upfront Payment

» more Financial info

Transfer Fee

\$25

Down Payment

\$7,140 (change)

Maximum 70% Loan

1st Instalment

\$399

Based on 3.75% interest rate

Compare

Shu Pei (LKKAuto)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Tuesday, 21 May 2019 9:09 AM
To: Shu Pei (LKKAuto)
Subject: Direct Settlement - Accident Involving YM68R (OI : QBE - TBA) AND SJH1405Z (TP : LKK REF - CC6/QBE19007121/Ueb3) on 23.04.2019
Attachments: YM68R.pdf

Our ref: VC012530

Hi Shu Pei

Please find attached as per requested.

regards

Jenny Toh

Senior Assistant

Claims / Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6224 6633 | +65 6477 1225

[Website](#) [LinkedIn](#) [Twitter](#)



From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 14 May 2019 9:44 AM
To: Jenny Toh <jenny.toh@qbe.com>
Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving YM68R (OI : QBE - TBA) AND SJH1405Z (TP : LKK REF - CC6/QBE19007121/Ueb3) on 23.04.2019

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Wednesday, 24 April 2019 12:36 PM

To: 'Jenny Toh' <jenny.toh@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: Direct Settlement - Accident Involving YM68R (OI : QBE - TBA) AND SJH1405Z (TP : LKK REF - CC6/QBE19007121/Ueb3) on 23.04.2019

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SJH 1405Z at M/s Fastech Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Khanchna (LKK Auto)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Thursday, 26 September 2019 11:45 AM
To: Khanchna (LKK Auto)
Cc: Jenny Toh
Subject: Direct Settlement - Accident Involving YM68R (OI : QBE - TBA) AND SJH1405Z (TP : LKK REF - CC6/QBE19007121/Ueb3) on 23.04.2019
Attachments: DS Supporting Documents.pdf; LKK Adjustment Report.pdf; LKK Inspection Report.pdf; LKK REINSPECTION PHOTOS (2).pdf; LKK REINSPECTION PHOTOS.pdf; LKK SURVEY PHOTOS.pdf

Our ref: VC012530

Dear Khanchna

Kindly proceed to settlement.

regards

Jenny Toh

Senior Assistant

Claims / Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6224 6633 | +65 6477 1225

[Website](#) [LinkedIn](#) [Twitter](#)



From: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Sent: Wednesday, 25 September 2019 9:55 AM
To: Jenny Toh <jenny.toh@qbe.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving YM68R (OI : QBE - TBA) AND SJH1405Z (TP : LKK REF - CC6/QBE19007121/Ueb3) on 23.04.2019

YOUR REF – VC012530

LKK REF – CC6/QBE19007121/Ukb3s2

=====

Dear Ms. Jenny,

ACCIDENT INVOLVING VEHICLES YM 68R (OI) & SJH 1405Z (TP) ON 23/04/2019

We refer to the above matter.

This is a head to rear end collision.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 25 September 2019 9:55 AM
To: Jenny Toh
Cc: Admin A
Subject: RE: Direct Settlement - Accident Involving YM68R (OI : QBE - TBA) AND SJH1405Z (TP : LKK REF - CC6/QBE19007121/Ueb3) on 23.04.2019
Attachments: DS Supporting Documents.pdf; LKK Adjustment Report.pdf; LKK Inspection Report.pdf; LKK REINSPECTION PHOTOS (2).pdf; LKK REINSPECTION PHOTOS.pdf; LKK SURVEY PHOTOS.pdf

Tracking:	Recipient	Delivery
	Jenny Toh	
	Admin A	
	olivialau@lkkauto.com	Delivered: 25/9/2019 9:55 AM
	Meikwan@lkkauto.com	Delivered: 25/9/2019 9:55 AM
	shupei@lkkauto.com	Delivered: 25/9/2019 9:55 AM

YOUR REF – VC012530

LKK REF – CC6/QBE19007121/Ukb3s2

=====

Dear Ms. Jenny,

ACCIDENT INVOLVING VEHICLES YM 68R (OI) & SJH 1405Z (TP) ON 23/04/2019

We refer to the above matter.

This is a head to rear end collision.

We had informed to the Insured company of the TP claim and NCD issues and they agreed to let Insurance handle.

In view of the above, we are of the view that BOLA 27 is applicable.

Summary to offer to repairer **FASTECH AUTO PTE LTD** is as follows:

TP CLAIMED		REVISED - TO OFFER
Cost of Repair (w/gst)	\$ 26,113.78	\$ 10,165.00
Loss of Use (\$60.00 x 12 days)	\$ 720.00	\$ 720.00 (\$60 x 12 days)
LTA Search Fee	\$ 2.00	\$ 2.00
TOTAL	\$ 26,835.78	\$ 10,887.00

Breakdown of days is as follows:

**10 days recommendation for repair +1 Sunday +1 Public Holiday = 12 days

Relevant supporting claim documents are attached herewith for your perusal and reference.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD			Ref : CC6/QBE19007121/Ukb3s2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Date : 30-10-2019	
			Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 68R	Veh. Inspected	SJH 1405Z	
Policy No.	8-XM111722-MVA-R014	Coverage (\$)	0.00	
Claim No.	VC012530	Excess (\$)	0.00	
Assign From		Assign Date	23/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	GE61090916	Colour	SILVER	
Odometer	163566	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/04/2019	Inspection Date	23/04/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 1405Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN	SHATTERED	1,105.30	1,105.30
1	REAR WINDSCREEN MOULDING	NECESSARY	68.50	68.50
1	REAR WINDSCREEN INNER SEAL	NECESSARY	35.00	35.00
1	REAR WINDSCREEN WIPER ARM	SERVICEABLE	121.00	-
1	REAR WIPER BLADE	NOT NECESSARY	68.50	-
1	REAR WIPER MOTOR	BENT / JAMMED	335.10	335.10
1	TAILGATE	BADLY DENTED	803.20	781.00
1	TAILGATE 'H' LOGO	NECESSARY	45.00	45.00
1	TAILGATE OUTER GARNISH	CRACKED	245.50	245.50
1	TAILGATE 'FIT' EMBLEM	NECESSARY	42.50	42.50
1	TAILGATE INNER BLACK	DENTED / JAMMED	266.20	245.50
1	TAILGATE WEATHERSTRIP	TWISTED	148.20	148.20
1	TAILGATE INNER TRIM BOARD	DEFORMED / TORN	341.80	341.80
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
2	TAILGATE INNER TOP SIDE GARNISHS @ \$195.20	NOT NECESSARY	390.40	-
2	TAILGATE REAR LICENCE LAMPS @ \$50.50	NOT NECESSARY	101.00	-
1	REAR BUMPER	DISTORTED	545.30	545.30
2	REAR BUMPER SIDE RETAINERS @ \$36.50	N/S BENT	73.00	36.50
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	REAR END PANEL	BADLY DENTED	306.30	306.30
1	REAR END PANEL TOP GARNISH	DISTORTED	166.50	166.50
2	REAR FENDERS @ \$971.00	O/S TO REPAIR SEE LABOUR/N/S BADLT DENTED/BUCKLED	1,942.00	971.00
2	REAR FENDER INNER TRIM BOARDS @ \$385.00	DISTORTED / TORN	770.00	770.00
1	SET REAR FENDER INNER TRIM BOARD CLIPS	NECESSARY	39.00	39.00
1	REAR FENDER INNER TOP SIDE GARNISH N/S	DEFORMED	248.00	165.50
1	REAR WHEEL HOUSING PANEL N/S	TO REPAIR SEE LABOUR	795.20	-
1	REAR TAILLAMP PANEL N/S	DENTED / BENT	288.50	288.50
2	TAILLAMPS @ \$305.00	N/S BROKEN / O/S	610.00	610.00

Report Ref No. CC6/QBE19007121/Ukb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR AIR VENT	NOT NECESSARY	86.20	-
2	REAR BUMPER SPLASH SHIELDS @ \$45.00	NOT NECESSARY	90.00	-
1	REAR DOOR N/S	TO REPAIR SEE LABOUR	971.10	-
1	REAR FENDER GLASS N/S	NOT NECESSARY	350.00	-
1	ROOF MOULDING N/S	NECESSARY	122.30	122.30
1	REAR SHOCK ABSORBER N/S	NOT NECESSARY	322.20	-
1	REAR WHEEL HUB BEARING N/S	NOT NECESSARY	380.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	911.40	-
1	REAR FLOOR PANEL TOP BOARD	WARPED	315.00	315.00
1	REAR FLOOR PANEL TOOLS SPONGE	TORN	485.00	485.00
1	ROOF LINING	SERVICEABLE	866.20	-
	LESS 20% DISCOUNT		-	-1,658.86
			14,880.40	6,635.44
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	200.00	-
1	REAR LICENCE PLATE W/HOLDER (SN)	SHORTED	50.00	40.00
1	SET REAR REVERSE CAMERA (SN)	SHORTED	380.00	350.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	TAILGATE TOP SPOILER (SN)	CRACKED	880.00	600.00
1	TAILGATE THIRD LAMP (SN)	BROKEN	185.00	185.00
1	REAR FENDER GLASS SEALANT N/S (SN)	NECESSARY	50.00	40.00
1	REAR BUMPER LOWER SKIRTING (SN)	CRACKED	820.00	500.00
1	SET FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	200.00	-
			3,095.00	1,955.00
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REPLACING REAR FENDER GLASS N/S.		100.00	80.00

Report Ref No. CC6/QBE19007121/Ukb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REFIX ROOF LINING.		280.00	150.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO DISMANTLE & REFIX REAR UNDERCARRIAGE.	NOT NECESSARY	280.00	-
	TO DISMANTLE & REFIX FUEL TANK.		100.00	60.00
	TO SPRAY RUST PROOFING.		180.00	100.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		180.00	80.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF O/S REAR FENDERS, REAR WHEEL HOUSING PANEL N/S, REAR DOOR N/S AND REAR FLOOR PANEL.		2,500.00	1,500.00
	TO PUTTY & SPRAY PAINTING.		2,000.00	1,400.00
			6,430.00	3,570.00
GRAND TOTAL			24,405.40	12,160.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,500.00

Report Ref No. CC6/QBE19007121/Ukb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.