

Surveyor:

KSL

DOI:

23/4/19

Date / Time:

23/4/19

Registered in / firm:

23/4/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SPB 3818Y

Name of Insured:

Low M1 How

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

22/04/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SPB 3818Y

STL 6538 U

SLV 9779 U



INSRS:

WSP:

Tel:

Liability:

RMKS:

07



INSRS:

WSP:

Tel:

Liability:

RMKS:

Alan's United



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

S\$

(

Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 5403.50

Loss of Rental (LOR):

S\$ 900.00

(

9

days) x \$100

Loss of Use (LOU):

S\$ -

(

3

x

days)

Loss of Income (LOI):

S\$ -

(

3

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/Independent)

Legal Cost

S\$ -

Total:

S\$ 6305.50

Global Sum S\$: 6300.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 6300.00

Name 1:

Alan's United Auto Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT 21/7/2020

ASS. REC. BY:

REF:

A/G/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

844k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

43 - \$ 5050 (Red \$ 5259.30 / 511.)

Veh No:

STL 65384 Yr Regn: 12, 08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Allion c.c. 1496

Colour:

White A/C: Insured / Std / NI / NA

Sp. Reading

203030 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

N87260 302P530

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F: 195/55R13

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6 mm

R/Bal.

63 mm

L/Bal.

6 mm

L/Bal.

83 mm

D.O.A.

22/4/19

D.O.I.

23/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

A/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ - RS - SI

Fixtures

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05962

Vehicle Insured : SKB3818Y
Accident Date : 22-Apr-2019

Date : 23-Apr-2019

Our Ref : 219061 (AIG) / CHAN

PAGE : 1

SOONG SOON HEE
BLK 816 JURONG WEST STREET 81
#07-56
Singapore 640816

Not Authorised
U/Ring B?
Resuming After Paint 7 days

ESTIMATED COST OF REPAIR FOR TOYOTA ALLION 1.5A SJL6538U

1 pc	Boot lid				Ry	785.53	—
1 pc	Boot lid inner lock				Ry	360.42	—
1 pc	Boot lid rubber				DR/DR	175.35	50% in
1 pc	Boot lid cable				Sm	52.50	X
1 pc	Boot lid "ALLION" emblem				Ry	42.35	—
1 pc	Boot lid logo				Ry	52.15	—
1 pc	Boot lid "A15" emblem				Ry	37.24	—
1 pc	Boot lid outer chrome				Wap	184.30	—
2 pcs	Taillamp	@ S\$285.89	CM	571.78			—
2 pcs	Taillamp gasket	@ S\$ 25.90	Ry	51.80			—
2 pcs	Taillamp corner panel	@ S\$ 94.71	Ry	189.42			—
1 pc	End panel				Ry	534.93	—
1 pc	End panel top garnish				mg D/L	876.30	—
1 pc	Spare tyre cover				Sm	167.93	X
1 pc	Spare tyre panel				Ry	876.30	X
1 pc	Rear bumper fascia				Ry	989.50	—
2 pcs	Rear bumper side retainer	@ S\$ 96.58		193.16			—
4 pcs	Rear bumper clip	@ S\$ 3.50	Ry	14.00			—
2 pcs	Rear bumper bracket	@ S\$ 48.44	DR	96.88			—
2 pcs	Rear bumper reflector	@ S\$ 56.90	DR	113.80			—
2 pcs	Headlamp	N.C	mg CM	@ S\$756.80		1,513.60	—
1 pc	Front bumper fascia				Bu	470.88	—
1 pc	Front bumper sponge				CM	75.20	—
1 pc	Front bumper reinforcement				Ry	267.57	—
1 pc	Front bumper lower grille				DR	134.90	—
2 pcs	Front bumper side retainer	@ S\$ 45.64		91.28	Sm		X

8,919.07

Less 25% : 2,229.77

6,689.30

Con't Page 2 ...

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	68212
Vehicle Details	
Vehicle No.:	5JL6538U
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ALLION 1.5 A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1NZD120206
Chassis No.:	NZT2603029530
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,582.00
Original Registration Date:	05 Dec 2008
First Registration Date:	05 Dec 2008
Transfer Count:	4
Actual ARF Paid:	\$14,582.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Dec 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$27,571.00
COE Rebate Amount:	\$26,497.00
Total Rebate Amount:	\$26,497.00

The information contained herein is correct as at 24 Apr 2019

OK

Transaction ref 20181126121518588712

Please check that the owner and vehicle details are correct:

- | | |
|--|---|
| 1. Name | : SOONG SOON HEE |
| 2. Identification No. Type | : Singapore NRIC |
| 3. Identification No. | : S1656821Z |
| 4. Country/Region | : - |
| 5. Vehicle Registration No. | : SJL6538U |
| 6. Previous Vehicle Registration No. | : - |
| 7. Effective Date of Ownership | : 26 Nov 2018 |
| 8. Original Registration Date | : 05 Dec 2008 |
| 9. First Registration Date | : 05 Dec 2008 |
| 10. Vehicle Type | : Z10 - Private Hire (Chauffeur)
Motor Car |
| 11. Vehicle Scheme | : Normal |
| 12. Attachment 1 | : No Attachment |
| 13. Attachment 2 | : - |
| 14. Attachment 3 | : - |
| 15. Vehicle Make Description | : TOYOTA |
| 16. Vehicle Model | : ALLION 1.5 A |
| 17. Year of Manufacture | : 2008 |
| 18. Primary Colour | : White |
| 19. Secondary Colour | : - |
| 20. Passenger Capacity | : 4 |
| 21. Chassis/Trailer Chassis No. | : NZT2603029530 / - |
| 22. Propellant | : Petrol |
| 23. Engine No./Motor No. | : 1NZD120206 / - |
| 24. Engine Capacity(cc)/Power Rating(kW) | : 1496 / - |
| 25. Maximum Power Output(kW/bhp) | : 81.0 / 108 |
| 26. Unladen Weight(kg) | : 1200 |
| 27. Maximum Laden Weight(kg) | : 1475 |
| 28. Open Market Value | : \$14,582.00 |
| 29. PARF Eligibility | : Yes |
| 30. PARF Eligibility Expiry Date | : 04 Dec 2018 |
| 31. Minimum PARF Benefit | : \$7,291.00 |
| 32. No. of Transfers | : 4 |

PRE-REPAIR INSPECTION REQUEST – SJL6538U vs SKB3818Y (OI) on D.O.A.: 22/04/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Sent: 23/4/2019 10:51:32 AM
Attachments:  SKM_288e19042309350.pdf

Hi,

Please refer to the enclosed request from Alan's United Auto Pte Ltd.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOL Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.sg

12:02pm @ 23/4/19
Alan
vehicle In
SJO Kenneth

From: kennychan@alanutd.com [mailto:kennychan@alanutd.com]
Sent: Tuesday, April 23, 2019 10:47 AM
To: Hor, Yinnul
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKB3818Y AND SJL6538U ON 22/04/2019

Dear Yinnul

Thank you for sending us SJE, we have decided to let LKK Auto Consultants Pte Ltd Mr. Kenneth Kong to conduct the pre survey.

Regards

kenny

Alan's United Auto Pte Ltd

64538686

From: Hor, Yinnul
Sent: Tue, 23 Apr 2019 02:22:16 +0000
To: kennychan@alanutd.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKB3818Y AND SJL6538U ON 22/04/2019

Without Prejudice

Your Reference : 219061 (AIG) / CHAN
Our Reference : SKB3818Y

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasui	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rui, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL Claims Operations – Auto

Yinui.Hor@aig.com | www.aig.sg

From: kennychan@alanutd.com [mailto:kennychan@alanutd.com]

Sent: Tuesday, April 23, 2019 9:32 AM

To: AIG SGP, Claims-Survey

Subject: [EXTERNAL] ATTACHED SJL6538U REPAIR ESTIMATE , POLICE REPORT FOR REQUEST JOINT EXPERT SURVEYOR TO CONDUCT PRE SURVEY

This message is from an external sender; be cautious with links and attachments.

Dear Motor Claims Dept.

Attached our client vehicle SJL6538U repair estimate , police report to request joint expert surveyor list for us to choose surveyor to conduct pre survey for t. p. claim your insured vehicle SKB3818Y accident on 22-04-2019 thank you .

Regards

Kenny

Alan's United Auto pte Ltd

64538686

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the

recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2019 Edit Reg		23 Apr 2019 00:00 Edit Adj Rpt	\$45,050.00 Edit Estimates	\$45,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LOW CHI HOW , ID: S7502338C									
Main Claimant: SOONG SOON HEE , ID: S1656821Z									
Vehicle Reg. No.: SJL6538U		Date of Loss: 22/04/2019 12:00 - :59	[124 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type: TP / 0502396165SG		Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured): SKB3818Y		Policy No. (Claimant):	S105763616						
Excess:									
Repairer: Alan's United Auto Pte Ltd (HQ) Bldg 7 Sin Ming Industrial Estate, #01-76, 575642 Sin Ming - Tel: 6453 8686									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/05/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL6538U (0502396165SG)
[SKB3818Y]
TP
SOONG SOON HEE
Apr 22 2019 12:00PM
[LOW CHI HOW]
Alan's United Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Video															1 per page	☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	25/04/19 13:50	Video - Accident TP front camera											Load MOV				
2	25/04/19 13:50	Video - Accident											Load MOV				
Letters/Correspondences															1 per page	☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit				
Photos/Images															3 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	07/11/19 14:06	General View											Load JPG	☒			
2	07/11/19 14:06	General View											Load JPG	☒			
3	07/11/19 14:06	General View											Load JPG	☒			
4	07/11/19 14:06	General View											Load JPG	☒			
5	07/11/19 14:06	General View											Load JPG	☒			
6	07/11/19 14:06	General View											Load JPG	☒			
7	07/11/19 14:06	General View											Load JPG	☒			
8	07/11/19 14:06	General View											Load JPG	☒			
9	07/11/19 14:06	General View											Load JPG	☒			
10	07/11/19 14:06	General View											Load JPG	☒			
11	07/11/19 14:06	General View											Load JPG	☒			
12	07/11/19 14:06	General View											Load JPG	☒			
13	07/11/19 14:06	General View											Load JPG	☒			
14	07/11/19 14:06	General View											Load JPG	☒			
15	07/11/19 14:06	General View											Load JPG	☒			
16	07/11/19 14:06	General View											Load JPG	☒			
17	07/11/19 14:06	General View											Load JPG	☒			
18	07/11/19 14:06	General View											Load JPG	☒			
19	07/11/19 14:06	General View											Load JPG	☒			
20	07/11/19 14:06	General View											Load JPG	☒			
21	07/11/19 14:06	General View											Load JPG	☒			
22	07/11/19 14:06	General View											Load JPG	☒			
23	07/11/19 14:06	General View											Load JPG	☒			
24	07/11/19 14:06	General View											Load JPG	☒			
25	07/11/19 14:06	General View											Load JPG	☒			
26	07/11/19 14:06	Odometer Reading											Load JPG	☒			
27	07/11/19 14:06	Chassis Number											Load JPG	☒			
28	07/11/19 14:06	General View											Load JPG	☒			
29	07/11/19 14:06	General View											Load JPG	☒			
Documentation															1 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	23/04/19 15:45	ACKNOWLEDGEMENT EMAIL TO AIG DD 23.04.2019											Load PDF				
2	23/04/19 15:45	EMAIL FROM AIG DD 23.04.2019											Load PDF				
3	23/04/19 15:45	TP ESTIMATE + TP GIA REPORT											Load PDF				
4	25/04/19 13:44	TP GIA REPORT											Load PDF				

Video				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
5	02/05/19 13:34	TP ESTIMATE - MARKED		Load PDF	
6	25/02/20 09:32	WORKSHOP INVOICE		Load PDF	
7	25/02/20 09:32	AUTHORISATION TO ACT FORM		Load PDF	
8	25/02/20 09:32	Release Voucher		Load PDF	
9	25/02/20 09:32	RENTAL RECEIPT		Load PDF	
10	25/02/20 09:32	GIA SEARCH		Load PDF	
11	25/02/20 09:32	LOD		Load PDF	
12	25/02/20 09:32	LETTER TO OI		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	24/04/19 09:16	OI GIA REPORT		Load PDF	
2	07/11/19 17:25	Police report of SLV9779U		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKB3818Y (Insd veh)	Model:	TOYOTA ALLION 1.5 (A)
	SJL6538U (TP veh)		
Date of Accident:	22/04/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	11,030.95
Final Repair Cost	:	\$	6,300.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	9 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	6,300.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop : Agreed Liability ____ 100 ____ (%)			
B) For GIA Registered Workshop : BOLA Applicable: Yes/ No BOLA Scenario No: ____			
BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Alan's United Auto Pte Ltd	:	\$ 6,300.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

25 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19007123/KDA3Q2

Date: 25/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SJL6538U

Insured Vehicle No : SKB3818Y

Date of Loss: 22/04/2019

Nature of Claim: TP

Claim No: 0502396165SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJL6538U

Make & Model: TOYOTA ALLION, 1.5 (A)

Engine No: 1N2D120206

Reg. Date: 05/12/2008 (Man. Year: 2008)

Chassis No: NZT2603029530

Colour: White

Odometer: 203030 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size:

195/55 R15

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 3 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,089.30	4,080.41	3,008.89	42.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	2,220.00	1,000.00	31.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,309.30	6,300.41	4,008.89	38.89
Approved Total (Overridden) (S\$)		5,050.00		
(S\$)	10,309.30	5,050.00	5,259.30	51.02
+ GST 7.00/7.00% (S\$)	721.65	353.50	368.15	51.02
Nett Amount (S\$)	11,030.95	5,403.50	5,627.45	51.02
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,305.50		
Global Sum Settlement (S\$)		6,300.00		

INSPECTION

Date of Assignment: 23/04/2019

Date Inspected: 23/04/2019 Inspected At:

 Alan's United Auto Pte Ltd (HQ)
 Blk 7 Sin Ming Industrial Estate, #01-76
 Singapore 575642

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	785.53 FL	*785.53 FL
2	1		*BOOT LID INNER LOCK	Dented	360.42 FL	*360.42 FL
3	1		*BOOT LID RUBBER (50%)	Distorted / Dented	131.51 FS	*87.68 FS
4	1		*BOOT LID CABLE	Serviceable	52.50 FL	*- FL
5	1		*BOOT LID ALLION EMBLEM	Necessary	42.35 FL	*42.35 FL
6	1		*BOOT LID LOGO	Necessary	52.15 FL	*52.15 FL
7	1		*BOOT LID A15 EMBLEM	Necessary	37.24 FL	*37.24 FL
8	1		*BOOT LID OUTER CHROME	Warped	184.30 FL	*184.30 FL
9	2		*TAILLAMP	Cracked	571.78 FL	*571.78 FL
10	2		*TAILLAMP GASKET	Necessary	51.80 FL	*51.80 FL
11	2		*TAILLAMP CORNER PANEL	Bent	189.42 FL	*189.42 FL
12	1		*END PANEL	Bent	534.93 FL	*534.93 FL
13	1		*END PANEL TOP GARNISH	Mtg Distorted	876.30 FL	*876.30 FL
14	1		*SPARE TYRE COVER	Serviceable	167.93 FL	*- FL
15	1		*SPARE TYRE PANEL	Repair	876.30 FL	*- FL
16	1		*REAR BUMPER FASCIA	Bent	989.50 FL	*989.50 FL
17	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	193.16 FL	*96.58 FL
18	4		*REAR BUMPER CLIP	Necessary	14.00 FL	*14.00 FL
19	2		*REAR BUMPER BRACKET	Distorted	96.88 FL	*96.88 FL
20	2		*REAR BUMPER REFLECTOR	Cracked	113.80 FL	*113.80 FL
21	2		*HEADLAMP (MTG CRACKED)	Not Consistent With The Impact	1,513.60 FL	*- FL
22	1		*FRONT BUMPER FASCIA (BUCKLED)	Not Consistent With The Impact	470.88 FL	*- FL
23	1		*FRONT BUMPER SPONGE (CRACKED)	Not Consistent With The Impact	75.20 FL	*- FL
24	1		*FRONT BUMPER REINFORCEMENT (BENT)	Not Consistent With The Impact	267.57 FL	*- FL
25	1		*FRONT BUMPER LOWER GRILLE (DISTORTED)	Not Consistent With The Impact	134.90 FL	*- FL
26	2		*FRONT BUMPER SIDE RETAINER (Serviceable)	Not Consistent With The Impact	91.28 FL	*- FL
27	1		*FRONT NO.PLATE WITH BOX (CRACKED)	Not Consistent With The Impact	50.00 FS	*- FS
28	1		*REAR NO.PLATE WITH BOX	Cracked	50.00 FS	*45.00 FS
29	1		*SET REAR BUMPER REVERSE SENSOR	Dented	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **9,275.23** **5,329.66**
- List Item Discount on L Items 25.00/25.00% (\$\$) **2,185.93** **1,249.25**
Total Parts (\$\$) **7,089.30** **4,080.41**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	80.00
2	TO APPLY UNDERSEALING	New	100.00	60.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	1,400.00	1,080.00
4	TO REMOVE,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	1,600.00	1,000.00
Gross Labour Cost (S\$)			3,220.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >