

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05962

Vehicle Insured : SKB3818Y  
Accident Date : 22-Apr-2019

Date : 23-Apr-2019

PAGE : 1

Our Ref : 219061 (AIG) / CHAN

SOONG SOON HEE  
BLK 816 JURONG WEST STREET 81  
#07-56  
Singapore 640816

*Not Authorise*  
*Li Ling B?*  
*Pursuing After Repair 9 days*

## ESTIMATED COST OF REPAIR FOR TOYOTA ALLION 1.5A SJL6538U

|       |                            |                   |  |     |  |         |          |         |
|-------|----------------------------|-------------------|--|-----|--|---------|----------|---------|
| 1 pc  | Boot lid                   |                   |  |     |  | Net     | 360.42   | ✓       |
| 1 pc  | Boot lid inner lock        |                   |  |     |  | DIS/Net | 175.35   | 50% Net |
| 1 pc  | Boot lid rubber            |                   |  |     |  |         | 52.50    | ?       |
| 1 pc  | Boot lid cable             |                   |  |     |  | Net     | 42.35    | ✓       |
| 1 pc  | Boot lid "ALLION" emblem   |                   |  |     |  | Net     | 52.15    | ✓       |
| 1 pc  | Boot lid logo              |                   |  |     |  | Net     | 37.24    | ✓       |
| 1 pc  | Boot lid "A15" emblem      |                   |  |     |  | Wap     | 184.30   | ✓       |
| 1 pc  | Boot lid outer chrome      |                   |  |     |  |         |          | ✓       |
| 2 pcs | Taillamp                   | @ S\$285.89       |  | CM  |  |         | 571.78   | ✓       |
| 2 pcs | Taillamp gasket            | @ S\$ 25.90       |  | Net |  |         | 51.80    | ✓       |
| 2 pcs | Taillamp corner panel      | @ S\$ 94.71       |  |     |  |         | 189.42   | ?       |
| 1 pc  | End panel                  |                   |  |     |  | B       | 534.93   | ✓       |
| 1 pc  | End panel top garnish      | 181.62            |  |     |  | mg Div  | 876.30   | ✓       |
| 1 pc  | Spare tyre cover           |                   |  |     |  |         | 167.93   | ?       |
| 1 pc  | Spare tyre panel           |                   |  |     |  | K       | 876.30   | X       |
| 1 pc  | Rear bumper fascia         |                   |  |     |  | B       | 989.50   | ✓       |
| 2 pcs | Rear bumper side retainer  | discm @ S\$ 96.58 |  |     |  |         | 193.16   | 4+      |
| 4 pcs | Rear bumper clip           | @ S\$ 3.50        |  |     |  | Net     | 14.00    | ✓       |
| 2 pcs | Rear bumper bracket        | @ S\$ 48.44       |  |     |  |         | 96.88    | ?       |
| 2 pcs | Rear bumper reflector      | discm @ S\$ 56.90 |  |     |  |         | 113.80   | 4+      |
| 2 pcs | Headlamp                   | mg cm @ S\$756.80 |  |     |  |         | 1,513.60 | ✓       |
| 1 pc  | Front bumper fascia        |                   |  |     |  | Bu      | 470.88   | ✓       |
| 1 pc  | Front bumper sponge        |                   |  |     |  |         | 75.20    | ?       |
| 1 pc  | Front bumper reinforcement |                   |  |     |  |         | 267.57   | ?       |
| 1 pc  | Front bumper lower grille  |                   |  |     |  | hit     | 134.90   | ✓       |
| 2 pcs | Front bumper side retainer | @ S\$ 45.64       |  |     |  | Net     | 91.28    | X       |

8,919.07  
Less 25% : 2,229.77

6,689.30

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Page : 2

Vehicle Insured : SKB3818Y

1 pc Front no.plate with box  
1 pc Rear no.plate with box  
1 pc Rear bumper reverse sensor(set

CM 45sn 50.00 sn  
CM 45sn 50.00 sn  
nd 200sn 300.00 sn

To remove roof lining, front and  
rear seats, trim board and carpet

120.00 801

To apply undersealing

100.00 601

To putty and spray replaced parts

1,400.00 12601

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

12001  
1,600.00

Total : S\$10,309.30

Singapore Dollars Ten Thousand Three Hundred  
and Nine and Cents Thirty Only

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: