

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

22-Apr-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6182 H

1 pc	Wheel cover	X repair	\$	116.00
1 pc	Rear o/s door	X repair	\$	791.00
2 pcs	Rear o/s door hinge @\$34.00	X see	\$	68.00
1 pc	Front o/s door	Ref	\$	765.00
2 pcs	Front o/s door hinge @\$34.00	X see	\$	68.00
1 pc	o/s rocker panel garnish	X repair	\$	286.00
			\$	2,094.00
		Less 10%	\$	209.40
			\$	1,884.60

S/NETT

1 set	o/s rocker panel garnish clips	X 4m	\$	38.00
1 set	o/s door stickers	see	\$	100.00
1 pc	Rear o/s fender sticker	see	\$	60.00
	Sundry		\$	50.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 X
	To dismantle / refit inner components of the Rear o/s door into new shell door		\$	150.00 X
	To dismantle / refit inner components of the front o/s door into new shell door		\$	150.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear bumper, rear o/s fender etc		\$	400
	To putty and spray painting on rear bumper, rear o/s fender, rear o/s door, front o/s door, o/s rocker panel garnish, o/s mirror		\$	900
	To apply rustproofing on the repaired and replaced panels.		\$	200.00 50
			\$	4,812.60

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

• To resurvey the damaged parts.
 • To display damages parts to the insurance company.
 • All prices are subject to confirmation by the insurance company on a "Without Prejudice" basis.
 • No legal modification is allowed.
 • Supplementary item(s) must be approved and is subject to final approval from Insurance company.
 Acknowledged by Repairer
 Signature:
 Date:

26/4/19
 total 45 \$ 1800 / 3 Dr
 //

1/Carpet 1000
 22/4/19 1705hr
 3 Dr
 45
 After Repair photo