

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Tel : 6389 - 6111
Fax : 6224 - 7478 / 7175

Quotation

DATE : 24.04.2019
VEH NO : SKX9381J
MODEL : Honda Vezel
D O A : 22.04.2019
YR REF : XD8115U

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKX9381J (Honda Vezel)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Bumper <i>Dehd.</i>	1	880.00 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	64.00 ✓
4	Rear Bumper Reflector - LH & RH <i>new</i>	2	302.40 ✓
5	Rear End Panel <i>Dehd.</i>	1	580.00 ✓
6	Rear End Panel Top Garnish <i>Dehd.</i>	1	101.00 ✓
7	Rear End Panel Buzzer <i>new</i>	1	65.00 x
8	Taillamp - LH & RH <i>lit</i>	2	920.00 ✓
9	Taillamp Lower Garnish - LH & RH <i>RH Dehd</i>	2	200.00 195 ✓
10	Tailgate <i>Distorted</i>	1	1,100.00 ✓
11	Tailgate Lock <i>Damaged</i>	1	185.00 ✓
12	Tailgate Lock Sensor <i>Damaged</i>	1	98.00 ✓
13	Tailgate Weatherstripe <i>lit</i>	1	165.00 ✓
14	Tailgate Outer Garnish <i>Repair</i>	1	325.00 x
15	Tailgate Outer Garnish Clips <i>new</i>	1 set	20.00 ✓
16	Tailgate Reflector - LH & RH <i>lit</i>	2	710.00 ✓
17	Tailgate Damper - LH & RH <i>Damaged</i>	2	360.00 ✓
18	Tailgate Inner Trim Board <i>Dehd</i>	1	225.00 ✓
19	Tailgate Inner Trim Board Clips <i>new</i>	1 set	30.00 ✓
20	Tailgate Glass Moulding <i>new</i>	1	125.00 ✓
21	Honda Logo <i>new</i>	1	32.00 ✓
22	Vezel Emblem <i>new</i>	1	65.00 ✓
23	Rear Fender Inner Trim Board - LH & RH <i>new</i>	2	490.00 x
24	Rear Fender Inner Trim Board Clips <i>new</i>	1 set	60.00 x
25	Spare Tyre Panel Top Cover <i>new</i>	1	305.00 x
26	Tools Tray Sponge <i>new</i>	1	225.00 x

\$ 7,852.40

5885

4708

RE : ESTIMATE FOR ACCIDENT REPAIR SKX9381J (Honda Vezel)

Less 20%

(1,570.48)

\$ 6,281.92

S/NETT ITEMS

1	Rear Number Plate	3 item	1	30.00	*
2	Rear Number Plate Holder		1	30.00	*
3	Rear Bumper Lower Chrome Moulding	HP new	1	250.00	+
4	Reverse Sensor	Damaged	1	280.00	200
5	Rear End Panel Sealant	new	1	60.00	✓
5	Tailgate Rubber Accessories	cut	1	200.00	150
6	Tailgate Glass Sealant	new	1	60.00	✓
7	Rear Camera	Damaged	1	480.00	380

\$ 1,390.00

Total parts

\$ 7,671.92

LABOUR CHARGE

1	To knocking out rear portion & renew above parts	\$	1,200.00	800
2	To putty & spray up paint works	\$	1,200.00	800
3	To check wiring system	\$	50.00	30
4	To underseal	\$	150.00	60
5	To remove reverse sensor	\$	100.00	50
6	To remove rear camera	\$	100.00	50
7	To remove upholstery	\$	150.00	80
8	To remove tailgate glass	\$	180.00	120
9	To transfer tailgate fittings	\$	150.00	80

Total Labour

\$ 3,280.00

Grand Total

\$ 10,951.92

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY

Total: 7628.
K/s: 6,1K / dk
06 Days.