

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Tel : 6389 - 6111
Fax : 6224 - 7478 / 7175

Joy

Quotation

DATE : 24.04.2019
VEH NO : SKX9381J
MODEL : Honda Vezel
D O A : 22.04.2019
YR REF : XD8115U

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKX9381J (Honda Vezel)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Bumper <i>Del'd</i>	1	880.00 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	64.00 ✓
4	Rear Bumper Reflector - LH & RH <i>new</i>	2	302.40 ✓
5	Rear End Panel <i>Del'd</i>	1	580.00 ✓
6	Rear End Panel Top Garnish <i>Del'd</i>	1	101.00 ✓
7	Rear End Panel Buzzer <i>new</i>	1	65.00 ✗
8	Taillamp - LH & RH <i>lt</i>	2	920.00 ✓
9	Taillamp Lower Garnish - LH & RH <i>RH Del'd</i>	2	300.00 195 ✓
10	Tailgate <i>Distorted</i>	1	1,100.00 ✓
11	Tailgate Lock <i>Del'd</i>	1	185.00 ✓
12	Tailgate Lock Sensor <i>Del'd</i>	1	98.00 ✓
13	Tailgate Weatherstripe <i>lt</i>	1	165.00 ✓
14	Tailgate Outer Garnish <i>Repair</i>	1	325.00 ✗
15	Tailgate Outer Garnish Clips <i>new</i>	1 set	20.00 ✓
16	Tailgate Reflector - LH & RH <i>lt</i>	2	710.00 ✓
17	Tailgate Damper - LH & RH <i>Del'd</i>	2	360.00 ✓
18	Tailgate Inner Trim Board <i>Del'd</i>	1	225.00 ✓
19	Tailgate Inner Trim Board Clips <i>new</i>	1 set	30.00 ✓
20	Tailgate Glass Moulding <i>new</i>	1	125.00 ✓
21	Honda Logo <i>new</i>	1	32.00 ✓
22	Vezel Emblem <i>new</i>	1	65.00 ✓
23	Rear Fender Inner Trim Board - LH & RH <i>?</i>	2	490.00 ✗
24	Rear Fender Inner Trim Board Clips <i>?</i>	1 set	60.00 ✗
25	Spare Tyre Panel Top Cover <i>new</i>	1	305.00 ✗
26	Tools Tray Sponge <i>new</i>	1	225.00 ✗

\$ 7,852.40

5885

4708

RE : ESTIMATE FOR ACCIDENT REPAIR SKX9381J (Honda Vezel)

Less 20%

(1,570.48)

\$ 6,281.92

S/NETT ITEMS

1	Rear Number Plate	3 new	1	30.00	+
2	Rear Number Plate Holder		1	30.00	+
3	Rear Bumper Lower Chrome Moulding	HP new	1	250.00	+
4	Reverse Sensor	Damaged	1	280.00	-200
5	Rear End Panel Sealant	new	1	60.00	✓
5	Tailgate Rubber Asscessories	at 850	1	200.00	150
6	Tailgate Glass Sealant	new	1	60.00	✓
7	Rear Camera	Damaged	1	480.00	380
				\$	1,390.00

Total parts

\$ 7,671.92

LABOUR CHARGE

1	To knocking out rear portion & renew above parts	\$	1,200.00	800
2	To putty & spray up paint works	\$	1,200.00	800
3	To check wiring system	\$	50.00	30
4	To underseal	\$	150.00	60
5	To remove reverse sensor	\$	100.00	50
6	To remove rear camera	\$	100.00	50
7	To remove upholstery	\$	150.00	80
8	To remove tailgate glass	\$	180.00	120
9	To transfer tailgate fittings	\$	150.00	80
			\$	3,280.00

Total Labour

\$ 3,280.00

Grand Total

\$ 10,951.92

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY

Total: 7628.

L/s : 6.1K

06 Days

RE : ESTIMATE FOR ACCIDENT REPAIR SKX9381J (Honda Vezel)

WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: