

SKETCH PLAN

NO COLLISION

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 05 Feb 2019, A ~~Vehicle~~ Vehicle SJR 9969 H have stop the car Infront
 me and mention that I scratch his car from behind as I didn't knock
 his car. So to prevent any hit and run, I need to submit any
 particular to him.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 19 March 2019
 11:42 am

Driver's Signature

(If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S665500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MSI119036778 Vehicle Registration No: FBN 2668M
Name (as shown in NRIC) : Xiao weilong NRIC/FIN/Passport No : S88247646
(*~~Vehicle Driver~~ / Vehicle Owner) (*) Please delete as appropriate
Address : BK 771 Yishun Ave 3 #02-237 Singapore (760711)
Contact (Tel) : _____ Mobile No. : 96497293
Email Address : longwa_88@live.com.sg
Date of Accident : 5.2.19 Time of Accident : 1400 hrs.
Place of Accident : In between boundary rd and Serangoon Central
Insurance Company : mslg

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I want to amend the correct name of insurance
company from XIC to mslg.

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: 21/3/19.
Date:

Enquire Vehicle & Owner Information (Vehicle No. FBN2668M As At 05 Feb 2019 / 16:30:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: RSS/1902-7092(HT)PD

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S8824764G
Owner Name: XIAO WEILONG
Registered Address Type: HDB / HUDC
Registered Block/House No.: 771
Registered Street Name: YISHUN AVENUE 3
Registered Unit No.: # 02 - 237
Registered Building Name: -
Registered Postal Code: 760771

Current Vehicle Details

Vehicle No.: FBN2668M
Make Description/Model: SYM / CRUISYM 300I ABS
Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Transaction Type

Please do not use your browser's Back or Forward buttons as this may result in information loss

Last updated: 17 Feb 2019

Best viewed using IE 11, Firefox 52, Chrome 56, Safari 8, Opera 43 and above

© 2019 Land Transport Authority of Singapore

[Terms of Use](#) | [Privacy Statement](#) | [Disclaimer](#) | [Rate this Website](#)

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440

Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783

Reg No: 201000228E

INVOICE

Chang Privauto
C/o: HT Automation
8 Kaki Bukit Ave 4 #03-24
Premier @ Kaki Bukit Singapore 415875

Invoice No: CL/190273

Ref No: HTA/03/1901/TP

Date: 06 March 2019

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. SJR 9969 H
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES
(INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL

S\$ 505.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Chang Privauto
C/o: HT Automation
8 Kaki Bukit Ave 4 #03-24
Premier @ Kaki Bukit Singapore 415875

Date : 06 March 2019
Our ref : HTA/03/1901/TP

Accident Date : 05 February 2019
Inspection Date : 01 March 2019
Repairer Name : HT Automation
8 Kaki Bukit Ave 4 #03-24
Premier @ Kaki Bukit Singapore 415875

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SJR 9969 H
Make / Model : Hyundai Avante
Chassis No : KMH DU41BR9U799311
Engine No : G4FC9U679091

Year / Capacity : 2009 / 1591 cc
Colour : Silver
Mileage : 132078

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Neuton	185/65 R15	5 mm	Sport
Front Offside	: Neuton	185/65 R15	5 mm	Sport
Rear Nearside	: Neuton	185/65 R15	5 mm	Sport
Rear Offside	: Neuton	185/65 R15	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear n/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 45 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 3,600.00** on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.

SCL APPRAISER PTE LTD

Vehicle Registration No: SJR 9969 H

Our Ref No: HTA/03/1901/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear boot lid X N/A	Damage	\$ 907.60	\$ 907.60 X
1	Rear boot o/s lamp / CUT	Damage	\$ 189.60	\$ 189.60 / 160
1	Rear boot lock X N/A	Intact	\$ 183.60	
1	Rear boot logo / N/A	Necessary	\$ 38.50	\$ 38.50 ✓
1	Rear boot rubber X N/A	Necessary	\$ 115.20	\$ 115.20 X
1	Rear boot "AVANTE" emblem / N/A	Necessary	\$ 35.00	\$ 35.00 ✓
1	Rear boot "S" emblem / N/A	Necessary	\$ 32.00	\$ 32.00 ✓
1	Rear n/s taillamp BR /	Damage	\$ 366.50	\$ 366.50 ✓ 274.50
1	Rear bumper / 00	Damage	\$ 486.90	\$ 486.90 ✓
1	Rear bumper top bracket X N/A	Intact	\$ 32.00	
1	Rear bumper clip (1 set) / N/A	Necessary	\$ 50.00	\$ 50.00 30
1	Rear bumper inner sponge / BR	Damage	\$ 122.00	\$ 122.00 ✓
1	Rear bumper reinforcement X N/A	Damage	\$ 354.00	\$ 354.00 X
1	Rear bumper reinforcement stay X N/A	Damage	\$ 135.00	\$ 135.00 X
1	Rear bumper side retainer / BT	Necessary	\$ 44.80	\$ 44.80 ✓
1	Rear n/s fender X R	Repair	\$ 1,703.00	
			\$ 4,795.70	\$ 2,877.10 1223.79
Less 20%			\$ 959.14	\$ 575.42 -20%
Total Cost - List Items			\$ 3,836.56	\$ 2,301.68 978.96

SPECIAL NETT ITEMS

1	Rear reverse sensor (1 set) BR /	Damage	\$ 350.00	\$ 350.00 290
Total Cost - Special Nett items			\$ 350.00	\$ 350.00

Total cost of parts

\$ 4,186.56 \$ 2,651.68

Vehicle Registration No: SJR 9969 H

Our Ref No: HTA/03/1901/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 4,186.56	\$ 2,651.68

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 30 ✓
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 X 60 ✓ △
3	To remove and refit rear reverse sensor.	\$ 150.00	\$ 120.00 30 ✓ ○
4	To transfer boot lid mechanism and wiring assembly to assist repair.	\$ 80.00	\$ 60.00 X
5	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 60.00 30 ✓
6	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,080.00	\$ 750.00 350 ✓ +50 △
7	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,000.00	\$ 660.00 600 ✓ ○ 1040 ✓

GRAND TOTAL

\$ 6,826.56 \$ 4,471.68

P- 978.96
 M- 200
 L- 1040
 2218.96
 L/S - 1775.16
 = 1800

3 days + 1 day △

Vehicle Registration No: SJR 9969 H

Our Ref No: HTA/03/1901/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 3,600.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Feb 2019		25 Feb 2019 16:31 Edit Adj Rpt	S\$1,850.00 Edit Estimates	S\$1,850.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	XIAO WEILONG , ID: S8824764G		
Main Claimant:	CHANG PRIVAUTO , Co. Reg. No.: 53366420M		
Vehicle Reg. No.:	SJR9969H	Date of Loss:	05/02/2019 16:00 - :59 [114 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/19-000214	Policy/Cover Note No.:	MSD/VMS/18-994798 (TP, Fire & Theft) Coverage: 28/08/2018 - 27/08/2019
Vehicle Reg. No. (Insured):	FBN2668M	Policy No. (Claimant):	
		Excess:	
Repairer:	Ht Automation (HQ) 8 Kaki Bukit Avenue 4, #03-24 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 98733215		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 23/04/2019]		
Adj Asg. Remarks:	on WP, Liability (Non-reporting) SJE DISAGREE APPOINT LKK. PLS CONTACT Ms. Clovis Ong @ 6384 7105		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (18/04/2019): Report Send Back Alerts - SJR9969H (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJR9969H (MSC/V/19-000214)
[FBN2668M]
TP
CHANG PRIVAUTO
Feb 5 2019 4:00PM
[XIAO WEILONG]
Ht Automation

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/03/19 11:44	Accident Statement Addm. #1 From: SC - Reg. No: FBB2668M, Claimant: XIAO WEILONG	Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/03/19 15:40	General View	Load JPG	☒
2	28/03/19 15:40	General View	Load JPG	☒
3	28/03/19 15:40	General View	Load JPG	☒
4	28/03/19 15:40	General View	Load JPG	☒
5	28/03/19 15:40	General View	Load JPG	☒
6	28/03/19 15:40	General View	Load JPG	☒
7	28/03/19 15:40	General View	Load JPG	☒
8	28/03/19 15:40	General View	Load JPG	☒
9	28/03/19 15:40	General View	Load JPG	☒
10	28/03/19 15:40	General View	Load JPG	☒
11	28/03/19 15:40	General View	Load JPG	☒
12	28/03/19 15:40	General View	Load JPG	☒
13	28/03/19 15:40	General View	Load JPG	☒
14	28/03/19 15:40	General View	Load JPG	☒
15	28/03/19 15:40	General View	Load JPG	☒
16	28/03/19 15:40	General View	Load JPG	☒
17	28/03/19 15:40	General View	Load JPG	☒
18	28/03/19 15:40	General View	Load JPG	☒
19	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒
20	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒
21	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒
22	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒
23	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒
24	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒
25	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒
26	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒
27	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒
28	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒
29	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒
30	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒
31	28/03/19 15:40	Photographs of Damaged Parts	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	28/03/19 15:40	Photographs of Damaged Parts	 Load JPG	✓
33	28/03/19 15:40	Photographs of Damaged Parts	 Load JPG	✓
34	28/03/19 15:40	Photographs of Damaged Parts	 Load JPG	✓
35	28/03/19 15:40	Photographs of Damaged Parts	 Load JPG	✓
36	28/03/19 15:40	Photographs of Damaged Parts	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/02/19 10:51	PRI & THIRD PARTY ACCIDENT REPORT	 Load PDF	
2	18/04/19 11:12	LOD & Supporting Documents	 Load PDF	
3	18/04/19 11:13	TP Survey Report	 Load PDF	
4	18/04/19 13:24	SJR9969H	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/04/19 09:06	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19003557/EVD3S2-1

Date: 29/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/18-994798
 Claimant Vehicle No: SJR9969H Insured Vehicle No: FBN2668M
 Date of Loss: 05/02/2019 Nature of Claim: TP Claim No: MSC/V/19-000214

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR9969H
 Make & Model: HYUNDAI HD AVANTE 1.6 A (BI-FUEL), 1.6 (A) Engine No: G4FC9U679091
 Reg. Date: 27/07/2009 (Man. Year: 2009) Chassis No: KMHDU41BR9U799311
 Colour: Silver Odometer: 132078 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15
 Front Left Side: HIFLY 5 mm Rear Left Side: HIFLY 5 mm
 Front Right Side: HIFLY 5 mm Rear Right Side: HIFLY 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,186.56	1,178.96	3,007.60	71.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,150.00	1,490.00	56.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,826.56	2,328.96	4,497.60	65.88
Approved Total (Overridden) (S\$)		1,850.00		
Nett Amount (S\$)	6,826.56	1,850.00	4,976.56	72.90

INSPECTION

Date of Assignment: 25/02/2019
 Date Inspected: 01/03/2019 Inspected At: Ht Automation (HQ)
 8 Kaki Bukit Avenue 4, #03-24 Premier @ Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Apr 2019)

Parts: 143 HYUNDAI HD AVANTE 1.6 A (BI-FUEL) 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJR9969H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Not Necessary	907.60 FL	*- FL
2	1		*REAR BOOT O/S LAMP	Cut	189.60 FL	*160.00 FL
3	1		*REAR BOOT LOCK	Not Necessary	183.60 FL	*- FL
4	1		*REAR BOOT LOGO	Necessary	38.50 FL	*38.50 FL
5	1		*REAR BOOT RUBBER	Not Necessary	115.20 FL	*- FL
6	1		*REAR BOOT AVANTE EMBLEM	Necessary	35.00 FL	*35.00 FL
7	1		*REAR BOOT S EMBLEM	Necessary	32.00 FL	*32.00 FL
8	1		*REAR N/S TAILLAMP	Broken	366.50 FL	*274.50 FL
9	1		*REAR BUMPER	Dented	486.90 FL	*486.90 FL
10	1		*REAR BUMPER TOP BRACKET	Not Necessary	32.00 FL	*- FL
11	1		*SET REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
12	1		*REAR BUMPER INNER SPONGE	Broken	122.00 FL	*122.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Not Necessary	354.00 FL	*- FL
14	1		*REAR BUMPER REINFORCEMENT STAY	Not Necessary	135.00 FL	*- FL
15	1		*REAR BUMPER SIDE RETAINER	Bent	44.80 FL	*44.80 FL
16	1		*REAR N/S FENDER	Repair	1,703.00 FL	*- FL
17	1		*SET REAR REVERSE SENSOR	Broken	350.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	5,145.70	1,423.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	959.14	244.74
Total Parts (\$\$)	4,186.56	1,178.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR.	New	150.00	30.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR.	New	80.00	0.00
5	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.	New	100.00	30.00
6	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,080.00	400.00
7	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTION WHERE CONSISTENT TO THE ACCIDENT.	New	1,000.00	600.00
Gross Labour Cost (S\$)			2,640.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >