

TPA 16
Cecilia

SJR8630R
Toyota Camry 1898cc
MRO53BK4107046673

Rear Bumper Distorted	468.30 ✓
Rear Bumper Clips. New	30 ✓
Rear Bumper Side Holder x 02 New	$57.2 \times 2 = 114.40$ ✓
Rear Bumper Reflector x 02 New	$70.2 \times 2 = 140.40$ X
Rear Bumper Reinforcement Bolt	361.80 ✓
Reverse Sensor Damaged	280.80 200(SN)
Tail Lamp x 02 crushed	$408 \times 2 = 816$ ✓
Rear End Panel Dented.	610.80 ✓
Rear End Panel Top Garnish deformed	353.80 ✓
Rear End Panel Sealant. New	60(SN) ✓
Boothlid Buckled	9.57 ✓
Boothlid Lock Damaged	287.40 ✓
Boothlid Weatherstripe. New	231.40 X
Boothlid Reflector x 02 New	$280.8 \times 2 = 561.60$ +
Boothlid Outer Garnish. New	381.50 X
Toyota Logo	58.80 ✓
Cammy Wording. New	62.50 ✓
2-0 Wording	45.40 ✓

SJR 8630R

Spere Tyre Panel Top Cover.	HP	245.80	x
Rear Exhaust Pipe	M	891.10	-
Rear Exhaust Tail Pipe	HP	150(SN)	x
Rear Exhaust Mounting	NEL	36.60	x
		4166.20	
		3124.65	

S.N: 200.

Panel Beeding
Spray Painting.
Wiring.

To underead

To remove reverse sensor

To remove upholstery.

To remove exhaust pipe

~~1000~~ 800

~~1200~~ 900

~~50~~ 30

~~150~~ 80

~~100~~ 50

~~150~~ 60

150.X. 1920

total: 5244.65

h/s: 4.21C.
06 hrs.

(4.21C)

06 hrs

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: