

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Authorized
L.B.1
Assuming B&P

Today

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 23.04.2019

Accident Date : 11.04.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Grace" Reg. No. SLP7194B Claiming Against Your Insured Reg. No. SKK6795L		
1pc	Front Fender RH	3.50	R 295.00 ✓
1pc	Front Fender Shield		D.I 84.00 ✓
10pcs	Front Fender Shield Clips		nn 35.00 ✓
1pc	Front Fender Badge Hybrid		nn 33.50 ✓
1pc	Front Door RH		R 722.00 ✓
1pc	Front Door Sticker		nn 20.00 ✓
1pc	Front Door Lower Hinge		R 65.00 X
1pc	Front Door Weatherstrip		nn 162.00 ✓
1pc	Front Door Wing Mirror		R 645.00 X
1pc	Front Door Wing Mirror Cover		L 64.00 X
1pc	Front Door Glass Regulator	3.50	269.00 ?
1pc	Front Door Glass Motor		269.00 ?
1pc	Front Door Lower Rubber Seal		nn 49.00 ✓
10pcs	Front Door Trim Board Clips		nn 35.00 X
1pc	Front Wheel Cap		R 175.00 X
1pc	Front Wheel Bearing		nn 285.00 X
1pc	Rocker Panel RH		R 1,120.00 ✓
1pc	Rear Door RH		R 832.00 ✓
1pc	Rear Door Sticker		nn 16.50 ✓
1pc	Rear Door Weatherstrip		nn 149.00 ✓
1pc	Rear Door Glass Regulator	3.50	211.00 ?
10pcs	Rear Door Trim Board Clips		nn 35.00 X
1pc	Rear Door Lower Hinge		64.00 ?
1pc	Rear Wheel Cap		nn 192.00 ✓
1pc	Rear Wheel Bearing		310.00 ?
1pc	Rear Shock Absorber		167.00 ?
1pc	Rear Bumper		nn 955.00 ✓
10pcs	Rear Bumper Clips		nn 35.00 ✓
1pc	Rear Bumper Reflector		nn 52.00 X
	Less 20%		1,469.20
			5,876.80
		C/F	5,876.80

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 23.04.2019

Accident Date : 11.04.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Grace" Reg. No. SLP7194B Claiming Against Your Insured Reg. No. SKK6795L		
		B/F	5,876.80
	To Conduct Front Electrical Check, Locking System, Etc		40.00 201
	To Dismantle / Transfer Door Fittings / Ancillary Accessories * 2		300.00 1201
	To Dismantle / Replace Front Wheel Bearing and Perform Press		nn 120.00 X
	To Dismantle / Replace Rear Wheel Bearing Perform Press & Absorber		180.00 ?
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		200.00 1201
	To Conduct Computerize Wheel Alignment Test		80.00 601
	To Conduct High Speed Balancing		nn 80.00 X
	To Supply Panel Joint Sealant - Rocker Panel		60.00 301
	To Reseal Rocker Panel Chip Resistant Primo		100.00 801
	To Dismantle / Refit Rear Seats, Floor Carpet		150.00 801
	To Diagnose / Erase /Reprogram Air Bag SRS Error Code		180.00 ?
	Labour Charge - Panel Beating, Repairing Of Front Fender Inner Panel Floor Panel, Door 'B' Pillar, Rear Fender Etc.Cnt, Weld Rocker Panel and Parts Replacement		1,200.00 9001
	To Respray Affected Areas		1,400.00 12001
			9,966.80

LKK Auto Consultants hereby notify
the Repairer of the following:

Total :

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: