

INS. CASE OWNER:

LKK:
IDAC:

Surveyor:

DOI:

Date / Time :

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

Excess Sec II :SS

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age :

Driver Tel No. :

HP:

D.O.A :

Nature of Accident :

(V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 10,791.79

(10 days)

Reduction:

SS 2,074.72

%

25

Email

Call

FINAL SETTLEMENT

Date/Time: 17/9/19

Confirm with

ARV

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. :

27

If NO or B 28, Ass. Lia :

Repair Cost:

(W/SS) SS 11,547.19

(As per TP LOD)

Centre different

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS 550.00

(\$ 50 x 11 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 12,097.19

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 12,097.19

Name 1:

Kah Motor Co sdn Bhd.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
21/10/19



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

LKK Auto Survey

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLL8150S

Chassis No : JHMRU1810GX201894

Model : HRV DX-SIN CVT YM 2016

Owner's Name : TAY YONG SING

Ins Policy No. : SD19V02321/VPC2/R01

Date of Accident : 20/4/2019

Document No. : SQT19001789 Page 1

Date : 22. Apr 2019

Customer No. : WZA006

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15B4531895

Date | Time : 22. Apr 2019 2:54:53 PM

Surveyor Name : DID : +65 6846 5673

Survey Date : HP : +65 8109 6306

Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: TAY YONG SING						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 20-04-2019@19.00PM						
	ACC: CTE BESIDE ATRALIAN INT. SCH.EXIT10 (L/P251)						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SMD7780K HUNDAI/ELEANTRA/BLACK&WHITE						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
71501-T7B-000	FACE RR.BUMPER	1	777.90	25	583.42	40.84	624.26
91505-TM8-003	CLIP,BUMPER	2	2.30	25	3.45	0.24	3.69
71593-T7A-J00	SPACER,R.RR.BUMPER SIDE	1	17.20	25	12.90	0.90	13.80
71598-T7A-J00	SPACER,L.RR.BPR S	1	17.20	25	12.90	0.90	13.80
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	94.10	25	70.57	4.94	75.51
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	94.10	25	70.57	4.94	75.51
66100-T7A-300ZZ	PANEL COMPRR.	1	373.10	25	279.82	19.59	299.41
65513-T7A-300ZZ	STIFFENERRR.JACK UP	1	61.40	25	46.05	3.22	49.27
65750-T5B-300ZZ	CROSSMEMBER COMPRR.FLOOR	1	83.70	25	62.77	4.39	67.16
04655-T7A-310ZZ	PANEL SETRR.FLOOR	1	675.50	25	506.62	35.46	542.08
74890-T7A-J12ZC	GARNISH ASSYRR.LICENSE	1	193.60	25	145.20	10.16	155.36

Printed on 22/4/2019 6:29:22 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLL8150S
Chassis No : JHMRU1810GX201894
Model : HRV DX-SIN CVT YM 2016
Owner's Name : TAY YONG SING
Ins Policy No. : SD19V02321/VPC2/R01
Date of Accident : 20/4/2019

Document No. : SQT19001789
Date : 22. Apr 2019
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B4531895
Date | Time : 22. Apr 2019 2:54:53 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
38387-TZ5-A01	ANTENNA ASSYL.F. <i>DM 61.4</i>	1	59.30	25	44.47	3.11	47.58
74940-TZ5-A01	BUZZER ASSYSMART <i>DM</i>	1	60.40	25	45.30	3.17	48.47
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR <i>re</i>	1	189.80	25	142.35	9.96	152.31
84550-T7A-J00	BOX ASSY,CARGO FLOOR <i>re</i>	1	129.50	25	97.12	6.80	103.92
75722-T7W-A01	EMBLEMRR. <i>gmc</i>	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC <i>gmc</i>	1	14.50	25	10.87	0.76	11.63
84640-T7A-J01ZA	LINING ASSYRR.PANEL <i>gmc</i>	1	43.90	25	32.92	2.30	35.22
74440-T7A-003	WEATHERSTRIPTAILGATE <i>BT</i>	1	98.70	25	74.02	5.18	79.20
74800-T7A-J02	LOCK ASSYTAILGATE <i>BT</i>	1	78.90	25	59.17	4.14	63.31
68100-T7A-J20ZZ	TAIL GATE COMP <i>gmc</i>	1	855.70	25	641.77	44.92	686.69
Sum Item					3080.69	215.61	3,296.30
BOSUN	SUNDRIES <i>net</i>	1	100.00	20	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	/	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT. <i>net</i>	1	100.00	/	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00	120	140.00	9.80	149.80
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PGS (N)	1	160.00	140	160.00	11.20	171.20
BP00R	APPLY BODY UNDERSIDE COATING (N)	1	250.00	200	250.00	17.50	267.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	350.00	300	350.00	24.50	374.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	350.00	300	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	300	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	550.00	450	550.00	38.50	588.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>450</i>	1	2800.00	2250	2800.00	196.00	2996.00
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN <i>500</i>	1	5800.00	3920	5800.00	406.00	6206.00
Sum Labor					11150.00	780.50	11,930.50

Survey By

Printed on 22/4/2019 6:29:22 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

P/P = \$10791.79



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLL8150S
Chassis No : JHMRU1810GX201894
Model : HRV DX-SIN CVT YM 2016
Owner's Name : TAY YONG SING
Ins Policy No. : SD19V02321/VPC2/R01
Date of Accident : 20/4/2019

Document No. : SQT19001789
Date : 22. Apr 2019
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B4531895
Date | Time : 22. Apr 2019 2:54:53 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time							
Excess							
Status							
Signature							
Total Amount					14,230.69	996.11	15,226.80
Total (Inclusive of GST)							15,226.80

14280.20

14416.028

10 Days.

before paint photos

Quo Qian - 82880282

15/7/19.

#14266.57

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 22/4/2019 6:29:22 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZA006 / AXA INSURANCE	Document No:	SVO19044456
Chassis No:	JHMRU1810GX201894	Printed By:	ARYCHUA
License No:	SLL8150S	Order Date:	15. July 2019
Mileage:	41244	Order Time:	2:54:53 PM
Engine No:	L15B4531895	Service Advisor:	ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 73040)						
	OWNER: TAY YONG SING						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 20-04-2019@19.00PM						
	ACC: CTE BESIDE ATRALIAN INT. SCH.EXIT10 (L/P251)						
	SURVEYED BY: GuoQiang(1kk) 15-07-2019@10.10am						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SMD7780K HUNDAI/ELEANTRA/BLACK&WHITE						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
91505-TM8-003	CLIP,BUMPER	2	2.30	25	3.45	0.24	3.69
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	1	17.20	25	12.90	0.90	13.80
71598-T7A-000	SPACER,L.RR.BUMPER SIDE	1	17.20	25	12.90	0.90	13.80
66100-T7A-300ZZ	PANEL COMPRR.	1	373.10	25	279.82	19.59	299.41
65513-T7A-300ZZ	STIFFENERRR.JACK UP	1	61.40	25	46.05	3.22	49.27
65770-T7J-H00ZZ	CROSSMEMBER COMPRR.FLOOR RR.	1	147.60	25	110.70	7.75	118.45
04655-T7A-310ZZ	PANEL SETRR.FLOOR	1	675.50	25	506.62	35.46	542.08
38387-TZ5-A11	ANTENNA ASSYL.F.	1	61.40	25	46.05	3.22	49.27
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR	1	189.80	25	142.35	9.96	152.31
84550-T7A-J00	BOX ASSY,CARGO FLOOR	1	129.50	25	97.12	6.80	103.92
75722-T7W-A01	EMBLEMRR.	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
74800-T7A-J02	LOCK ASSYTAILGATE	1	78.90	25	59.17	4.14	63.31
68100-T7A-J20ZZ	TAIL GATE COMP	1	855.70	25	641.77	44.92	686.69
ch/74940-TZ5-A01	BUZZER ASSYSMART	1	60.40	25	45.30	3.17	48.47
ch/74646-T7A-010	COVERR R.FLOOR UN	1	120.70	25	90.52	6.34	96.86
	SUM PARTS:				2,591.79	181.40	2,773.19
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BOBC	EXT-YBH	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BOJSE	EXT-YJ	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT.						
BML02I	EXT-YJ	1	120.00		120.00	8.40	128.40
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER TEST.(N)						
BA02R	EXT-YJ	1	140.00		140.00	9.80	149.80
	REMOVE & INSTALL REVERSE						
	SENSORS-4 PCS (N)						
BP00R	EXT-YBH	1	200.00		200.00	14.00	214.00
	APPLY BODY UNDERSIDE COATING (N).						

WD=10

Rare

W



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMRU1810GX201894
License No: SLL8150S
Mileage: 41244
Engine No: L15B4531895

Document No: SVO19044456
Printed By: ARYCHUA
Order Date: 15. July 2019
Order Time: 2:54:53 PM
Service Advisor: ARY CHUA WAI NGEE

BC011R	0760 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	300.00	300.00	21.00	321.00
BC012R	0760 RESET VEHICLE SMART ENTRY SYSTEM	1	300.00	300.00	21.00	321.00
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	300.00	300.00	21.00	321.00
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00	450.00	31.50	481.50
BP06R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,250.00	2,250.00	157.50	2,407.50
BKRP02M	EXT-YJ CUT OFF & RENEW REAR END PANEL & FLOOR END PANEL FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	3,920.00	3,920.00	274.40	4,194.40
			SUM LABOUR:	8,200.00	574.00	8,774.00
			TOTAL SGD	10,791.79	755.40	11,547.19
			Total Payable (SGD)		11,547.19	

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: ****8299J / TAY YONG SING
Chassis No: JHMRU1810GX201894
License No: SLL8150S
Mileage: 41244
Engine No: L15B4531895

Document No: SVO19044456
Printed By: ARYCHUA
Order Date: 15. July 2019
Order Time: 2:54:53 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 73040) OWNER: TAY YONG SING OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 20-04-2019@19.00PM ACC: CTE BESIDE AUSTRALIAN INT. SCH.EXIT10 (L/P251) SURVEYED BY: GuoQiang(lkk) 15-07-2019@10.10am REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SMD7780K HUNDAI/ELEANTRA/BLACK&WHITE SUPPLIMENTARY ITEM PARTS & LABOR						
74940-TZ5-A01	BUZZER ASSYSMART	1	60.40	25	45.30	3.17	48.47
74646-T7A-010	COVERR R.FLOOR UN	1	120.70	25	90.52	6.34	96.86
	SUM PARTS:				135.82	9.51	145.33
	TOTAL SGD				135.82	9.51	145.33
	Total Payable (SGD)						145.33

Duplicate Item.

GST Amount is calculated from Individual line(s)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	8299J
Vehicle No.:	SLL8150S
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 DX CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4531895
Chassis No.:	JHMRU1810GX201894
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,880.00
Original Registration Date:	10 Mar 2017
First Registration Date:	10 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$14,880.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Mar 2027
PARF Rebate Amount:	\$11,160.00
COE Expiry Date:	09 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,430.00
COE Rebate Amount:	\$37,795.00
Total Rebate Amount:	\$48,955.00

The information contained herein is correct as at 15 Jul 2019

OK

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 23 April 2019 11:16 AM
To: assignments
Subject: RE: TPDS: SLL8150S (L) & SMD7780K (AXA) DOA: 20-04-2019@19.00PM

Hi

TP smart. Kindly assist.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

2.04pm@ 23/4/19
Any
vehicle not in
pls check liability

From: Ary Chua <arychua@honda.com.sg>
Sent: Monday, 22 April, 2019 6:33 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: TPDS: SLL8150S (L) & SMD7780K (AXA) DOA: 20-04-2019@19.00PM

Hi OIC-AXA,
Kindly Establish this case Liability Issue Before Arrange for Car Survey. Car Not In Ubi Bodyshop.
Our Client got Front Video Footage.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor **Kah Motor Co.Sdn.Bhd.** Address:15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg H/P:81006306 DID:68465673 Fax: 67480770



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Monday, 8 July 2019 9:26 AM
To: Ary Chua
Cc: Liew Thye Wui; Faeaz; Admin A; assignments
Subject: RE: TPDS: SLL8150S (L) & SMD7780K (AXA) DOA: 20-04-2019@19.00PM *** LKK
REF: CC4/ASM19007173/fa3

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC4/ASM19007173/fa3
Your Ref: SLL 8150S

Dear Sir/Madam,

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

In the meantime, kindly arrange TP survey ASAP.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 2/9/2019

Survey Details:

Date of loss	20-Apr-19
Date of appointment	23-Apr-19
Date of survey	15-Jul-19
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLL8150S
Make and Model	HONDA HRV 1.5 DX CVT
Date of registration	10-Mar-17
Parf Rebate	
Market Value	\$ 73,000.00
Parf Rebate	\$ 50,073.00
Nett Loss	\$ 22,927.00

Repair details:

Initial Estimate	\$ 14,366.51
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 2,591.79
Check items (estimate)	\$ -
Labour	\$ 8,200.00
Total	\$ 10,791.79
Lump Sum(if applicable)	\$ -

Number of days for repair	10.0
---------------------------	-------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

10 RECOMMENDED REPAIR DAYS + 1 PRS= 11 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 11,547.22	W/GST
Loss of use	\$ 550.00	11days x \$50
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ -	
Others	\$ -	
Proposed Total	\$ 12,097.22	



<MANDATE IA> - S9M01KY4 {ACCIDENT INVOLVING SMD 7780K(OI) & SLL 8150S(TP) ON 20/04/2019}

Type

🔔 Question

Message

LIABILITY: 100% BOLA S27: INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$12,097.22 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL / INSTRUCTION. THANKS - CECILIA

Reply



Re:<MANDATE IA> - S9M01KY4 {ACCIDENT INVOLVING SMD 7780K(OI) & SLL 8150S(TP) ON 20/04/2019}

Type

Question

Message

Proceed. Thanks

Reply



Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4

Singapore 408610

Tel : +65 6841 3838

Fax : +65 6748 0770

www.honda.com.sg

M/s **AXA Insurance Pte Ltd**
C/o LKK Auto Consultants Pte Ltd
8 Shenton Way
#27-01
Singapore 068811

Date:

29/8/19

Your ref: C4/ASM19007173/fa3

Our ref: SLL8150S

Attn: Motor Claims Department

Dear Sir / Madam,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SLL8150S AND SMD7780K ON 20.04.19

We refer to the items(s) marked (✓) below:

- (✓) We refer to LKK – Poh Kin's email dated 08.07.19
- (✓) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- (✓) Kindly forward the discharge voucher for our client's signature within 2 weeks via email to emillinliew@honda.com.sg or faeaz@honda.com.sg
- (✓) We return your discharge voucher duly completed.
- (✓) Kindly expedite settlement the following:-

Repair Cost	S\$11,547.19 payable to Kah Motor Co Sdn Bhd
Loss of Use	S\$50.00 X 11 Days = S\$550.00 payable to Tay Yong Seng
Rental	NIL
TP Search Bill	NIL
LTA Search Bill	NIL
- (✓) Kindly let us have your cheque made in favour of the above mentioned names(s) for our transmission as soon as possible.
- (✓) Letter of Authority

Thank you.

Yours faithfully,

Ary Chua

**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, SINGAPORE 408610

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer Code : CU0129734

Payment Term : 30 Days

Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Invoice No. : SINV-BS19001619
Invoice Date : 27/08/19
Order No. : SVO19044456
Reference :
Job Card No. : 73040
Date/Time Received : 15/07/19 / 2:54:53 PM
Licence No. : SLL8150S
Model : HRV DX-SIN CVT YM 2016
Car Chassis No. : JHMRU1810GX201894
Car Engine No. : L15B4531895
Mileage : 41244
Service Advisor : ARY CHUA WAI NGEE 1490A
Served By : ARYCHUA
Page : 1

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	Incl GST
	TP DIRECT SETTLEMENT (J/NO: 73040)							
	OWNER: TAY YONG SING							
	OWNER INSURER: LIBERTY INSURANCE PTE LTD							
	ACC DATE: 20-04-2019@19.00PM							
	ACC: CTE BESIDE AUSTRALIAN INT. SCH.EXIT10 (LP251)							
	SURVEYED BY: GuoQiang(LKK-AUTO) 15-07-2019@10.10am							
	REF NO: CC4/ASM19007173/FA3							
	TP INSURER: AXA INSURANCE S'PORE PTE LTD							
	TP VEH: SMD7780K HUNDAI/ELEANTRA/BLACK&WHITE							
BOSUN	0760 SUNDRIES	1	Hours	20.00		20.00	1.40	21.40
BOBC	EXT- YBH BODY UNDERSIDE COATING (N)	1	Hours	100.00		100.00	7.00	107.00
BOJSE	EXT- YJ BODY JOINT SEALANT.	1	Hours	100.00		100.00	7.00	107.00
BML02I	EXT- YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	Hours	120.00		120.00	8.40	128.40
BA02R	EXT- YJ REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	Hours	140.00		140.00	9.80	149.80
BP00R	EXT- YBH APPLY BODY UNDERSIDE COATING (N).	1	Hours	200.00		200.00	14.00	214.00
BC011R	0760 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	Hours	300.00		300.00	21.00	321.00
BC012R	0760 RESET VEHICLE SMART ENTRY SYSTEM	1	Hours	300.00		300.00	21.00	321.00
BMI03D	EXT- YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	Hours	300.00		300.00	21.00	321.00
BKTG02R	EXT- YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	Hours	450.00		450.00	31.50	481.50
BP06R	EXT- YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	Hours	2,250.00		2,250.00	157.50	2,407.50
BKRP02M	EXT- YJ CUT OFF & RENEW REAR END PANEL & FLOOR END PANEL FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	Hours	3,920.00		3,920.00	274.40	4,194.40
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	Each	60.00		60.00	4.20	64.20
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	Each	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	Each	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	Each	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	Each	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	Each	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	Each	5.30	25	7.95	0.56	8.51

Printed by ARYCHUA on 27 Aug 2019 at 5:18:29 PM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.
 Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.
 Interest will be charged at 2% per month on overdue amounts.

Please give us your feedback by scanning the QR Code using mobile device.



**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, SINGAPORE 408610

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer Code : CU0129734

Payment Term : 30 Days

Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Invoice No. : SINV-BS19001619
Invoice Date : 27/08/19
Order No. : SVO19044456
Reference :
Job Card No. : 73040
Date/Time Received : 15/07/19 / 2:54:53 PM
Licence No. : SLL8150S
Model : HRV DX-SIN CVT YM 2016
Car Chassis No. : JHMRU1810GX201894
Car Engine No. : L15B4531895
Mileage : 41244
Service Advisor : ARY CHUA WAI NGE 1490A
Served By : ARYCHUA
Page : 2

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	Incl GST
91536-SS0-J01	FASTENER AW/SHIELD	2	Each	3.80	25	5.70	0.40	6.10
04715-T7A-900ZZ	FACE,RR.BUMPER	1	Each	463.70	25	347.77	24.34	372.11
91505-TM8-003	CLIP,BUMPER	2	Each	2.30	25	3.45	0.24	3.69
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	1	Each	17.20	25	12.90	0.90	13.80
71598-T7A-000	SPACER,L.RR.BUMPER SIDE	1	Each	17.20	25	12.90	0.90	13.80
66100-T7A-300ZZ	PANEL COMPRR.	1	Each	373.10	25	279.82	19.59	299.41
65513-T7A-300ZZ	STIFFENERRR.JACK UP	1	Each	61.40	25	46.05	3.22	49.27
65770-T7J-H00ZZ	CROSSMEMBER COMPRR.FLOOR RR.	1	Each	147.60	25	110.70	7.75	118.45
04655-T7A-310ZZ	PANEL SETRR.FLOOR	1	Each	675.50	25	506.62	35.46	542.08
38387-TZ5-A11	ANTENNA ASSYL.F.	1	Each	61.40	25	46.05	3.22	49.27
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR	1	Each	189.80	25	142.35	9.96	152.31
84550-T7A-J00	BOX ASSY,CARGO FLOOR	1	Each	129.50	25	97.12	6.80	103.92
75722-T7W-A01	EMBLEMRR.	1	Each	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	Each	14.50	25	10.87	0.76	11.63
74800-T7A-J02	LOCK ASSYTAILGATE	1	Each	78.90	25	59.17	4.14	63.31
68100-T7A-J20ZZ	TAIL GATE COMP	1	Each	855.70	25	641.77	44.92	686.69
74940-TZ5-A01	BUZZER ASSYSMART	1	Each	60.40	25	45.30	3.17	48.47
74646-T7A-010	COVERR R.FLOOR UN	1	Each	120.70	25	90.52	6.34	96.86

Sum Labor	8,200.00	574.00	8,774.00
Sum Item	2,591.79	181.40	2,773.19
Total SGD	10,791.79	755.40	11,547.19
Total Payable (SGD)			11,547.19

Printed by ARYCHUA on 27 Aug 2019 at 5:18:29 PM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.
Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.
Interest will be charged at 2% per month on overdue amounts.

Please give us your
feedback by scanning
the QR Code using
mobile device.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19007173/Gga3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 22-10-2019



ATTN: KIAN CHUAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMD 7780K	Veh. Inspected	SLL 8150S
Policy No.	CN012027	Coverage (\$)	0.00
Claim No.	S9M01KY4	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	23/04/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA HRV 1.5	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMRU1810GX201894	Colour	WHITE
Odometer	041243	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/04/2019	Inspection Date	15/07/2019
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 8150S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	RUBBER CR.WINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	14.47	14.47
1	DAMPERSTD 5X5 (SN) (CONSISTENT)	NECESSARY	6.37	6.37
1	RUBBER CL.WINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	14.47	14.47
1	CAPPIVOT (SN) (CONSISTENT)	NECESSARY	3.60	3.60
4	FASTENER BW/SHIELD (SN) (CONSISTENT)	NECESSARY	15.90	15.90
2	FASTENER B (SN) (CONSISTENT)	NECESSARY	7.95	7.95
2	FASTENER AW/SHIELD (SN) (CONSISTENT)	NECESSARY	5.70	5.70
1	FACE RR.BUMPER (SN) (CONSISTENT)	DEFORMED	583.42	347.77
2	CLIP, BUMPER (SN) (CONSISTENT)	NECESSARY	3.45	3.45
1	SPACER,R.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	12.90	12.90
1	SPACER,L.RR.BPR S (SN) (CONSISTENT)	NECESSARY	12.90	12.90
1	FACER.RR.BUMPER CORNER (SN) (CONSISTENT)	NOT NECESSARY	70.57	-
1	FACEL.RR.BUMPER CORNER (SN) (CONSISTENT)	NOT NECESSARY	70.57	-
1	PANEL COMPRR. (SN) (CONSISTENT)	BUCKLED	279.82	279.82
1	STIFFENERRR.JACK UP (SN) (CONSISTENT)	BENT	46.05	46.05
1	CROSSMEMBER COMPRR.FLOOR (SN) (CONSISTENT)	BENT	110.70	110.70
1	PANEL SETRR.FLOOR (SN) (CONSISTENT)	BENT	506.62	506.62
1	GARNISH ASSYRR.LICENSE (SN) (CONSISTENT)	NOT NECESSARY	145.20	-
1	ANTENNA ASSYL.F. (SN) (CONSISTENT)	DAMAGED	46.05	46.05
1	BUZZER ASSYSMART (SN) (CONSISTENT)	DAMAGED	45.30	45.30
1	BOARD ASSYTRUNK FLOOR (SN) (CONSISTENT)	DEFORMED	142.35	142.35
1	BOX ASSY,CARGO FLOOR (SN) (CONSISTENT)	DEFORMED	97.12	97.12
1	EMBLEMRR. (SN) (CONSISTENT)	NECESSARY	9.97	9.97
1	EMBLEM,RR. I-VTEC (SN) (CONSISTENT)	NECESSARY	10.87	10.87
1	LINING ASSYRR.PANEL (SN) (CONSISTENT)	NOT NECESSARY	32.92	-
1	WEATHERSTRIP TALGATE (SN) (CONSISTENT)	NOT NECESSARY	74.02	-
1	LOCK ASSYTAILGATE (SN) (CONSISTENT)	BENT	59.17	59.17
1	TAIL GATE COMP (SN) (CONSISTENT)	BUCKLED	641.77	641.77
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	20.00
1	BODY JOINT SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	100.00

Report Ref No. CC4/ASM19007173/Gga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUZZER ASSYSMART (SN) (CONSISTENT) (ADDITIONAL)	REPEATED	45.30	-
1	COVERR R.FLOOR UN (SN) (CONSISTENT) (ADDITIONAL)	TORN	90.52	90.52
			3,466.02	2,711.79
	LABOUR			
	BODY UNDERSIDE COATING.		100.00	100.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		140.00	120.00
	REMOVE & RENEW REVERSE SENSORS.		160.00	140.00
	APPLY BODY UNDERSIDE COATING.		250.00	200.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		350.00	300.00
	RESET VEHICLE SMART ENTRY SYSTEM.		350.00	300.00
	TO REMOVE & INSTALL REAR COMPARTMENT LININGS.		450.00	300.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &.		550.00	450.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		2,800.00	2,250.00
	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN.		5,800.00	3,920.00
			10,950.00	8,080.00
	GRAND TOTAL		14,416.02	10,791.79
	RECOMMENDED COST OF REPAIRS			10,791.79

Report Ref No. CC4/ASM19007173/Gga3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.