

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

LKK Auto Survey

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLL8150S

Chassis No : JHMRU1810GX201894

Model : HRV DX-SIN CVT YM 2016

Owner's Name : TAY YONG SING

Ins Policy No. : SD19V02321/VPC2/R01

Date of Accident : 20/4/2019

Document No. : SQT19001789 Page 1

Date : 22. Apr 2019

Customer No. : WZA006

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15B4531895

Date | Time : 22. Apr 2019 2:54:53 PM

Surveyor Name : DID : +65 6846 5673

Survey Date : HP : +65 8109 6306

Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAY YONG SING OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 20-04-2019@19.00PM ACC: CTE BESIDE AUSTRALIAN INT. SCH.EXIT10 (L/P251) SURVEYED BY: REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SMD7780K HUNDAI/ELEANTRA/BLACK&WHITE						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
71501-T7B-000	FACE RR.BUMPER	1	777.90	25	583.42	40.84	624.26
91505-TM8-003	CLIP,BUMPER	2	2.30	25	3.45	0.24	3.69
71593-T7A-J00	SPACER,R.RR.BUMPER SIDE	1	17.20	25	12.90	0.90	13.80
71598-T7A-J00	SPACER,L.RR.BPR S	1	17.20	25	12.90	0.90	13.80
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	94.10	25	70.57	4.94	75.51
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	94.10	25	70.57	4.94	75.51
66100-T7A-300ZZ	PANEL COMPRR.	1	373.10	25	279.82	19.59	299.41
65513-T7A-300ZZ	STIFFENERRR.JACK UP	1	61.40	25	46.05	3.22	49.27
65750-T5B-300ZZ	CROSSMEMBER COMPRR.FLOOR	1	83.70	25	62.77	4.39	67.16
04655-T7A-310ZZ	PANEL SETRR.FLOOR	1	675.50	25	506.62	35.46	542.08
74890-T7A-J12ZC	GARNISH ASSYRR.LICENSE	1	193.60	25	145.20	10.16	155.36

Printed on 22/4/2019 6:29:22 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLL8150S
Chassis No : JHMRU1810GX201894
Model : HRV DX-SIN CVT YM 2016
Owner's Name : TAY YONG SING
Ins Policy No. : SD19V02321/VPC2/R01
Date of Accident : 20/4/2019

Document No. : SQT19001789
Date : 22. Apr 2019
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B4531895
Date | Time : 22. Apr 2019 2:54:53 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
38387-TZ5-A01	ANTENNA ASSYL.F. ? / DM	1	59.30	25	44.47	3.11	47.58
74940-TZ5-A01	BUZZER ASSYSMART ?	1	60.40	25	45.30	3.17	48.47
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR - RE	1	189.80	25	142.35	9.96	152.31
84550-T7A-J00	BOX ASSY,CARGO FLOOR - RE	1	129.50	25	97.12	6.80	103.92
75722-T7W-A01	EMBLEMRR. / SMC	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC - SMC	1	14.50	25	10.87	0.76	11.63
84640-T7A-J01ZA	LINING ASSYRR.PANEL ?	1	43.90	25	32.92	2.30	35.22
74440-T7A-003	WEATHERSTRIPTAILGATE ?	1	98.70	25	74.02	5.18	79.20
74800-T7A-J02	LOCK ASSYTAILGATE - NT	1	78.90	25	59.17	4.14	63.31
68100-T7A-J20ZZ	TAIL GATE COMP / BUC	1	855.70	25	641.77	44.92	686.69
Sum Item					3080.69	215.61	3,296.30
BOSUN	SUNDRIES	1	100.00	20	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	/	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00	/	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00	120	140.00	9.80	149.80
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00	140	160.00	11.20	171.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	200	250.00	17.50	267.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	350.00	300	350.00	24.50	374.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	350.00	300	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	300	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	550.00	450	550.00	38.50	588.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1450	2800.00	2250	2800.00	196.00	2996.00
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1500	5800.00	3920	5800.00	406.00	6206.00
Sum Labor					11150.00	780.50	11,930.50

Survey By _____

Printed on 22/4/2019 6:29:22 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLL8150S
Chassis No : JHMRU1810GX201894
Model : HRV DX-SIN CVT YM 2016
Owner's Name : TAY YONG SING
Ins Policy No. : SD19V02321/PC2/R01
Date of Accident : 20/4/2019

Document No. : SQT19001789
Date : 22. Apr 2019
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B4531895
Date | Time : 22. Apr 2019 2:54:53 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Total Amount					14,230.69	996.11	15,226.80
Total (Inclusive of GST)							<u>15,226.80</u>
Date & Time							
Excess							
Status							
Signature							

10 Days.

before paint photos

Quo Qian - 82880282

15/7/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 22/4/2019 6:29:22 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.