

## ASSIGNMENT

Steve

DOI:

19/5/19

Date / Time:

24/4/19

Registered in Merimen:

24/4/19

210-180/100/UCU/ETE



Insured Vehicle No.:

SLV 9709Y

Name of Insured:

TIN TAN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

20/04/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLG 4384L



INSRS:

WSP:

Tel:

Liability:

RMKS:

pm



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

26/4

at 1

SLG 4384L - X

SLV 9709Y - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

20th 29/4/19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: CRY

Repair Cost:

PP \$30,754.05

(14 days) Reduction:

%

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with (ABOVE)

Email ☒ Call ☐

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

w/165 \$320,306.83

Loss of Rental (LOR): w/165

\$94.60

(14 days) x 80

Loss of Use (LOU):

\$0

(3 x days)

Loss of Income (LOI):

\$0

(3 x days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$0

Medical:

\$0

Disbursement:

\$0

(e.g. Tow/ Independent)

Legal Cost:

\$0

Total:

\$33,448.43

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with: CRY

Email ☒ Call ☐

Payee 1:

\$33,448.43

Name 1:

PERFORMANCE MODELS LIMITED

Payee 2 (if any):

\$94.60

Name 2:

BORN RENT A CAR PTE LTD

Payee 3 (if any):

\$0

Name 3:

Steve

REF: AIG

## ASSIGNMENT

From:

Date:

11/5/19

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLG 4384L

at Workshop no:

Performance

of:

303 Alexander Road

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Before 12pm  
Intuition

(Policy Condition)

Remarks: The veh had commenced its  
repair at the time of inspection.

Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

A

days

Res: Yes or No

Lump Sum:

-

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS <sup>1up</sup>

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLG 4384L

Vr Design:

30/9/16

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 218i Coupe

CC:

1499

Colour:

White

ABC: Insured / Std / NI / NA

Op. Reading:

26041

T/Rader: Insured / Std / NI / NA

Eng No:

C/Nr:

WBA2F/2969V75F323

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

OS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal:

7

mm

Rear

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A:

20/4/19

D.O.A:

14/5/19

Survey held at:

Performance

Des. of Damages: Frl / Rear / ☒ O/S / W/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-149K

PIP: +20,754.05 (RED: +1,816.95 87%)

Date/Time, File Refers to?

☐

: Prel. Report

If:

☐

: Final Report

Date/Time, File Refers to?

21

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / L.B.I. (\$

Survey Fee:

Transportation:

) S + H.S. of

) Check:

) Others:

TOTAL

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7545Z
<b>Vehicle Details</b>	
Vehicle No.:	SLG4384L
Vehicle to be Exported:	No
Intended Deregistration Date:	14 May 2019
Vehicle Make:	B.M.W.
Vehicle Model:	218i COUPE AT HID ABS NAV SR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	F1611442B38B15A
Chassis No.:	WBA2F12060V758323
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$26,822.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$24,551.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2026
PARF Rebate Amount:	\$18,413.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Sep 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,956.00
COE Rebate Amount:	\$41,668.00
<b>Total Rebate Amount:</b>	<b>\$60,081.00</b>

The information contained herein is correct as at 14 May 2019

OK

## Performance Motors Limited

A Bime Darby Motors Company  
Co. Reg. No. 197401589W GST Reg. No. M2-0020081-x  
Toll-Free Number (1800-2255269)

103, Alexandra Road  
Sine Darby Performance Centre  
Singapore 159941  
Fax: 64747770

180, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63445773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

24 APR 2019

## ESTIMATE

Estimate No. : b1 50962 Page No. : 1 of 5  
Date Estimated : 24/04/2019  
Prepared By : Inthiran A/L Thurasamy

<p>- ESTIMATE REPAIR FOR -</p> <p>Cheng Suet Lai, Elaine (Zeng XueLi, Els</p> <p>Apt Blk 916 Tampines Street 91</p> <p>#03-79</p> <p>Singapore 520916</p>	<p>- ACCOUNT - 121</p> <p>AIG Asia Pacific Insurance Pte. Ltd.</p> <p>78 Shenton Way</p> <p>#08-16 Chartis Building</p> <p>Singapore 079120</p>
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLG4384L	V758323	30/09/2016	218iA/2	0

DESCRIPTION	VALUE
To replace rear right fender, right door, side sill right, 8 d <sub>g</sub> attachments and repair rear bumper including knocking on area cause by accident. <i>850</i>	<i>6800</i> ✓ 7,650.00
Painting rear bumper, rear right fender, right door, side sill, tail panel and trunk floor, <i>742</i> RH DOOR TRIM AND RH C/PANEL <i>511</i>	<i>4417</i> ✓ <i>549</i> 4,908.00
To replace tyre and wheel rim including balancing. (1x).	<i>80</i> ✓ 94.00
To check steering geometry and conduct wheel alignment according to BMW specification (1x)	<i>451</i> ✓ 531.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).	<i>451</i> ✓ 531.00
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	<i>742</i> ✓ 873.00
To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests. <i>(photo)</i>	<i>451</i> ✓ 531.00
To remove and install fuse box at the rear section to facilitate repairs. <i>(photo)</i>	<i>451</i> ✓ 531.00
To carry out body cavity preservation. (Per panel).	<i>100</i> ✓ 118.00
To carry out body cavity preservation. (For cut panel).	<i>451</i> ✓ 531.00

Total Labour 1:	16.298.00
-----------------	-----------

DESCRIPTION	QTY	PRIC	VALUE
PLASTIC NUT FOR COARSE THREADED PIN <i>X AEE 1/4"</i>	8	0.80	6.40

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401359M GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64787770

380, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64786601 (AfterSales)  
64786624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 50962  
Date Estimated : 24/04/2019  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLG4384L	V758323	30/09/2016	218iA/2	0

## DESCRIPTION

REAR RH SIDE PANEL *DD*  
Reinforcemen *X ALK*  
Reinforcemen *X ALK*  
Reinforcemen *X ALK*  
FRT RH DOOR *DD*  
RH SIDE GUIDE FOR BUMPER *X ALK*  
PLASTIC NUT *X ALK*  
FRT RH DOOR EDGE PROTECTION *X ALK*  
RH SILL STRIP PRIMED *X ALK*  
CAVITY PROTECTION WAX REMOVER 500ML *X ALK*  
BLIND RIVET AVIBVLB *X ALK*  
SCREW (SF PLUS M5X15) *X ALK*  
(DG/SL) BODY ADHESIVE K5B (195ML) *X ALK*  
PUNCH RIVET N5 *X ALK*  
(DG) BODYWORK ADHESIVE K5A (50ML) *X ALK*  
(DG) CLEANER R1 (100ML) *X ALK*  
PUNCH RIVET N4 *X ALK*  
(S/L) SEAM SEAL 300ML *X ALK*

QTY	PRIC	VALUE
1	1,352.55	1,352.55
1	52.90	52.90
1	52.40	52.40
1	68.00	68.00
1	1,346.70	1,346.70
1	49.05	49.05
5	0.85	4.25
1	152.50	152.50
1	277.35	277.35
1	18.45	18.45
15	0.55	8.25
5	0.55	2.75
1	326.80	326.80
20	0.55	11.00
1	112.70	112.70
1	26.15	26.15
10	0.55	5.50
1	33.80	33.80

Total Parts : 3,907.50

(Supp) Alloy wheel R. for CUT / 2950.70

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	16,298.00
Parts	:	3,907.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,414.39
Grand Total	:	21,619.89

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Silver Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M3-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 50962  
Date Estimated : 24/04/2019  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Cheng Suet Lai, Elaine (Zeng XueLi, Ela  
Apt Blk 916 Tampines Street 91  
#03-79  
Singapore 520916

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLG4384L	V758323	30/09/2016	2181A/2	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To remove and install rear RH fender fixed window glass to facilitate repairs and conducting water leak tests	413.00		413.00	/
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00	/
# To check electrical wiring system and lightings at the rear section include resetting and checking air bags for function	250.00		250.00	/

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT • / APC	0.60	2.00		1.20
# EXPANDING NUT • / APC	0.60	1.00		0.60
# EXPANDING NUT • / APC	2.00	3.00		6.00
# SNAP LOCK COUPLING • / APC	3.65	1.00		3.65
# FRT LH DOOR BRAKE • / APC (hand type)	71.00	1.00		71.00
# TORX-BOLT WITH WASHER • / APC	1.40	2.00		2.80
# HOOK AND LOOP FASTENER • / APC	2.85	3.00		8.55
# PLUG IN NUT 0.8MM • / APC	1.40	2.00		2.80
# EXPANDING NUT (4.8) • / APC	1.00	3.00		3.00
# TYPE IDENTIFICATION PLATE (CODED) • / APC	29.30	1.00		29.30
# LABEL TIRE PRESSURE • / APC	24.40	1.00		24.40

Total Labour : 894.00  
Total Parts : 153.30  
Total Labour & Parts : 1,047.30



## FINAL REPORT

Estimate No. : b1 50962  
Date Estimated : 24/04/2019  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Cheng Suet Lai, Elaine (Zeng XueLi, Ela  
Apt Blk 916 Tampines Street 91  
#03-79  
Singapore 520916

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLG4384L	V758323	30/09/2016	218iA/2	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, rear RH door and attachments, rear RH fender, RH side skirting include making good the tail end panel, trunk floor panel, RH roof frame, RH 'C' pillar and knocking out dents caused by the accident	6800.00		6,800.00	
* To spray paint rear bumper, rear RH fender, front RH door, RH side skirting, tail end panel, trunk floor panel, RH roof frame and RH 'C' pillar	5149.00		5,149.00	
To replace wheel rim include balancing (1x)	80.00		80.00	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00	
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (1x)	451.00		451.00	
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs	742.00		742.00	
To remove and install fuel tank to facilitate repairs include extracting fuel and conducting leak tests	451.00		451.00	
To remove and install fuse box at the rear section to facilitate repairs	451.00		451.00	
To carry out body cavity preservation (Per panel)	100.00		100.00	
To carry out body cavity preservation (For cut panel)	451.00		451.00	
# To remove and install rear RH fender fixed window glass to facilitate repairs and conducting water leak tests	413.00		413.00	
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00	



## FINAL REPORT

# To check electrical wiring system and lightings at the rear section include resetting and checking air bags for function	250.00	250.00 /
Sundries	150.00	150.00 /

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	0.60	2.00		1.20 /
# EXPANDING NUT *	0.60	1.00		0.60 /
# EXPANDING NUT *	2.00	3.00		6.00 /
# SNAP LOCK COUPLING *	3.65	1.00		3.65 /
ALLOY RIM 7.5JX17 STAR SPOKE 379	921.70	1.00		921.70 /
REAR RH SIDE PANEL	1,352.55	1.00		1,352.55 /
FRT RH DOOR	1,346.70	1.00		1,346.70 /
# FRT LH DOOR BRAKE *	71.00	1.00		71.00 /
# TORX-BOLT WITH WASHER *	1.40	2.00		2.80 /
# HOOK AND LOOP FASTENER *	2.85	3.00		8.55 /
# PLUG IN NUT 0.8MM *	1.40	2.00		2.80 /
RH SILL STRIP PRIMED	277.35	1.00		277.35 /
# EXPANDING NUT (4.8) *	1.00	3.00		3.00 /
# TYPE IDENTIFICATION PLATE (CODED) *	29.30	1.00		29.30 /
# LABEL TIRE PRESSURE *	24.40	1.00		24.40 /
BLIND RIVET AVIBVLB	0.55	20.00		11.00 /
SCREW (SF PLUS M5X15)	0.55	10.00		5.50 /
(DG/SL) BODY ADHESIVE K5B (195ML)	326.80	1.00		326.80 /
PUNCH RIVET N5	0.55	20.00		11.00 /
PUNCH RIVET N4	0.55	10.00		5.50 /
(DG) BODYWORK ADHESIVE K5A (50ML)	112.70	1.00		112.70 /
(DG) CLEANER R1 (100ML)	26.15	1.00		26.15 /
(S/L) SEAM SEAL 300ML	33.80	1.00		33.80 /

### # SUPPLEMENTARY ITEMS

Total Labour :	16,170.00
Total Parts :	4,584.05
Total Labour & Parts :	20,754.05 /
Deduction for Excess :	0.00
Total Repair Costs less Excess:	20,754.05
GST @7%:	1,452.78
Grand Total :	22,206.83

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Monday, 29 April 2019 10:56 AM  
**To:** PBSP  
**Cc:** CS A Team; Admin A; assignments  
**Subject:** RE: REQUEST FOR DIRECT SETTLEMENT - SLG4384L & SLV9709Y ON 20/04/2019 \*\*\*  
LKK REF: CC3/AIG19007180/pa3

### Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

**\*\*Kindly arrange for survey.**

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Monday, 29 April 2019 10:37 AM  
**To:** Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>  
**Cc:** CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; assignments <assignments@lkkauto.com>

**Subject:** Re: REQUEST FOR DIRECT SETTLEMENT - SLG4384L & SLV9709Y ON 20/04/2019 \*\*\* LKK REF: CC3/AIG19007180/pa3

Dear Sirs,

Kindly reply on liability.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

**Sent:** Wednesday, 24 April 2019 10:22:07 AM

**To:** PBSP

**Cc:** CS A Team; 甯珺 ©; Hsiao Tong (LKKAuto); assignments

**Subject:** RE: REQUEST FOR DIRECT SETTLEMENT - SLG4384L & SLV9709Y ON 20/04/2019 \*\*\* LKK REF: CC3/AIG19007180/pa3

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear Caroline,

We refer to the above matter.

Please be informed that we are currently **pending for our principal to release OI GIA report.**

Kindly note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

***Meanwhile, please arrange appointment for survey.***

***To check availability of the case handler, you may contact the undersigned.***

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** PBSP <pml-pbsp@sime-darby.com.sg>  
**Sent:** Wednesday, 24 April, 2019 8:41 AM  
**To:** CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** REQUEST FOR DIRECT SETTLEMENT - SLG4384L & SLV9709Y ON 20/04/2019

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Friday, 2 August 2019 4:42 PM  
**To:** Loh, Chee-Heng  
**Subject:** [MANDATE REQUEST] Your ref : 3790291274SG, ACCIDENT ON 20/04/2019 INVOLVING SLV 9709Y (OI) & SLG 4384L (TP)

Your ref : **3790291274SG**  
Our ref : CC3/AIG19007180/Eea3

Dear Sirs,

### **ACCIDENT ON 20/04/2019 INVOLVING SLV 9709Y (OI) & SLG 4384L (TP)**

We refer to the above matter.

The accident occurred when our insured exit from the parking lot and hit third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer " **PERFORMANCE MOTORS LTD**" at **\$ 23,148.43 (all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 24,150.97	\$ 22,206.83
2. Loss of Rental (11days x \$80)	\$ 941.60	\$ 941.60 (11days x \$80) (BKW RENTAL)
Total	\$ 25,092.57	<b><u>\$ 23,148.43</u></b>

**For your approval in merimen please.**

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Print Received Message

This mail is associated with :

**\*SLG4384L (3790291274SG)**  
**[SLV9709Y]**

TP

CHENG SUET LAI ELAINE

Apr 20 2019 3:00PM

[TIN TUN]

Performance Motors Limited

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 05/08/2019 17:23 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$23148.43) - SLG4384L - Claim Handler: Loh, Chee-Heng

Approved:23148.43.



# CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 ■ Road Transport Act, 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VPA/P1991251 Account No. : 13854  
Coverage : Comprehensive  
Sum Insured : Market Value At The Time Of Loss  
Name of Policy Holder : CHENG SUET LAI ELAINE (ZENG XUELI ELAINE)  
Vehicle Registration No. : SLG4384L  
Period of Insurance : From 30/09/2018 To 29/09/2019 (Both Dates Inclusive)

## PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE\*

- (a) The Policyholder  
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner  
(b) Any other person who is driving on the Policyholder's order or with his permission  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

## LIMITATIONS AS TO USE\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess : SGD 600.00

An Additional Excess is applicable as follows:

S\$500.00 for Unnamed Authorized Driver &/or Declared Young & Inexperienced Driver.

S\$5,000.00 for Undeclared Young and Inexperienced Driver.

(Please refer to your policy on the terms & conditions)

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOVKRS on 10/09/2018

### IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Member **S7927545Z**

Name  
**CHENG SUET LAI, ELAINE**  
(ZENG XUELI, ELAINE)

Birth Date: 09 Sep 1979  
Issue Date: 18 Feb 2016

002538723H



REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. **S7927545Z**



Name

**CHENG SUET LAI, ELAINE**  
(ZENG XUELI, ELAINE)

曾雪麗

Race

**CHINESE**

Date of birth

**09-09-1979 F**

Country of birth

**SINGAPORE**

S7927645Z

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight  $\leq$  3000kg with  $\leq$  7 passengers, exclusive of driver; and other motor vehicles with unladen weight  $\leq$  2500kg 23 Sep 1998

NP 429A



Licence No: S7927545Z



448546

NRIC No: **S7927545Z**



Date of issue

**22-09-2009**

Address

**APT BLK 916 TAMPINES STREET 91**  
**#03-79**  
**SINGAPORE 520916**

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1<sup>ST</sup> JUNE 2008  
(PAYMENT BREAKDOWN)**

<b>Vehicle No:</b>	SLG4384L	<b>Model:</b>	BMW 718 i Coupe
<b>Date of Accident:</b>	20.04.2019		

<b>Global Sum Settlement:</b>	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	: \$	21,619.89	
Final Repair Cost	: \$	22,206.83	
Loss of Use	: \$	--	days at \$ per day
Rental (if any)	: \$	-- K BPW	days
LTA / GIA Search Fee	: \$	--	
Others	: \$	--	
	: \$	--	
Final Settlement Sum	: \$	22,206.83	

<b>Is Third Party Workshop GIA Registered?</b> <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Application: <input checked="" type="checkbox"/> Yes / No <input type="checkbox"/> No 24
	BOLA Scenario No: _____
BOLA Liability: <u>100</u> (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown			
1)	Performance Motor Limited	: \$	22,206.83
2)		: \$	
3)		: \$	


  
 Signed by appointed surveyor

  
 Date

**Please attach all the supporting documents to the form.**  
**Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;**  
**Survey Report; Medical Report / Bill (if any)**



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19007180/pa3

09 MAY 2019

**TIN TUN**

914 TAMPINES STREET 91

#06-33

SINGAPORE 520914

Dear Sir/Madam,

**ACCIDENT INVOLVING SLV 9709Y & SLG 4384L ALONG/AT CARPARK BLK 914  
TAMPINES ST 91 ON 20/04/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLG 4384L against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your driver's favour as your vehicle reversing out from parking lot and collided with third party who driving straight. Under Motor Accident Guide, Vehicle reversing in/out or moving in/out of parking lot should exercise greater caution. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

**CHEW HSIAO TONG**

Case Handler

DID: 6742 3197

FAX: 6741 4108

Email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)*


**AUTHORIZATION TO ACT**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

I, Chang Suet Lai Elaine ("the third party claimant")  
of Blk 916 Tampines S+91 #03-79 S(520916) (address),  
owner of SLG4384L (vehicle no.) hereby authorize  
*Performance Motors Ltd*  
("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SLG4384L that was  
damaged pursuant to the accident which occurred on 20/4/19 (date) along  
Block 914 Tampines S+91 (location)  
involving vehicle no/s SLV9701Y ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment further to settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 14 day of 05 (month) 20 19 (year)

  
Signed by "the third party claimant"

  
Signed by "the workshop"

Stamp: AIG Asia Pacific Insurance Co. Ltd, Singapore

**RELEASE VOUCHER**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 22,206.83 (repair costs), S\$ 941.60 (loss of use/rental) S\$ - (search fees) for vehicle no. SLG4384L that was damaged pursuant to the accident which occurred on 20/4/19 (date) along Block 914 Tampines St 91 (location) involving vehicle no/s SLV9709Y.

This is pursuant to the inspection conducted on 14/5/19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Cheng Suet Lai Elaine ("third party claimant") of vehicle no. SLG4384L to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLG4384L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 27 day of 08 (month) 20 19 (year)



*chy*

Signed by AIG appointed surveyor

*[Signature]*  
Chopped & Signed by "the workshop"





303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438190  
Tel. 63190888 (AfterSales)  
Fax. 63449773

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190538 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

Asheer

**SERVICE TAX INVOICE**Repair Order No. : **B1 1361950**Date IN : **14/05/2019**Motor Claim Advisor: **Inthiran A/L Thurasamy**Page No. : **1 of 3**Invoice Number : **2118921 / WSB**Invoice Date : **04/07/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Toh Jing Xuan****- CUSTOMER INFORMATION -**

**Ms Cheng Suet Lai, Elaine (Zeng XueLi, E)**  
**Apt Blk 916 Tampines Street 91**  
**#03-79**

Singapore 520916

**- INVOICE TO - 121**

**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO.  
**SLG4384L**

CHASSIS NO.  
**V758323**

REGN. DATE  
**30/09/2016**

MODEL  
**218IA/2**

MILEAGE  
**26041**

**- - - - LABOUR 1 - - - -****NETT**

To replace rear bumper and attachments, rear right door  
and attachments, rear right fender, right side skirting  
including make good the tail end panel,

**6,800.00**

trunk floor panel, right roof frame, right 'C' pillar and knock out  
dented area caused by the accident.

To respray rear bumper, rear right fender, front right  
door, right side skirting, tail end panel, trunk floor  
panel, right roof frame and right 'C' pillar.

**5,149.00**

To replace right rear wheel rim including balancing.

**80.00**

To check steering geometry and conduct wheel alignment in  
accordance with BMW specifications.

**451.00**

To transfer lock mechanism from old to new door including  
conduct checks on new door power window system for proper  
function. (1 door).

**451.00**

To remove and install rear hat-tray, rear seat, carpet  
and roof top lining to facilitate repairs.

**742.00**

To remove and install fuel tank to facilitate repairs  
including extract fuel and conduct leak tests.

**451.00**

To remove and install fuse box at the rear section to  
facilitate repairs.

**451.00**

To carry out body cavity preservation.  
(Per panel).

**100.00**

To carry out body cavity preservation.  
(For cut panel).

**451.00**

To remove and install rear right fender fixed window  
glass to facilitate repairs and conduct water leak tests.

**413.00**

To remove and install boot compartment carpet and garnish  
to facilitate repairs.

**231.00**

To check electrical wiring systems and lightings at the  
rear section including reset and check air bags for  
function.

**250.00**

Sundries.

**150.00**

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

**0.00**

DATE OF ACCIDENT : 20.04.2019. 3RD PARTY CAR : SLV9709Y.

YOUR REF NO : NIL.

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

380, Kampong Arang Road  
East Coast Centre  
Singapore 439180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : B1 1361950

Page No. : 2 of 3

Date IN : 14/05/2019

Invoice Number : 2118921 / WSB

Invoice Date : 04/07/2019

Motor Claim Advisor: Inthiran A/L Thurasamy

Payment Terms : 30 Days From Invoice

Invoice By : Toh Jing Xuan

VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK AUTO  
ON 14.05.2019 AT 12PM. AUTHORISED REPAIR BY MS CHEW  
HSIAO TONG FROM LKK AUTO ON 29.04.2019 VIA EMAIL.  
COURTESY CAR PROVIDED BY BKW.

0.00

Total Labour 1: 16,170.00

- - - - P A R T S - - - -		Retail		NETT
	Qty	Price		
BLIND RIVET AVIBVLB	20	0.55		11.00
SCREW (SF PLUS M5X15)	10	0.55		5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	1	326.80		326.80
PUNCH RIVET N5	20	0.55		11.00
(DG) BODYWORK ADHESIVE K5A (50ML)	1	112.70		112.70
(DG) CLEANER R1 (100ML)	1	26.15		26.15
PUNCH RIVET N4	10	0.55		5.50
(S/L) SEAM SEAL 300ML	1	33.80		33.80
REAR RH SIDE PANEL	1	1,352.55		1,352.55
FRT RH DOOR	1	1,346.70		1,346.70
ALLOY RIM 7.5JX17 STAR SPOKE 379	1	921.70		921.70
EXPANDING NUT	2	0.60		1.20
EXPANDING NUT (4.8)	3	1.00		3.00
EXPANDING NUT	3	2.00		6.00
PLUG IN NUT 0.8MM	2	1.40		2.80
TORX-BOLT WITH WASHER	2	1.40		2.80
FRT LH DOOR BRAKE	1	71.00		71.00
RH SILL STRIP PRIMED	1	277.35		277.35
HOOK AND LOOP FASTENER	3	2.85		8.55
SNAP LOCK COUPLING	1	3.65		3.65
EXPANDING NUT	1	0.60		0.60
TYPE IDENTIFICATION PLATE (CODED)	1	29.30		29.30
LABEL TIRE PRESSURE	1	24.40		24.40
Total Parts :				4,584.05

- - - - L A B O U R 2 - - - -

NETT

0.00

Total Labour 2: 0.00



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

288, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel: 63190888 (AfterSales)  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel: 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax: 64794601 (AfterSales)  
64794624 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1361950</b>	Page No. : <b>3 of 3</b>
Date IN : <b>14/05/2019</b>	Invoice Number : <b>2118921 / WSB</b>
Motor Claim Advisor: <b>Inthiran A/L Thurasamy</b>	Invoice Date : <b>04/07/2019</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Toh Jing Xuan</b>

Labour Charges : <b>16,020.00</b>	Total Labour & Parts Charges : <b>S\$ 20,754.05</b>
Parts Charges : <b>4,584.05</b>	Less Insurance Excess : <b>S\$ 0.00</b>
Lubricant/Misc : <b>150.00</b>	Invoice Total Amount Exclude GST : <b>S\$ 20,754.05</b>
	GST @ 7% : <b>S\$ 1,452.78</b>
	Invoice Total Amount Include GST : <b>S\$ 22,206.83</b>

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 22,206.83**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



**TAX INVOICE**

GST REG. NO.: 200106276D

INVOICE TO
AIG ASIA PACIFIC INSURANCE PTE. LTD. 78 SHENTON WAY #07-16 SINGAPORE 079120 ATTN: CLAIMS DEPARTMENT C/O LKK AUTO CONSULTANT PTE LTD

DATE	INVOICE NO.
27-May-2019	P 2506

		VHA NO.	DUE DATE	VEH. NO.
		P 2506	27-May-2019	SLL 5259 H
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT	
RENTAL FROM 14 MAY 2019 TO 25 MAY 2019 (INCLUDED TWO SATURDAY, ONE SUNDAY AND ONE PUBLIC HOLIDAY) YOUR REF: SLG4384L & SLV9709Y (PERFOMANCE)	11	80.00	880.00	
GST @ 7%			\$61.60	
<b>TOTAL</b>			\$941.60	

*All cheques must be made payable to BKW Rent A Car Pte Ltd.  
Please write the vehicle and invoice number on the reserve.*

## HIRER'S PARTICULARS

Name (as in IC) **CHENG SUE TLAH ELAINE**  
 NRIC/Passport No: **S7927545Z** Date of Birth: **09 Sep 1979**  
 Address: **BK 916 TAMPAKES ST 91 Age: 39**  
**#03-79 S520916**  
 Name & Address of Employer: \_\_\_\_\_  
 Occupation: \_\_\_\_\_ Driving Exp: **19**  
 Driving Licence No: **S7927545Z** Passed Date: **23 Sep 1999**  
 D/L Type: Local/Int'l/Others: \_\_\_\_\_  
 Tel(O) \_\_\_\_\_ (R) \_\_\_\_\_ HP **98555357**


## DRIVER'S PARTICULARS

Name (as in IC) \_\_\_\_\_  
 NRIC/Passport No: \_\_\_\_\_ Date of Birth: \_\_\_\_\_  
 Address: \_\_\_\_\_ Age: \_\_\_\_\_  
 \_\_\_\_\_ S( ) \_\_\_\_\_  
 Occupation: \_\_\_\_\_ Driving Exp: \_\_\_\_\_ Yrs  
 Driving Licence No: \_\_\_\_\_ Passed / Expiry Date: \_\_\_\_\_  
 D/L Type: Local/Int'l/Others: \_\_\_\_\_ Contact No: \_\_\_\_\_

With  
Front  
Camera

### INDICATE:

A - Accidents  
 D - Dents  
 S - Scratches  
 X - Crack



Hirer's Own Vehicle No: **SLG4384** Replace Veh No: \_\_\_\_\_  
 Loan Vehicle No: **SL5259H** VR No: \_\_\_\_\_  
 Make & Model: **VW JETTA** Auto/Manual Group: **Auto**  

CHARGES		:	\$	cts	
Daily	<b>11</b> day	@ \$	<b>80</b>	Per day	<b>880</b> <b>00</b>
Weekly/Monthly	week	@ \$		Per week/Monthly	
Others					
CDW/PAI	@ \$			Per day/Monthly	
Delivery/Collection Svc					
GST					
OR No: _____ (A) SUB-TOTAL					
Petrol Level & Surcharge	OUT	E	1/4	1/2	3/4
	IN				
First _____ km FREE per day				GST	<b>7%</b> <b>61</b> <b>60</b>
Excess mileage is chargeable at _____ cents per km				TOTAL CHARGES	<b>941</b> <b>60</b>

Security Deposit : \$ \_\_\_\_\_ Bank: **UOB**  
 CASH/NET/ISA/MC/AMEX/CHQ No: **4265 8840 3532 339**  
 Expiry Date: **12/23** Card ID No: **990**  
 Name as in Card: **ELAINE CHENG**

NON WAIVER EXCESS (Subject to GST) \$ **2000**

### ACCESSORIES CHECK

☐ Data Cards ☐ Camera Systems ☐ Hub Cap ☐ Radio / CD Cartridge  
☐ Jack ☐ Tyre Opener ☐ Petrol Cap ☐ Spare Tyre

Hirer's Signature: \_\_\_\_\_

Additional Driver's Signature: \_\_\_\_\_

SINGAPORE Use Only

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given BKW Rent A Car Pte Ltd in connection with this agreement is true.

### IMPORTANT

- The Hirer and the authorized driver must be over 23 years of age and under 65 years and be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be borne by the Hirer/the Authorised Driver.
- All vehicles are supplied with petrol and should returned with petrol level likewise. A service charge of \$5 on top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level.
- No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day, inclusive of CDW and/or PAI where applicable. Any returns after our operation hours will be charged as a full day rental.
- Use of the vehicle for illegal purpose (For instance, in connection with theft, drug peddling or trafficking, smuggling) is strictly prohibited.
- Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of BKW Rent A Car Pte Ltd. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
- The hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
- The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expenses (including

- legal costs on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amount have to be paid immediately in the event of an accident. The owner reserve the right not to replace an replacement vehicle if an accident occurred. Any damage to the car will be repair at BKW authorized workshop.
- Smoke or permit smoking and transport of pet in the vehicle are not allowed. Any offensive smell e.g. cigarette, durian or pet's smell, the hirer and/or driver shall bear the cost of removing the offensive smell or pet's hair between \$200 - \$400.
- The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such responses at \$50.00 per trip.
- In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to borne all liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
- The hirer/Driver also have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is stall and does not have sufficient water. Any damage to the engine will be bear by the hirer/driver.
- All customers' data will be kept strictly confidential and is solely used for the purpose of completing the sales transactions and other relating matters.
- I understand and agree to the personal data collection statement stated on the Terms and Conditions Page.

Date Out	Time Out	Mileage	Check By	Remarks
<b>14/05/19</b>	<b>1100</b>	<b>38475</b>	<b>NIK</b>	<b>Whtapp Screenshot</b>

Return Of Vehicle: The Hirer Driver Is Required To Sign In The Column Signature Of Hirer/Driver Filling Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To BKW Rent A Car Pte Ltd And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupons, etc)

Date In	Time In	Mileage	Check By	Remarks
<b>25.05.19</b>	<b>11.30</b>	<b>37691</b>	<b>PEN L</b>	<b>Check in 25/5/19</b>

Hirer's/Driver Signature

Signature of Customer

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Apr 2019 <a href="#">Edit Reg</a>		14 May 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$20,754.05</b> <a href="#">Edit Estimates</a>	<b>S\$20,754.05</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>TIN TUN</b> , ID: S26942811									
Main Claimant: <b>CHENG SUET LAI ELAINE</b> , ID: S7927545Z									
Vehicle Reg. No.:	<b>SLG4384L</b>	Date of Loss:	20/04/2019 15:00 - :59 [30 Months and 21 Days From LTA Reg. Date (Man Yr)]						
Claim Type:	<b>TP / 3790291274SG</b>	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLV9709Y</b>	Policy No. (Claimant):	P1991251						
Excess:									
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loh, Chee-Heng</b> ] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Final Rpt due 06/05/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG_EXPRESS (05/08/2019): Alert - Adj Mandate Approved (S\$23148.43) - SLG4384L - Claim Handler: Loh, Chee-...									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLG4384L (37902912745G)  
[SLV9709Y]

TP

CHENG SUET LAI ELAINE

Apr 20 2019 3:00PM

[TIN TUN]

Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown															Edit			
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
2	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
3	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
4	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
5	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
6	14/05/19 19:14	Odometer Reading															Load JPG <input checked="" type="checkbox"/>			
7	14/05/19 19:14	Chassis Number															Load JPG <input checked="" type="checkbox"/>			
8	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
9	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
10	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
11	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
12	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
13	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
14	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
15	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
16	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
17	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
18	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
19	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
20	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
21	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
22	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
23	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
24	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
25	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
26	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
27	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
28	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
29	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
30	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
31	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
32	14/05/19 19:14	General View															Load JPG <input checked="" type="checkbox"/>			
33	23/05/19 08:55	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			
34	23/05/19 08:55	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			
35	23/05/19 08:55	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			
36	23/05/19 08:55	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			
37	23/05/19 08:55	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			
38	23/05/19 08:55	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			
39	23/05/19 08:55	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			
40	23/05/19 08:55	Reinspection Photo															Load JPG <input checked="" type="checkbox"/>			

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					<input checked="" type="checkbox"/>
41	23/05/19 08:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	23/05/19 08:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	23/05/19 08:55	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/04/19 10:20	TP ESTIMATE + docs		Load PDF	
2	24/04/19 10:20	TP GIA REPORT		Load PDF	
3	16/05/19 20:35	TP ESTIMATE - MARKED		Load PDF	
4	28/05/19 11:51	RENTAL RECEIPT		Load PDF	
5	26/07/19 15:04	LETTER TO OI		Load PDF	
6	12/09/19 10:37	WORKSHOP INVOICE		Load PDF	
7	12/09/19 10:37	AUTHORISATION TO ACT FORM		Load PDF	
8	12/09/19 10:37	Release Voucher		Load PDF	
9	12/09/19 10:37	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	25/04/19 09:23	OI GIA REPORT		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLV9709Y (Insd veh)	Model:	BMW 218I 1.5 COUPE HID
	SLG4384L (TP veh)		ABS SR (A)
Date of Accident:	20/04/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	24,150.97
Final Repair Cost	:	\$	22,206.83
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	941.60 11 days
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	23,148.43

**Is Third Party Workshop GIA Registered?** ☒ YES ☐ NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_ (%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ 100 \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 22,206.83
2)	BKW Rent-A-Car Pte Ltd	:	\$ 941.60

\_\_\_\_\_  
JOANNE LEE KHANG MIN

\_\_\_\_\_  
LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
12 Sep  
2019

\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19007180/EEA3Q2

Date: 12/09/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

## Claimant

Vehicle No : SLG4384L

Insured Vehicle No : SLV9709Y

Date of Loss: 20/04/2019

Nature of Claim: TP

Claim No: 3790291274SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLG4384L

Make &amp; Model: BMW 218I, 1.5 COUPE HID ABS SR (A)

Engine No: F1611442B38B15A

Reg. Date: 30/09/2016 (Man. Year: 2016)

Chassis No: WBA2F12060V758323

Colour: White

Odometer: 26041 km

Engine Capacity: 1499 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,138.00	4,734.05	403.95	7.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,433.00	16,020.00	1,413.00	8.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>22,571.00</b>	<b>20,754.05</b>	<b>1,816.95</b>	<b>8.05</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,579.97</b>	<b>1,452.78</b>	<b>127.19</b>	<b>8.05</b>
<b>Nett Amount (S\$)</b>	<b>24,150.97</b>	<b>22,206.83</b>	<b>1,944.14</b>	<b>8.05</b>
<b>+ Car Rental (11.0 x S\$80.00/day + 7.00% GST) (S\$)</b>		<b>941.60</b>		
<b>Nett Liability (S\$)</b>		<b>23,148.43</b>		

## INSPECTION

Date of Assignment: 14/05/2019

Date Inspected: 14/05/2019 Inspected At:

Performance Motors Limited  
(Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre

Singapore 159941

Estimated Period of Repair: 14.0 days

Adjuster: CHEN TSUE YEE

Manager: Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNRIES	Necessary	150.00 FS	*150.00 FS
2	8		*PLASTIC NUT FOR COARSE THREADED PIN	Not Necessary	6.40 FS	*- FS
3	1		*ALLOY RIM 7.5JX17 STAR SPOKE 379	Cut	921.70 FS	*921.70 FS
4	1		*REAR RH SIDE PANEL	Dented	1,352.55 FS	*1,352.55 FS
5	1		*REINFORCEMENT	Not Necessary	52.90 FS	*- FS
6	1		*REINFORCEMENT	Not Necessary	52.40 FS	*- FS
7	1		*REINFORCEMENT	Not Necessary	68.00 FS	*- FS
8	1		*FRT RH DOOR	Dented	1,346.70 FS	*1,346.70 FS
9	1		*RH SIDE GUIDE FOR BUMPER	Not Necessary	49.05 FS	*- FS
10	5		*PLASTIC NUT	Not Necessary	4.25 FS	*- FS
11	1		*FRT RH DOOR EDGE PROTECTION	Not Necessary	152.50 FS	*- FS
12	1		*RH SILL STRIP PRIMED	Cut	277.35 FS	*277.35 FS
13	1		*CAVITY PROTECTION WAX REMOVER 500ML	Not Necessary	18.45 FS	*- FS
14	20		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
15	10		*SCREW (SF PLUS M5X15)	Necessary	5.50 FS	*5.50 FS
16	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	326.80 FS	*326.80 FS
17	20		*PUNCH RIVET N5	Necessary	11.00 FS	*11.00 FS
18	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	112.70 FS	*112.70 FS
19	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
20	10		*PUNCH RIVET N4	Necessary	5.50 FS	*5.50 FS
21	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
22	2		*EXPANDING NUT	Necessary	1.20 FS	*1.20 FS
23	1		*EXPANDING NUT	Necessary	0.60 FS	*0.60 FS
24	3		*EXPANDING NUT	Necessary	6.00 FS	*6.00 FS
25	1		*SNAP LOCK COUPLING	Necessary	3.65 FS	*3.65 FS
26	1		*FRT LH DOOR BRAKE	Necessary	71.00 FS	*71.00 FS
27	2		*TORX -BOLT WITH WASHER	Necessary	2.80 FS	*2.80 FS
28	3		*HOOK AND LOOP FASTENER	Necessary	8.55 FS	*8.55 FS
29	2		*PLUG IN NUT 0.8MM	Necessary	2.80 FS	*2.80 FS
30	3		*EXPANDING NUT (4.8)	Necessary	3.00 FS	*3.00 FS
31	1		*TYRE IDENTIFICATION PLATE (CODED)	Necessary	29.30 FS	*29.30 FS
32	1		*LABEL TIRE PRESSURE	Necessary	24.40 FS	*24.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	5,138.00	4,734.05
--------------------	----------	----------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND INSTALL REAR RH FENDER FIXED WINDOW GLASS TO FACILITATE REPAIRS AND CONDUCTING WATER LEAK TESTS	New	413.00	413.00
2	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	231.00	231.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTINGS AT THE REAR SECTION INCLUDE RESETTNG AND CHECKING AIR BAGS FOR FUNCTION	New	250.00	250.00
4	TO REPLACE REAR RIGHT FENDER ,RIGHT DOOR SIDE SILL RIGHT,ATTACHMENTS AND REPAIR REAR BUMPER INCLUDING KNOCKING ON AREA CAUSED BY ACCIDENT	New	7,650.00	6,800.00
5	PAINTING REAR BUMPER ,REAR RIGHT FENDER ,RIGHT DOOR ,SIDE SILL ,TAIL PANEL AND TRUNK FLOOR,RH ROOF FRAME AND RH CPILLAR	New	5,149.00	5,149.00
6	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
7	TO CHECK STEERING GEOEMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
8	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
9	TO REMOVE AND INSTALL REAR HAT-TRAY ,REAR SEAT ,CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
10	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING EXTRACT FUEL AND CONDUCT LEAK TESTS	New	531.00	451.00
11	TO REMOVE AND INSTALL FUSE BOX AT THE REAR SECTION TO FACILITATE REPAIRS	New	531.00	451.00
12	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
13	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
<b>Gross Labour Cost (S\$)</b>			<b>17,433.00</b>	<b>16,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >