

Labour Description				
1		TO REPLACE FRONT DOOR RH, DOOR MIRROR RH AND ROCKER PANEL RH. REPAIR FRONT FENDER RH AND AREAS AFFECTED BY THE ACCIDENT.	\$ 2,970.00	\$ 3,300.00
2	MZ-SP-SFRT01	TO RESPRAY FRONT FENDER RH, COVER DOOR MIRROR RH, FRONT DOOR RH AND ROCKER PANEL RH. (TO BLEND REAR FENDER RH AND FRONT PILLAR OUTER RH)	\$ 2,520.00	\$ 2,835.00
3		TO SUPPLY BODY COATING (INVOICES ATTACHED) ✓	\$ 450.00	TBA (A)
4		TO SUPPLY CHASSIS STICKER.	\$ 120.00	\$ 120.00
5	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	\$ 330.00	\$ 330.00
6	MZ-BR-TRIMS1	TO REMOVE & REFIT CARPET & TRIMS ON THE FRONT SECTION TO GIVE WAY TO THE REPAIR ON THE FRONT SECTION.	\$ 660.00	\$ 990.00
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	\$ 180.00	\$ 350.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
11	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00

TOTAL LABOUR	\$ 7,740.00	\$ 8,875.00
TOTAL PARTS	\$ 2,476.62	\$ 3,272.13
TOTAL	\$ 10,216.62	\$ 12,147.13
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ 10,216.62	
GST 7%	\$ 715.16	\$ -
GRAND TOTAL	\$ 10,931.78	\$ -

REMARKS:

10 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

12597.13