

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 717A**AAD1904-200***Not Authored
Resumy B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 717A

VF1ABL15AUC283320

RENAULT

LATITUDE

18.4.2019

III

29/12/2017

PART**LIST**

1	BUMPER COVER FRT	\$	<i>Bz</i> 1,259.42	✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75	X
1	BUMPER ABSORBER FRT	\$	394.68	?
1	BUMPER RETAINER FRT RH	\$	<i>Dis</i> 150.77	✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88	X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83	X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80	X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>mir</i> 207.21	✓
1	BUMPER BEAM FRT	\$	914.08	?
1	HEADLAMP RH	\$	<i>mgcm</i> 1,184.43	✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	X
1	FENDER PANEL FRT RH	\$	<i>Bz</i> 783.83	✓
1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84	X
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79	X
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84	X
1	WIPER RESERVOIR	\$	<i>Sn</i> 348.25	X
1	WIPER RESERVOIR NECK	\$	<i>Sn</i> 136.11	X
1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i> 270.06	X
1	RADIATOR GRILLE	\$	<i>CM</i> 1,707.78	✓
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>re</i> 225.36	✓
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75	X
1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90	X
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	X

TOTAL	\$	11,264.31
10%	\$	1,126.43
TOTAL	\$	10,137.88

Trans-cab Auto Services Pte Ltd**AAD1904-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 717A**Specical Nett**

1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00 ✓
1	BUMPER BRACKET CLIP FRT RH	\$	<i>nn</i> 12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>nn</i> 10.50 X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00 X
		\$	157.50
TOTAL PARTS		\$	10,295.38

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00 <i>4000</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>4400</i>
To rust-proofing of the affected areas.	\$	170.00 <i>300</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>200</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1904-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 717ATo vacuum, replace, refix and recharge Air
Intercooler

\$

na 170.00 X**TOTAL \$ 8,210.00****Over All Total \$ 18,505.38****PART-BY-PART (REPAIR DAY)**~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: