

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5397L**AAD1904-216***Not Authored*
11 Sep \$5500

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5397L

VF1ABL15AUC279403

RENAULT

LATITUDE

21.4.2019

III

4/11/2014

PART**LIST**

1	DOOR PANEL REAR RH	\$	<i>2,844.66</i> ✓
1	DOOR GUIDE REAR RH	\$	<i>176.82</i>
1	DOOR HINGE UPPER RH	\$	<i>274.50</i>
1	DOOR HINGE LOWER RH	\$	<i>300.55</i>
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>203.06</i>
1	DOOR LOCK REAR RH	\$	<i>908.75</i>
1	DOOR HANDLE OUTER REAR RH	\$	<i>126.49</i>
1	DOOR HANDLE CAP REAR RH	\$	<i>35.52</i>
1	DOOR HANDLE SEAL REAR RH	\$	<i>7.89</i>
1	DOOR HANDLE COVER REAR RH	\$	<i>13.22</i>
1	DOOR HANDLE MODULE REAR RH	\$	<i>133.60</i>
1	DOOR REGULATOR REAR RH	\$	<i>1,135.10</i>
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>893.75</i>
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>12.43</i>
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>6.31</i>
1	DOOR FINISHER REAR RH	\$	<i>423.10</i>
1	DOOR MOULDING REAR RH	\$	<i>176.82</i>
1	DOOR MOULDING CLIP L70Y	\$	<i>5.92</i>
1	DOOR MOULDING SCREW L70Y	\$	<i>6.91</i>
1	DOOR CASING REAR RH	\$	<i>1,509.06</i>
1	DOOR WATER SHIELD REAR RH	\$	<i>30.39</i>
1	DOOR CASING CLIP	\$	<i>12.63</i>
1	DOOR CASING LIGHT L70Y	\$	<i>48.74</i>
1	DOOR FINISHER INNER REAR RH	\$	<i>323.44</i>
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>46.97</i>
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>20.33</i>
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>20.33</i>
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>20.33</i>
1	DOOR GRAB HANDLE REAR RH	\$	<i>210.96</i>

X

Trans-cab Auto Services Pte Ltd

AAD1904-216

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5397L

1	DOOR BLIND REAR RH	\$	Sn	741.80	} X
1	DOOR WHEATHESTRIIP REAR RH	\$	Sn	410.66	
1	DOOR SEAL REAR RH	\$	Sn	162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	Sn	229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	Sn	334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	Sn	115.64	
1	FENDER PANEL REAR RH	\$	R	3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	Sn	671.45	
1	WHEELARCH REAR RH	\$	Sn	543.47	
1	DOOR MIRROR ASSY RH	\$	Sn	1,483.40	
1	ROCKER PANEL INNER GARNISH RH	\$	Sn	466.51	
1	ROCKER PANEL INNER RH	\$	R	1,024.79	
1	ROCKER PANEL CENTER RH	\$	R	990.25	
1	BUMPER COVER REAR	\$	R	1,108.46	
1	BUMPER LOWER REAR	\$	Sn	768.84	
1	BUMPER BRACKET CTR REAR	\$	Sn	113.47	
1	BUMPER BRACKET SIDE RH REAR	\$	Sn	135.97	
1	BUMPER RETAINER RH REAR	\$	Sn	44.99	
1	REAR TAILAMP RH	\$	Sn	552.55	
1	DOOR PANEL FRT RH	\$	R	2,844.66	✓
		\$		25,970.63	
		10% \$		2,597.06	
		\$		23,373.57	

Specical Nett

1	REAR DOOR STICKER '6555-3333'	\$	R	80.00	605m-
1	DOOR CHECK BOLT	\$	R	22.69	✓
1	DOOR GUIDE SCREW	\$	R	10.85	✓
1	DOOR HINGE BOLT	\$	R	10.85	✓
1	DOOR HINGE NUT RH	\$	R	14.60	✓
1	DOOR CHECK BOLT	\$	R	22.69	✓
1	FRONT DOOR STICKER 'TRANS-CAB'	\$	R	80.00	605m-
1	FRONT DOOR STICKER 'CHASSIS'	\$	R	50.00	155m
1	DOOR CATCH SCREW L70Y	\$	R	10.06	✓

TOTAL	\$	301.76
--------------	-----------	---------------

Trans-cab Auto Services Pte Ltd

AAD1904-216

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5397L

TOTAL PARTS	\$	23,675.33
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 <i>500</i>
Putty and spray painting of the affected portion.	\$	4,200.00 <i>880</i>
To rust-proofing of the affected areas.	\$	170.00 <i>60</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <i>60</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>20</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 <i>60</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 <i>60</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>

To transfer of Rear bumper fittings, attachment and perform water seepage test.		\$	<i>nn</i> 380.00 <i>X</i>
TOTAL		\$	11,710.00
Over All Total		\$	35,385.33

PART-BY-PART (REPAIR DAY)

Acknowledged by Repairer
Signature:
Date:

15 DAYS
4 days