



Cecilia

Section A - Accident Details

Registration Number	SHB203B
Case Reference Number	TAX/04/19/2079
Registration Date	28/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NG WOON KWANG
Type of Accident	Head To Side
Accident Date and Time	18/4/2019 3:40 PM
Accident Reported Date and Time	18/4/2019 4:18 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101135
Special Instruction to ARC, if any	TP
Prepared Date and Time	23/4/2019 10:35 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Location

P/P \$1619.51/- 3 days

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$1,296.00	\$400.00
Total Spare Part Cost	\$3,550.95	\$799.51
Total Other Cost	\$820.00	\$20.00
TOTAL COST	\$6,511.95	\$1,619.51 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Zhi Yang Phua	Hwee Jia (LKK) / AIG
ARC / Surveyor Sign Off Date	23/04/2019 10:47 AM	23/04/2019 1:33 PM
Signature		
Remarks	P/P REPAIR, PHOTO BEFORE PAINT.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0453	Invoice Number	
Quotation Date	29.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,296.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIX VIEW MIRROR	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$820.00	\$20.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53801470 80	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	25.00	\$699.83	Replace	Replace
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given
		42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given
		67001471 52	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		87915470 70A1	COVER, OUTER MIRROR, RH	0.00	\$89.50	0.00	\$0.00	Replace	Not Given
		75850479 10	MOULDING ASSY, BODY ROCKER PANEL, RH	0.00	\$576.00	0.00	\$0.00	Replace	Not Given
Total					\$4,714.60		\$799.51		

799.51
+ 400.00
+ 420.00
1619.51

BK
rec
X
X
X
X
X
X
X
X