

Kd

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Notified
Resurvey By paint
3 days

81436.72

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 23.04.2019

Accident Date : 15.04.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	貨名 DESCRIPTION	單價 Unit Price	總 Amount 額 \$ cts.
	Estimate Cost Of Repair To "Hyundai Elantra" Reg. No. SKW7937A Claiming Against Your Insured Reg. No. GBE2101D		
1pc	Rear Bumper		ngcm 502.00
16pcs	Rear Bumper Clips	2.00	32.00
1pc	Rear Bumper Reinforcement(Fiber)		495.00 X
3pcs	Rear Bumper Plastic Holders	52.00	156.00 X
1pc	Boot Auto Sensor Receiver		203.00 X
1pc	Boot Emblem		30.50
1pc	Boot Badge Elantra		53.60
1pc	Boot Badge Gls		27.80
			1,499.90
	Less 20%		299.98
			1,199.92
	Rear Bumper Sensor		280.00 SN
	To Conduct Rear Electrical Check and Dismantle / Replace / Transfer Rear Parking Distance Sensor. Reprogram Frequency Unit, Drilling, Testing etc		120.00 201
	Labour Charge - Panel Beating, Repairing Of Boot, End Panel & Parts Replacement		450.00 301
	To Spray Painting Affected Areas		550.00 401
		Total :	2,599.92

UIC Auto Consultants hereby notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: