

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not available
Repairing B4 part
3 days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 23.04.2019

Accident Date : 15.04.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Hyundai Elantra" Reg. No. SKW7937A Claiming Against Your Insured Reg. No. GBE2101D		
1pc	Rear Bumper	2.00	502.00 7
16pcs	Rear Bumper Clips		32.00 7
1pc	Rear Bumper Reinforcement(Fiber)		495.00 X
3pcs	Rear Bumper Plastic Holders	52.00	156.00 X
1pc	Boot Auto Sensor Receiver		203.00 7
1pc	Boot Emblem		30.50 —
1pc	Boot Badge Elantra		53.60 —
1pc	Boot Badge Gls		27.80 —
			1,499.90
			299.98
	Less 20%		1,199.92
	Rear Bumper Sensor		280.00 SN
	To Conduct Rear Electrical Check and Dismantle / Replace / Transfer Rear Parking Distance Sensor. Reprogram Frequency Unit, Drilling, Testing etc		120.00 201
	Labour Charge - Panel Beating, Repairing Of Boot, End Panel & Parts Replacement		450.00 300
	To Spray Painting Affected Areas		550.00 400
		Total :	2,599.92

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: