

Form 100

ASS. REC. BY:

REF: CS/SMO190072121 KSD 302

Special Instructions:

Surveyor: Caruth

ASSIGNMENT (Office)

From (Person): Ruth Chua Get Tiam of SMO

Date/Time: 24.4.2019 13.43PM

Estimated Cost: _____ Bill to: _____

OP / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 855L Insured: _____

at Workshop m/s Ah Lim motor Tel: 64831244

of 10 Amk Industrial Park 2A #01-09

Policy No: D18MTPV 01008413 Claim No: MTD 1901970

Sum Insured: _____ Excess: \$500 (waived)

Make of Veh: _____ D.O.A. 18.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 24.4.19 2.06 p.m Person Contacted: Eileen Zila H.O.D. Endorsement: _____

Vehicle IN / OUT

Date/Time	Action/Instruction
	Estimated (1)
	SLD 855L - CS/SMO19007112 / RSD3 D.O.A - 23/04/2019
10/7	\$8380.70 Carburant
	8070.70
	(\$ 5,036.20 Red - 38%)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$0/- woi

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$ 73k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 09 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLD 855L Yr Regn: 06/16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Make c.c. 1598

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 38329 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053REH10.4551317

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. P mm

L/Bal. P mm

D.O.A. 18/4/19

Survey held at

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 24/4/19

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

25/04/19 @ 11:45 p.m. revised PA to Ruth Chua via memo.

25/04/19 @ 11:54 p.m. mandate requested authorise repair to Ruth Chua
via memo.25/04/19 @ 14:14 p.m. mandate approved by Ruth Chua Goh Tiong via
memo.25/04/19 @ 14:53 p.m. revert authorise repair to Zila (operator) via
email.

Date/Time, File Pass to?

16/7/19

1) Type: 4

Date/Time, File Return to?

2)

☐ : Prell. Report☒ : Final Report

RECEIVED 17 JUL 2019

Days Of Repair: 9

Resurvey No. of Trip: 2

Survey Fee:

Transportation: \$ - RS. \$

Fees:

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

Lump Sum 1.B.2 (\$ 2,070.70

361

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Apr 2019 Sendback Est	24 Apr 2019 11:09 S\$12,432.90	24 Apr 2019 13:43 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	TEO KENG HWA, ID: S7273790C, Tel: +6598343013, Email: KENGHWA.TEO@GMAIL.COM		
Vehicle Reg. No.:	SLD855L	Date of Loss:	18/04/2019 19:00 - :59 [34 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1901970	Policy/Cover Note No.:	D18MTPV01008413 (Comprehensive)
		Excess:	
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/05/2019]		
Driver/Custodian:	TEO KENG HWA (46 / Male), NRIC: S7273790C, Tel: +6598343013 Email: KENGHWA.TEO@GMAIL.COM		
Adj Asg. Remarks:	FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View All

Search Tasks

Create New Task

Complete

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3790C

Vehicle Details

Vehicle No.: SLD855L
Vehicle to be Exported: No
Intended Deregistration Date: 20 Apr 2019
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: 1ZR574967
Chassis No.: MR053REH104551317
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$17,982.00
Original Registration Date: 01 Jun 2016
First Registration Date: 01 Jun 2016
Transfer Count: 0
Actual ARF Paid: \$17,982.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 31 May 2026
PARF Rebate Amount: \$13,486.00

Intended COE Rebate Details

COE Expiry Date: 31 May 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$47,020.00
COE Rebate Amount: \$33,444.00
Total Rebate Amount: \$46,930.00

The information contained herein is correct as at 20 Apr 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 16 July 2019 4:33 PM
To: 'Mui Hong @ Ah Lim Motor'; Kenneth Kong (LKKAuto)
Cc: SUR
Subject: RE: Draft Finalisation - SLD855L
Attachments: ESTIMATE & SUPP MARKED.pdf

Hi Mui Hong,

As spoken, supplementary approved by SOMPO.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mui Hong @ Ah Lim Motor [mailto:muihong@ahlimmotor.com.sg]
Sent: Saturday, 6 July 2019 11:22 AM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Cc: sur@lkkauto.com
Subject: Draft Finalisation - SLD855L

Dear Kenneth,

Pls see attached the Draft Finalisation - SLD855L for your approval.

Pls advise

Thanks

Best Regards,

Kee Mui Hong
Ah Lim Motor @ AMK
10, Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint S568047
Tel : 6483 1244 Fax : 6483 6170

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 25 April 2019 2:53 PM
To: zila@ahlimmotor.com.sg
Cc: SUR
Subject: SLD 855L OD SOMPO DOA - 18/04/2019

Dear Zila,

As instructed by our client, please proceed to repair the insured vehicle **SLD 855L (Excess \$ 0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SLD855L (CMTD1901970)

OD

Apr 18 2019 7:00PM

[TEO KENG HWA]

Ah Lim Motor Company

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sompo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 16/07/2019 10:08 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9189.90) - SLD855L - Claim Handler: Ruth Chua Gek Tiang

Approved:9189.90:OD EXCESS \$500 WAIVED

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SLD855L (CMTD1901970)

OD

Apr 18 2019 7:00PM

[TEO KENG HWA]

Ah Lim Motor Company

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sompo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 25/04/2019 14:15 PM.
To LKK_HQ; sur@lkkauto.com; assignments@lkkauto.com
Subject OD authorisation given (SLD855L)

Hi,

OD authorisation given.

Please proceed to authorise repairs.

OD excess \$500.00 - waived

Regards

Ruth

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SLD855L (CMTD1901970)

OD

Apr 18 2019 7:00PM

[TEO KENG HWA]

Ah Lim Motor Company

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sompo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 25/04/2019 14:14 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8665.90) - SLD855L - Claim Handler: Ruth Chua Gek Tiang

Approved:8665.90:OD EXCESS \$500 WAIVED

DOCUMENTS SUMMARY

There are no documents.

View Sent Message

This mail is associated with :

SLD855L (CMTD1901970)

OD

Apr 18 2019 7:00PM

[TEO KENG HWA]

Ah Lim Motor Company

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 25/04/2019 12:03 PM.
To ruth.chua@sompo.com.sg
CC sur@lkkauto.com
Subject Re: Please expedite OD repairs - Pls verify chassis no and engine no of SLD855L - CMTD1901970/RUC

Hi Ruth,

Chassis no please refer to the photo no .28 in merimen.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Bik S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: SOMPO_SG

To: LKK_HQ; sur@lkkauto.com; assignments@lkkauto.com

Sent On: 24/04/2019 02:10 PM

Subject: Please expedite OD repairs - Pls verify chassis no and engine no of SLD855L - CMTD1901970/RUC

Hi,

Please expedite OD survey.

Please verify Chassis No. and Engine No of SLD855L.

OD excess - \$500 waived

Regards

Ruth

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 16 Jul 2019

Preliminary Advice

Vehicle No	: SLD855L	Accident Date	: 18/04/2019
Make	: TOYOTA COROLLA ALTIS	Policy No.	: D18MTPV01008413
Assignment Date	: 24/04/2019	Excess	: S\$0.00
Date of Inspection	: 24/04/2019	Est. Duration of Repair	: 9 days
Inspection At	: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,106.90 (Inclusive Supp)
Revised Amount	:S\$	5,343.10 (Inclusive Supp)
Check Items (Estimated)	:S\$	3,846.80
Total	:S\$	9,189.90
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	73,000.00
COE / PARF Rebate	:S\$	46,930.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,070.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 524.00.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 25 Apr 2019

Preliminary Advice

Vehicle No	: SLD855L	Accident Date	: 18/04/2019
Make	: TOYOTA COROLLA ALTIS	Policy No.	: D18MTPV01008413
Assignment Date	: 24/04/2019	Excess	: S\$0.00
Date of Inspection	: 24/04/2019	Est. Duration of Repair	: 9 days
Inspection At	: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,432.90
Revised Amount	:S\$	4,819.10
Check Items (Estimated)	:S\$	3,846.80
Total	:S\$	8,665.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	73,000.00
COE / PARF Rebate	:S\$	46,930.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,070.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/04/2019 11:53
Date Of Accident	18/04/2019 19:40
Exact Location Of Accident	JUNCTION @ WOODLANDS RD & TURF CLUB RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLD855L
Insured/Policyholder	
Name Of Registered Owner	TEO KENG HWA
NRIC No	S7273790C
Email Address	KENGHWA.TEO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98343013
Alternative Phone No	OTHERS-98343013
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01008413
Cover Note Number	01/06/2018 - 31/05/2019
Driver	
Name of Driver	TEO KENG HWA
NRIC No	S7273790C
Date Of Birth	29/10/1972
Occupation	INDOOR
Date Of Driving Pass	09/02/1998
Driving Experience	21 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98343013
Fax Number	
Contact Number	OTHERS-98343013
Email Address	KENGHWA.TEO@GMAIL.COM



Address	12 ANG MO KIO CENTRAL 3
	#
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : NG GEK YIN THERESA
	GENDER: : FEMALE
Passenger 2	NAME: : KENDRICK TEO TZE YU
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7825R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 20 Apr 19
9.30am


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

Date of accident: 10/11/19 Time: 19:40 Location: Junction @ Widdals Rd & Turf Club Ave
My Vehicle A: SLD 955 L Vehicle B: SH19 78252 Vehicle C: -

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At the junction of above, my car hit the comfort Taxi coming from Woodland Road. At that time it was green light. There were two cars stationary before the line at the 1st and 2nd lane.

Car B- 2ndal Bu owner
11697366A

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop :

Email address :

& myself

Email address : kenghwa.teo@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 20 Apr 19
9:30am

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Law Enforcement's Signature _____

Name:

NRIC/FIN No.:


Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 196905490E | GST Reg. No.: M200003198

PRIVATE CAR POLICY SCHEDULE

Intermediary Code : 11P04201

Policy No. : D18MTPV01008413

This Schedule is issued in accordance and should be read in conjunction with the terms, conditions and exceptions of the PRIVATE CAR Policy wordings, ref. MTP 27

Insured : TEO KENG HWA
Address : 12 ANG MO KIO CENTRAL 3
11-19
SINGAPORE 567746

Business/Profession : MANAGER

INSURED DETAILS

Date of Birth & Age : 29 OCT 1972 & 45 years old
Driving Experience in Singapore : 15 years
Identification Type : NRIC(Singaporean PR)
Identification No. : S7273790C
Marital Status : MARRIED
Gender : Male

Period of Insurance : 01 JUNE 2018 00:00 TO 31 MAY 2019 23:59

Persons or Classes of Persons entitled to drive : Refer to Certificate of Insurance

Limitations as to use : Refer to Certificate of Insurance

VEHICLE DETAILS

Vehicle Registration No. : SLD855L
Chassis No. : NIL
Engine No. : NIL
Vehicle Make & Model : TOYOTA COROLLA ALTIS
1.6
Cc : 1598
Type of Body : SALOON
Year of Registration : 2016
Seating Capacity (including driver) : 5
Estimated value of Vehicle : Market value at time of loss
Hire Purchase Owner : CENTURY TOKYO LEASING PTE LTD

PREMIUM DETAILS

Premium	1,444.80
Less No Claim Discount (50%)	(722.40)
Less Offence free Discount (5%)	(36.12)
Less EDG Discount (10%)	(68.63)
Add others :	
Less Loyalty Discount(5%)	(30.88)
Total	\$5 585.77
GST	\$5 41.97
Premium (incl. GST)	\$5 627.84

Coverage : Comprehensive - ExcelDrive GOLD

Excess : \$ 500 - Section I
(Waived up to \$51,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)

Voluntary Excess : N.A.

Additional Excess : Named Young and/or Inexperienced Drivers or Elderly Drivers - \$1,500
Un-named Young and/or Inexperienced Drivers or Elderly Drivers - \$3,000
Un-named All Other Drivers - \$500

The terms shall be defined as follows:

'Young Drivers' shall be defined as drivers (including the Insured) who are below 25 years old.

'Inexperienced Drivers' shall be defined as drivers (including the Insured) who have less than 2 years of driving experience in Singapore

'Elderly Drivers' shall be defined as drivers (including the Insured) who are above 70 years old.

Paragraph 2 of Endorsement E in the policy will not apply to insured's spouse provided he/she is 25 years old & above but less than 70 years old &/or has 2 or more years driving experience.

Windscreen Excess : \$5100.00 - Waived If Repair at ExcelDrive Workshop

Endorsements Applicable : Endorsement D - Young and/or Inexperienced or Elderly Drivers Excess

Endorsement E - Excess Clause

Endorsement H - Total Loss

Endorsement L - Hire Purchase

Endorsement M - Inclusion Of Special Perils


Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048633
 Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
 Co. Reg. No.: 198905490E | GST Reg. No.: M200903195

PRIVATE CAR POLICY SCHEDULE

Intermediary Code : 11P04201

Policy No. : D18MTPV01008413

Endorsement P6 - Riot And Strike Endorsement

Endorsement V - No Claim Discount Protection

Endorsement Y2 - ExcelDrive Gold Plan

Endorsement Z - Loss of Use Benefit

Additional Cover

: NIL

Named Drivers

1. Name : TEO KENG HWA
 Date of Birth & Age : 29 OCT 1972 & 45 years old
 Driving Experience in Singapore : 16 years

Date of Issue

: 04 MAY 2018

Intermediary Name

: PHILLIP SECURITIES PTE LTD

Producer Code & Name

: PST04588 & CHUA KIAN KOON

User Code

: AZELSEAHIPST04588

Old Policy No.

: D17MTPV01006445

Signed on this 04th day of May 2018
 for and on behalf of SOMPO INSURANCE SINGAPORE PTE. LTD.

Authorised Signatory

CI Code : 22A

24-HOUR EMERGENCY HOTLINE

Tel: (65) 6226 3323

Specialist from 24 Hours Mobile Accident Response Service (MARS) will:

- Take photographs of the vehicle involved.
- Assist the driver to complete the accident statement and arrange for e-filing to General Insurance Association of Singapore (GIA) within 24 hours.
- Arrange towing service if necessary to the nearest ExcelDrive Workshop.
- * When overseas, inform the operator that you would like to place a collect call, or call on reverse charge basis.




98343013

O/c
NR in jng.
current.

3 av.

- (P) 1) Ng Gek Yin Theresa
(M) 2) Kendrick Teo Tze Yu.



AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
 #01-09 AMK AUTOPOINT Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST Reg No: M9-0009639-E

INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MTPV01008413	Date of Loss:	18/04/2019
Vehicle Reg. No.:	SLD855L	Driveable?	
Driver Age/Info:	46 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TEO KENG HWA	Contact No:	+6598343013
Driver:	TEO KENG HWA		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Vehicle Reg. Date:	01/06/2016
Vehicle Colour:	SILVER	Chassis No:	MR053REH104551317
Engine No:	1ZR574967		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10 days		
Description of Accident/Loss	REFER TO THE SKETCH PLAN BY DRIVER		
Remarks:	CAR IN @ ALM AMK AUTOPOINT WORKSHOP		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

COST OF CLAIMS

Parts
 Miscellaneous Items
 Labour
 Paintwork Labour
 Towing

Lik Lim Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Gross Total (S\$)	12,432.90	12,432.90
+ GST 7.00% (S\$)	870.30	
Nett Amount (S\$)	13,303.20	

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Apr 2019)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/SLD855L/24/04/2019 11:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*FRONT WIPER GARNISH	CM	0.00	0.00	*220.00 F	—
2	1		*FRONT BONNET	B	0.00	0.00	*265.00 F	—
3	2		*FRONT BONNET HINGE LH & RH	A101	0.00	0.00	*40.00 F	—
4	1		*FRONT BONNET INSULATOR - CHECK PRICE	in	0.00	0.00	*F	X
5	10		*FRONT BONNET INSULATOR CLIPS	in	0.00	0.00	*10.00 F	X
6	1		*FRONT BONNET RUBBER FRONT	in	0.00	0.00	*110.00 F	—
7	1		*FRONT BONNET INNER LOCK	D17	0.00	0.00	*45.00 F	—
8	1		*FRONT BONNET CABLE		0.00	0.00	*28.00 F	—
9	2		*FRONT BONNET SPRAY NOZZLE LH & RH	ALSM	0.00	0.00	*30.00 F	—
10	1		*FRONT GRILLE ASSY (CHROME)	CRA	0.00	0.00	*140.00 F	—
11	6		*FRONT GRILLE CLIPS	in	0.00	0.00	*6.00 F	—
12	1		*FRONT GRILLE TOP COVER		0.00	0.00	*38.00 F	—
13	2		*HEADLAMP LH & RH	mgcm	0.00	0.00	*440.00 F	—
14	1		*FRONT BUMPER	CRA	0.00	0.00	*170.00 F	—
15	2		*FRONT BUMPER SIDE RETAINER LH & RH	D17	0.00	0.00	*40.00 F	—
16	15		*FRONT BUMPER CLIPS	in	0.00	0.00	*15.00 F	—
17	1		*FRONT BUMPER LOWER AIR GRILLE	AD1D17	0.00	0.00	*55.00 F	—
18	1		*FRONT BUMPER REINFORCEMENT		0.00	0.00	*110.00 F	—
19	1		*FRONT BUMPER SPONGE		0.00	0.00	*35.00 F	—
20	2		*FOGLAMP LH & RH		0.00	0.00	*160.00 F	—
21	2		*FOGLAMP COVER LH & RH	ALSM	0.00	0.00	*70.00 F	—
22	1		*FRONT BUMPER UNDER COVER	CM	0.00	0.00	*55.00 F	—
23	10		*FRONT BUMPER UNDER COVER CLIPS	in	0.00	0.00	*15.00 F	—
24	2		*FRONT FENDER LH & RH	Bu	0.00	0.00	*400.00 F	—
25	2		*FRONT FENDER COWLING LH & RH		0.00	0.00	*96.00 F	—
26	16		*FRONT FENDER COWLING CLIPS		0.00	0.00	*16.00 F	—
27	2		*FRONT FENDER DUAL VVTI LOGO LH & RH	in	0.00	0.00	*50.00 F	—
28	1		*RADIATOR SUPPORT PANEL	B	0.00	0.00	*180.00 F	—
29	1		*BRACE PANEL	B	0.00	0.00	*35.00 F	—
30	2		*HORN	in	0.00	0.00	*90.00 F	—
31	1		*AIR CON CONDENSER	Pu	0.00	0.00	*280.00 F	—
32	2		*AIR CON CONDENSER TOP BUSH LH & RH	in	0.00	0.00	*6.00 F	—
33	2		*AIR CON CONDENSER BOTTOM BUSH LH & RH	in	0.00	0.00	*6.00 F	—
34	1		*AIR CON CONDENSER PIPE (COND-COMP)	in	0.00	0.00	*150.00 F	—
35	1		*AIR CON CONDENSER PIPE (COND-VALVE)	A1	0.00	0.00	*210.00 F	—
36	1		*AIR CON CONDENSER PIPE (COMP-VALVE)	in	0.00	0.00	*140.00 F	—
37	1		*RADIATOR ASSY	Pu	0.00	0.00	*320.00 F	—
38	1		*RADIATOR FAN MOTOR	in	0.00	0.00	*120.00 F	—
39	1		*RADIATOR FAN BLADE	in	0.00	0.00	*45.00 F	—
40	1		*RADIATOR FAN COWLING	CM	0.00	0.00	*65.00 F	—
41	2		*RADIATOR TOP BRACKET LH & RH	in	0.00	0.00	*60.00 F	—
42	2		*RADIATOR TOP BUSH LH & RH	in	0.00	0.00	*16.00 F	—
43	2		*RADIATOR BOTTOM BUSH LH & RH	in	0.00	0.00	*30.00 F	—
44	1		*RADIATOR TOP COWLING	in	0.00	0.00	*35.00 F	—
45	1		*RADIATOR TOP HOSE	in	0.00	0.00	*18.00 F	—

Ah Lim Motor Company/SLD855L/24/04/2019 11:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
46	1		*RADIATOR BOTTOM HOSE	0.00	0.00	*18.00 F	X
47	1		*INTAKE MANIFOLD	0.00	0.00	*280.00 F	Y
48	1		*AIR FILTER BOX ASSY	0.00	0.00	*250.00 F	X
49	1		*AIR INTAKE HOSE	0.00	0.00	*48.00 F	X
50	1		*RESONATOR TANK	0.00	0.00	*48.00 F	X
51	1		*FUSE BOX TOP	0.00	0.00	*35.00 F	X
52	1		*FUSE BOX LOWER	0.00	0.00	*40.00 F	X
53	1		*BATTERY TRAY	0.00	0.00	*28.00 F	X
54	1		*WIPER WASHER TANK	0.00	0.00	*62.00 F	X
55	1		*WIPER WASHER TANK NECK	0.00	0.00	*15.00 F	X
56	2		*FRONT CHASSIS LH & RH	0.00	0.00	*600.00 F	X
57	2		*FRONT WHEELHOUSE PANEL LH & RH	0.00	0.00	*360.00 F	X
58	1		*ENGINE MOUNTING FRONT	0.00	0.00	*70.00 F	X
59	1		*ENGINE MOUNTING RH	0.00	0.00	*115.00 F	X
60	1		*ENGINE MOUNTING REAR	0.00	0.00	*75.00 F	X
61	1		*GEZRBOX MOUNTING LH	0.00	0.00	*80.00 F	X
62	1		*NUMBER PLATE	0	0.00	*35.00 FS	X
63	1		*RADIATOR COOLANT	0	0.00	*30.00 FS	2014

F=Franchise part. S=SpcNett.

Sub Total (S\$)	6,654.00
+ Margin on L,N Items 10.00% (S\$)	658.90
Total Parts (S\$)	7,312.90

Ah Lim Motor Company/SLD855L/24/04/2019 11:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			201
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	100.00 ✓
3	TO REMOVE AND REFIT ENGINE ASSEMBLY WITH TRANSMISSION TO FACILITATE REPAIR.	New (Photo)	350.00 280
4	TO REMOVE & REPLACE ENGINE MOUNTING & GEZRBX MOUNTING	New	150.00 120
5	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	280.00 220
6	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL; FRONT CHASSIS ; FRONT WHEELHOUSE PANEL TO KNOCK & REPAIR FRONT DOOR RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	2,200.00 1260
7	TO SPRAY FRONT BONNET; FRONT BUMPER; FRONT FENDER LH & RH; FRONT DOOR RH; RADIATOR SUPPORT PANEL; FRONT CHASSIS LH & RH; FRONT WHEELHOUSE PANEL LH & RH.	New	2,000.00 1260
Gross Labour Cost (S\$)			5,120.00

Ah Lim Motor Company/SLD855L/24/04/2019 11:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

8070.70 B4 exas

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Estimate No: MC1900328
Date: 30 Apr 2019
Policy No: D18MTPV01008413
Veh Reg No: SLD855L
Make/Model: TOYOTA COROLLA
ALTIS CLASSIC 1.6

Your Ref No: SLD855L
Claim Type: Own Damage
Accident Date: 18/04/2019

Estimate Repair Cost to Vehicle No :SLD855L

Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary Parts to Repair				
SPARE PARTS				
1 BATTERY TOP BRACKET		1 PC	35.00	✓
2 BATTERY BASE CARRIER		1 PC	35.00	—
3 BATTERY BASE CARRIER BRACKET		1 PC	20.00	—
4 FRONT CROSSMEMBER TO SUPPORT PANEL		1 PC	150.00	✓
5 BATTERY (+) COVER		1 PC	0.0000	check price/special order
			240.00	
	Add 10%		24.00	264.00
LABOUR				
6 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.		1 PC	350.00	200
7 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	60.00	✓
				410.00
Amount Before Excess			S\$ 674.00	
GST Amount			S\$ 47.18	
Total Amount payable			S\$ 721.18	

The above vehicle was surveyed by KENNETH KONG -LKK on 24/04/2019

For AH LIM MOTOR COMPANY
AH LIM MOTOR CO.
ANG MO KIO INDUSTRIAL PARK 2A
#01-09, AMK AUTOPOINT
SINGAPORE 568047
AUTHORISED SIGNATURE

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Apr 2019 Sendback Est	24 Apr 2019 11:09 S\$12,432.90	24 Apr 2019 13:43 Edit Adj Rpt	S\$8,070.70 Edit Estimates	S\$8,070.70 View Rpt		Pending for Survey Report Cancel Case
Supp #1	06 Jul 2019 11:21	06 Jul 2019 11:24 S\$674.00	06 Jul 2019 11:24			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	TEO KENG HWA, ID: S7273790C, Tel: +6598343013, Email: KENGHWA.TEO@GMAIL.COM								
Vehicle Reg. No.:	SLD855L	Date of Loss:	18/04/2019 19:00 - :59 [34 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / CMTD1901970	Policy/Cover Note No.:	D18MTPV01008413 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 06/05/2019]								
Driver/Custodian:	TEO KENG HWA (46 / Male), NRIC: S7273790C, Tel: +6598343013 Email: KENGHWA.TEO@GMAIL.COM								
Adj Asg. Remarks:	FOR EXCESS & AUTHORISATION, PLEASE REFER TO THE HANDLER								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- SOMPO_SG (16/07/2019): Alert - Adj Mandate Approved (S\$9189.90) - SLD855L - Claim Handler: Ruth Chua Ge... - SOMPO_SG (04/07/2019): Please submit Finalisation report (OD SLD855L) - SOMPO_SG (25/04/2019): OD authorisation given (SLD855L) - SOMPO_SG (25/04/2019): Alert - Adj Mandate Approved (S\$8665.90) - SLD855L - Claim Handler: Ruth Chua Ge... - SOMPO_SG (24/04/2019): Please expedite OD repairs - Pls verify chassis no and engine no of SLD855L - CM...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLD855L (CMTD1901970)

OD

Apr 18 2019 7:00PM

[TEO KENG HWA]

Ah Lim Motor Company

Upload Documents		Upload Photos	Compose New Letter	View View in Browser v	
Assessment Reports				1 per page v	☒
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
1	20/04/19 13:02	Accident Statement		Load HTM	
2	24/04/19 11:09	Repairer Estimates		Load HTM	
3	06/07/19 11:24	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/04/19 11:45	Adjuster Immediate Advice		Load HTM	
2	16/07/19 09:42	Adjuster Immediate Advice		Load HTM	
3	16/07/19 09:51	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/04/19 11:48	General View		Load JPG	☒
2	25/04/19 11:48	General View		Load JPG	☒
3	25/04/19 11:48	General View		Load JPG	☒
4	25/04/19 11:48	General View		Load JPG	☒
5	25/04/19 11:48	General View		Load JPG	☒
6	25/04/19 11:48	General View		Load JPG	☒
7	25/04/19 11:48	General View		Load JPG	☒
8	25/04/19 11:48	General View		Load JPG	☒
9	25/04/19 11:48	General View		Load JPG	☒
10	25/04/19 11:48	General View		Load JPG	☒
11	25/04/19 11:48	General View		Load JPG	☒
12	25/04/19 11:48	General View		Load JPG	☒
13	25/04/19 11:48	General View		Load JPG	☒
14	25/04/19 11:48	General View		Load JPG	☒
15	25/04/19 11:48	General View		Load JPG	☒
16	25/04/19 11:48	General View		Load JPG	☒
17	25/04/19 11:48	General View		Load JPG	☒
18	25/04/19 11:48	General View		Load JPG	☒
19	25/04/19 11:48	General View		Load JPG	☒
20	25/04/19 11:48	General View		Load JPG	☒
21	25/04/19 11:48	General View		Load JPG	☒
22	25/04/19 11:48	General View		Load JPG	☒
23	25/04/19 11:48	General View		Load JPG	☒
24	25/04/19 11:48	General View		Load JPG	☒
25	25/04/19 11:48	General View		Load JPG	☒
26	25/04/19 11:48	General View		Load JPG	☒
27	25/04/19 11:48	General View		Load JPG	☒
28	25/04/19 11:48	General View		Load JPG	☒
29	25/04/19 11:48	General View		Load JPG	☒
30	25/04/19 11:48	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
31	25/04/19 11:48	General View	 Load JPG	☒
32	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
33	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
34	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
35	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
36	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
37	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
38	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
39	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
40	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
41	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
42	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
43	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
44	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
45	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
46	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
47	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
48	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
49	16/07/19 09:41	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	24/04/19 14:05	LTA DETAILS	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/04/19 11:45	SLD 855L GIA.pdf	 Load PDF	
2	25/04/19 11:45	ESTIMATE.pdf	 Load PDF	
3	16/07/19 09:40	SUPP.pdf	 Load PDF	
4	16/07/19 16:24	ESTIMATE & SUPP MARKED.pdf	 Load PDF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	20/04/19 12:26	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	20/04/19 13:02	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	20/04/19 12:26	Accident Photo	 Load JPG	☒
2	20/04/19 12:26	Accident Photo	 Load JPG	☒
3	20/04/19 12:26	Accident Photo	 Load JPG	☒
4	20/04/19 12:26	Accident Photo	 Load JPG	☒
5	20/04/19 12:26	Accident Photo	 Load JPG	☒
6	20/04/19 12:26	Accident Photo	 Load JPG	☒
7	20/04/19 12:26	Accident Photo	 Load JPG	☒
8	20/04/19 12:26	Accident Photo	 Load JPG	☒
9	20/04/19 12:26	Accident Photo	 Load JPG	☒
10	20/04/19 12:26	Accident Photo	 Load JPG	☒
11	20/04/19 12:26	Accident Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
12	20/04/19 12:26	Accident Photo	 Load JPG	☒
13	20/04/19 12:26	Accident Photo	 Load JPG	☒
14	20/04/19 12:26	Accident Photo	 Load JPG	☒
15	20/04/19 12:26	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	20/04/19 13:02	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19007212/KSD3E2

Date: 24/07/2019

REFERENCE

Insured/Claimant: TEO KENG HWA Policy No: D18MTPV01008413
Date of Loss: 18/04/2019 Nature of Claim: OD Claim No: CMTD1901970

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD855L**
Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZR574967
Reg. Date: 01/06/2016 (Man. Year: 2016) Chassis No: MR053REH104551317
Colour: Metallic Silver Odometer: 38329 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$73,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 7 mm
Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,576.90	4,550.70	3,026.20	39.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,530.00	3,520.00	2,010.00	36.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,106.90	8,070.70	5,036.20	38.42
+ GST 7.00/7.00% (S\$)	917.48	564.95	352.53	38.42
Nett Amount (S\$)	14,024.38	8,635.65	5,388.73	38.42

INSPECTION

Date of Assignment: 24/04/2019 Present Location: Ah Lim Motor Company (AMK)
Date Inspected: 24/04/2019 Inspected At: Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09
AMK Autopoint
Singapore 568047
Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD855L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WIPER GARNISH (WCP)	Cracked	220.00 F	*220.00 F
2	1		*FRONT BONNET (WCP)	Bent	265.00 F	*265.00 F
3	2		*FRONT BONNET HINGE LH & RH (WCP)	Bent / Distorted	40.00 F	*40.00 F
4	1		*FRONT BONNET INSULATOR - CHECK PRICE (WCP)	Serviceable	0.00 F	*- F
5	10		*FRONT BONNET INSULATOR CLIPS (WCP)	Not Necessary	10.00 F	*- F
6	1		*FRONT BONNET RUBBER FRONT (WCP)	Missing	110.00 F	*15.00 F
7	1		*FRONT BONNET INNER LOCK (WCP)	Distorted	45.00 F	*45.00 F
8	1		*FRONT BONNET CABLE (WCP)	Serviceable	28.00 F	*- F
9	1		*FRONT BONNET SPRAY NOZZLE LH & RH (WCP)	N/S Cracked / O/S Serviceable	30.00 F	*15.00 F
10	1		*FRONT GRILLE ASSY (CHROME) (WCP)	Cracked	140.00 F	*140.00 F
11	6		*FRONT GRILLE CLIPS (WCP)	Necessary	6.00 F	*6.00 F
12	1		*FRONT GRILLE TOP COVER (WCP)	Dented	38.00 F	*38.00 F
13	2		*HEADLAMP LH & RH (WCP)	Mtg Cracked	440.00 F	*440.00 F
14	1		*FRONT BUMPER (WCP)	Cracked	170.00 F	*170.00 F
15	2		*FRONT BUMPER SIDE RETAINER LH & RH (WCP)	Distorted	40.00 F	*40.00 F
16	15		*FRONT BUMPER CLIPS (WCP)	Necessary	15.00 F	*15.00 F
17	1		*FRONT BUMPER LOWER AIR GRILLE (WCP)	Dented / Distorted	55.00 F	*55.00 F
18	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	110.00 F	*110.00 F
19	1		*FRONT BUMPER SPONGE (WCP)	Cracked	35.00 F	*35.00 F
20	2		*FOGLAMP LH & RH (WCP)	Serviceable	160.00 F	*- F
21	1		*FOGLAMP COVER LH & RH (WCP)	N/S Missing	70.00 F	*35.00 F
22	1		*FRONT BUMPER UNDER COVER (WCP)	Cracked	55.00 F	*55.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
23	10		*FRONT BUMPER UNDER COVER CLIPS (WCP)	Necessary	15.00 F	*15.00 F
24	2		*FRONT FENDER LH & RH (WCP)	Buckled	400.00 F	*400.00 F
25	2		*FRONT FENDER COWLING LH & RH (WCP)	Serviceable	96.00 F	*- F
26	16		*FRONT FENDER COWLING CLIPS (WCP)	Not Necessary	16.00 F	*- F
27	2		*FRONT FENDER DUAL VVTI LOGO LH & RH (WCP)	Necessary	50.00 F	*50.00 F
28	1		*RADIATOR SUPPORT PANEL (WCP)	Bent	180.00 F	*180.00 F
29	1		*BRACE PANEL (WCP)	Bent	35.00 F	*35.00 F
30	2		*HORN (WCP)	Serviceable	90.00 F	*- F
31	1		*AIR CON CONDENSER (WCP)	Punctured	280.00 F	*280.00 F
32	2		*AIR CON CONDENSER TOP BUSH LH & RH (WCP)	Serviceable	6.00 F	*- F
33	2		*AIR CON CONDENSER BOTTOM BUSH LH & RH (WCP)	Serviceable	6.00 F	*- F
34	1		*AIR CON CONDENSER PIPE (COND-COMP) (WCP)	Serviceable	150.00 F	*- F
35	1		*AIR CON CONDENSER PIPE (COND-VALVE) (WCP)	Bent	210.00 F	*210.00 F
36	1		*AIR CON CONDENSER PIPE (COMP-VALVE) (WCP)	Serviceable	140.00 F	*- F
37	1		*RADIATOR ASSY (WCP)	Punctured	320.00 F	*320.00 F
38	1		*RADIATOR FAN MOTOR (WCP)	Serviceable	120.00 F	*- F
39	1		*RADIATOR FAN BLADE (WCP)	Serviceable	45.00 F	*- F
40	1		*RADIATOR FAN COWLING (WCP)	Cracked	65.00 F	*65.00 F
41	2		*RADIATOR TOP BRACKET LH & RH (WCP)	Repair	60.00 F	*- F
42	2		*RADIATOR TOP BUSH LH & RH (WCP)	Serviceable	16.00 F	*- F
43	2		*RADIATOR BOTTOM BUSH LH & RH (WCP)	Serviceable	30.00 F	*- F
44	1		*RADIATOR TOP COWLING (WCP)	Serviceable	35.00 F	*- F
45	1		*RADIATOR TOP HOSE (WCP)	Serviceable	18.00 F	*- F
46	1		*RADIATOR BOTTOM HOSE (WCP)	Serviceable	18.00 F	*- F
47	1		*INTAKE MANIFOLD (WCP)	Serviceable	280.00 F	*- F
48	1		*AIR FILTER BOX ASSY (WCP)	Cracked	250.00 F	*250.00 F
49	1		*AIR INTAKE HOSE (WCP)	Dented	48.00 F	*48.00 F
50	1		*RESONATOR TANK (WCP)	Dented	48.00 F	*48.00 F
51	1		*FUSE BOX TOP (WCP)	Serviceable	35.00 F	*- F
52	1		*FUSE BOX LOWER (WCP)	Serviceable	40.00 F	*- F
53	1		*BATTERY TRAY (WCP)	Serviceable	28.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*WIPER WASHER TANK (WCP)	Dented	62.00 F	*62.00 F
55	1		*WIPER WASHER TANK NECK (WCP)	Serviceable	15.00 F	*- F
56	2		*FRONT CHASSIS LH & RH (WCP)	Repair	600.00 F	*- F
57	2		*FRONT WHEELHOUSE PANEL LH & RH (WCP)	Repair	360.00 F	*- F
58	1		*ENGINE MOUNTING FRONT (WCP)	Cracked	70.00 F	*70.00 F
59	1		*ENGINE MOUNTING RH (WCP)	Serviceable	115.00 F	*- F
60	1		*ENGINE MOUNTING REAR (WCP)	Cracked	75.00 F	*75.00 F
61	1		*GEZRBX MOUNTING LH (WCP)	Serviceable	80.00 F	*- F
62	1		*NUMBER PLATE	Bent	35.00 FS	*35.00 FS
63	1		*RADIATOR COOLANT	Necessary	30.00 FS	*20.00 FS
Supplementary #1						
64	1		*BATTERY TOP BRACKET (WCP)	Bent	35.00 F	*35.00 F
65	1		*BATTERY BASE CARRIER (WCP)	Dented	35.00 F	*35.00 F
66	1		*BATTERY BASE CARRIER BRACKET (WCP)	Distorted	20.00 F	*20.00 F
67	1		*FRONT CROSSMEMBER TO SUPPORT PANEL (WCP)	Bent	150.00 F	*150.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	6,894.00	4,142.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	682.90	408.70
Total Parts (\$\$)	7,576.90	4,550.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	20.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	100.00	100.00
3	TO REMOVE AND REFIT ENGINE ASSEMBLY WITH TRANSMISSION TO FACILITATE REPAIR.	New	350.00	280.00
4	TO REMOVE & REPLACE ENGINE MOUNTING & GEZRBX MOUNTING	New	150.00	120.00
5	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	280.00	220.00
6	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL;FRONT CHASSIS ;FRONT WHEELHOUSE PANEL.TO KNOCK & REPAIR FRONT DOOR RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	2,200.00	1,260.00
7	TO SPRAY FRONT BONNET;FRONT BUMPER;FRONT FENDER LH & RH;FRONT DOOR RH;RADIATOR SUPPORT PANEL;FRONT CHASSIS LH & RH;FRONT WHEELHOUSE PANEL LH & RH.	New	2,000.00	1,260.00
Supplementary #1				
Labour Items				
8	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	New	350.00	200.00
9	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	60.00	60.00
Gross Labour Cost (S\$)			5,530.00	3,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >