

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

ISNAN BIN KHALID

23/04/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Con Pac
Ashes.

Accident date: 20/04/2019

Estimated repair cost for vehicle no: SMC7355K MITSUBISHI ATTRAGE 1.2 A '18

CHASSIS: MMBSTA13AJH002486

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$854.20 ✓
2	2	Rear Boot Lid Hinge <i>Best</i>	\$234.00	\$468.00 ✓
3	1	Rear Boot Lid Emblem Logo <i>3pc</i>		\$45.50 ✓
4	1	Rear Boot Lid Attrage Logo		\$32.50 ✓
5	1	Rear Boot Lid Mivec Technology Logo <i>3pc</i>		\$31.00 ✓
6	1	Rear Boot Lid Cc Logo		\$35.00 ✓
7	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$58.30	\$116.60 +
8	1	Rear Boot Lid Center Chrome Moulding <i>cracked</i>		\$206.30 ✓
9	1	Rear Boot Lid Outer Lock Switch Button <i>new</i>		\$85.70 +
10	1	Rear Boot Lid Inner Lock <i>changed</i>		\$198.70 ✓
11	1	Rear Boot Lid Inner Rubber <i>lit</i>		\$180.20 ✓
12	2	Rear Tail Lamp <i>cracked</i>	\$336.50	\$673.00 ✓
13	4	Rear Tail Lamp Clip <i>in</i>	\$8.00	\$32.00 ✓
14	2	Rear Tail Lamp Panel <i>both dented</i>	\$169.20	\$338.40 ✓
15	1	Rear Bumper <i>behind</i>		\$835.50 ✓
16	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 30
17	2	Rear Bumper Side Retainer <i>new</i>	\$47.30	\$94.60 ✓
18	2	Rear Bumper Side Reflector <i>cracked</i>	\$44.20	\$88.40 ✓
19	2	Rear Bumper Inner Bracket <i>new</i>	\$82.60	\$165.20 +
20	2	Rear Fender <i>lit Buckleed</i>	\$843.80	\$1,687.60 843.80
21	2	Rear Fender Inner Panel <i>Repair</i>	\$375.70	\$751.40 +
22	2	Rear Fender Cowling <i>new</i>	\$39.80	\$79.60 +
23	16	Rear Fender Cowling Clip <i>new</i>	\$6.50	\$104.00 +
24	2	Rear Fender Inner Trim Board <i>3/4s total</i>	\$487.60	\$975.20 + 410
25	16	Rear Fender Inner Trim Board Clip <i>in new</i>	\$6.50	\$104.00 + 60
26	1	Rear End Panel <i>cracked</i>		\$397.50 ✓
27	1	Rear End Panel Top Garnish <i>behind</i>		\$145.50 ✓
28	1	Rear End Panel Air Duct <i>behind new</i>		\$108.70 X

29	1	Rear End Panel Air Duct Cover	cancel		\$119.80	-
30	1	Rear End Panel Lock Alarm Sensor	cancel		\$267.60	85
31	1	Rear End Panel Antenna			\$235.70	95
32	1	Rear Spare Tyre Panel Assy	Regr		\$1,427.30	+
33	1	Rear Spare Tyre Panel Carpet	new		\$248.70	+
34	1	Rear Spare Tyre Panel Top Cover	cancel		\$304.20	-
35	1	Rear Exhaust			\$604.90	+
36	2	Rear Exhaust Mounting	2 new	\$38.70	\$77.40	+
37	1	Rear Center Exhaust			\$1,204.70	+

6604.10
5943.69

Subtotal:- \$13,389.60

S/n	Qty	Items / Special Nett	U/price	Amount
38	1	Rear Boot Lid Number Plate	new	\$50.00 +
39	1	Rear Boot Lid Top Spoiler	Reprinted	\$850.00 +
40	1	Rear Boot Lid Camera	Paint	\$650.00 380
41	1	Rear Bumper Reverse Sensor	Paint	\$380.00 200
42	1	Body Kit Assembly (1 Set)	Paint.	\$3,800.00 2000

2580

Subtotal:- \$5,730.00

Labour charges

To remove & refit rear cushion	\$280.00 80
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To remove & refit body kit	\$380.00 2w
To remove & refit rear camera	\$50.00 ✓
To remove & refit reverse sensor	\$120.00 50
To remove & refit rear exhaust & center exhaust	\$380.00 *
To check wiring	\$150.00 30
Tuff kote	\$150.00 100
Towing fee	\$150.00 x60
Panel beating	\$2,000.00 1400
Spray painting	\$1,800.00 1600

3740

Subtotal :- \$5,180.00

Total:- \$24,299.60

total 12263.69

H/s 9.8K

Adrian Lj
H/s 23/04/19.

09 Days.

9.8K

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: