

Wed May 2010 2:00 PM

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Company: SOMPO INSURANCE SINGAPORE PTE LTD

(MOTOR CLAIMS DEPARTMENT)

NO 50, RAFFLES PLACE, #05-01/06

SINGAPORE LAND TOWER, S(048623)

64616555

FAX: 62257947

Model : HYUNDAI ACCENT

No. KMHCU41BTKU465076

ne of Accide 23.04.2019/2315

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting

- To display damaged part(s) during resurvey

* Parts prices are subject to confirmation

* Third party survey is on a "Without Disaffection" basis

- No illegal modification(s) is allowed

• Supplementary term(s) must be reviewed and approved by the Editor-in-Chief.

is subject to final approval from Insurance Company

Vehicle Condition by Repairer

SMK4972G

Signature: _____

Date:

als Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	SPARE TYRE FLOOR PANEL <i>✓ BUC</i>	1	\$ 896.90	\$ 896.90
2	SPARE TYRE TOP MAT <i>✓ BT</i>	1	\$ 258.20	\$ 100 258.20
3	REAR END PANEL <i>✓ BT</i>	1	\$ 608.70	\$ 608.70
4	REAR END PANEL TOP GARNISH <i>✓ ee</i>	1	\$ 192.50	\$ 192.50
5	BOOTLID <i>✓ BUC</i>	1	\$ 1,198.60	\$ 1,198.60
6	BOOTLID INNER TRIM <i>✓ TN</i>	1	\$ 285.10	\$ 285.10
7	BOOTLID HINGE <i>✓ BT</i>	2	\$ 145.80	\$ 291.60
8	BOOTLID INNER TRIM <i>X</i>	1	\$ 105.60	\$ 105.60
9	BOOTLID NUMBER PLATE LAMP <i>X</i>	2	\$ 80.90	\$ 161.80
10	BOOTLID LOGO <i>✓ ee</i>	1	\$ 85.60	\$ 85.60
11	BOOTLID "ACCENT" EMBLEM <i>✓ REC</i>	1	\$ 79.50	\$ 79.50
12	BOOTLID WEATHERSTRIP <i>✓ TWI</i>	1	\$ 192.60	\$ 192.60
13	BOOTLID INNER LOCK <i>✓ BT</i>	1	\$ 185.90	\$ 185.90
14	BOOTLID OUTER GARNISH <i>✓ ee</i>	1	\$ 236.70	\$ 236.70
15	BOOTLID NUMBER PLATE LAMP <i>X</i>	2	\$ 80.90	\$ 161.80
16	REAR BUMPER <i>✓ ee</i>	1	\$ 679.80	\$ 679.80
17	REAR BUMPER REFLECTORS <i>✓ REC</i>	2	\$ 127.50	\$ 255.00
18	REAR BUMPER SIDE RETAINERS <i>✓ ee</i>	2	\$ 75.90	\$ 151.80
19	REAR BUMPER REINFORCEMENT <i>✓ BT</i>	1	\$ 759.60	\$ 759.60
20	REAR REINFORCEMENT BRACKETS <i>✓ BT</i>	2	\$ 69.70	\$ 139.40
21	REAR FENDER <i>✓ BUC</i>	2	\$ 1,845.60	\$ 3,691.20
22	REAR FENDER INNER TRIM <i>✓ TN</i>	2	\$ 389.50	\$ 779.00
23	REAR FENDER INNER COWLING <i>✓ TN</i>	1	\$ 195.60	\$ 195.60
24	REAR SILENCER BOX <i>✓ BT</i>	1	\$ 745.80	\$ 745.80
25	REAR SILENCER BOX MOUNTING <i>X</i>	1	\$ 45.60	\$ 45.60
26	REAR SILENCER BOX HEAT SHIELD <i>X</i>	1	\$ 187.20	\$ 187.20
27	REAR WINDSCREEN MOULDING <i>✓ REC</i>	1	\$ 185.90	\$ 185.90
				\$ 12,998.20

Price	Cost
10	10
20	20
30	30
40	40
50	50
60	60
70	70
80	80
90	90
100	100

PARTS DISCOUNT 20%

S	10,398.56
---	-----------

floor panel spray 2 / 258.2
pl.

7792.5

20% 6234

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1*	REAR BUMPER CLIPS / <i>acc</i>	1 SET	\$ 30.00	\$ <i>20</i> 30.00
2	REAR NUMBER PLATE WITH CASING / <i>acc</i>	1 SET	\$ 50.00	\$ <i>40</i> 50.00
3	REAR FENDER COWLING <i>clips / acc</i>	2 SET	\$ 60.00	\$ <i>20</i> 60.00
4	REAR FENDER INNER TRIM <i>clips / acc</i>	2 SET	\$ 60.00	\$ <i>20</i> 60.00
5	BOOTLID INNER TRIM <i>clips / acc</i>	1 SET	\$ 30.00	\$ <i>10</i> 30.00
6	END PANEL TOP GARNISH CLIPS / <i>acc</i>	1 SET	\$ 30.00	\$ <i>10</i> 30.00
7	REVERSE SENSORS / <i>DM</i>	1 SET	\$ 250.00	\$ <i>200</i> 250.00
8	REVERSE SENSORS HARDNESS / <i>DM</i>	1	\$ 280.00	\$ <i>100</i> 280.00
9	END PANEL TOP GARNISH CLIPS / <i>acc</i>	1 SET	\$ 30.00	\$ <i>10</i> 30.00
10	EMERGENCY SIGN KIT <i>X</i>	1	\$ 200.00	\$ <i>X</i> 200.00
11	END PANEL SEALANTS / <i>acc</i>	2	\$ 80.00	\$ <i>40</i> 80.00
12	WINDSCREEN SEALANTS / <i>acc</i>	2	\$ 80.00	\$ <i>40</i> 80.00
13	SPARE TYRE FLOOR INSULATOR <i>X</i>	1	\$ 250.00	\$ <i>X</i> 250.00
Total Special Nett Items				\$ <i>1,430.00</i>

repeat.

S/O

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 3,000.00

1600 ~~*1400*~~

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,800.00

1200

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ <i>80</i> 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ <i>60</i> 150.00
TO REMOVE/ REFIT REAR WINDSCREEN TO FACILITATE FENDER REPLACEMENT	\$ <i>100</i> 180.00
TO APPLY SEALANT TO THE AFFECTED AREAS	<i>NN</i> \$ <i>X</i> 180.00
TO REMOVE/ REFIT WIRING CHECKS	\$ <i>30</i> 120.00
TO REMOVE/ REFIT FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ <i>60</i> 250.00
TO REMOVE/ REFIT / REPLACE REAR SILENCER BOX	\$ <i>60</i> 180.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ <i>40</i> 180.00
TO REMOVE AND REPLACE/ REFIT BOOTLID MECHANISM	\$ <i>50</i> 200.00

Total Others Cost

GRAND TOTAL

\$ 1,640.00

2380

CAS GARAGE PTE LTD

UEN 201828067M

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

12 Days.

umpsum Repair.

After repair

Gmo Riap.

24/4/19.

10600.49

20% 8450.

21/3 Confirmed with Allan

CAS GARAGE PTE LTD

Person Incharge: Allan

Direct Contact: +65 8782 7171

mail: allangoh.cas@gmail.com

fax: +65 6509 9501

Consultants hence notify the Repairer of the following:

- resurvey before/after spray painting
- display damaged parts during resurvey
- estimates are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary terms must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer

Signature:

Date:

REQUEST FOR SUPPLEMENTS PARTS

	Date of Collection	
SMK4972G	Date of Request	25.04.2019
HYUNDAI ACCENT	Number of Days to Extend (If any)	

Item No	Part Description	Quantity	Unit Price
	REAR FENDER AIR DUCT RH / <i>el</i>	1	\$95.60 <i>38</i>
	REAR BOOT SMART RELEASE ANTENNA(OUTER) / <i>dam</i>	1	\$285.70 <i>128.86</i>
	REAR BOOT SMART KEY ANTENNA(INNER) / <i>dam</i>	1	\$285.70 <i>128.86</i>
	REAR REINFORCEMENT METAL BRACKET RH / <i>mis</i>	1	\$185.60 <i>69.2</i>
	REAR BOOT TOP PANEL RH / <i>bu</i>	1	\$325.80 <i>230.7</i>

<<< Please submit photographs for damaged parts >>>

595.62

20%, 476.49

CAS GARAGE PTE LTD

UEN 201828067M

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

Amo Qp.

25/4/19.