

ASS. REC. BY:

REF: CS/CMO19007216 / G9d3n2

Special Instruction:

Survey: G9

minim

ASSIGNMENT (Office)From (Person): Thelma Chooof smpDate/Time: 24.4.19 4:01 p.m

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMK 49729Insured: GBF 5294 Eat Workshop m/s CAS GarageTel: 87827171of 1 Kaki Bukit Ave 6 # 02-22Policy No: D18MTHKVE003196Claim No: CMTD1902024

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23.4.2019

CA / REV / REP. / REV 24 HRS

"w"

Date/Time: 24.4.19 2:26 p.m

H.O.D. Endorsement:

Person Contacted: AllanVehicle IN / OUT

Date/Time	Action/Instruction	Estimate (✓)
	SMK 49729 - X	
	GBF 5294 E - X	
25/4/19 @	2.59pm revised to Thelma Choo via Messenger.	
31/3/20	XCR finalised with Allan is \$8450, 12 days. (Red 611075-12, 571/2)	

Barcode

612

REF:

SMO


2206D

ASSIGNMENT

Front: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐
 To inspect Vehicle No: _____
 at Workshop n/s Cas Garage
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 12 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Veh No: SMK4972G Yr Regn: 12 Apr 2019
 Type: ☒ M Car ☐ M.Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover
 Truck / Trailer or _____
 Make: Hyundai Accent cc. 1368
 Colour: Red A/C ☐ Insured ☐ Std ☐ NI ☐ NA
 Sp. Reading: 814 T/Radio: Insured ☐ Std ☐ NI ☐ NA
 Eng/No: _____
 C/No: KMHCU41BTKU465076
 Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ Burnt
 Steering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or
 Brake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or
 Modi: ☒ Nil ☐ S/Rim ☐ STD A/Rim or
 Tyre Size: F: 175/70R14
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or KUMHO

Front: _____ Rear: _____
 R/Bal: 9 mm R/Bal: 9 mm
 L/Bal: 9 mm L/Bal: 9 mm
 D.O.A. _____ D.O.I. 24-04-19
 Survey held at w/s 5:30pm
 Des. of Damages: Frt ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 31 MAR 2020

Date/Time, File Pass to? ☐ : Preli. Report

1) 31/3 12:00pm ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee

Transportation:

☐ S + RS ☐ SI

☐ Photos

☐ Others

☐

TOTAL

Report Format: WER

Lump Sum / I.B. (\$) 8450

450
11

461

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 25 Apr 2019

Preliminary Advice

Insured Vehicle No	: GBF5294E	Accident Date	: 23/04/2019
TP Vehicle No	: SMK4972G	Assignment Date	: 24/04/2019
Make	: HYUNDAI ACCENT	Est. Duration of Repair	: 12.00
Date of Inspection	: 24/04/2019		
Inspection At	: CAS GARAGE PTE LTD (HQ) NO.1, KAKI BUKIT AVE 6, #02-22 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,268.56
Revised Amount	:S\$	10,726.40
Check Items (Estimated)	:S\$	4,342.72
Total	:S\$	15,069.12

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Apr 2019		24 Apr 2019 14:01 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:		DIESEL INJECTRONIC PTE LTD, Co. Reg. No.: 200206731N		[Created by insurer]
Main Claimant:		HAFIDAH BINTE SAIDOLLAH, ID: S8312206D		
Vehicle Reg. No.:		SMK4972G	Date of Loss:	23/04/2019 00:00 - :59
Claim Type:		TP / CMTD1902024	Policy/Cover Note No.:	D18MTHCVE003196 (Comprehensive)
Vehicle Reg. No. (Insured):		GBF5294E	Policy No. (Claimant):	
			Excess:	
Repairer:		Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 6, #02-22 Autobay, 417883 Kaki Bukit - Tel:		
Handling Insurer:		Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/05/2019]		
Adj Asp. Remarks:		WS: ALLAN GOH 8782 7171 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2206D
Vehicle Details	
Vehicle No.:	SMK4972G
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Apr 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ACCENT (RB) 1.4 CVT
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	G4LCKU145787
Chassis No.:	KMHCU41BTKU465076
Maximum Power Output:	73.6 kW (98 bhp)
Open Market Value:	\$8,949.00
Original Registration Date:	12 Apr 2019
First Registration Date:	12 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$8,949.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Apr 2029
PARF Rebate Amount:	\$6,711.00
Intended COE Rebate Details	
COE Expiry Date:	11 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$29,159.00
COE Rebate Amount:	\$29,052.00
Total Rebate Amount:	\$35,763.00

The information contained herein is correct as at 25 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/04/2019 10:25
Date Of Accident	23/04/2019 23:15
Exact Location Of Accident	ALONG BUKIT BATOK ROAD TOWARDS PIE (TUAS/CHANGI)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK4972G
Insured/Policyholder	
Name Of Registered Owner	HAFIDAH BINTE SAIDOLLAH
NRIC No	S8312206D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96746660
Alternative Phone No	OFFICE-96746660
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	ACCENT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN041442
Cover Note Number	CN041442
Driver	
Name of Driver	SITI AISYAH BINTE IRWAN
NRIC No	S8909949H
Date Of Birth	23/03/1989
Occupation	INDOOR
Date Of Driving Pass	30/10/2010
Driving Experience	8 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-85886160
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address: 548B SEGAR ROAD
#14-672

Postcode: 672548

Was driver an employee of the Insured's Company: NO

If No, Relationship of the Driver with the Insured: RELATIVE

Vehicle Registration Number of Driver's Own Vehicle: -

Insurance Company of Driver's Own Vehicle: -

General Information of the Accident

Type Of Accident: COLLISION - HEAD TO REAR

Weather Conditions: CLEAR

Road Surface: DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident: 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver): 3

Passenger 1: NAME: : HAFIDAH BINTE SAIDOLLAH
GENDER: : FEMALE

Passenger 2: NAME: : MARDIAH BT KHOZALI MUSA
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: FILE TOO LARGE

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number: GBF5294E

Vehicle Make/Model/Colour:

Details Of Properties:

Vehicle Category: COMMERCIAL VEHICLE

Name of Driver:

NRIC/Passport Number:

Contact Number:

Address:

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

SITI AISYAH BINTE IRWAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

HAFIDAH BINTE SAIDOLLAH

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 3

Name

MARDIAH BT KHOZALI MUSA

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the signing of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
(Name:
NRIC/TIN No.):

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time

Reporting Centre Personnel's Signature
 Name:
 NRIC/IN No:

On 23.04.19 at about 2315 hours at the T-Junction of Bukit Batok Road and Bukit Batok West Ave 6 (77F). I was on Bukit Batok Road heading towards PIE (TUAS/ Changi Airport) traveling at Lane 2.

I saw the traffic light changed to amber and I slowed down and stopped my vehicle (A). Vehicle (B) came from the back and hit directly at rear portion of my vehicle causing severe damages to my vehicle.

There were 2 more passengers in my vehicle.

Vehicle (A) : SMK4972G

Vehicle (B) : GBF5294E

Aysha

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATEInsurance Company: SOMPO INSURANCE SINGAPORE PTE LTD
(MOTOR CLAIMS DEPARTMENT)Address: NO 50, RAFFLES PLACE, #05-01/06
SINGAPORE LAND TOWER, S(048623)

Telephone: 64616555 Fax: 62257947

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed

Date: 24.04.2019
is subject to final approval from Insurance Company

Vehicle No: SMK4972G
Insured by Repairer
Signature:
Date:

Make/ Model : HYUNDAI ACCENT

Chassis No : KMHCU41BTKU465076

Date/Time of Accide 23.04.2019/2315

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	SPARE TYRE FLOOR PANEL ?	1	\$ 896.90		\$ 896.90
2	SPARE TYRE TOP MAT ?	1	\$ 258.20		\$ 258.20
3	REAR END PANEL / BT	1	\$ 608.70		\$ 608.70
4	REAR END PANEL TOP GARNISH / de	1	\$ 192.50		\$ 192.50
5	BOOTLID / Bue	1	\$ 1,198.60		\$ 1,198.60
6	BOOTLID INNER TRIM / TN	1	\$ 285.10		\$ 285.10
7	BOOTLID HINGE / BT	2	\$ 145.80		\$ 291.60
8	BOOTLID INNER TRIM ?	1	\$ 105.60		\$ 105.60
9	BOOTLID NUMBER PLATE LAMP ?	2	\$ 80.90		\$ 161.80
10	BOOTLID LOGO / de	1	\$ 85.60		\$ 85.60
11	BOOTLID "ACCENT" EMBLEM / de	1	\$ 79.50		\$ 79.50
12	BOOTLID WEATHERSTRIP / Twi	1	\$ 192.60		\$ 192.60
13	BOOTLID INNER LOCK / BT	1	\$ 185.90		\$ 185.90
14	BOOTLID OUTER GARNISH / de	1	\$ 236.70		\$ 236.70
15	BOOTLID NUMBER PLATE LAMP X Repeat	2	\$ 80.90		\$ 161.80
16	REAR BUMPER / de	1	\$ 679.80		\$ 679.80
17	REAR BUMPER REFLECTORS / de	2	\$ 127.50		\$ 255.00
18	REAR BUMPER SIDE RETAINERS / de	2	\$ 75.90		\$ 151.80
19	REAR BUMPER REINFORCEMENT ?	1	\$ 759.60		\$ 759.60
20	REAR REINFORCEMENT BRACKETS ?	2	\$ 69.70		\$ 139.40
21	REAR FENDER / Bue	2	\$ 1,845.60		\$ 3,691.20
22	REAR FENDER INNER TRIM ?	2	\$ 389.50		\$ 779.00
23	REAR FENDER INNER COWLING ?	2	\$ 195.60		\$ 391.20
24	REAR SILENCER BOX ?	1	\$ 745.80		\$ 745.80
25	REAR SILENCER BOX MOUNTING ?	2	\$ 45.60		\$ 91.20
26	REAR SILENCER BOX HEAT SHIELD ?	1	\$ 187.20		\$ 187.20
27	REAR WINDSCREEN MOULDING / de	1	\$ 185.90		\$ 185.90

Total List Price Cost**\$ 12,998.20****PARTS DISCOUNT 20%****\$ 10,398.56**

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	REAR BUMPER CLIPS / <i>acc</i>	1 SET	\$ 30.00		\$ 30.00
2	REAR NUMBER PLATE WITH CASING / <i>acc</i>	1 SET	\$ 50.00		\$ <i>40</i> 50.00
3	REAR FENDER COWLING <i>clips / acc</i>	2 SET	\$ 60.00		\$ 60.00
4	REAR FENDER INNER TRIM <i>clips / acc</i>	2 SET	\$ 60.00		\$ 60.00
5	BOOTLID INNER TRIM <i>clips - acc</i>	1 SET	\$ 30.00		\$ 30.00
6	END PANEL TOP GARNISH CLIPS / <i>acc</i>	1 SET	\$ 30.00		\$ 30.00
7	REVERSE SENSORS / <i>DM</i>	1 SET	\$ 250.00		\$ 250.00
8	REVERSE SENSORS HARDNESS ?	1	\$ 280.00		\$ 280.00
9	END PANEL TOP GARNISH CLIPS / <i>acc</i>	1 SET	\$ 30.00		\$ 30.00
10	EMERGENCY SIGN KIT ?	1	\$ 200.00		\$ 200.00
11	END PANEL SEALANTS / <i>acc</i>	2	\$ 80.00		\$ 80.00
12	WINDSCREEN SEALANTS / <i>acc</i>	2	\$ 80.00		\$ 80.00
13	SPARE TYRE FLOOR INSULATOR ?	1	\$ 250.00		\$ 250.00
Total Special Nett Items					\$ 1,430.00

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 3,000.00
<i>1400 - 1700</i>	
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,800.00
<i>1200</i>	
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ <i>80</i> 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ <i>60</i> 150.00
TO REMOVE /REFIT REAR WINDSCREEN TO FACILITATE FENDER REPLACEMENT	\$ <i>100</i> 180.00
TO APPLY SEALANT TO THE AFFECTED AREAS	\$ <i>X</i> 180.00
TO REMOVE/ REFIT WIRING CHECKS	\$ <i>30</i> 120.00
TO REMOVE/ REFIT FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ <i>60</i> 250.00
TO REMOVE/ REFIT / REPLACE REAR SILENCER BOX	\$ <i>60</i> 180.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ <i>40</i> 180.00
TO REMOVE AND REPLACE/REFIT BOOTLID MECHANISM	\$ <i>50</i> 200.00
Total Others Cost	\$ 1,640.00
<i>25/4/19</i> GRAND TOTAL	
	\$ 19,268.56

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

10-12 Days.
umpsm repair.

After repair photos
Gmo Riang.
24/4/19.

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax: +65 6509 9501

Consultants hence notify the Repairer of the following:

- Resurvey below after spray painting
- Respray damaged parts during resurvey
- Estimates are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Approved by Repairer
 Signature: _____
 Date: _____

REQUEST FOR SUPPLEMENTS PARTS

Accident Case Number		Date of Collection	/ /
Vehicle No	SMK4972G	Date of Request	25.04.2019
Vehicle Model	HYUNDAI ACCENT	Number of Days to Extend (If any)	

#N	Part Number	Part Description	Quantity	Unit Price
1		REAR FENDER AIR DUCT RH / <i>el</i>	1	\$95.60 <i>38</i>
2		REAR BOOT SMART RELEASE ANTENNA(OUTER) / <i>for</i>	1	\$285.70 <i>128.81</i>
3		REAR BOOT SMART KEY ANTENNA(INNER) / <i>for</i>	1	\$285.70 <i>128.81</i>
4		REAR REINFORCEMENT METAL BRACKET RH / <i>mis</i>	1	\$185.60 <i>69.20</i>
5		REAR BOOT TOP PANEL RH / <i>guc</i>	1	\$325.80 <i>73.70</i>

<<< Please submit photographs for damaged parts >>>

6mo Rep.

25/4/19.

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

**CAS GARAGE PTE LTD**

(Reg No: 201028067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: SOMPO INSURANCE SINGAPORE PTE LTD

(MOTOR CLAIMS DEPARTMENT)

Address: NO 50, RAFFLES PLACE, #05-01/06

SINGAPORE LAND TOWER, S(048623)

Telephone: 64616555 Fax: 62257947

Email: motorclaim@sompo.com.sg

Make/ Model : HYUNDAI ACCENT

Chassis No : KMHCU41BTKU465076

Date/Time of Accide 23.04.2019/2315

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: 24.04.2019

Vehicle Acknowledged by Repairer SMK4972G

Signature: _____

Date: _____

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	SPARE TYRE FLOOR PANEL ✓ BUC	1	\$ 896.90		\$ 896.90
2	SPARE TYRE TOP MAT ✓ BT	1	\$ 258.20		\$ 100 258.20
3	REAR END PANEL / BT	1	\$ 608.70		\$ 608.70
4	REAR END PANEL TOP GARNISH / BT	1	\$ 192.50		\$ 192.50
5	BOOTLID / BUC	1	\$ 1,198.60		\$ 1,198.60
6	BOOTLID INNER TRIM / TN	1	\$ 285.10		\$ 285.10
7	BOOTLID HINGE / BT	2	\$ 145.80		\$ 291.60
8	BOOTLID INNER TRIM X NN	1	\$ 105.60		\$ 105.60
9	BOOTLID NUMBER PLATE LAMP X NN	2	\$ 80.90		\$ 161.80
10	BOOTLID LOGO / MC	1	\$ 85.60		\$ 85.60
11	BOOTLID "ACCENT" EMBLEM / MC	1	\$ 79.50		\$ 79.50
12	BOOTLID WEATHERSTRIP / TWI	1	\$ 192.60		\$ 192.60
13	BOOTLID INNER LOCK / BT	1	\$ 185.90		\$ 185.90
14	BOOTLID OUTER GARNISH / EE	1	\$ 236.70		\$ 236.70
15	BOOTLID NUMBER PLATE LAMP X Repeat	2	\$ 80.90		\$ 161.80
16	REAR BUMPER / EE	1	\$ 679.80		\$ 679.80
17	REAR BUMPER REFLECTORS / GUL	2	\$ 127.50		\$ 255.00
18	REAR BUMPER SIDE RETAINERS / EE	2	\$ 75.90		\$ 151.80
19	REAR BUMPER REINFORCEMENT ✓ BT	1	\$ 759.60		\$ 759.60
20	REAR REINFORCEMENT BRACKETS ✓ BT	2	\$ 69.70		\$ 139.40
21	REAR FENDER / BUC	2	\$ 1,845.60		\$ 3,691.20
22	REAR FENDER INNER TRIM ✓ TN	2	\$ 389.50		\$ 779.00
23	REAR FENDER INNER COWLING PH X TN	2	\$ 195.60		\$ 391.20
24	REAR SILENCER BOX ✓ BT	1	\$ 745.80		\$ 745.80
25	REAR SILENCER BOX MOUNTING X NN	2	\$ 45.60		\$ 91.20
26	REAR SILENCER BOX HEAT SHIELD X NN	1	\$ 187.20		\$ 187.20
27	REAR WINDSCREEN MOULDING / MC	1	\$ 185.90		\$ 185.90
Total List Price Cost					\$ 12,998.20

PARTS DISCOUNT 20%

\$ 10,398.56

Floor Panel spony 2 / DE 258.2

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1*	REAR BUMPER CLIPS / <i>acc</i>	1 SET	\$ 30.00		\$ <i>20</i> 30.00
2	REAR NUMBER PLATE WITH CASING / <i>scr</i>	1 SET	\$ 50.00		\$ <i>40</i> 50.00
3	REAR FENDER COWLING <i>clips - acc</i>	2 SET	\$ 60.00		\$ <i>20</i> 60.00
4	REAR FENDER INNER TRIM <i>clips - acc</i>	2 SET	\$ 60.00		\$ <i>20</i> 60.00
5	BOOTLID INNER TRIM <i>clips - acc</i>	1 SET	\$ 30.00		\$ <i>10</i> 30.00
6	END PANEL TOP GARNISH CLIPS / <i>acc</i>	1 SET	\$ 30.00		\$ <i>10</i> 30.00
7	REVERSE SENSORS / <i>DM</i>	1 SET	\$ 250.00		\$ <i>200</i> 250.00
8	REVERSE SENSORS HARDNESS / <i>DM</i>	1	\$ 280.00		\$ <i>100</i> 280.00
9	END PANEL TOP GARNISH CLIPS / <i>acc</i>	1 SET	\$ 30.00		\$ <i>10</i> 30.00
10	EMERGENCY SIGN KIT <i>X NN</i>	1	\$ 200.00		\$ 200.00 <i>X</i>
11	END PANEL SEALANTS / <i>acc</i>	2	\$ 80.00		\$ <i>40</i> 80.00
12	WINDSCREEN SEALANTS / <i>acc</i>	2	\$ 80.00		\$ <i>40</i> 80.00
13	SPARE TYRE FLOOR INSULATOR <i>✓ replace</i>	1	\$ 250.00		\$ 250.00 <i>X</i>
Total Special Nett Items					\$ 1,430.00

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 3,000.00
<i>1600 1400 - 1700</i>	
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,800.00
<i>1200</i>	
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ <i>80</i> 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ <i>60</i> 150.00
TO REMOVE /REFIT REAR WINDSCREEN TO FACILITATE FENDER REPLACEMENT	\$ <i>100</i> 180.00
TO APPLY SEALANT TO THE AFFECTED AREAS <i>NN</i>	\$ <i>X</i> 180.00
TO REMOVE/ REFIT WIRING CHECKS	\$ <i>30</i> 120.00
TO REMOVE/ REFIT FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ <i>60</i> 250.00
TO REMOVE/ REFIT / REPLACE REAR SILENCER BOX	\$ <i>60</i> 180.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ <i>40</i> 180.00
TO REMOVE AND REPLACE/REFIT BOOTLID MECHANISM	\$ <i>50</i> 200.00
Total Others Cost	\$ 1,640.00
GRAND TOTAL	
	\$ 19,268.56

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax: +65 6509 9501

10-12 Days .
umpsm repair.
After repair
Gmo Riang.
24/4/19.

photos Consultants hence notify the Repairer of the following:

- Resurvey before/after spray painting
- Respray damaged part(s) during resurvey
- All works are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer

Signature: _____

Date: _____

19475.12

REQUEST FOR SUPPLEMENTS PARTS

	Date of Collection	
SMK49720	Date of Request	24.04.2019
HYUNDAI ACCENT	Number of Days to Extend (if any)	

Part Description	Quantity	Unit Price
REAR FENDER AIR DUCT RH / <i>el</i>	1	\$95.60 <i>38</i>
REAR BOOT SMART RELEASE ANTENNA(OUTER) / <i>50mm</i>	1	\$285.70 <i>128.86</i>
REAR BOOT SMART KEY ANTENNA(INNER) / <i>50mm</i>	1	\$285.70 <i>128.86</i>
REAR REINFORCEMENT METAL BRACKET RH / <i>mis</i>	1	\$185.60 <i>69.2</i>
REAR BOOT TOP PANEL RH / <i>Due</i>	1	\$325.80 <i>230.7</i>

Please submit photographs for damaged parts.

595.62

20%, 476.49

CAS GARAGE PTE LTD.
UEN 20192947M
1 KAKI BUNT AVENUE #02-22 AUTOBAY
SINGAPORE 417881

6mo Qy.

25/4/19.

**CAS GARAGE PTE LTD**

REG. NO. 20120200100

1 KAKI BUNT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417603

VEHICLE REPAIR ESTIMATE

Company: SOMPO INSURANCE SINGAPORE PTE LTD
 (NOT FOR CLAIMS DEPARTMENT)
 NO. 50, RAFFLES PLACE, #05-01/06
 SINGAPORE LAND TOWER, S(045623)
 Tel: 64816055 Fax: 63257947

Model: HYUNDAI ACCENTNo: KMHCL41BTK12465076Date of Accident: 23.04.2019/2315

LKK Auto Consultants hence notify
 the Repairer of the following:

- To survey before/after body painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- This policy survey is not a "Without Prejudice" basis
- No digital modification is allowed
- Supplementary items must be removed, etc.
- Is subject to final approval from Insurance Company

Vehicle Insured by: SOMPO

Signature:

Date:

Estimate Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

QTY	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	SPARE TYRE FLOOR PANEL <i>✓ BUC</i>	1	\$ 596.90	\$ 596.90
2	SPARE TYRE TOP MAT <i>✓ BT</i>	1	\$ 258.20	\$ 100 258.20
3	REAR END PANEL <i>✓ BT</i>	1	\$ 608.70	\$ 608.70
4	REAR END PANEL TOP GARNISH <i>✓ DE</i>	1	\$ 192.30	\$ 192.30
5	BOOTLID <i>✓ BUC</i>	1	\$ 1,198.60	\$ 1,198.60
6	BOOTLID INNER TRIM <i>✓ TN</i>	1	\$ 285.30	\$ 285.30
7	BOOTLID HINGE <i>✓ BT</i>	2	\$ 145.80	\$ 291.60
8	BOOTLID INNER TRIM <i>✓ X</i>	1	\$ 105.60	\$ 105.60
9	BOOTLID NUMBER PLATE LAMP <i>✓ X</i>	2	\$ 80.90	\$ 161.80
10	BOOTLID LOGO <i>✓ DE</i>	1	\$ 85.60	\$ 85.60
11	BOOTLID "ACCENT" EMBLEM <i>✓ DE</i>	1	\$ 79.50	\$ 79.50
12	BOOTLID WEATHERSTRIP <i>✓ TW</i>	1	\$ 192.60	\$ 192.60
13	BOOTLID INNER LOCK <i>✓ BT</i>	1	\$ 185.90	\$ 185.90
14	BOOTLID OUTER GARNISH <i>✓ DE</i>	1	\$ 236.70	\$ 236.70
15	BOOTLID NUMBER PLATE LAMP <i>✓ X</i>	2	\$ 80.90	\$ 161.80
16	REAR BUMPER <i>✓ DE</i>	1	\$ 679.80	\$ 679.80
17	REAR BUMPER REFLECTORS <i>✓ GEL</i>	2	\$ 127.50	\$ 255.00
18	REAR BUMPER SIDE RETAINERS <i>✓ DE</i>	2	\$ 75.90	\$ 151.80
19	REAR BUMPER REINFORCEMENT <i>✓ BT</i>	1	\$ 759.60	\$ 759.60
20	REAR REINFORCEMENT BRACKETS <i>✓ BT</i>	2	\$ 69.70	\$ 139.40
21	REAR FENDER <i>✓ BUC</i>	1	\$ 1,845.60	\$ 1,845.60
22	REAR FENDER INNER TRIM <i>✓ W</i>	1	\$ 389.50	\$ 389.50
23	REAR FENDER INNER COWLING <i>✓ TN</i>	1	\$ 195.60	\$ 195.60
24	REAR SILENCER BOX <i>✓ BT</i>	1	\$ 745.80	\$ 745.80
25	REAR SILENCER BOX MOUNTING <i>✓ X</i>	1	\$ 45.60	\$ 45.60
26	REAR SILENCER BOX HEAT SHIELD <i>✓ X</i>	1	\$ 187.20	\$ 187.20
27	REAR WINDSCREEN MOULDING <i>✓ DE</i>	1	\$ 185.90	\$ 185.90
Price Cost				\$ 12,998.20
PARTS DISCOUNT 20%				\$ 10,398.56

Floor Panel spongy *✓* 258.20 7792.5
DE.

20% 6234

580
165.4
132
150
X
X
60
166.8
X
463
137.2
46.6
390.8
1099.8
255.6
195.6
X
X
X

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR BUMPER CLIPS / AC	1 SET	\$ 30.00	\$ 20 30.00
2	REAR NUMBER PLATE WITH CASING / SD	1 SET	\$ 50.00	\$ 40 50.00
3	REAR FENDER COWLING clips / AC	2 SET	\$ 60.00	\$ 20 60.00
4	REAR FENDER INNER TRIM clips / AC	2 SET	\$ 60.00	\$ 20 60.00
5	BOOTLID INNER TRIM clips / AC	1 SET	\$ 30.00	\$ 10 30.00
6	END PANEL TOP GARNISH CLIPS / AC	1 SET	\$ 30.00	\$ 10 30.00
7	REVERSE SENSORS / DM	1 SET	\$ 250.00	\$ 200 250.00
8	REVERSE SENSORS HARDNESS / DM	1	\$ 280.00	\$ 100 280.00
9	END PANEL TOP GARNISH CLIPS / AC	1 SET	\$ 30.00	\$ 10 30.00
10	EMERGENCY SIGN KIT X	1	\$ 200.00	\$ X 200.00
11	END PANEL SEALANTS / AC	2	\$ 80.00	\$ 40 80.00
12	WINDSCREEN SEALANTS / AC	2	\$ 80.00	\$ 40 80.00
13	SPARE TYRE FLOOR INSULATOR X repeat.	1	\$ 250.00	\$ X 250.00
Total Special Net Items				\$ 1,430.00

S/O

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE HEAT, WELD, REALIGN AND ALIGN ALL PARTS	\$ 3,000.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,800.00

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 80 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 60 150.00
TO REMOVE/ REFIT REAR WINDSCREEN TO FACILITATE FENDER REPLACEMENT	\$ 100 180.00
TO APPLY SEALANT TO THE AFFECTED AREAS	\$ X 180.00
TO REMOVE/ REFIT WIRING CHECKS	\$ 30 120.00
TO REMOVE/ REFIT FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 60 250.00
TO REMOVE/ REFIT / REPLACE REAR SILENCER BOX	\$ 60 180.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ 40 180.00
TO REMOVE AND REPLACE/ REFIT BOOTLID MECHANISM	\$ 50 200.00
Total Others Cost	\$ 1,610.00

GRAND TOTAL \$ 19,268.5

CAS GARAGE PTE LTD
UEN 201828067M
1 RAKI BUKIT AVENUE #02-22 AUTOBAY,
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
mail: allan@cas@gmail.com
tel: +65 6509 9501

12 Days
Unspray Repair.
After repair
Gao Qiang.
24/4/19.

10600.49

20% 8450.

31/3 Confirmed with Allan

photos. Consultants hence notify
my Repairer of the following:
• 30 mins before after spray painting
• Insure damage if car is during resurvey
• S.I. may be subject to compensation
• Don't touch car, don't a "Without Prejudice" case
• No legal notification is allowed
• If preliminary terms must be resurveyed and
• If it is not to final approval from Insurance Company
By: _____
Signature
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19007216/GQD3N2

Date: 01/04/2020

REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D18MTHCVE003196
 Claimant Vehicle No: SMK4972G Insured Vehicle No: GBF5294E
 Date of Loss: 23/04/2019 Nature of Claim: TP Claim No: CMTD1902024

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK4972G
 Make & Model: HYUNDAI ACCENT, 1.3 (A) Engine No: G4LCKU145787
 Reg. Date: 12/04/2019 (Man. Year: 2019) Chassis No: KMHCU41BT KU465076
 Colour: Red Odometer: 814 km
 Engine Capacity: 1368 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
 Front Left Side: Kumho 9 mm Rear Left Side: Kumho 9 mm
 Front Right Side: Kumho 9 mm Rear Right Side: Kumho 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,977.84	7,320.50	5,657.34	43.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,440.00	3,280.00	4,160.00	55.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,417.84	10,600.50	9,817.34	48.08
Approved Total (Overridden) (S\$)		8,450.00		
Nett Amount (S\$)	20,417.84	8,450.00	11,967.84	58.61

INSPECTION

Date of Assignment: 24/04/2019
 Date Inspected: 24/04/2019 Inspected At: Cas Garage Pte Ltd (HQ)
 No.1, Kaki Bukit Ave 6, #02-22 Autobay
 Singapore 417883
 Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2020)
Parts:	143	HYUNDAI ACCENT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK4972G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE TYRE FLOOR PANEL	Buckled	896.90 FL	*896.90 FL
2	1		*REAR END PANEL	Bent	608.70 FL	*580.00 FL
3	1		*REAR END PANEL TOP GARNISH	Deformed	192.50 FL	*155.40 FL
4	1		*BOOTLID	Buckled	1,198.60 FL	*1,198.60 FL
5	1		*BOOTLID INNER TRIM	Torn	285.10 FL	*132.00 FL
6	2		*BOOTLID HINGE	Bent	291.60 FL	*150.00 FL
7	1		*BOOTLID INNER TRIM	Not Necessary	105.60 FL	*- FL
8	2		*BOOTLID NUMBER PLATE LAMP	Not Necessary	161.80 FL	*- FL
9	1		*BOOTLID LOGO	Necessary	85.60 FL	*85.60 FL
10	1		*BOOTLID ACCENT EMBLEM	Necessary	79.50 FL	*60.00 FL
11	1		*BOOTLID WEATHERSTRIP	Twisted	192.60 FL	*192.60 FL
12	1		*BOOTLID INNER LOCK	Bent	185.90 FL	*166.80 FL
13	1		*BOOTLID OUTER GARNISH	Deformed	236.70 FL	*236.70 FL
14	2		*BOOTLID NUMBER PLATE LAMP	Repeated	161.80 FL	*- FL
15	1		*REAR BUMPER	Deformed	679.80 FL	*483.00 FL
16	2		*REAR BUMPER REFLECTORS	Scratched	255.00 FL	*137.20 FL
17	2		*REAR BUMPER SIDE RETAINERS	Deformed	151.80 FL	*46.60 FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	759.60 FL	*390.80 FL
19	4		*REAR REINFORCEMENT BRACKETS	Bent	139.40 FL	*139.40 FL
20	2		*REAR FENDER	Buckled	3,691.20 FL	*1,099.80 FL
21	2		*REAR FENDER INNER TRIM	Torn	779.00 FL	*255.60 FL
22	1		*REAR FENDER INNER COWLING (2 Pcs)	Torn (1 Pc only)	391.20 FL	*195.60 FL
23	1		*REAR SILENCER BOX	Bent	745.80 FL	*745.80 FL
24	2		*REAR SILENCER BOX MOUNTING	Not Necessary	91.20 FL	*- FL
25	1		*REAR SILENCER BOX HEAT SHIELD	Not Necessary	187.20 FL	*- FL
26	1		*REAR WINDSCREEN MOULDING	Necessary	185.90 FL	*185.90 FL
27	1		*FLOOR PANEL SPONGE	Deformed	258.20 FL	*258.20 FL
28	1		*REAR FENDER AIR DUCT RH	Deformed	95.60 FL	*38.00 FL
29	1		*REAR BOOT SMART RELEASE ANTENNA (OUTER)	Damaged	285.70 FL	*128.86 FL
30	1		*REAR BOOT SMART KEY ANTENNA (INNER)	Damaged	285.70 FL	*128.86 FL
31	1		*REAR REINFORCEMENT METAL BRACKET RH	Missing	185.60 FL	*69.20 FL
32	1		*REAR BOOT TOP PANEL RH	Buckled	325.80 FL	*230.70 FL
33	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*20.00 FS
34	1		*SET REAR NUMBER PLATE WITH CASING	Scratched	50.00 FS	*40.00 FS
35	2		*SET REAR FENDER COWLING CLIPS	Necessary	60.00 FS	*20.00 FS
36	2		*SET REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*20.00 FS
37	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	30.00 FS	*10.00 FS
38	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
39	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
40	1		*SET REVERSE SENSOR HARDNESS	Damaged	280.00 FS	*100.00 FS
41	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
42	1		*EMERGENCY SIGN KIT	Not Necessary	200.00 FS	*- FS
43	2		*END PANEL SEALANTS	Necessary	80.00 FS	*40.00 FS
44	2		*WINDSCREEN SEALANTS	Necessary	80.00 FS	*40.00 FS
45	1		*SPARE TYRE FLOOR INSULATOR	Repeated	250.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*SPARE TYRE TOP MAT	Bent	206.56 FS	*100.00 FS
F=Franchise part, S=SpcNett, L=ListItemDisc.						
Sub Total (\$\$)					15,813.16	8,998.12
- List Item Discount on L Items 20.00/20.00% (\$\$)					2,835.32	1,677.62
Total Parts (\$\$)					12,977.84	7,320.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS,REPLACE,BEAT,WELD,REALIGN AND ALIGNE ALL PARTS	New	3,000.00	1,600.00
2	TO RESPRAY AFFECTED AREAS	New	2,800.00	1,200.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	80.00
4	TO REMOVE/REFIT INTERIOR UPHOLSTERY	New	150.00	60.00
5	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE FENDER REPLACEMENT	New	180.00	100.00
6	TO APPLY SEALANT TO THE AFFECTED AREAS	New	180.00	0.00
7	TO REMOVE/REFIT WIRING CHECKS	New	120.00	30.00
8	TO REMOVE/REFIT FUEL TANK TO FACILITATE FENDER REPLACEMENT	New	250.00	60.00
9	TO REMOVE/REFIT/REPLACE REAR SILENCER BOX	New	180.00	60.00
10	TO REMOVE/REPLACE REVERSE SENSORS	New	180.00	40.00
11	TO REMOVE AND REPLACE/REFIT BOOTLID MECHANISM	New	200.00	50.00
Gross Labour Cost (\$\$)			7,440.00	3,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >