22/03/2002 ASS. REC. BY:	REF: (5/EQ11900\$224)	A+d302 Special Instruction:
Surveyor: Adran From (Person): Joel Goh Estimated Cost:	ASSIGNMENT (Office of FQ	
OD TP WS/TP RES/OD R To Inspect Vehicle No:	Pa520B	Insured: 94 1710 M
of I karbi Bulaid Ave 6	igh Spray Mainting #01-29	Tel: 6749 2917
Policy No:Sum Insured:	Claim No	DM194001033-16
Make of Veh: (Client's Record)		D.O.A. 9.4. 2019
CA / REV / REP. / REV 24 Date/Time: 24.3.19 (0.6)	HRS Person Contacted: Jack	H.O.D. Endorsement:
Date/Time Action/Instruction		
GY 17-10 m -	- NA/III 10017 960/r	D.OA - 08/09/2010
lump Suw 5doup	\$4200] (Red: 10143	.147, 70%)

Adrian	SIGNMENT .
From: Date:	Veh No: 499520B. Yr Regn: 2018, Sept.
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van/1.org / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Mit Esso Contes c.c 2988
at Workshop m/s	Colour While . A/C: Insured / Std / NI / NA
of	Sp.Reading 30538 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: FEB21EA25310
Claims No.	Gen. Cond Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil S/Rim / STD A/Rim or
	Tyre Size: F: \$8/85845
(Poticy Condition)	R: 185/85 R15.
Remark: The veh had commenced its N/S O/S	BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bai. 06 mm R/Bai. 09 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est. Repairs: days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No	D.O.A. D.O.I. 23/04/19.
	Survey held at Flying Hish -
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Frant O/S.
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
IPEQ	
DECEN.	/FD 1 6 MAY 2019 ·
RECEIV	PED 1 0 PIAT 2013
mv :	
PV:	
Nett:	
	· · · · · · · · · · · · · · · · · · ·
Date/Time, File Pass to? Date/Time, File Return to?	
Date/Time, File Pass to? Date/Time, File Return to?	Part Prices Check: Survey Fee: Date:
3) 4)	IN OUT Basic & Add
5) 6)	Photos
Preli. Report: Final Report:	Others
· man isoport.	TOTAL 230

REF:

ASS, REC. BY:

Catherine Chong (LKK Auto)

From:

Joel Goh <joel.goh@eginsurance.com.sg>

Sent:

Tuesday, 23 April, 2019 8:04 PM

To:

assignments

Subject:

RE: PRE REPAIR SURVEY --- YOUR REF: GY 1710 M --- ACCIDENT INVOLVING YP

9520 B AND GY 1710 M ON 9 APRIL 2019 ALONG YISHUN AVENUE 6 BEFORE

JUNCTION OF YISHUN AVENUE 9 AT ABOUT 1700 HOURS (DM19HO01033-JG)

Attachments:

GY1710M.pdf; YP9520B.pdf

Dear LKK

Attached both accident reports for your attention.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190 www.eginsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify i

From: Joel Goh

Sent: Tuesday, April 23, 2019 8:03 PM

To: 'Elaine Toh' Cc: 'assignments'

Subject: RE: PRE REPAIR SURVEY --- YOUR REF: GY 1710 M --- ACCIDENT INVOLVING YP 9520 B AND GY 1710 M ON 9 APRIL 2019 ALONG YISHUN AVENUE 6 BEFORE JUNCTION OF YISHUN AVENUE 9 AT ABOUT 1700 HOURS

(DM19HO01033-JG)

Without Prejudice

Dear Elaine

Thank you for your confirmation. We will arrange accordingly.

Dear LKK

Please assist on the following PRS.

Best Regards,

Joel Goh



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190 www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t

From: Elaine Toh [mailto:Elainetoh@visionlawllc.com]

Sent: Monday, April 22, 2019 5:13 PM

To: Joel Goh

Subject: RE: PRE REPAIR SURVEY --- YOUR REF: GY 1710 M --- ACCIDENT INVOLVING YP 9520 B AND GY 1710 M ON 9 APRIL 2019 ALONG YISHUN AVENUE 6 BEFORE JUNCTION OF YISHUN AVENUE 9 AT ABOUT 1700 HOURS

(DM19HO01033-JG) Importance: High

Our Ref: YP 9520 B (et) WITHOUT PREJUDICE

Dear Joel.

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue:

M/s Flying High Spray Painting

1 Kaki Bukit Ave 6

#01-29 Autobay @ Kaki Bukit

Singapore 417883

Contact:

Jack @ 6749 2997 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

(8)

 Appointed surveyor (Name & Signature)

Date & Time of Inspection:

Regards, Elaine Toh

Vision Law LLC

Tel: 65342811 (Ext. 122)

Fax: 65356802

cc:

YP 9520 B – By email only

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]

Sent: Monday, 22 April, 2019 3:04 PM

To: Elaine Toh

Subject: RE: PRE REPAIR SURVEY --- YOUR REF: GY 1710 M --- ACCIDENT INVOLVING YP 9520 B AND GY 1710 M ON 9

APRIL 2019 ALONG YISHUN AVENUE 6 BEFORE JUNCTION OF YISHUN AVENUE 9 AT ABOUT 1700 HOURS

(DM19HO01033-JG)

Without Prejudice Save As To Costs

Dear Elaine

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please <u>revert within 2 working days</u> if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

AJAX Inspection Services Pte Ltd	Automobile Inspection Services Pte Ltd
Tel: 6255 0808	Tel: 6286 0155
Fax: 6849 9155	Fax: 6284 1539
	Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd	4) Priority Services
L.B.S. Auto Consultants Pte Ltd	Tel: 62934822
Tel: 6281 6690 / 62832866	Fax: 62963283
Fax: 6281 8748	Contact Person: Sharon
Contact Person: Amy/ Grace	
5) Infiniti Appraisal Service	6) LKK Auto Consultants Pte Ltd
Tel: 96684818 / 90099001	Tel: 6256-3561
Fax: 64587432	Fax: 6741-4108
7) Kelvin Automotive Appraising Services	8) Automotive Appraiser & Surveying Services
Tel: 81825263	Tel: 96623655
Fax: 67461148	Fax: 67655662
Contact Person: Kelvin	Contact Person: Mr Chee
9) JP Knights Pte Ltd	10) Appraisals Associates Pte Ltd
Tel: 63450068	Tel: 67472822
Fax: 63445328	Fax: 67470070

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190 www.eqinsurance.com.sg





Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t

From: Elaine Toh [mailto:Elainetoh@visionlawllc.com]

Sent: Monday, April 22, 2019 10:27 AM

To: EQI PRS

Subject: PRE REPAIR SURVEY --- YOUR REF: GY 1710 M --- ACCIDENT INVOLVING YP 9520 B AND GY 1710 M ON 9

APRIL 2019 ALONG YISHUN AVENUE 6 BEFORE JUNCTION OF YISHUN AVENUE 9 AT ABOUT 1700 HOURS

Importance: High

Our Ref: YP 9520 B (et) WITHOUT PREJUDICE

Dear Sir/Madam,

We are instructed by <u>HIAP ENG HONG ENGINEERING PTE LTD</u> to notify you of a road traffic accident on 9 April 2019 at about 1700 hours along Yishun Avenue 6 before junction of Yishun Avenue 9 involving our client's vehicle registration number YP 9520 B and vehicle registration number GY 1710 M driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thank you.

Regards, Elaine Toh Vision Law LLC

Tel: 65342811 (Ext. 122)

Fax: 65356802

cc: YP 9520 B - By email only

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413 Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing

and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email

transmission or any illegal or unauthorised usage or tampering of its email system.

VISION LAW LLC

Advocates & Solicitors (Incorporated with limited liability) Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413 Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email

transmission or any illegal or unauthorised usage or tampering of its email system.

MSME19046851 / SME Motor Pte Ltd - Kaki Bukit ENTRY DATE & TIME: 10/04/2019 16:05 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	10/04/2019 16:05
Date Of Accident	09/04/2019 17:00
Exact Location Of Accident	YISHUN AVE 6 BEFORE JUNCTION OF YISHUN AVE 9
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE

	DEDICATE OF THE PERSON
Vehicle Registration Number	YP9520B

Vehicle Registration Number

Insured/Policyholder

Name Of Registered Owner

Co Reg No 201325224K

Email Address

MAIN@HIAPENGHONG.COM

HIAP ENG HONG ENGINEERING PTE LTD

Mobile Phone No

Alternative Phone No

OFFICE-68441131

Vehicle Particulars

Manufacturer Model

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

MITSUBISHI

CANTER

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy NO

Policy Number

5103796804-01

Cover Note Number

Driver

Name of Driver THANGAVEL RAMACHANDRAN

NRIC No G6554155L Date Of Birth 20/08/1989 Occupation OUTDOOR Date Of Driving Pass 15/12/2017

1 YEAR AND 3 MONTHS Driving Experience

MALE Gender

Mobile Number (LOCAL) +65-88091630

Fax Number

Contact Number

EMail Address NOEMAIL Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

......

Number of vehicles (including own vehicle) involved in the accident

2

NO

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: KALRAJ RASAL

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ON THE LEFT LANE ON A 2 LANE STREET AND WAS PLANNING TO TURN LEFT AT JUNCTION. A VAN FROM THE RIGHT LANE SUDDENLY CUT INTO MY LANE WITHOUT SIGNALLING AND HIT ONTO THE FRONT RIGHT OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GY1710M

Vehicle Make/Model/Colour

VEHICLE B

Details Of Properties

COMMERCIAL VEHICLE

Vehicle Category Name of Driver

KANDASAMY KAVIARASAN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 - The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 - Any false reporting may be referred to the Police for Investigation.
 - The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
 - By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
 - 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

s Signature Oriver's Signa (If driver is no


Oriver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:


NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SE ETCH PLAN	17/4/4/4	7	
4 4	run Area		4-
GESCRIBE CIRCUINST	ANCES OF THE ACCIDENT	B-GY	952DB
and	s driving on the was Hanning	loft land to turn loft	on a 2 lane strut at Junetin - A Van unly cut into my
lan the	the Right Ca a Without Size front Right of	alling are	unly cut into my dut touch way the
			2
DECLARATION I/We declare the pregoing in	particulars are true in every respe	ct.	
Policy Po	Driver's Signature (If driver is not the pol Date & Time:	> -	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Sketch Plan #3 Pg. 1









Sketch Plan #4 Pg. 1



Certificate of Insurance

	OTOR VEHICLES (THIRD PARTY RISKS AND COMPENSAT OTOR VEHICLES (THIRD PARTY RISKS AND COMPENSAT		
	DAD TRANSPORT ACT, 1987 (MALAYSIA)		
M	OTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MA	LAYSIA)	
Ce	rtificate Number: 5103796804-01		Cover : Preferred Workshop Plan
1.	Index mark and Registration Number of Vehicle	3	YP9520B
	Chassis Number	-	FEB21EA25310
2.	Name of Policyholder		HIAP ENG HONG ENGINEERING PTE. LTD.
3.	Effective Date of Insurance	1	03 Jan 2019
4.	Expiry Date of Insurance	- 1	02 Jan 2020
5.	Persons or Classes of Persons entitled to drive#		
	(a) The Policyholder.		
	(b) Any other person who is driving on the Policyhold	der's ord	er or with his/her permission.

- Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
- 6. Limitations as to Use#
 - (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.
 - (b) Use for the carriage of passengers or goods in connection with the Policyholder's business.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.
- # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	4	\$\$600
EXCESS (SECTION 2)	1	N/A
WINDSCREEN EXCESS		S\$100
INSURE WITH COE		YES
HIRE PURCHASE COMPANY	3	GOLDBELL FINANCIAL SERVICES PTE LTD
SUM INSURED	:	MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor

Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) : ABWIN PTE LTD (00000614234) Agency Date of Issue : 12 Dec 2018 14:29 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By: **Authorised Officer** Chief Executive **Accident Photo**

	CHASSIS NUM		
U.W :	CHASSIS NUMB	KG	
	(F) 195 85R 1 (O) 195 85R 1	KG .	
The state of the s	R CAPACITY: 1 DRIVER	OTHERS	



Accident Photo











高飛汽車噴漆廠

FLYING HIGH SPRAY PAINTING

Blk 1, Kaki Bukit Ave 6, #01-29 Singapore 417883 (AutoBay@Kaki Bukit) Tel: 6749 2997 Fax: 6744 2942 Email: info@ohmycar.sg Business Reg. No. 42523200W

Vehicle Reg No: YP 9520 B

TPEQ.

Vehicle model: MITSUBISHI CANTER

Denise.

Name: HIAP ENG HONG ENGINEERING PTE LTD

Date of Accident: 09/04/2019

FEB21EA2S310

Address:C/O No 1 kaki bukit ave 6

#01-29 AutoBay S(417883)

	Parts Replacement List Item	Amount
1	Right Front "A" Pillar	\$1982.72
2	Right Front "A" Pillar Inner Trim Not Nec	\$249.25
3	Right Front Door Distoiled.	\$2401.45
4	Right Front Door Upper Hinge He New	\$162.54
5	Right Front Door Lower Hinge Bent	\$162.54
6	Right Front Door Check Not Nec	\$83.50
7	Right Front Door Surround Rubber NH NCC	\$454.90
8	Right Front Door Inner Trimboard Coulced	\$684.10
9	Right Front Door Trimboard Lamp Not Nec	\$87.46
10	Right Front Door Trim Ash Tray	\$99.12
11	Right Front Door Trim Switch Panel Z	\$383.99
12	Right Front Door Window Glass	\$544.94
13	Right Front Door Outer WeatherStrip Z Not	\$268.19
14	Right Front Door Inner WeatherStrip J Nec	\$379.50
15	Right Front Door Window Corner Garnish - Front	\$137.56

	Total	\$300.00	
34	Front Door Company "Letterings & Logo" Net 250	\$300.00	250
	Special Net		
	Total	\$12,293.14	
	Less 25%	\$4097.71	
	Total H0325/1, 5/807/	\$16,390.85	
	1 1. red . 2. 70° C7		
33	Front Bumper RH Pad Cover New 1505196	\$152.00	+.
32	Front Bumper RH Pad Ut	\$341.71	1
31	Front Bumper Brackets x2	\$392.48	+
30	Front Bumper Reinforcement	\$633.20	+
29	Front Bumper 2	\$1210.36	*
28	Right Headlamp Side Garnish XX Nec	\$222.53	X
27	Right Headlamp "HID" Creeked.	\$910.64	5012
26	Right Front Signal Lamp Caulced	\$266.36	-
25	Right Front Mirror Arm Bracket – Lower	\$282.85	X.
24	Right Front Mirror Arm Bracket – Upper (Not)	\$365.20	X
23	Right Front Mirror Stay Cover	\$81.21	×
22	Right Front Mirror Stay Bend	\$439.05	/
21	Right Front Corner Panel	\$566.76	4
20	Right Front Door Inner Lower Rubber Not Nec	\$86.50	×
19	Right Front Door Lower Arch Garnish – Inner	\$180.80	/
18	Right Front Door Inner Lock XH Nec	\$589.10	7.
17	Right Front Door Window Glass Inner Rubber	\$171.34	X

	Grand Total		\$14,343.14
	Total	1310	\$1750.00
39	To Transfer Front Door Fittings	RIO.	\$150.00
38	To remove Upholstery		\$100.00
37	Wiring		\$199.00
36	Spray Painting		\$600.00
35	Panel Beating		\$800.00
	LABOUR		

total 5348.97 HS: 4.2K. 05 Days

600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation	Internationale Des	Experts En /	Automobile
--------------------------	--------------------	--------------	------------

EQ INSURANCE COMPANY LTD

Ref: CS/EQI19007224/Atd3e2

5 MAXWELL ROAD

#17-00 TOWER BLOCK

Date: 22-05-2019

	O COMPLEXSING		Date : 22 00 20 10	W
			Code: EQI	
1.		Policy Particular	s :- THIRD PARTY CLA	IM
	Insured Veh.	GY 1710M	Veh. Inspected	YP 9520B
	Policy No.		Coverage (\$)	0.00
	Claim No.	DM19HO01033-JG	Excess (\$)	0.00
	Assign From	JOEL GOH	Assign Date	23/04/2019
2.		Vehicle Par	ticulars & Condition	
	Make & Model	MITSUBISHI CANTER	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	FEB21EA25310	Colour	WHITE
	Odometer	30538	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.	STREET STREET	Cond	itions of Tyres	SEASON FOR COMME
		Size	Make	Balance
	R/H Front Tyre	195/85 R15	DUNLOP	6 mm
	L/H Front Tyre	195/85 R15	DUNLOP	6 mm
	R/H Rear Tyre	195/85 R15	DUNLOP	6 mm
	L/H Rear Tyre	195/85 R15	DUNLOP	6 mm
4.		Descrip	tion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE F	RONT O/S PORTION.	
	DAMAGES SEE D	ETAILS.		
5.	. 四点。		ral Information	
	Accident Date	09/04/2019	Inspection Date	23/04/2019
	Survey held at	FLYING HIGH SPRAY PAINTI	NG	
		BLK 1 KAKI BUKIT AVE 6 #01-29 AUTOBAY SINGAPORE 417883		
5a.	P. Called St.	NAMES OF THE PERSON OF THE PER	Remarks	AND RESIDENCE OF SHEEK
	A)THE INSPECTION	ON WAS CONDUCTED ON A"W	ITHOUT PREJUDICE" BAS	SIS.
5h	B)IN ACCORDANG	CE TO YOUR INSTRUCTIONS,	e Days of Repair	SED REPAIRS.
5b.	LEGTIMATED NOD	MAL PERIOD FOR REPAIR:	5 Working Day	ve



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 9520B

у	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RIGHT FRONT "A" PILLAR	TO REPAIR SEE LABOUR	1,982.72	-
1	RIGHT FRONT "A" PILLAR INNER TRIM	NOT NECESSARY	249.25	
1	RIGHT FRONT DOOR	DISTORTED	2,401.45	2,001.00
1	RIGHT FRONT DOOR UPPER HINGE	NOT NECESSARY	162.54	
1	RIGHT FRONT DOOR LOWER HINGE	BENT	162.54	162.54
1	RIGHT FRONT DOOR CHECK	NOT NECESSARY	83.50	
1	RIGHT FRONT DOOR SURROUND RUBBER	NOT NECESSARY	454.90	
1	RIGHT FRONT DOOR INNER TRIMBOARD	CRACKED	684.10	684.10
1	RIGHT FRONT DOOR TRIMBOARD LAMP	NOT NECESSARY	87.46	
1	RIGHT FRONT DOOR TRIM ASH TRAY	NOT NECESSARY	99.12	,
1	RIGHT FRONT DOOR TRIM SWITCH PANEL	NOT NECESSARY	383.99	
1	RIGHT FRONT DOOR WINDOW GLASS	NOT NECESSARY	544.94	
1	RIGHT FRONT DOOR OUTER WEATHERSTRIP	NOT NECESSARY	268.19	
1	RIGHT FRONT DOOR INNER WEATHERSTRIP	NOT NECESSARY	379.50	
1	RIGHT FRONT DOOR WINDOW CORNER GARNISH - FRONT	NOT NECESSARY	137.56	
1	RIGHT FRONT DOOR REGULATOR GEAR WITH MOTOR	NOT NECESSARY	1,417.00	
1	RIGHT FRONT DOOR WINDOW GLASS INNER RUBBER	NOT NECESSARY	171.34	
1	RIGHT FRONT DOOR INNER LOCK	NOT NECESSARY	589.10	
1	RIGHT FRONT DOOR LOWER ARCH GARNISH - INNER	CUT	180.80	180.80
1	RIGHT FRONT DOOR INNER LOWER RUBBER	NOT NECESSARY	86.50	
1	RIGHT FRONT CORNER PANEL	DEFORMED	566.76	475.00
1	RIGHT FRONT MIRROR STAY	BENT	439.05	439.0
1	RIGHT FRONT MIRROR STAY COVER	NOT NECESSARY	81.21	
1	RIGHT FRONT MIRROR ARM BRACKET - UPPER	NOT NECESSARY	365.20	
1	RIGHT FRONT MIRROR ARM BRACKET - LOWER	NOT NECESSARY	282.85	
1	RIGHT FRONT SIGNAL LAMP	CRACKED	266.36	266.3
1	RIGHT HEADLAMP "HID"	CRACKED	910.64	501.4
1	RIGHT HEADLAMP SIDE GARNISH	NOT NECESSARY	222.53	
1	FRONT BUMPER	NOT NECESSARY	1,210.36	:

Report Ref No. CS/EQI19007224/Atd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	633.20	-
2	FRONT BUMPER BRACKETS	NOT NECESSARY	392.48	-
1	FRONT BUMPER RH PAD	CUT	341.71	341.71
1	FRONT BUMPER RH PAD COVER	NOT NECESSARY	152.00	-
	LESS 25% DISCOUNT		-4,097.71	-1,262.99
			12,293.14	3,788.97
	SPECIAL NETT ITEMS			
1	FRONT DOOR COMPANY "LETTERINGS & LOGO" (SN)	NECESSARY	300.00	250.00
			300.00	250.00
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF RIGHT FRONT "A" PILLAR.		800.00	600.00
	SPRAY PAINTING.		600.00	600.00
	WIRING.		100.00	30.00
	TO REMOVE UPHOLSTERY.	NOT NECESSARY	100.00	-
	TO TRANSFER FRONT DOOR FITTINGS.		150.00	80.00
			1,750.00	1,310.00
	GRAND TOTAL		14,343.14	5,348.97

RECOMMENDED COST OF LUMP SUM REPAIRS	DG-ANTERIOR	STATE OF THE PARTY OF	4,200.00
(TO ITS PRE-ACCIDENT CONDITION)			

Report Ref No. CS/EQI19007224/Atd3e2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.