

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G*Sdang*
*Alan Marcus***Customer:** WZH023 / SOMPO INSURANCE
Chassis No: JHMRC1890JC201715
License No: SLZ4818C
Mileage: 21458
Engine No: K24W72400914**Document No:** SVO19026920
Printed By: TWLIEW
Order Date: 29. April 2019
Order Time: 11:24:08 AM
Service Advisor: LIEW THYE WEI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72625) OWNER: LIM KEE KWONG OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 19/4/19 SURVEYED BY: MARCUS (LKK) DATE: 29/04/19 @ 11.15AM REF NO: CMTD1901987 / GPL TP INSURER: SOMPO INSURANCE SINGAPORE PTE LTD TP VEH: SJD7326A						
73226-SZW-000	DAMPERSTD 5X5	2 ✓	8.50	25	12.75	0.89	13.64
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2 ✓	18.00	25	27.00	1.89	28.89
73225-TM8-000	RUBBER AWINDSHIELD DAM	1 ✓	3.70	25	2.77	0.19	2.96
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1 ✓	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1 ✓	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4 ✓	3.90	25	11.70	0.82	12.52
76711-T6A-003	CAPPIVOT	1 ✓	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4 ✓	5.30	25	15.90	1.11	17.01
91536-SS0-J01	FASTENER AW/SHIELD	2 ✓	3.80	25	5.70	0.40	6.10
91502-S70-003	FASTENER B	2 ✓	5.30	25	7.95	0.56	8.51
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1 ✓	60.00		60.00	4.20	64.20
68100-T6A-Q10ZZ	TAILGATE COMP	1 ✓	1,070.80	25	803.10	56.22	859.32
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1 ✓	175.50	25	131.62	9.21	140.83
75722-T6A-901	EMBLEM,RR.	1 ✓	31.00	25	23.25	1.63	24.88
75701-T6A-000	EMBLEMH	1 ✓	26.30	25	19.72	1.38	21.10
91505-TM8-003	CLIP,BUMPER	7 ✓	2.30	25	12.07	0.84	12.91
	SUM PARTS:				1,162.47	81.37	1,243.84
BOSUN	0760 SUNDRIES	1 ✓	20.00		20.00	1.40	21.40
BML02I	1863 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1 ✓	80.00		80.00	5.60	85.60
BA02R	1863 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1 ✓	120.00		120.00	8.40	128.40
BG02D	1863 REMOVE & INSTALL RR. WINDSCREEN, (N)	1 ✓	300.00		300.00	21.00	321.00
BKTG02R	1863 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1 ✓	450.00		450.00	31.50	481.50
BC011R	1863 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1 ✓	250.00		250.00	17.50	267.50
BC01R	1863 PERFORM SETTING ON AUTO TAILGATE. RESET MEMORY.	1 ✓	280.00		280.00	19.60	299.60
BMI03D	1863 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1 ✓	120.00		120.00	8.40	128.40



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZH023 / SOMPO INSURANCE	Document No:	SVO19026920
Chassis No:	JHMRC1890JC201715	Printed By:	TWLEW
License No:	SLZ4818C	Order Date:	29. April 2019
Mileage:	21458	Order Time:	11:24:08 AM
Engine No:	K24W72400914	Service Advisor:	LIEW THYE WEI

BKRP02S	1863 STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1 /	840.00	840.00	58.80	898.80	
BP03R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1 /	1,350.00	1,350.00	94.50	1,444.50	
BP00P	**TATANIOM COATING**	1	0.00	0.00	0.00	0.00	
				SUM LABOUR:	3,810.00	266.70	4,076.70
				TOTAL SGD	4,972.47	348.07	5,320.54

Total Payable (SGD) 5,320.54

GST Amount is calculated from individual line(s)