

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 30 Apr 2019

Preliminary Advice

Insured Vehicle No	: SJD7326A	Accident Date	: 18/04/2019
TP Vehicle No	: SLZ4818C	Assignment Date	: 24/04/2019
Make	: HONDA ODYSSEY	Est. Duration of Repair	: 5
Date of Inspection	: 29/4/2019		
Inspection At	: KAH MOTOR CO SDN BHD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,549.01
Revised Amount	:S\$	4,972.47
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,972.47
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :The above survey was conducted on a 'Without Prejudice' basis.