

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5038Z**AAD1904-208***Not Authorised*
L1 Sup & 25506

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5038Z

VF1ABL15AUC276035

RENAULT

LATITUDE

22.4.2019

CHINA TAIPING

2/12/2013

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Am</i> 1,259.42 —
1	BUMPER SPOILER FRT	\$	<i>Sm</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sm</i> 394.68 X
1	BUMPER RETAINER FRT LH	\$	<i>Mr</i> 151.41 —
1	BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88 X
1	BUMPER RETAINER FRT RH	\$	<i>Sm</i> 150.77 X
1	BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>Sm</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sm</i> 266.80 X
1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sm</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP LH	\$	<i>mgmt</i> 1,184.43 —
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15
1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83
1	WHEELARCH FRT LH	\$	<i>Sm</i> 278.84
1	FENDER BRACKET LOWER LH	\$	<i>Sm</i> 15.79
1	FENDER INSULATOR LH	\$	<i>Sm</i> 130.84
1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66 } X
1	RADIATOR GRILLE	\$	<i>Sm</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sm</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sm</i> 1,353.75
1	RADIATOR FAN COWLING	\$	<i>Sm</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>Sm</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>Sm</i> 1,479.46
1	RADIATOR GRILLE FRAME	\$	<i>Sm</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	AIR CLEANER BOX	\$	<i>Sm</i> 464.20
1	AIR CLEANER HOSE	\$	<i>Sm</i> 175.85

Trans-cab Auto Services Pte Ltd

AAD1904-208

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5038Z

1	DOOR MIRROR ASSY LH	\$	<i>Sen</i> 1,483.40 <i>X</i>
---	---------------------	----	------------------------------

TOTAL	\$	20,374.41
10%	\$	2,037.44
	\$	18,336.97

Specical Nett

1SET	BUMPER CLIP FRT	\$	<i>na</i> 66.00	<i>X</i>
1	BUMPER BRACKET CLIP FRT LH	\$	<i>na</i> 12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>na</i> 10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i> 70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>Sen</i> 20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>Sen</i> 30.00	
1SET	WHEELARCH CLIP FRT RH	\$	<i>na</i> 30.50	
1	FRONT LEFT TYRE RIM	\$	<i>Sen</i> 330.00	
1	FRONT LEFT TYRE	\$	<i>Sen</i> 300.00	
		\$	938.00	

TOTAL PARTS	\$	19,274.97
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	3,500.00	<i>3000</i>
----	----------	-------------

Putty and spray painting of the affected portion.

\$	3,000.00	<i>4400</i>
----	----------	-------------

To rust-proofing of the affected areas.

\$	<i>na</i> 170.00	<i>X</i>
----	------------------	----------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	<i>na</i> 380.00	<i>X</i>
----	------------------	----------

To check steering geometry and computer wheel alignment

\$	<i>na</i> 220.00	<i>X</i>
----	------------------	----------

Trans-cab Auto Services Pte Ltd

AAD1904-208

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5038Z

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>2d</i>
To transfer of Front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To transfer of Door fittings, attachment and perform water seepage test.	\$	<i>4</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>4</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>4</i> 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>4</i> 170.00 X

TOTAL	\$	9,090.00
--------------	-----------	-----------------

Over All Total	\$	28,364.97
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____