Surveyor: GR	ASSIC	GNMENT (Office)	4	
From (Person): (hong	Buon Sen of	CTI	Date/Time: 24.4.19	9.319.1
Estimated Cost:				
To Inspect Vehicle No:	PC 7394	MV / CS	Insured: PC7976C Tel: 92996636	
	untah Motor W		Tel: 9299 6636	12
of BIK 14 Defu	land 10 #01-40	6		
Policy No: DMBISN	19139019000	Claim No:	SVM 19020179 1002	2
Sum Insured:		Excess:		
Make of Veh:			D.O.A. 19.4 2019	1/1/
(Client's Record) CA / REV / REP. / I Date/Time: 24.4.16)	REV 24 HRS Person Conta		H.O.D. Endorsement:	
Date/Time Action/In	struction (×) Esti	mate		
	26C-X			
Aster	epair: 26/4/2019			
	,			

Surreyor Gol. CII	SIGNMENT	
700	The second secon	Regn: Jul / 11
From: Date:		
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Ta	xt / Prime Mover /
DD TP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or	
To Inspect Vehicle No: PC \$39 Y	Make: Tayota Hiac	
at Workshop m/s Jernentah Modor.	colour white A/C:	Insured / Std / NI / NA
of BIK 14 Defu Lane 10 #01-406	Sp.Reading 654770 T/Ra	dio: Insured / Std / NI / NA
Insured:	Eng/No:	
Policy No.	C/No: JTFST22P8000	10790
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt	
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt	or
(Client's Record)	Brake: In@rder / Jammed / Leaked / Burnt	
Make of Veh:	Modi: NH) / S/Rim / STD A/Rim or	
Wake of Ven.	Tyre Size: F: 195 R 15	C ".
(Defendantition)	R:	
(Policy Condition) Remark: The yet had commenced its N/S 0/6	7	OHTSU / PIR / SUMI /
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	TOYO / YOKO or	
Topul ut the time of mapassess.		
Bal, or Market Value:	R/Bal. R/Bal. R/B	6
IDAC Accident Rport: Consistent? : Yes or No	6	/ -
GIA / PR Seen: Consistent? : Yes or No	L/Bai. mm	- 0
Est. Repairs: S days Res.: Yes or No	D.O.A. D.O	-(10(-1)
Lum Sum: % 3 Val.: Yes or No	Survey held at	1230
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / 0/8 N/S /	1
Vehicle: IN / O		15 rear
Date: Person Contacted:	The U/C / Chassis frame / Body Struct	tire affected due to collision
Date / Time Action / Instruction	A	
\$ 3000 - \$ 4000	Moranglo	
	\wedge	
	25/4/2019	
Y	021.1	
7-	RECEIVED 1 4 JUN 2019	
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 5	
Final Banart		rvey Fee: 160
1) : Final Report Date/Time, File Return to?		rvey Fee: 150
Add		S+RS,SI
z) Add I		iolos
Papart Format : DOG		hers
Report Format : PRQ .	: Weekend (\$	
Lump Sum / I.B.I; (\$		OTAL . 150
		OTAL 190

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adi Assigned	Adj Rpt	Adj Subi	mitted	Ins Auth'ed	Status	
Main	13 Jun 2019	13 Jun 2019						Pending f Report Cancel Ca	or Survey
	Main	Re	ference		Claim Details		Documen	its	Show All
CLAIM S	UBFOLDER DE	TAILS				[Create	ed by insurer]		
Insured:									
Main Claimant:	M/S ZHO	NG BANG BUS SI	RVICES, Co.	Reg. No.: 53	3338145B				
Vehicle Re No.:	g. PC739Y				Date of Loss: Policy/Cover	19/04/2	2019 13:00 - :59		
Claim Type	e: TP / SNI	TP / SNM19D201791C02				DMB1SN19139019000			
Vehicle Re No. (Insured):	PC7926C	PC7926C				DMBSN1913901900			
(11100100)					Excess:	S\$0.00			
Repairer:	Jemental	Motor Works -	Defu Lane (HQ) BLK 14 DE	FU LANE 10 #01	-406, 539	9195 Defu Lane - T	el: 9299 6636	5
Handling Insurer:							ndled by Chong Bo		
Claimant's Insurer:	China Tai	ping Insurance							21/25/2212
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Handled by]	XING GU	IO QIANG] [Fi	nal Rpt due	24/06/2019]
ASSOCIA	TED MAIL RE	CEIVED						View All	compose Case Mai
There are	no mail for this	case.							
ALL ASS	OCIATED TAS	sks⊟				View /	All Search Tasks	Create New	
	te Priority	Type Task	Group Sub	ject Har	dler Assign	ned By	Completed O	n Creat	ed On Done
Due Da									

Nivitha (LKK Auto)

From:

Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent:

Wednesday, 24 April 2019 9:31 AM

To:

Sim Teo Koon

Cc:

assignments

Subject:

RE: ACCIDENT INVOLVING PC739Y & PC7926C ON 19-4-2019. O ref:

JEQ/190309/0419/JEM / OUR REF: SNM19D201791

WITHOUT PREJUDICE SAVE AS TO COSTS

Dear Sir

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK.

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Sim Teo Koon [mailto:tk sim@juseq.com.sg]

Sent: Tuesday, 23 April, 2019 11:28 AM

To: Chong Boon Sen

boonsen.chong@sg.cntaiping.com>

Subject: RE: ACCIDENT INVOLVING PC739Y & PC7926C ON 19-4-2019. O ref:

JEQ/190309/0419/JEM / OUR REF: SNM19D201791

Dear Sirs.

We refer to your letter / email.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Veh lu

Fursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) PAR Automotive Consultancy,
- 2) SK Auto Consultants,
- Chartered Auto Assessors,
- 4) LCW APPRAISER PTE LTD
- Sincere Appraisal Services,
- Pal's Appraisal Pte Ltd,
- Mc-Coy Appraiser Pte Ltd,
- 8) CL Appraiser Pte Ltd.

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for prerepair inspection at the under-stated workshop:-

Jementah Motor Works

Blk 14 Defu Lane 10 #01-406, Singapore 539194

Fax: 6285 7054 Tel: 9299 6636 Person In-Charge: Chuan.

* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation.

Tel: 6506 6065, Fax: 6536 9339 E-mail: tk_sim@juseq.com.sg

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

Sent: 23 April 2019 09:50 To: tk_sim@juseq.com.sg

Subject: RE: ACCIDENT INVOLVING PC739Y & PC7926C ON 19-4-2019. O ref:

JEO/190309/0419/JEM / OUR REF: SNM19D201791

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle Vehicle Owner Particulars Company Owner ID Type: 4348R Owner ID: Vehicle Details PC739Y Vehicle No.: No Vehicle to be Exported: 14 Jun 2019 Intended Deregistration Date: TOYOTA Vehicle Make: TOYOTA HIACE HIROOF AUTO 14 SEATER Vehicle Model: White Primary Colour: 2011 Manufacturing Year: 1KD2102037 Engine No.: JTFST22P800010790 Chassis No.: Maximum Power Output: \$37,122.00 Open Market Value: 12 Jul 2011 Original Registration Date: 12 Jul 2011 First Registration Date: 1 Transfer Count: \$1,857.00 Actual ARF Paid: Intended PARF Rebate Details No PARF Eligibility: PARF Eligibility Expiry Date: \$0.00 PARF Rebate Amount: Intended COE Rebate Details 11 Jul 2021 COE Expiry Date: C - Goods Vehicle & Bus COE Category:

The information contained herein is correct as at 14 Jun 2019

COE Period(Years):

COE Rebate Amount:

Total Rebate Amount:

QP Paid:

OK

\$29,006.00

\$6,015.00

\$6,015.00





1 of 3

Report No. T/20190420/2022

Police Station Of Origin: Bukit Merah West N.P.C 500 Bukit Merah View #01-01 SINGAPORE 159682

Tel No: 1800-3779999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:	Vide Report No.:	Station Diary No.:
Date/ Time Report Made.	A STATE OF PARTICIPATION OF THE PARTICIPATION OF TH	4-
20/04/2019 05:09		17
20/04/2013 00.03		

20/04/2019 05:09							
Informa	nt's Particu	ulars	Area State of the	美国内部 国际企业的主义			
Name of Informant: WONG SIEW MUN			Address: APT BLK 128 BUKIT MERAH VIEW #12-18 SINGAPORE 150128				
ID Type / ID No.: NRIC NO / S2179823A		23A	Contact No.: Home/Office:	Mobile: 96177686			
National SINGAP	ity: ORE CITIZ	EN	Email:				
Sex: Age: Date of Birth:		Date of Birth: 01/10/1956	Type of Informant: Driver				
Race: Chinese		•	Language: English	Institution / School Name:			
Occupation: Bus driver			Driving Licence Information Class: 3,4	n: Date of Expiry:			

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 19/04/2019 13:30	Type of Location Car Park	
		lay Carpark	50		
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate	
Type of Collis	sion: ring Vehicles - Rear to	o Side		Anyone conveyed by ambulance:	

Details of v	ehicle Involved					
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge
PC739Y	Bus/Coach/Mi nibus				Slightly Damaged	0
PC7926C	Bus/Coach/Mi nibus				No Damage	0

Details of Person Involved	5.2. 经财政的基础 医多类型 计图片 化甲酰胺
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





2 of 3

Report No. T/20190420/2022

Police Station Of Origin: Bukit Merah West N.P.C 500 Bukit Merah View #01-01 SINGAPORE 159682

Tel No: 1800-3779999

CONTINUATION OF REPORT

A THE REAL PROPERTY.	\$P\$美国的特别的最近的特别的	建筑设施		da.k.		· 新疆·莫尔里伊斯·西
Driver Name	WONG SIEW MUN		ID No.		S2179823A	
Related Vehicle	PC7926C (Bus/Coach/Minibus)			Conta	ct No.	96177686
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g ce &	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Disc		NIL		
No. of Days gran	ted Medical Leave	NIL	Degree o	f Injury	NIL	

Brief Details.

On 19/04/2019 at bout 1330hrs, I was driving my Company Bus bearing PC7926C at the Changi Airport Terminal 2 Coach Bay carpark. I saw a bus wanted to reverse out in front of me, as such I reverse as well so that the bus could move out. Subsequently while I was reversing slowly, I saw through my left side mirror that It seems that I might have accidentally knock onto another bus behind me. The Bus behind me was bearing PC739Y and he was also coming out from the coach bay lot as well while I was doing reversing. I came out of my vehicle to take a look and realize that the rear bus's right side last window was shattered and the body had dented in. The driver said that my vehicle left rear portion had hit onto his right side rear portion. However there was totally no damages onto my Bus at all. Subsequently we took pictures and the driver said that he will claimed through insurance. I wish to state that I did notify my company about the matter. I wish to state that I did not felt any impact at all before the collision and I do not have any camera inside my bus to view of the accident. No one was injured at that point of time. I am lodging this report for record purpose for my company filing. That is all.





T/20190420/2022

3 of 3 Report No. T/20190420/2022

Police Station Of Origin: Bukit Merah West N.P.C 500 Bukit Merah View #01-01 SINGAPORE 159682

Tel No: 1800-3779999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: D / Sgt 2 TAN HWA TIONG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 20/04/2019 05:09
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Starts SINGAPORE POLICE FORCE	SN 45

CICMATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status		
Main	13 Jun 2019	3 3411 2019		S\$0.00 Edit Estimat	5\$0.00 S\$0.00 View Rpt			Report Cancel C	for Survey	
1	1ain	R	eference	Clain	n Details		Docume	nts	Show All	
CLAIM SUI	BFOLDER DE	TAILS				[Created	by insurer]			
Insured:	-, Co. Re	g. No.: -								
Main Claimant:	M/S ZHO	NG BANG BUS SE	ERVICES, Co. Reg	. No.: 5333814	15B					
Vehicle Reg. No.:	PC739Y			Da	te of Loss:		19/04/2019 13:00 - :59 [93 Months and 7 Days From LTA Reg Date (Man Yr)]			
Claim Type:	TP / SN	419D201791C0	12		icy/Cover te No.:	DMB1SN19139019000				
Vehicle Reg. No. (Insured):	PC7926C				icy No. aimant):	DMBSN1913901900				
				Ex	cess:	S\$0.00				
Repairer:	Jemental	Motor Works -	Defu Lane (HQ) BL	K 14 DEFU LAN	NE 10 #01-	406, 539195	5 Defu Lane - To	el: 9299 6636		
Handling Insurer:	China Tai	ping Insurance ((Singapore) Pte. L	td. (HQ) - Tel:	6389 611	1 [Handle	d by Chong Bo	oon Sen]		
Claimant's Insurer:			(Singapore) Pte. L							
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Ha	andled by)	KING GUO Q	QIANG] [Fir	nal Rpt due 2	4/06/2019]	
ASSOCIAT	ED MAIL RE	CEIVED					0	View All Con	pose Case Mail	
There are no	mail for this	case.								
ALL ASSO	CIATED TAS	sks⊟			1)	View All	Search Tasks	Create New Tas	k Complete	
Due Date	Priority	Type Task	Group Subjec	t Handler	Assig	ned By	Completed C	n Created	I On Done?	

Claim Documents

*PC739Y (SNM19D201791C02) [PC7926C] TP M/S ZHONG BANG BUS SERVICES Apr 19 2019 1:00PM [-] Jementah Motor Works - Defu Lane

Ass	essment Reports		1 per page	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbna	il Prin
1	06/06/19 13:42	Accident Statement	1 Load HTM	1
2	06/06/19 13:51	Addendum Sheet	1 Load TIF	
3	06/06/19 13:51	Accident Statement Addm. #1	Load HTM	
Pho	tos/Images		3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	_
1	14/06/19 11:54	General View	■ Load JPG	V
2	14/06/19 11:54	General View	■ Load JPG	V
3	14/06/19 11:54	General View	■ Load JPG	V
4	14/06/19 11:54	General View	Load JPG	V
5	14/06/19 11:54	General View	Load JPG	
6	14/06/19 11:54	General View	Load JPG	V
7	14/06/19 11:54	General View	Load JPG	1 =
8	14/06/19 11:54	General View	■ Load JPG	_
9	14/06/19 11:54	General View	■ Load JPG	
10	14/06/19 11:54	General View	Load JPG	
11	14/06/19 11:54	General View	Load JPG	
12	14/06/19 11:54	General View	Load JPG	
13	14/06/19 11:54	General View	1 Load JPG	
14	14/06/19 11:54	General View	♠ Load JPG	-
15	14/06/19 11:54	General View	■ Load JPG	
16	14/06/19 11:54	General View	1 Load JPG	
17	14/06/19 11:54	General View	Load JPG	-
18	14/06/19 11:54	General View	1 Load JPG	_
19	14/06/19 11:54	General View	1 Load JPG	-
20	14/06/19 11:54	General View	■ Load JPG	
21	14/06/19 11:54	General View	1 Load JPG	
22	14/06/19 11:54	General View	1 Load JPG	-
_		General View	1 Load JPG	
23	14/06/19 11:54	Photo After Spray	1 Load JPG	
24	14/06/19 11:56		1 Load JPG	
25	14/06/19 11:56	Photo After Spray	1 Load JPG	
26	14/06/19 11:56	Photo After Spray	1 Load JPG	
27	14/06/19 11:56	Photo After Spray	1 Load JPG	
28	14/06/19 11:56	Photo After Spray	1 Load JPG	
29	14/06/19 11:56	Photo After Spray	1 Load JPG	
30	14/06/19 11:56	Photo After Spray		-
31	14/06/19 11:56	Photo After Spray	Load JPG Load JPG	

Assessment Reports		1 per	oage 🔻	V	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail		Print
Doc	cumentation		1 per	page 🔻	V
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	06/06/19 10:35	Sketch Plan [Linked Accident Report Documents]	0	Load TIF	
2	06/06/19 10:35	POLICE REPORT [Linked Accident Report Documents]	0	Load TIF	
3	06/06/19 13:41	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	0	Load TIF	
4	06/06/19 13:50	OWNER'S NRIC, DRIVING LICENCE + VOCATIONAL LICENCE [Linked Accident Report Documents]	0	Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/06/19 10:55	pri contact	0	Load PDF	

Linked Accident Report Documents

			View	View in Browser	
Assessment Reports		1 per page		Y	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	06/06/19 13:42	Accident Statement	0	Load HTM	
2	06/06/19 13:51	Addendum Sheet	0	Load TIF	
3	06/06/19 13:51	Accident Statement Addm. #1	0	Load HTM	
4	14/06/19 12:13	Addendum Sheet	0	Load TIF	
5	14/06/19 12:17	Accident Statement Addm. #2	0	Load HTM	
6	14/06/19 13:30	Addendum Sheet	0	Load TIF	
7	14/06/19 13:31	Accident Statement Addm. #3	0	Load HTM	
Pho	tos/Images		3 per s	page 🔻	V
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	14/06/19 12:17	THIRD PARTY -VEHICLE: PC 739X - ACCIDENT PHOTO	0	Load JPG	~
2	14/06/19 12:17	THIRD PARTY - VEHICLE: 9C 739X - ACCIDENT PHOTO	0	Load JPG	✓
Doc	umentation		1 per	page 🔻	V
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	06/06/19 10:35	Sketch Plan	0	Load TIF	
2	06/06/19 10:35	POLICE REPORT	0	Load TIF	
3	06/06/19 13:41	CERTIFICATE OF INSURANCE	0	Load TIF	
4	06/06/19 13:50	OWNER'S NRIC, DRIVING LICENCE + VOCATIONAL LICENCE	0	Load TIF	
5	14/06/19 12:13	Accident Sketch Plan	0	Load TIF	
6	14/06/19 13:31	Accident Sketch Plan	0	Load TIF	

Documents Checklist

There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
		^
		~

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/CTI19007229/GCD3E2

Date:

20/06/2019

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMB1SN19139019000

Claimant Vehicle PC739Y No:

Insured Vehicle

PC7926C No:

Date of Loss:

19/04/2019

Nature of Claim: TP

Claim No:

SNM19D201791C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

PC739Y

Make & Model:

TOYOTA HIACE, 2.0 (M)

Engine No:

1KD2102037

654770 km

Reg. Date:

12/07/2011 (Man. Year: 2011)

Chassis No: Odometer:

JTFST22P800010790

Colour: **Engine Capacity:**

2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195 R15C

Rear Tyre Size:

195 R15C

Front Left Side:

Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

13/06/2019

Date Inspected:

24/04/2019 Inspected At:

Jementah Motor Works - Defu Lane (HQ)

BLK 14 DEFU LANE 10 #01-406

Singapore 539195

Estimated Period of Repair:

5.0 days

Adjuster:

XING GUO QIANG

Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen ... 20/6/2019

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Jun 2019)

Parts: N/A TOYOTA HIACE 2.0 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC739Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >