

ACE

ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

KMH DH41CM 64653692

Page No. 1

TP A1G.

Jiale

Vehicle No. SDQ990E HYUNDAI ELIANTRA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT HEADLAMP RH <i>crushed.</i>		2150.00	✓ 1756
1	FRONT HEADLAMP BRACKET RH <i>new</i>		91.00	+
1	FRONT BONNET <i>Repis</i>		1532.00	X
2	FRONT BONNET HINGE LH & RH @ \$85.00 <i>new</i>		170.00	X
1	FRONT BUMPER <i>Distorted.</i>		745.00	✓
2	FRONT BUMPER SIDE RETAINER LH & RH @ \$80.00 <i>LH 2x</i>		160.00	36
1	FRONT BUMPER FOGLAMP RH <i>crushed</i>		320.00	233.50
1	FRONT BUMPER FOGLAMP COVER RH <i>crushed</i>		159.00	59
1	FRONT BUMPER SPONGE <i>crushed.</i>		300.65	129.60
1	FRONT BUMPER TOW COVER <i>new</i>		78.00	+
1	FRONT FENDER RH <i>Distorted.</i>		510.00	✓
1	FRONT FENDER COWLING RH <i>tom</i>		210.00	+
1	FRONT FENDER MUDFLIP RH <i>new</i>		110.00	+
1	FRONT SUPPORT PANEL <i>crushed</i>		1265.00	849
1	FRONT WHEELHUB <i>and</i>	673820	1110.00	16570
1	FRONT TIE ROD LH <i>Bent</i>	5390.56	423.00	101.30
1	FRONT KNUCKLE ARM LH <i>Bent</i>		552.00	381
1	FRONT BEARING LH <i>and</i>		630.00	145.10
1	FRONT SPARE TANK <i>crushed</i>		220.00	✓
1	Front Shock Absorber LH <i>2 Bent</i>	348 ✓		
1	Front Lower Arm LH <i>1 Bent</i>	356 ✓		
		less	20%	20%
			10735.65	
			2147.13	
			8588.52	
	SPECIAL NETT ITEMS			
1 SET	PARKING SENSOR <i>David</i>		350.00	200
1 SET	FRONT CAR PLATE WITH HOLDER <i>new</i>		70.00	+
1 SET	FRONT BUMPER CLIPS <i>new</i>		80.00	30
1	FRONT RIM RH <i>cut</i>		1091.50	550
1 SET	FRONT FENDER COWLING CLIPS <i>new</i>		100.00	30
1	RADIATOR COOLANT <i>new</i>		100.00	40
	Total Parts		10380.02	

850



ACE AUTOLUTION PTE LTD

13 Kall Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SDQ990E HYUNDAI ELIANTRA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1200.00 800	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00 400	
3	To remove and refix wiring at damaged areas	100.00 30	
4	To perform anti rust treatment on affected areas	200.00 X	
5	To remove and replace parking sensors and check for proper functions	120.00 50	
6	To conduct water seepage test	150.00 X	
7	To remove & replace undercarriage parts	230.00 ✓	1710
8	To conduct wheel alignment test	120.00 80	
Labour Total :		3120.00	
TOTAL (PARTS & LABOUR) :		13500.02	

9 To remove condenser and radiator

~~180~~ 120

total 7950.56

L/s: 6.3K.

07 Days.

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

6.3K