

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0060/19
DATE : 22-JAN-2019

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : LOH YEEN YING
ADDRESS : BLK 3 MARINE TERRACE
#06-284
S(440003)
TELEPHONE NO : 97342763

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SBH2810A
MODEL CODE : BDRUREWJ32EYAD---A
MODEL/YEAR : NISSAN TEANA 200XL
ENGINE NO : MR20833941A
CHASSIS NO : JN1BDUJ32Z0001252
MILEAGE : 100546 KM
DATE IN : 22/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH - 96450079
ACCIDENT DATE : 22/01/2019

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SBH2810A

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO RENEW FRONT BUMPER AND LH FRONT FENDER. 390	700.00	585
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME. 250	650.00	500
3 ZZ/003	RENEW DAMAGED HEADLAMP AND FOCUS.	48.00	/
TOTAL LABOUR CHARGES		1398.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SBH2810A

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NPN			60.00 20
2 HEADLAMP LH / CUT	26060-JN25A	595.20		
3 L/F FENDER STAY ?	63181-JN20A	42.00		
4 L/F FENDER PROTECTOR COVER ?	63841-JN20A	99.40		
5 FENDER-FRONT LH / DO	F3101-JN2MA	706.60		
6 FRT BUMPER SIDE MLDG LH / CUT	62075-JN00B	121.20		
7 FRT BUMPER SIDE RETAINER LH cut ?	62241-JN00A	25.20		
8 FRT BUMPER SIDE BRACKET LH / BR	62221-JN20A	55.50		
9 CLIP FRT BUMPER @ 1.30 EACH / 11C	01553-09321	7.80		
10 FRONT BUMPER FASCIA / TN	62022-JN20H	720.00		
SUB TOTAL		2372.90	0.00	60.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		474.58	0.00	0.00
GRAND TOTAL		1898.32	0.00	60.00
OVERALL TOTAL		1958.32		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

Steve (LKK) with Pradya
 83228813 26/4/19, 10-15 am
 P/P
 R-y bef spray
 4 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SBH2810A

TOTAL LABOUR CHARGES	1398.00
TOTAL SPARE PARTS CHARGES	1958.32

GRAND TOTAL	3356.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.