

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0498/2019/DY/TF
Date : 17-Apr-19

Vehicle NOT IN workshop

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm. Ng Hong Hwei
Address : Blk 52 Toh Tuck Road
#05-04
Singapore 596743
Telephone : HP +65 9386 813
Type of Claim : Own Damage Claims
Policy No. : 2100482879-02
Vehicle No : **SLF 9587 R** ✓
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Sep-16
Engine No : CZC 564589
Chassis No : WAUZZZ8V8G1105386
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Apr-19
Place of Accident : Dunearn Rd (CITY) at Newton Circus

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 9587 R

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according to damage.	s/n \$ 280.00 ✓
2	To dismantle and renew rear bumper. Inspect end panelling. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00 500
3	To respray rear bumper.	\$ 800.00 550
4	To carry out diagnostic check.	s/n \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 2,172.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 9587 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Rehnd</i>	\$ 1,708.00	✓
2	REAR BUMPER FIXING PARTS <i>neu</i>	\$ 175.00	f
3	REAR BUMPER GUIDE SECTION - LH / RH <i>neu</i>	\$ 30.00	f
4	REAR BUMPER LOCKING MECHANISM	2 \$ 53.00	x
5	REAR BUMPER REFLECTOR - LH / RH <i>neu</i>	\$ 76.00	x
6	REAR BUMPER SPOILER <i>at</i>	\$ 216.00	✓
7	REAR REINFORCEMENT BAR <i>neu</i>	\$ 522.00	x
8	REAR BUMPER BRACKET - LH / RH <i>neu</i>	\$ 24.00	x
9	REAR BUMPER SENSOR <i>neu</i>	2 \$ 462.00	x
10	REAR BUMPER SENSOR SEAL RING <i>neu</i>	4 \$ 12.00	x
11	EXHAUST CHROME TRIM - LH <i>Not m</i>	TBC	x
12	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS		\$ 3,578.00	
TOTAL LABOUR CHARGES		\$ 2,172.00	
GRAND TOTAL		\$ 5,750.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 28/04/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repairs, 03 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant