

FIRST AUTOWORKS

Repair Estimate

2019.
Date : 23/04/2018

Make : Chevrolet
Orlando

To Whom It May Concern

Dear Sir,

Re: VEHICLE. SLE 4325T
CHASSIS NO.: KL1YA7589GK347418
ENGINE NO.: A14NET161440738

Name of insured : Mohd Faaiz Bin Ishar
Date of accident : 22/04/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer.

Signature:

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	RH WING MIRROR ASSY <i>Damaged</i>	1,180.00

1180
708
Parts Total : 1180.00
Less 40% : 472.00
Total : 708.00

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts	300.00 <i>100</i>
2	Carry out spray painting on affect area Rh Side portion	300.00 <i>100</i>
3	To disconnect front wire harness of electrical component to facilitate repair, reconnect & check electrical function after repair	50.00 <i>30</i>

230
Labour Total : 650.00

Total : 1358.00
Gst (7%) : 95.06
Grand Total: 1453.06

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Ronnie Tan

total 938
(P/P)

Adrian King
P/P 10/10 02 Pyp.