

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle No: SFY 709L

Vehicle Model: Mitsubishi Lancer

Accident on: 22/4/2019

Page 2 of 2
Your ref. TP-SJP 6059P AXA
Job No. 70440
Our ref. 19.04.35
Payment
Date 24/4/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To dismantle + refix rear cushion assy + rear speaker board, etc	120.00	80.00	120.00 ✓
1.00		To dismantle + renew rear bumper lower spoiler + transfer parking sensors	160.00	140.00	160.00 ✓
1.00		To straighten rear body including cutting and welding, to knock dents on rear spare tyre panel RH and renew of parts	1,100.00	1,000.00	1,100.00 ✓
1.00		To spray paint	1,000.00	900.00	1,000.00 ✓

Lump sum repair
Repair days 8 days

24/4/19 1730

Lim Teow Guan Mr

97361577

Sub-Total
GST 7.00%
Total

5,546.65
388.27
5,934.92

S\$

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022076
Hui Kwok Thong

Page 1 of 2
Your ref. TP-SJP 6059P AXA
Job No. 70440
Our ref. 19.04.35
Payment
Date 24/4/2019

Attn

Vehicle No SFY 709L
Vehicle Model : Mitsubishi Lancer
Accident on ... 22/4/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear windscreen moulding	28.00	10.00	25.20 NEC✓
1.00	Pc	Rear fender RH	666.00	10.00	599.40 DD✓
1.00	Pc	Rear end panel	495.00	10.00	445.50 DD✓
1.00	Pc	Rear tail lamp RH	421.00	10.00	378.90 BR✓
1.00	Pc	Rear tail lamp bush (top) RH	6.00	10.00	5.40 } NEC✓
1.00	Pc	Rear tail lamp bush (lower) RH	6.00	10.00	5.40 }
1.00	Pc	Rear bumper	689.00	10.00	620.10 BR✓
1.00	Pc	Rear bumper lower spoiler	688.00	10.00	619.20 DL✓
1.00	Pc	Rear bumper beam RH	56.00	10.00	50.40 BT✓
1.00	Pc	Rear bumper centre beam	209.00	10.00	188.10 ? X svc
1.00	Pc	Rear bumper inner shield RH	38.00	10.00	34.20 TN✓
3.00	Pcs	Rear bumper inner shield clips RH	5.50	10.00	14.85 NEC✓
Labour & Misc:					
1.00		To remove + refix rear windscreen	140.00		140.00 NEC✓
1.00		To supply sealant	40.00		40.00 NEC✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."