

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

CS3/ASM19007274/Ua3s2 AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 Date: 03-07-2019 **AXA TOWERSINGAPORE 068811** ATTN: LYNN KHONG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **GBB 148Z** Veh. Inspected SMA 4016U Policy No. GA336377/1 Coverage (\$) 0.00 S9M01KNH 0.00 Claim No. Excess (\$) LYNN KHONG 24/04/2019 **Assign From Assign Date** 2. **Vehicle Particulars & Condition** Make & Model HONDA STREAM (A) 1799 HIDDEN 2009 Engine No. Year of Reg. RN61069327 Chassis No. Colour **GREY** Odometer 140889 KM Steering IN ORDER **Brakes** IN ORDER Modification SPORTS RIM General GOOD **Conditions of Tyres** 3. Size Make **Balance** 6 mm 205/65R15 **KUMHO** R/H Front Tyre L/H Front Tyre 205/65R15 KUMHO 6 mm 205/65R15 **KUMHO** R/H Rear Tyre 6 mm 205/65R15 **KUMHO** 6 mm L/H Rear Tyre 4. **Description of Damages** THW VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 17/04/2019 Inspect Date / Time 24/04/2019 ( 12:47 PM ) **Accident Date** ACE AUTO SOLUTION Survey held at

23 KAKI BUKIT AVE 4,#04-01 (SOUTH WING) SINGAPORE 415933

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

Report Ref No. CS3/ASM19007274/Ua3s2

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.