

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204

SINGAPORE 528840

TEL : 67853933 FAX: 67883933

R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S6985562H

ZHENG HONG

BLK BLK 838 TAMPINES STREET 82

10-85

SINGAPORE 520838

TEL : FAX :

PH : 91878738

ATTN :

Term:

ESTIMATE BILL

Number : EBK0000270

Date : 23/04/2019

Case No : ADK0000343

Vehicle No : SKJ1416U

Chassis:

Year of Mfr

Policy No

Model : HYUNDAI ELANTRA

1.6 AT

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRT BUMPER	1.0	450.00	20	360.00
2	FRT BUMPER SIDE RETAINER LH RH	2.0	18.00	20	28.80
3	FRT BUMPER CLIPS	12.0	5.00	20	48.00
4	FRT FENDER LH	1.0	445.00	20	356.00
List Price - Parts Sub Total					792.80
Parts Total					792.80
5	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	600.00
6	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	600.00	0	600.00
Labour 1 Sub Total					1,200.00
SINGAPORE DOLLARS : TWO THOUSAND ONE HUNDRED THIRTY-TWO AND CENTS THIRTY ONLY					
Less Excess					0.00
SUBTOTAL					1,992.80
GST 7.00%					139.50
TOTAL					2,132.30

NOT AFFECTED
LH RH
P/L & 600
2 Ltr.
25/4/19
Take pmt. After rep.

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Date of accident : 09/04/2019 08:40 PM. Place : TAMPINES ST 82

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST