

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL :67853933 FAX:67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S6985562H
ZHENG HONG
BLK BLK 838 TAMPINES STREET 82
10-85
SINGAPORE 520838
TEL : FAX :
PH : 91878738
ATTN :

ESTIMATE BILL

Number : EBK0000270
Date : 23/04/2019
Case No : ADK0000343
Vehicle No : SKJ1416U
Chassis:
Year of Mfr
Policy No
Model : HYUNDAI ELANTRA
1.6 AT

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRT BUMPER	1.0	450.00	20	360.00
2	FRT BUMPER SIDE RETAINER LH RH	2.0	18.00	20	28.80
3	FRT BUMPER CLIPS	12.0	5.00	20	48.00
4	FRT FENDER LH	1.0	445.00	20	356.00
List Price - Parts Sub Total					792.80
Parts Total					792.80
5	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	600.00
6	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	600.00	0	600.00
Labour 1 Sub Total					1,200.00
SINGAPORE DOLLARS : TWO THOUSAND ONE HUNDRED THIRTY-TWO AND CENTS THIRTY ONLY					
Less Excess					0.00
SUBTOTAL					1,992.80
GST 7.00%					139.50
TOTAL					2,132.30

Date of accident : 09/04/2019 08:40 PM. Place : TAMPINES ST 82

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST